

Welome to Ames Performance Engineering

We want to thank you for requesting our newest Full Size & Grand Prix catalog.

Ames Performance Engineering sells *only* Pontiac parts and is in its twenty-fourth year of supplying enthusiasts worldwide. During this time we have established a reputation among our customers for prompt service and the finest quality available. This attention to quality is especially evident in our reproduction items, many more of which are now being made in our own shop. As in the past we will critique our products in order to inform our customers of the quality of each reproduction.

Both phone and mailorders will be processed and shipped within 24 hours, except during shows or in backorder situations. During 1999 our large in-house inventory allowed us to ship 93% of all orders within that deadline.

Therefore, if an order is called in to us by 10 a.m. Monday, it should be in your hands by Tuesday if you live in eastern New York and New England (except Northern Maine). You'll have it Wednesday in New Jersey, Eastern New York and parts of Delaware and Maryland. On Thursday your order should be delivered to most of North Carolina, Virginia, West Virginia, Ohio and Western New York. All other continental sections of the country should receive their orders by Friday or the following Monday. (The above service is dependent on typical UPS shipping schedules.)

In order to make this catalog as helpful as possible, we have divided it into the following nineteen sections:

- | | | |
|----------------------|------------------------|---------------------------|
| 1. INTERIOR | 7. CONVERTIBLE TOP | 14. TRANSMISSION, CLUTCH, |
| 2. FRONT END TRIM | 8. REAR 1/4 TRIM | & BRAKE |
| 3. FRONT FENDER TRIM | 9. TRUNK COMPONENTS | 15. SUSPENSION |
| 4. HOOD COMPONENTS | 10. REAR END TRIM | 16. WHEELS & TIRES |
| 5. DOOR COMPONENTS | 11. ELECTRICAL RELATED | 17. MISCELLANEOUS |
| 6. WINDSHIELD & REAR | 12. ENGINE COMPONENTS | 18. LITERATURE |
| WINDOW RELATED | 13. ENGINE COMPARTMENT | 19. DECALS |

All parts in this catalog are sold with a satisfaction guaranteed policy. Please examine your order immediately. All shortages, incorrect items, and damages should be reported as soon as possible. To return an item to us, please contact us for instructions. If Ames is responsible for the incorrect shipment we will reimburse the customer for his return shipping charges (under no circumstances will Ames pay for additional charges incurred by using packaging services, air shipping or accept COD shipments). For your protection, send the package by UPS or insured Parcel Post, saving the receipt until you hear from us. If the package was damaged in shipment, save the merchandise and packaging. Notify the carrier immediately for instructions.

We will maintain the prices in this catalog as long as possible. However, we reserve the right to make price changes whenever necessary. Prices charged shall be those prevailing at time of shipment. Items may be discontinued at any time.

Parts may be ordered by calling our Toll-Free ORDER LINE 800-421-AMES (2637). Please tell us which catalog you are using, your customer number from your catalog mailing label, the part numbers, and a brief description of the items desired. Parts may also be ordered by mailing or faxing the order blank located toward the rear of this catalog.

Methods of payment: We accept VISA, MasterCard, Discover, and moneyorders. (Personal and company checks are also accepted for mail orders only. However, we reserve the right to hold large personal checks for proper clearance.) We also offer COD shipping (Note: **Certified Check or Money Orders**); COD charges are \$5.00 additional per box. Note: We cannot ship COD orders by air. When using credit cards be sure to give complete card number and expiration date on each order.

Minimum order is \$10. Note: We cannot accept credit cards at flea markets.

Glossary of abbreviations:

AC	= Air Conditioning	DB	= Disc Brakes	OD	= Outside Diameter
AP	= After-Product	GM	= Factory Part	OEM	= Original Equipment
AS	= Air Suspension	HD	= Heavy Duty		Manufacturer
AT	= Auto Transmission	HO	= High Output	RE	= Reproduction
APE	= Our Own Product	LH	= Driver Side	RH	= Passenger Side
CPE	= Hardtop Coupe	MT	= Manual Transmission	RP	= Replacement Part
CVT	= Convertible	NOS	= New Old Stock	Sedan	= Sport Coupe (w/post)
Disc	= Discontinued		(factory parts no longer available from GM)	SW	= Station Wagon
				TI	= Transistorized Ignition

Ames Performance Engineering

© Copyright 1999 Ames Performance Engineering.

All rights reserved. No part of this catalog may be reproduced without written permission from Ames Performance Engineering.

BONNEY ROAD — MARLBOROUGH, N.H. 03455

ORDER LINE: 800-421-2637, FAX: 603-876-4767, E-MAIL: customer.service@amesperf.com

TELEPHONE: 603-876-4514, 603-876-4656 OR 603-876-3345

SEARCH FOR PARTS & ORDER ONLINE-<http://www.amesperf.com>

NO RETAIL OUTLET — SALES BY MAIL AND AT SHOWS ONLY

WHY CHOOSE AMES PERFORMANCE ?

- * **PRICES:** Always fair
- * **CATALOGS:** Always free
- * **QUALITY:** Twenty-three years of the finest! Disregard those "Us vs them" ads since we have always tested and chosen the best products.
- * **BACK ORDERS:** Lowest rate in the industry.
- * **INVENTORY:** Nation's largest - we couldn't supply a 98.6% order fill rate without it.
- * **SHIPPING:** Same day with no additional charges.
- * **SHIPPING CHARGES:** Low - plus we only charge an additional amount for each overweight or oversized UPS item, as noted under each item. Beware of some graduated shipping scales—as an example, a \$300 order without oversized items can cost between \$17 and \$20. Our charge is \$6.50 no matter how large your order of non-over sized products.
- * **PRODUCTS:** We have over 300 Pontiac products manufactured and distributed throughout the industry (these are denoted with an (APE) in our catalog.) It is best to purchase products from manufacturers when possible since customer satisfaction is our responsibility.
- * **SHOW PARTICIPATION:** We make the commitment to talk to customers and display our products on the road.
- * **SPECIALISTS:** We sell Pontiac only - one company cannot expect to be efficient and knowledgeable in several car lines.
- * **EXPERTISE:** Extensive Pontiac technical knowledge as well as many Pontiacs on site for immediate research. We have twice as many Pontiac tech-advisers as any other supplier in the country.
- * **LONGEVITY:** We've been in business since 1976.
- * **SERVICE:** We've built this company on service.
- * **REPUTATION:** Unparalleled excellence in the industry.

Best Quality, Best Service, and Best Prices are never found with the same supplier except at Ames Performance.

**An Ames Performance Gift Certificate Is Perfect
For That Particular Enthusiast Who Has Everything.
————— Please Inquire. —————**

SAVE UP TO 10% ON PREPAID ORDERS!

Save 3% on mail or phone orders over \$500.00 with MC, VISA or Discover.

Save 5% on mail orders over \$500.00 with cashier's check or money order.

Save 8% on mail or phone orders over \$1000.00 with MC, VISA or Discover.

Save 10% on mail orders over \$1000.00 with cashier's check or money order.

NOTE: Discounts do not apply to shipping charges or specially marked items.

Also, discount applies on individual order only.

LOW MILEAGE

WANTED

LOW PRODUCTION

We continue to add Pontiac muscle cars to our collection. If you have or know of a very low mileage original car or low production in any condition please call 800-421-2637. Finder's Fee Paid

IMPORTANT NOTE:

This catalog covers all full-size Pontiac models from 1955-76 and Grand Prix up to 1977. In 1969 Pontiac changed the Grand Prix from the full-size "B" body to the intermediate size "G" body. To avoid confusion for the years 1969-1977, we will use "ALL" after the part description if the part fits both Grand Prix and full-size. If a part only fits full-size models then "FS" will follow the part description. If a part only fits Grand Prix, then "GP" will follow the part description. Please note this when ordering.

SECTION ONE-INTERIORS

ACCESSORY MATS

Note 2: As with any large rubber product, small air pockets or blemishes may be present.

Please add \$7.00 shipping for PA100.



PA100

PA100 1956-57 Accessory Mats (RE)\$169.00/set

Note : Since these mats are the same shape as originals, the rears must be cut for different body styles. This same procedure was used by GM so please specify what body style you have when ordering.

Comments: This project has been well-received by many collectors of mid-fifties Pontiacs. These original-style mats have always been extremely scarce and in some cases ridiculously expensive. These mats are molded using exactly the same design and shape as original. They are manufactured using solid colored materials of black, blue, and red, and have proved to be extremely durable and fade-resistant. They are excellent for everyday use.

Note 1: Although not originally available for 1949-'55 Pontiacs, these mats add a finishing touch for those same models.



PA100E

PA100E 1958 Accessory Mats (RE)\$169.00/set

These original-style mats are available in solid material of black, blue, and red.

Please refer to comments under PA100 for further information about this product.

Please add \$7.00 shipping for PA100E.





PA100K

PA100K 1961-63 Accessory Mats (RE).....\$169.00/set

These original-style mats are available in solid material of black, blue, and red.

Please refer to comments under PA100 for further information about this product.

Please add \$7.00 shipping for PA100K.



PA101

PA101 1964-70 Accessory Mats-FS (RE)..... 99.00/set

PA102 1971-72 Accessory Mats-FS (RE)..... 99.00/set

PA102 1969-72 Accessory Mats-GP (RE) 99.00/set

Note: Please include \$7.00 shipping for PA101 and PA102.

PA120 1964-70 Front Accessory Mats-FS—Black Only (RE)..... 65.00/pr.

PA121 1971-72 Front Accessory Mats-FS—Black Only (RE)..... 65.00/pr.

PA121 1969-72 Front Accessory Mats-GP—Black Only (RE)..... 65.00/pr.

PA123 1964-72 Rear Accessory Mats-ALL—Black Only (RE)..... 60.00/pr.

Comments: Very good—one of our most popular reproductions, these accessory floor mats are molded using exactly the same design and shape as original.

Colors and Ordering Information: For the past eleven years, these mats have only been available in black. We now have supplies of blue, and red material. **Please add \$10.00 for blue and red mat sets. Colored mats available in full sets only.**



PA102

Important Note: Our mats are now manufactured using an insert for the Pontiac crest. Black, blue, and red mats are now practically indestructible.

Note: As with any large rubber product, small air pockets or blemishes may be present.

Since the rear mats have the same shape as original, they must be cut for bucket seat applications. This procedure was used by GM from 1964-72. Instructions are included.

CARPET SETS



The following carpet sets are available at this time. In the future as correct materials become available, we will add to this list.

Important: Please specify model, body style, number of doors, with or without bucket seats

and/or console, manual or automatic transmission, with or without Power Brakes, and color desired. If you are interested in blue, red, saddle, green or gold carpets, we suggest you request samples for color match.

Note: All 4-door carpets are a special order.

- PA130** 1955-57 Daytona Weave Carpet, 2 Dr. (RE)...\$219.00/set
PA130B 1955-57 Daytona Weave Carpet, 4 Dr. (RE).. 219.00/set
PA130D 1955-57 Daytona Weave Carpet Safari (RE) .. 219.00/set

Different quality Daytona weave carpets have been available for Chevrolets for years. The supplier of the nation's finest product (a special foam-backed material) has made an excellent reproduction of the 1955-57 carpets to fit the Pontiac floor pan.

This manufacturer has also duplicated the original heel pad. Because of their dedication to quality, we highly recommend this carpet.

Daytona Weave carpet colors available: Grey, lt. green, dk. green, lt. blue, med. blue, dk. blue, aqua, bronze, black, red and beige.

- PA131** 1955-57 80/20 Loop Pile Carpet, 2 Dr. (RE)... 119.00/set
PA131B 1955-57 80/20 Loop Pile Carpet, 4 Dr. (RE)... 119.00/set
PA131D 1955-57 80/20 Loop Pile Carpet Safari (RE) ... 119.00/set
PA132 1958 Lurex Weave Carpet w/Front & Rear Bucket Seats (RE)..... 319.00/set
PA133 1958 Lurex Weave Carpet w/Front Buckets and Std. Rear (RE) 319.00/set
PA134 1958 Lurex Weave Carpet w/Bench Seat (RE) 319.00/set

PA132 through PA134 are excellent reproductions with the correct style lurex thread.

Colors Available: Charcoal, lime green, sunset glow, dk. turquoise, red and blue, all with silver thread and copper with gold thread.

- PA135** 1958 80/20 Loop Pile Carpet (RE) 119.00/set
 These carpets are correctly contoured and are an exact fit. They will not have the lurex thread.

- PA137** 1959 Lurex Weave Carpet, 2 Dr. HT (RE). 319.00/set
PA138 1959 Lurex Weave Carpet, Conv. (RE) 319.00/set
PA138D 1959 Lurex Weave Carpet, 4 Dr. HT (RE). 319.00/set

These carpets are excellent reproductions with the correct style lurex thread.

Colors Available: Charcoal, lime green, sunset glow, dk. turquoise, red and blue, all with silver thread.

- PA139** 1959 80/20 Loop Pile Carpet (RE) 119.00/set
PA140 1960 80/20 Loop Pile Carpet (RE) 119.00/set
PA142 1961-64 80/20 Loop Pile Carpet-ALL exc. Bonneville and 63-64 GP w/Console (RE)..... 119.00/set
PA143 1961-64 80/20 Loop Pile Carpet-Bonneville (RE)..... 119.00/set
PA144 1963-64 80/20 Loop Pile Carpet-GP w/Console (RE)..... 119.00/set

- PA145** 1965-70 80/20 Loop Pile Carpet-FS (RE).....\$119.00/set

Note: Beware of companies selling less expensive, incorrect Chevrolet B-body carpets. We sell only Pontiac carpets which have the correct extra material up front to meet the fire-wall pad. Pontiacs are the only GM cars that utilize this extra length.


- PA150** 1971-73 80/20 Loop Pile Carpet-FS (RE) 119.00/set
PA152 1969-72 80/20 Loop Pile Carpet-GP (RE) 95.00/set
PA153 1973 80/20 Loop Pile Carpet-GP (RE) 95.00/set

Comments: Over the past years, several new companies have started manufacturing 80/20 carpet sets. In keeping with our on-going policy of analyzing all products in our field, we have tested these new carpets. It is our opinion that none compares to the original 80/20 style carpets we have supplied to the GTO and Firebird market for the last nineteen years. Discount carpets have no place in a fine restoration. Depend on our quality.

- PA154** 1974-76 100% Nylon Cut Pile Carpet-FS (RE)..... 119.00/set
PA156 1974-76 100% Nylon Cut Pile Carpet (2 pc.)-GP (RE) 95.00/set
PA157 1977 100% Nylon Cut Pile Carpet (1 pc.)-GP (RE)..... 95.00/set

Note: Please add \$7.00 for carpet shipping.

FLOOR INSULATION



- PA160** 1955-57 Standard Floor Insulation Kit -(RE) ... 49.00/set
PA160A 1955-57 Correct Floor Insulation Kit -(RE)..... 69.00/set
PA162 1959-60 Standard Floor Insulation Kit -(RE) ... 49.00/set
PA162A 1959-60 Correct Floor Insulation Kit -(RE)..... 69.00/set
PA163 1961-64 Standard Floor Insulation Kit-(RE) 49.00/set
PA163A 1961-64 Correct Floor Insulation Kit-(RE) 69.00/set
PA165 1965-70 Standard Floor Insulation Kit-FS (RE)..... 49.00/set
PA165A 1965-70 Correct Floor Insulation Kit-FS (RE).. 69.00/set
PA166 1971-76 Standard Floor Insulation Kit-FS (RE)..... 49.00/set
PA166A 1971-76 Correct Floor Insulation Kit-FS (RE).. 69.00/set
PA169 1969-72 Standard Floor Insulation Kit-GP (RE)..... 39.00/set
PA169A 1969-72 Correct Floor Insulation Kit-GP (RE) 59.00/set
PA170 1973-77 Standard Floor Insulation Kit-GP (RE)..... 39.00/set
PA170A 1973-77 Correct Floor Insulation Kit-GP (RE) 59.00/set

These sets replace the floor insulation under the carpet. Many times upon replacing the carpet you will find the original material cracked and useless.

Comments: The standard kits are made from a material very similar to the original tar paper type. They are manufactured in smaller dovetailed pieces than the factory's because of shipping problems. Correct floor insulation kits are made of an exact reproduction of the original paper-backed material.

Please add \$7.00 for shipping.



Note: For new door sill plates see PF640 - PF655L.



BUCKET SEAT BACK PANELS



PA174BJ

PA174B 1968 Bucket Seat Back Panels, Black (RE)..... \$ 65.00/pr.

PA174BD 1968 Bucket Seat Back Panels, Colors (RE)..... 75.00/pr.

Note: For 69-71 bucket seat interiors with a passenger seat recliner use PA174B panels.


PA174BJ 1969-72 Bucket Seat Back Panels, Black (RE)..... 65.00/pr.

PA174BK 1969-72 Bucket Seat Back Panels, Colors (RE)..... 75.00/pr.

These are the plastic panels that make up the back of your bucket seats. Originals often are scratched or have disintegrated with age (many times producing a fine white powder).

These new reproduction panels are much better than those previously available. They now have the correct simulated vinyl grain and correct gloss.

The '68 panels come complete with chrome piping and piping caps, the 69-72 panels come with chrome piping and correct molded ends on the panels.



PB174BL

PA174BL 1968-72 Lower Side Seat Panel, Black (RE)..... \$89.00/set

PA174BM 1968-72 Lower Side Seat Panel, Colors (RE)..... 109.00/set

As a complement to the seat back panels we also offer the lower side panels. Made from the same grained plastic they also come complete with seat piping chrome. Each set consists of four pieces.



For the best possible savings, order your seat back panels and lower side seat panels as a kit.

PA174BN 1968 Seat Panel Kit-Black135.00/kit

PA174BP 1968 Seat Panel Kit-Colors.....165.00/kit

PA174BS 1969-72 Seat Panel Kit-Black135.00/kit

PA174BT 1969-72 Seat Panel Kit-Colors.....165.00/kit

Note: Discounts do not apply to seat panel kits.

BUCKET SEAT HEADREST COVERS




PA174S 1969-72 Bucket Seat Headrest Covers (GP)27.00/pr.

These replacement headrest covers are pre-sewn and ready to install over the old headrest. Inquire on colors availables.

Comments: Not molded like originals, quality is fair to good.

BUCKET SEAT SPRINGS



PA175FC

PA175FC 1962-65 Bucket Seat Bottom Side Support Spring Kit (RE)..... \$ 15.00/kit


Contains enough springs and fasteners for the sides of one bucket seat bottom.

PA175FK 1966-67 Bucket Seat Bottom Side Support Spring Kit (RE)..... 25.00/kit

Contains enough springs and fasteners for the sides of one bucket seat bottom.

PA175FN 1968-72 Bucket Seat Bottom Side Support Spring Kit-ALL (RE) 25.00/kit

Contains enough springs and fasteners for the sides of two bucket seat bottoms.



PA175HB 1962-65 Bucket Seat Bottom Spring Assembly w/Side Support Springs (RE) 79.00/ea.

PA175HD 1962-65 Bucket Seat Back Spring Assembly (RE)..... 69.00/ea.

PA175HH 1966-67 Bucket Seat Bottom Spring Assembly w/Side Support Springs (RE)..... 79.00/ea.

PA175HK 1966-67 Bucket Seat Back Spring Assembly (RE)..... 69.00/ea.

PA175HN 1968-72 Bucket Seat Bottom Spring Assembly w/Side Support Springs All (RE) 79.00/ea.

PA175HR 1968-72 Bucket Seat Back Spring Assembly All (RE) 69.00/ea.

BUCKET SEAT PADDING




PA177

PA176J 1962-65 Bucket Seat Padding (RE) \$115.00/set
PA177 1966-72 Bucket Seat Padding (RE) 115.00/set
PA177B 1973-77 Bucket Seat Padding-GP (RE)..... 199.00/set

This four-piece contoured set of bucket seat foam restores original shape and resilience to worn buckets. If shape or foam density of your bucket is a problem, we recommend these seat pads be installed.

Please add \$7.00 for shipping bucket seat padding.

BUCKET SEAT PIPING AND CAPS



PA178

PA179

PA178 1966-68 Bucket Seat Chrome Piping 12.00/set

This material is the chrome plastic bead that runs up the sides and over the top of the bucket seats. It is not an exact reproduction but conforms very close to original. Enough material is included to refinish both front buckets.

PA178K 1966-67 Molded Bucket Seat Chrome Piping (APE)..... Inquire

PA178N 1968-72 Molded Bucket Seat Chrome Piping (APE)..... Inquire

PA178K and PA178N are correct reproductions
Comments: Quality of these reproductions is excellent

PA179 1966-68 Bucket Seat Chrome Piping Cap (RE)..... 2.00/ea.

These are the small chrome caps that cover the ends of the PA178 piping. In many cases these are missing from original interiors.

PA180 1969-77 Bucket Seat Piping (RE)75/ft.

Again, this is not an exact reproduction but works well. Major difference is smaller diameter.



PA182M

PA182M Upholstery Installation Kit 8.00/kit

For customers installing their own seat upholstery, this kit includes one pair of hog ring pliers and enough hog rings for one seat kit.

VINYL YARDAGE

Vinyl yardage is available. Price is \$24.00 per running yard (36" x 54") of Seville or Madrid Grain. Please call for samples.

SEAT COMPONENTS



PA184



PA185



PA186

PA184 1962-65 Bucket Seat Chrome Rod End Cap (RE)..... \$ 2.50/ea.

This cap covers the pivot rod that allows the bucket seat back to fold forward.



PA184JB



PA184JD



PA184JG

PA184JB 1955-56 Upper Seat Back Stops (RE)..... 5.50/set

PA184JD 1955-56 Lower Seat Back Bumper (RE)..... 6.00/set

PA184JG 1957 Upper Seat Back Bumper (RE) 6.00/set

PA185 1964-65 Seat Back Bumper (RE)..... 2.50/ea.

The reproduction seat back bumpers have correct size, shape, and include steel insert.

PA186 1964-77 Seat Back Bumper (GM) 2.00/ea.

Both PA185 and PA186 have been found on 1964 models. Please check your car and refer to diagrams before placing your order.

PA186J 1965-67 Folding 3rd Seat Rear Bumpers SW (RE) 1.50/pr.



PA190



PA193



PA196



PA196C

PA190 1955-57 Chrome Seat Adjustment Knob (RE) 6.00/ea.

PA192 1959-60 Chrome Seat Adjustment Knob (RE) 19.00/ea.

This knob also fits '61 Bonneville convertible.

PA193 1961-64 Chrome Seat Adjustment Knob-Exc. Bonneville & GP (RE) 19.00/ea.

PA194 1962-64 Chrome Seat Adjustment Knob-Bonneville & GP w/Bucket Seats (RE)..... 19.00/ea.

Note: Requires two.

PA195 1965 Chrome Seat Adjustment Knob-ALL (RE)..... 11.00/ea.

PA195 1966 Chrome Seat Adjustment Knob Bench Seat (RE) 6.00/ea.

PA196 1967-70 Chrome Seat Adjuster Knob-ALL (RE)..... 6.00/ea.

PA196C 1967-70 Bench Seat Release Knob (RE) 6.00/ea.

PA198 1970-77 Black Plastic Seat Adjuster Knob-ALL (GM) 4.00/ea.



PA200



PA201

PA199S 1969 Bucket Seat Headrest Escutcheon (RE)..... \$ 9.50/ea.

This is the escutcheon only.

PA200 1970-72 Bucket Seat Headrest Lock Assembly w/Escutcheon (RE)..... 14.00/ea.

PA201 1969-72 Bucket Seat Release Button Assembly (RE) 22.00/ea.

This is the chromed plastic button assembly mounted in the seat back. Each assembly comes complete with the spring steel attaching clip.

Comments: Quality of all these reproductions (PA199S through PA201) is excellent.

SEAT MOUNTING BRACKETS



PA204

PA204 1967-72 Bucket Seat Mounting Brackets (RE) 19.00/pr.

These brackets mount the inside bucket seat track to the floor. They are needed when converting from bench to bucket seats or when floors are badly rusted.



PA204D


PA204D 1962-72 Power Seat Mounting Bracket (RE) .. 75.00/ea.

One of these brackets is needed for a bucket seat installation while two are required for bench seats.

SEAT BELTS AND COMPONENTS



PA206AA



PA206AH

PA206AA 1955-57 Front Seat Belt (1 person) (RP)..... 55.00/ea.

PA206AC 1955-57 Rear Seat Belt (1 person) (RP)..... 55.00/ea.

PA206AH 1955-57 Seat Belt Mounting Hardware (1 person) (RP)..... 3.50/ea.

With State Laws requiring the use of passenger restraints, these original style buckles provide the correct appearance of dealer installed seatbelts. These belts meet all required current federal safety standards. They have chrome plated fixed anchor ends and satin finished lift up release lid.



Colors available include white, black, red, light blue, medium blue, light turquoise, dark turquoise, dark green, beige, copper, brown and dark gray.

PA206BA 1958-65 Front Seat Belt (1 person) (RP)..... \$ 55.00/ea.

PA206BC 1958-65 Rear Seat Belt (1 person) (RP)..... 55.00/ea.

See note under 1955-57 seatbelts. These 1958-65 belts are basically the same belt except the buckle is chrome plated instead of the satin finish.

The same colors are available as were for PA206AA and PA206AC. In addition: maroon, bright red, fawn, dark fawn and medium gold are available.

PA206AH 1958-65 Seat Belt Mounting Hardware (1 person) (RP)..... 3.50/ea.

PA206BA 1955-65 Seat Belt (1 person) Front or Rear w/ Mounting Hardware (RP)..... 29.00/ea.

Note: These belts are offered as an inexpensive alternative with a chrome clasp. Available in black, white, dark blue, red and maroon



PA206GM

PA206GM 1967-72 Seat Belt Buckle Cover-Black, with GM Mark of excellence Decal (RE)..... 22.00/ea.

This is a plastic cover like those used on standard interiors.



PA206HR

PA206HT

PA206HR 1967-72 Seat Belt Retractor Anchor Bolt (1/2"-13 x13/16") (GM)..... 14.00/ea.

PA206HT 1969-72 Inner Seat Belt and Shoulder Strap Anchor Bolt (1/2"-13 x13/16" w/ .556 Shoulder) (RP)..... 5.50/ea.

This bolt has a shoulder which allows the seat belt to swivel on the bolt.



PA208R

PA208L 1977 Shoulder Belt Guide Support, LH-GP (GM)..... 4.00/ea.

PA208R 1977 Shoulder Belt Guide Support, RH-GP (GM)..... 4.00/ea.

PA209 1977 Shoulder Belt Guide Support, R or L-FS (GM)..... \$ 2.00/ea.

PA208L & R and PA209 are the supports that the shoulder belt guide snaps into. Paint to match.



PA211J



PA211K

PA211J 1974-76 Shoulder Belt Guide, Black (GM) 2.00/ea.

PA211K 1977 Shoulder Belt Guide, Black (GM) 2.00/ea.

PA211J and PA211K are paint to match.

DOOR PANEL COMPONENTS



PA215 1964-65 2+2 Door Panel Emblems (RE) 54.00/pr.

Note: Because of the limited market, PA215 is not die-cast. It is a low-pressure casting and the quality is good.

PA220 1964-77 Door Panel Trim Fastener (RE)..... .35/ea.

PA221 1964-77 Door Panel Fastener Kit (RE) 4.00/kit

Note: This kit contains 12 PA220 and 12 original style screws.

PA222 1964-77 Door Panel Trim Fastener Grommet (RE)..... .40/ea.

This is the grommet that the trim fastener plugs into. Most cars require 12 pieces.



PA225 1960-73 Door Panel Carpeting, 80/20 Loop (RP)..... 25.00/pr.

PA226 1974-77 Door Panel Carpeting, Cut Pile (RP) 25.00/pr.

Note 1: PA225 & PA226 are 18" x 74" pieces of carpeting which is enough to replace worn out carpeting on both door panels. It must be cut to fit. Does not come with vinyl strip.

Note 2: This carpeting can also be used on automobiles with carpeted kick panels.



DOOR PANEL WATER SHIELDS



PA228K

PA228D	1959-60	Paper Backed Door Panel Water Shields (RE)	\$ 11.50/pr.
PA228F	1961-62	Paper Backed Door Panel Water Shields (RE)	11.50/pr.
PA228H	1963-64	Paper Backed Door Panel Water Shields (exc. GP) (RE)	11.50/pr.
PA228K	1963-64	Paper Backed Door Panel Water Shields GP (RE)	11.50/pr.
PA228N	1965-66	Paper Backed Door Panel Water Shields (RE)	11.50/pr.



PA230K	1977	Door Assist Pull Strap Escutcheon Cover-All (GM)	2.00/ea.
---------------	------	--	----------

Requires two per strap.



PA233J

PA233J	1970-72	Remote Mirror Control Knob Escutcheon-GP (GM)	15.00/ea.
PA233K	1971-72	Remote Mirror Control Knob Escutcheon-FS (GM)	Disc.

These are the chrome bezels that surround the mirror control knob.

POWER WINDOW SWITCHES



PA235B


PA235B	1964-68	Power Window Switch-LH Door, Exc. 1967 Bon. & GP (4 button) (NOS) ...	65.00/ea.
PA235D	1967	Power Window Switch-RH Door (1 button), Bonneville & GP (GM) ...	39.00/ea.

PA235B	1969	Power Window Switch-LH Door (4 button), ALL exc. Bonneville and GP (NOS)	\$ 65.00/ea.
PA235H	1969-72	Power Window Switch-RH Door and Rear 1/4 Window (1 button), GP (GM)	54.00/ea.
PA235J	1971	Power Window Switch-LH Door (4 button), FS (GM)	97.00/ea.
PA235J	1972-74	Power Window Switch-LH Door (4 button), Catalina (GM)	97.00/ea.
PA235H	1971	Power Window Switch-RH Door and Rear 1/4 Window (1 button), FS (GM)	54.00/ea.
PA235H	1972-74	Power Window Switch-RH Door and Rear 1/4 Window (1 button), Catalina (GM)	54.00/ea.
PA235D	1972-77	Power Window Switch-RH Door and Rear 1/4 Window (1 button), ALL FS exc. Catalina (GM)	39.00/ea.

UNDERDASH INSULATION

PA239J	1969-72	Underdash Insulation-GP (RE)	15.00/set
---------------	---------	------------------------------------	-----------

This 3-piece insulation set is a felt-backed black plastic and mounts directly under the dash.



FIREWALL PADS



PA248

PA249

PA240	1955-56	Firewall Pad (RE)	155.00/ea.
PA240B	1957	Firewall Pad (RE)	155.00/ea.
PA240D	1958	Firewall Pad (RE)	135.00/ea.
PA240F	1959-60	Firewall Pad (RE)	135.00/ea.
PA240H	1961-62	Firewall Pad (RE)	155.00/ea.
PA240J	1963-64	Firewall Pad (RE)	100.00/ea.

PA240-PA240J are molded ABS panels with embossed leatherette grain and jute backing. These panels were made from original molded style cardboard pads, and are ready to install. They are black and can be painted to match your interior color. Almost all original pads are either cracked, dried-up or completely gone. This is an excellent alternative.

Please add \$8.50 shipping for PA240-PA240J.

PA241	1957	Firewall Pad - Rubber (AP)	41.00/ea.
--------------	------	----------------------------------	-----------

This pad, unlike the original jute-backed molded board, is rubber-faced with a jute backing. It is not original but it does make an inexpensive replacement.

PA245	1965-66	Firewall Pad w/o AC (RE)	41.00/ea.
PA245A	1965-66	Firewall Pad w/AC (RE)	41.00/ea.

PA245D	1965-68 Firewall Heater Box Gasket	
	Seal w/o AC (RE)	\$ 12.00/ea.
PA247J	1968 Firewall Pad (RE)	55.00/ea.
PA248	1969-72 Firewall Pad - GP (RE)	29.00/ea.
PA249	1959-72 Firewall Pad Clip - ALL (RE)75/ea.

STEERING COLUMN SEALS




PA250A

PA252A

PA250	1955-56 Inner Seal - AT (RE)	9.00/ea.
PA250A	1955-56 Inner Seal - MT (RE)	16.00/ea.
PA251	1957 Inner Seal - AT (RE)	9.00/ea.
PA251A	1957 Inner Seal - MT (RE)	16.00/ea.
PA252	1955-57 Sponge Seal - AT (RE)	12.00/ea.
PA252A	1955-57 Sponge Seal - MT (RE)	12.00/ea.
PA253	1958 Inner Seal - AT (RE)	12.00/ea.
PA253B	1958 Sponge Seal - AT (RE)	8.00/ea.
PA253D	1958 Inner Seal - MT (RE)	12.00/ea.
PA253F	1958 Sponge Seal - MT (RE)	8.00/ea.
PA253Z	1969-72 Steering Column Seal - GP (RE)	5.00/ea.

Note: These are the seals which surround the steering column where it goes through the fire-wall.

ARMREST BASES & PADS



PA255

PA255	1960-64 Front Chrome Armrest Bases - Exc. Bonneville Brougham (APE)	30.00/pr.
PA255	1965-67 Front Chrome Armrest Bases - Exc. Bonneville and GP (APE)	30.00/pr.


Comments: The finest available - we actually use copper-nickel-chrome plating. Others use the original GM method of vacuum plating which results in yellowing and fading within months - (your originals are a perfect example of this problem).



PA256

PA256	1965-66 Front Chrome Armrest Bases - Bonneville and GP (APE)	\$ 49.00/pr.
--------------	---	--------------

PA256 is now available. Quality is comparable to our highly successful PA255 and PA260 armrest bases.



PA260

PA260	1960-64 Rear Chrome Armrest Bases - ALL 2 Dr. Sedans and ALL 4 Dr. Rear Doors (APE)	35.00/pr.
PA260	1965-67 Rear Chrome Armrest Bases - ALL 2 Dr. Sedans and ALL 4 Dr. Rear Doors (exc. Bonneville) (APE) ..	35.00/pr.

Comments: Excellent—Superior to all others on the market.

These bases match those found originally on 1960-61 Catalinas, but many originals were not chrome plated. Paint to match.



PA270L

PA270L	1968-70 Front Armrest Base - Exc. Bonneville and GP (RE)	25.00/ea.
PA270R	1968-70 Front Armrest Base - Exc. Bonneville and GP (RE)	25.00/ea.

These bases were previously reproduced using reinforced rubber. A new correct plastic reproduction has just been released. Quality is very good. Paint to match.



PA270V

PA270V 1969-70 Front and Rear Chrome Armrest Base Backing Plates Cat and Exec 4Dr's (RE) \$ 49.00/pr.

These plates were used as a more luxurious look to some 4Dr models.

PA274 1960-62 Front Armrest Pads (APE) 35.00/pr.

Note: This is the correct thin pad used only in 1960-62.

PA275 1963-64 Front Armrest Pads (APE) 35.00/pr.

PA276 1965-67 Front Armrest Pads - Exc. Bonneville and GP 35.00/pr.

PA277 1963-64 Rear Armrest Pads - ALL 2 Dr. Sedans and ALL 4 Dr. Rear Doors (APE) 35.00/pr.

PA278 1965-67 Rear Armrest Pads - ALL 2 Dr. Sedans and ALL 4 Dr. Rear Doors (exc. Bonneville) (APE) 35.00/pr.

Note: PA274 through PA278 fit PA255 and PA260 armrest bases only.

These pads are manufactured using the same process as original GM. They use new stamped steel, foam and high quality vinyl. Colors available: Black, parchment, white, red, aqua, blue, fawn, and gold.

Comments: One of our finest reproductions.

PA278A 1965-66 Front Armrest Pads - Bonneville and GP (APE) 40.00/pr.

These pads are manufactured using the same process as our highly successful PA275 and PA276 front pads. These pads fit PA256.



PA279

PA279 1968-70 Front Armrest Pads Exc. Bonneville and GP (RE) 40.00/pr.



These new reproductions are similar to original GM pads except they use vacuum-formed plastic as reinforcement.

Colors available: Black, blue, parchment, red, pearl, green and sandalwood.



PA281



PA281G

PA281 1960-67 Armrest Base to Door Screw (RP)75/ea.

This replacement screw differs from original since it has 14 threads/inch vs. 10 threads/inch.

PA281C 1968-70 Armrest Base to Door Screw - Exc. Bonneville and GP (RP) \$ 1.50/ea.

PA281G 1960-70 Armrest Base to Pad Screw (RP)35/ea.

ARMREST COMBINATIONS



PA286

PA284 1960-62 Front Armrests and Pads (APE) 60.00/set

PA285 1963-64 Front Armrests and Pads (APE) 60.00/set

PA286 1965-67 Front Armrests and Pads - Exc. Bonneville and GP (APE) 60.00/set

PA286J 1965-66 Front Armrests and Pads - Bonneville and GP (APE) 85.00/set

PA287 1963-64 Rear Armrests and Pads (APE) 65.00/set

PA288 1965-67 Rear Armrests and Pads - Exc. Bonneville and GP (APE) 65.00/set

PA289 1963-64 Rear Armrests, Pads and Ashtrays (APE) 95.00/set

PA290 1965-67 Rear Armrests, Pads and Ashtrays - Exc. Bonneville and GP (APE) 95.00/set

PA291 1963-64 Front and Rear Armrests, Pads and Rear Ashtrays (APE) 148.00/set

PA292 1965-67 Front and Rear Armrests, Pads and Rear Ashtrays - Exc. Bonneville and GP (APE) 148.00/set

Note 1: These armrest combinations are an excellent value containing all the parts needed to refurbish your worn armrests.

Note 2: Additional discounts do not apply to armrest combinations.

Note 3: Except for PA286J, PA284 through PA292 use PA255 and PA260 armrest bases only. PA286J uses PA256 bases.



REAR ARMREST STEEL & COVERS




PA295BB

PA295B 1955 Convertible Rear Armrest Panels Steel (RE) 359.00/pr.

PA295BB 1956-57 Convertible Rear Armrest Panels Steel (RE) 359.00/pr.

PA295BD 1958 Convertible Rear Armrest Panels Steel (RE) 359.00/pr.

Note: These are the steel structures that the vinyl rear armrest covers adhere to.



PA297

PA297B

- PA297** 1965-68 Convertible Rear Armrest Covers (RE)..... \$ 55.00/pr.

These covers are two-piece stitched vinyl like originals. For colors available please refer to armrest pad colors.

- PA297B** Rear Armrest Screws (RE)..... .35/ea.

ASHTRAYS



PA300

PA301

- PA300** 1955-58 Rear Ashtray Cover and Frame, 2 Dr. HT and Conv. (RE) 25.00/ea.

- PA301** 1955-58 Rear Ashtray Insert for PA300 (RE) ... 10.00/ea.



PA305

PA306

- PA305** 1959-67 Rear Ashtray - ALL 2 Dr. Models w/ashtray built into armrest (APE) 30.00/pr.

- PA306** 1959-67 Rear Ashtray Bezel, Fits PA305 (APE)..... 10.00/pr.

- PA307** 1959-67 Rear Ashtray Sets (Includes two ashtrays (PA305) and two bezels (PA306)) (APE)..... 38.00/pr.

A high-quality reproduction. The bezels are also well done and are recommended to complement PA305.

Comments: Very good.



PA310

- PA310** 1960-67 Rear Ashtrays - ALL 4 Dr. Models and 2 Dr. Sedans exc. 1964 Bonneville Brougham and 1965-67 Bonneville (APE) \$ 35.00/pr.

With so many originals badly deteriorated, we've decided to manufacture these ashtrays using stainless steel. Dimensions and luster exhibit our usual high quality.

Comments: Very good to excellent.



PA316

- PA315** 1968-72 Rear Ashtray - ALL 2 Dr. Models - FS (GM) 19.00/ea.

- PA316** 1969-72 Rear Ashtray - GP (GM) 19.00/ea.

Note: These GM replacement ashtrays no longer are available with the original ribbed covers.

IN-DASH TACHS



- PA318** 1969 In-dash Tach 5100 RPM Redline - GP (RE) 129.00/ea.

- PA318A** 1969 In-dash Tach 5500 RPM Redline - GP (RE) 129.00/ea.

- PA319** 1970-72 In-dash Tach 5100 RPM Redline - GP (RE) 129.00/ea.

- PA319A** 1970-72 In-dash Tach 5500 RPM Redline - GP (RE) 129.00/ea.

Note 1: These tachs look identical to the original units when installed and carry a multi-year warranty (units must not be altered). Wiring harness is included.

Note 2: Although originally incorrect, we offer a 5500 RPM tach for those people requesting a tach to complement their high performance engines.

STEERING WHEEL COMPONENTS



PA320



PA321

- PA320** 1964 Sport Steering Wheel Horn Button Emblem (APE) \$ 40.00/ea.

This is our own reproduction of the plastic emblem that goes in the chrome horn button (attach with epoxy).

Comments: Excellent—red may differ slightly from original.

- PA321** 1964 Sport Steering Wheel Horn Button w/o Rubber Collar (RE) 89.00/ea.

This piece is spun resulting in the hollow center. Once the emblem is inserted the assembly looks the same as original.

Comments: Very good—high cost is due to limited market.

- PA322** 1964 Installation Package for PA321 (RE). Disc.
This kit includes hardware to install the '64 horn button. It does not include the small spring-loaded conductor.



PA326




PA325

- PA325** 1965-68 Sport Steering Wheel Horn Button Emblem (RE)..... 35.00/ea.

This emblem sits in the chrome horn button. Practically every original we've seen is cracked or faded.

Comments: Excellent (attach w/epoxy).

Note: These reproductions exhibit excellent machine work and chrome.



- PA326** 1965-66 Complete Wood Wheel Horn Button Assembly w/o Switch (RE) 145.00/ea.

- PA327** 1967 Complete Wood Wheel Horn Button Assembly w/o Switch (RE) \$145.00/ea.

- PA328** 1968 Complete Wood Wheel Horn Button Assembly w/o Switch (RE) 134500/ea.

These complete assemblies include the emblem, chrome cover and chrome housing.



PA329



PA336

- PA329** 1965-66 Wood Wheel Horn Button Chrome Cover (RE) 62.00/ea.

- PA330** 1967 Wood Wheel Horn Button Chrome Cover (RE) 59.00/ea.

- PA331** 1968 Wood Wheel Horn Button Chrome Cover (RE) 59.00/ea.

- PA332** 1965-66 Wood Wheel Horn Button Chrome Housing (RE) 62.00/ea.

- PA333** 1967 Wood Wheel Horn Button Chrome Housing (RE) 62.00/ea.

- PA334** 1968 Wood Wheel Horn Button Chrome Housing (RE) 62.00/ea.

With the value of 65-68 wood wheels escalating, these high quality products greatly enhance the value of your investment.


- PA336** 1965-66 Wood Wheel Horn Button Collar (RE)..... 35.00/ea.

- PA337** 1967 Wood Wheel Horn Button Collar (RE)..... 35.00/ea.

- PA338** 1968 Wood Wheel Horn Button Collar (RE)..... 35.00/ea.

- PA339** 1969-72 Sport Wheel Horn Button Collar (RE)..... 35.00/ea.

These collars bolt under the wood wheel and finish the transition between the wheel and steering column. Due to increased manufacturing costs, these are now available only in plastic.



- PA340** 1965-66 Wood Wheel Spoke Inserts (RE) 59.00/set


These spoke inserts are die-cast and attach directly to the wood wheel spokes. On most wheels these are badly pitted.

FORMULA WHEEL



- PA342** 1970-71 Formula Wheel (RE).....\$199.00/ea.
PA342 does not include collar, cover or other components. This is the wheel only.

CONSOLE COMPONENTS



PA350

- PA350** 1965-66 Automatic Console Selector Insert (APE)..... 7.50/ea.



PA354

- PA354** 1969-72 Automatic Console Selector Insert - GP (APE)..... 7.50/ea.




PA354BJ

- PA354BJ** 1973 Automatic Console Selector Insert Backing Plate GP (RE) 5.50/ea.



PA355

- PA355** 1962-64 Console Courtesy Lamp Lens (APE) . 7.50/ea.
PA356 1962-64 Console Compartment Box (RE) 15.00/ea.



PA357

- PA357** 1965-68 Console Compartment Box (RP)..... \$ 15.00/ea.

This replacement is now available. While original boxes were injected plastic, this box is a flocked lined cardboard.

Comments: Not original but nice replacement.



PA359J

- PA359J** 1963-68 Console Compartment Light (RE-RP)..... 15.00/ea.

This is the one-piece switch light assembly mounted inside the console compartment. The switch is activated by the console door. Wire lead is 29" long and can be spliced into existing harness.



PA360

PA360A

- PA360** 1965-66 "421" Console Emblem (RE)..... 35.00/ea.
PA360A 1967-68 "428" Console Emblem (RE)..... 21.00/ea.
PA360AC 1969-72 "Model J" Console Emblem (RE) 19.00/ea.
PA360B 1969-72 "Model SJ" Console Emblem (RE) ... 19.00/ea.

Note: Because of the limited market, PA360 through PA360B are not die-cast, they are low pressure castings. Overall the quality is good.

CONSOLE LOCKS & BRACKET



PA361

PA365

- PA361** 1962-65 Console Lock w/2 Late-Style Keys (NOS)..... 19.00/ea.
PA361A 1962-65 Console Lock w/2 Original-Style Keys (NOS) 24.00/ea.
PA362 1966-68 Console Lock w/2 Late-Style Keys (NOS)..... 18.50/ea.
PA362A 1966 Console Lock w/2 Original-Style Keys (NOS) 23.00/ea.
PA363A 1967-68 Console Lock w/2 Original-Style Keys (NOS) 23.00/ea.



PA364

- PA364** 1969-72 Console Lock w/2 Keys
w/ Black Bezel - GP (NOS) \$ 18.00/ea.
- PA364A** 1969-72 Console Lock w/2 Keys
Chrome Bezel (NOS) 35.00/ea.
- Lock pawl is not included with PA364 or
PA364A. You must use your original.
- PA365** 1962-68 Console Lock Retainer w/screw (RE) 6.00/ea.

INSIDE MIRRORS AND COMPONENTS



- PA380** 1955-57 Inside Rearview Mirror
Non-Tilt (RE) 19.00/ea.
- This is meant as a replacement for the non-tilt
standard mirror.
- PA381** 1955-57 Inside Rearview Mirror - Non-Glare
Tilt (RE) 75.00/ea.



PA382

- PA382** 1957-64 Inside Rearview Mirror - Tilt (RE) 75.00/ea.
- Note:* 1964 was a transition year for the tilt
knob. This mirror has the black tab with
day/night printed on it.



PA383

- PA383** Late 1961-66 Inside Rearview Mirror
Non-Tilt (RE) 20.00/ea.
- PA384** 1964-66 Inside Rearview Mirror - Tilt (RE) Inquire
- This mirror utilizes the chrome triangular tab
to change the tilt.



PA385A

- PA385A** 1967-68 Inside Tilt Mirror - 10" (RE) 49.00/ea.
- Finally an exact reproduction of the original
stainless steel tilt mirror.
- Note 1:* 1967 models had two knob designs.
Both the triangular knob and this lever style
were used on these cars.

Note 2: Due to current anti-glare legislation this
original style mirror is not sold for street use but
for shows, exhibitions, etc.

- PA386A** 1969-70 Inside Tilt Mirror, 12" - FS (RE) \$ 59.00/ea.
- PA386A** 1969-72 Inside Tilt Mirror, 12" - GP (RE) 59.00/ea.

This 12" stainless steel mirror exhibits the same
excellent quality as the '67-'68 mirror de-
scribed above.

Note 1: Most 1969 models had mirrors that
were color coded to the interior. The gray plas-
tic surround on this reproduction easily accepts
vinyl spray for that finishing touch.

Note 2: Due to current anti-glare legislation this
original style mirror is not sold for street use but
for shows, exhibitions, etc.

- PA388** 1971-77 Inside Tilt Mirror - FS (GM) 54.00/ea.
- PA388** 1973-77 Inside Tilt Mirror - GP (GM) 54.00/ea.

PA388 has a black back.



PA391

- PA390** 1955-57 Chrome Mirror Support (Conv.)
(RE) 39.00/ea.
- PA391** 1955-57 Chrome Mirror Support (HT and
Sedan) (RE) 20.00/ea.


Comments: Die-cast and excellent.



- PA392J** 1968 Chrome Mirror Support - FS, HT
(RE) 26.00/ea.
- PA392K** 1969-72 Chrome Mirror Support - GP (RE) 26.00/ea.



PA393



PA393A

- PA393** 1971-76 Inside Rearview Mirror Support - FS
(GM) 8.00/ea.
- PA393** 1973-77 Inside Rearview Mirror Support - GP
(GM) 8.00/ea.
- PA393AJ** 1958-69 Inside Mirror Mounting Screw - ALL
(GM) 1.00/ea.

PA393AJ 1970-72 Inside Mirror Mounting Screw - GP (GM)..... \$ 1.00/ea.

This 10/32 x 9/16" screw mounts the mirror to the bracket.

PA393AM 1971-76 Inside Rearview Mirror Adhesive Kit - FS (AP)..... 3.50/kit

PA393AM 1973-77 Inside Rearview Mirror Adhesive Kit - GP (AP) 3.50/kit



PA393J

PA393J 1969-70 Inside Rearview Mirror Bracket Boot - GP (RE) 22.00/ea.

PA393J fits over the mirror bracket and holds the inside grommets of the sunvisors. Black - Paint to match.

VISOR VANITY MIRRORS



PA395

PA395 1955-77 Visor Vanity Mirror (Clip-on Style w/Pontiac Script) (10"x3 1/2") (RE) 31.00/ea.

PA396 1955-56 Visor Vanity Mirror (Clip-on Style w/Pontiac Script) (5"x6") (RE) 31.00/ea.

Although originally used only on the early Pontiacs, these accessory mirrors are a nice addition to any model. Quality of these highly sought-after accessories is excellent.

PA397J 1965-73 Vanity Mirror (Stick-on) (7 1/8"x3 3/8") (GM)..... Disc.

PA397K 1974-77 Vanity Mirror (Push-in stud style) (7 1/8"x3 3/8") (GM) 29.00/ea.

This mirror has no "Pontiac" script but has two studs 4 7/8" apart. Your sunvisor must be equipped with the two nylon inserts to attach this mirror.

WOOD DASH INSERTS



PA401

PA399 1960 Wood Dash Insert w/o rear speaker - Bonneville - 3 Pc. Unstained (RE) .. 27.00/ea.

PA399A 1960 Wood Dash Insert w/o rear speaker - Bonneville - 3 Pc. Stained (RE)..... 34.00/ea.

PA399C 1960 Wood Dash Insert w/ rear speaker - Bonneville - 3 Pc. Unstained (RE) .. 27.00/ea.

PA399D 1960 Wood Dash Insert w/rear speaker - Bonneville - 3 Pc. Stained (RE)..... 34.00/ea.

PA400 1963-64 Wood Dash Inserts, Std. Trans. or Console Shift Auto - Bonneville and GP - 5 Pc. Unstained (RE) \$ 27.00/ea.

PA400A 1963-64 Wood Dash Insert, Std. Trans. or Console Shift Auto - Bonneville and GP - 5 Pc. Unstained (RE) 34.00/ea.

PA400 1964 Wood Dash Insert, Std. Trans. or Console Shift Auto - 2+2 - 5 Pc. Unstained (RE) 27.00/ea.


PA400A 1964 Wood Dash Insert, Std. Trans. or Console Shift Auto - 2+2 - 5 Pc. Stained (RE) 34.00/ea.

PA401 1963 Wood Dash Insert, Column Shift Auto - Bonneville and GP - 5 Pc. Unstained (RE) 27.00/ea.

PA401A 1963 Wood Dash Insert, Column Shift Auto - Bonneville and GP - 5 Pc. Stained (RE) 34.00/ea.

PA401B 1964 Wood Dash Insert, Column Shift Auto - 2 +2, GP and Bonneville - 5 Pc. Unstained (RE) 27.00/ea.

PA401C 1964 Wood Dash Insert, Column Shift Auto - 2+2, GP and Bonneville - 5 Pc. Stained (RE) 34.00/ea.



PA402 1965 Wood Dash Insert - Bonneville and GP - Type I - Unstained (RE) 48.00/ea.

PA402A 1965 Wood Dash Insert - Bonneville and GP - Type 1 - Stained (RE) 55.00/ea.

PA402C 1965 Wood Dash Insert - Bonneville and GP - Type 2 - Unstained (RE) 48.00/ea.

PA402D 1965 Wood Dash Insert - Bonneville and GP - Type 2 - Stained (RE) 55.00/ea.

When ordering '65 dashes, use diagrams to determine which type you need.

PA404 1966 Wood Dash Insert, w/ or w/o Air - Bonneville and GP - Unstained (RE) 27.00/ea.

PA404A 1966 Wood Dash Insert, w/ or w/o Air - Bonneville and GP - Stained (RE)..... 34.00/ea.

Note: PA400 through PA404A come complete with dash and steering wheel inserts.

WOOD CONSOLE INSERTS



PA406	1963-64	Wood Console Shifter Plate Insert, Auto - Bonneville and GP - Unstained (RE)	\$ 10.00/ea.
PA406A	1963-64	Wood Console Shifter Plate Insert, Auto - Bonneville and GP - Stained (RE)	13.00/ea.
PA407	1965-66	Wood Console Insert, Auto - Bonneville and GP - Unstained (RE)	27.00/ea.
PA407A	1965-66	Wood Console Insert, Auto - Bonneville and GP - Stained (RE).....	34.00/ea.
PA408	1965-66	Wood Console Insert, 4 Sp. - Bonneville and GP - Unstained (RE)	27.00/ea.
PA408A	1965-66	Wood Console Insert, 4 Sp. - Bonneville and GP - Stained (RE).....	34.00/ea.

WOOD DASH AND CONSOLE COMBINATIONS

PA410	1963-64	Wood Dash and Console Shifter Plate Inserts, Auto - Bonneville and GP - Unstained (RE)	35.00/ea.
PA410A	1963-64	Wood Dash and Console Shifter Plate Inserts, Auto - Bonneville and GP - Stained (RE)	45.00/ea.
PA412	1965	Wood Dash and Console Inserts - Type 1 - Auto - Bonneville and GP - Unstained (RE)	72.00/ea.
PA412A	1965	Wood Dash and Console Inserts - Type 1 - Auto - Bonneville and GP - Stained (RE)	85.00/ea.
PA412B	1965	Wood Dash and Console Inserts - Type 1 - 4 Sp. - Bonneville and GP - Unstained (RE)	72.00/ea.
PA412C	1965	Wood Dash and Console Inserts - Type 1 - 4 Sp. - Bonneville and GP - Stained (RE)	85.00/ea.
PA412D	1965	Wood Dash and Console Inserts - Type 2 - Auto - Bonneville and GP - Unstained (RE)	72.00/ea.
PA412E	1965	Wood Dash and Console Inserts - Type 2 - Auto - Bonneville and GP - Stained (RE)	85.00/ea.
PA412F	1965	Wood Dash and Console Inserts - Type 2 - 4 Sp. - Bonneville and GP - Unstained (RE)	72.00/ea.
PA412G	1965	Wood Dash and Console Inserts - Type 2 - 4 Sp. - Bonneville and GP - Stained (RE)	85.00/ea.
PA414	1966	Wood Dash and Console Inserts, Auto - Bonneville and GP - Unstained (RE)	52.00/ea.
PA414A	1966	Wood Dash and Console Inserts, Auto - Bonneville and GP - Stained (RE)	64.00/ea.
PA414B	1966	Wood Dash and Console Inserts, 4 Sp. - Bonneville and GP - Unstained (RE)	52.00/ea.
PA414C	1966	Wood Dash and Console Inserts, 4 Sp. - Bonneville and GP - Stained (RE)	64.00/ea.

Note 1: Save money by purchasing wood dash and console inserts together.

Note 2: Dash inserts are real walnut veneer, available either unstained or prestained in medium walnut. Inserts do not have aluminum backing and are usually cemented over existing material.

Comments: Very good—nice die-work. Only difference from original is thickness.

VINYL DASH INSERTS



The following dashes are available in two designs. Catalina, 2+2, Ventura, and Executive use vinyl walnut wood grain inserts while Bonneville and GP use vinyl, elm-burl grain inserts.

At time of printing the elm-burl material is not available. We are in the process of looking for a new manufacturer. Please check in on the status of this project.



PA420	1967	Vinyl Dash Insert, w/o Air, Column Shift Auto - Catalina, 2+2, and Executive (RE)	\$ 20.00/ea.
PA420A	1967	Vinyl Dash Insert, w/Air, Column Shift Auto - Catalina, 2+2, and Executive (RE)	20.00/ea.
PA420B	1967	Vinyl Dash Insert, w/o Air, Std. or Console Shift Auto - Catalina, 2+2, and Executive (RE)	20.00/ea.
PA420C	1967	Vinyl Dash Insert, w/Air, Std. or Console Shift Auto - Catalina, 2+2, and Executive (RE)	20.00/ea.
PA421	1967	Vinyl Dash Insert, w/o Air, Column Shift Auto - Bonneville and GP (RE)	Inquire
PA421A	1967	Vinyl Dash Insert, w/Air, Column Shift Auto - Bonneville and GP (RE)	Inquire
PA421B	1967	Vinyl Dash Insert, w/o Air, Std. or Console Shift Auto - Bonneville and GP (RE)	Inquire
PA421C	1967	Vinyl Dash Insert, w/Air, Std. or Console Shift Auto - Bonneville and GP (RE)	Inquire
PA423	1968	Vinyl Dash Insert, w/o Air, Column Shift Auto - Catalina, Ventura, and Executive (RE)	20.00/ea.
PA423A	1968	Vinyl Dash Insert, w/Air, Column Shift Auto - Catalina, Ventura, and Executive (RE)	20.00/ea.
PA423B	1968	Vinyl Dash Insert, w/o Air, Std. or Console Shift Auto - Catalina, Ventura, and Executive (RE)	20.00/ea.
PA423C	1968	Vinyl Dash Insert, w/Air, Std. or Console Shift Auto - Catalina, Ventura, and Executive (RE)	20.00/ea.
PA424	1968	Vinyl Dash Insert, w/o Air, Column Shift Auto - Bonneville and GP (RE)	Inquire

PA424A	1968	Vinyl Dash Insert, w/Air, Column Shift Auto - Bonneville and GP (RE)	Inquire
PA424B	1968	Vinyl Dash Insert, w/o Air, Std. or Console Shift Auto - Bonneville and GP (RE)	Inquire
PA424C	1968	Vinyl Dash Insert, w/Air, Std. or Console Shift Auto - Bonneville and GP (RE)	Inquire
PA426	1969-70	Vinyl Dash Insert, w/o Air, Column Shift Auto - GP (RE)	Inquire
PA426A	1969-70	Vinyl Dash Insert, w/Air Column Shift Auto - GP (RE)	Inquire
PA426B	1969-70	Vinyl Dash Insert, w/o Air, Std. or Console Shift Auto - GP (RE)	Inquire
PA426C	1969-70	Vinyl Dash Insert, w/Air, Std. or Console Shift Auto - GP (RE)	Inquire

VINYL CONSOLE INSERTS



The following console inserts are available in two designs. Catalina, 2+2, Ventura, and Executive use vinyl walnut wood grain inserts while Bonneville and GP use elm burl grain inserts. **At time of printing the elm-burl material is not available. We are in the process of looking for a new manufacturer. Please check in on the status of this project.**

PA432	1967-68	Vinyl Console Insert, Auto - Catalina, 2+2, Ventura, Executive (RE)	\$ 25.00/ea.
PA432A	1967-68	Vinyl Console Insert, Auto - Bonneville and GP (RE)	Inquire
PA433	1967-68	Vinyl Console Insert, 4 Sp. - Catalina, 2+2, Ventura, Executive (RE)	25.00/ea.
PA433A	1967-68	Vinyl Console Insert, 4 Sp. - Bonneville and GP (RE)	Inquire



PA433H	1967-68	Vinyl Console 8-Track Insert w/ console Catalina 2+2 Ventura Executive (RE)	13.00/ea.
PA433J	1967-68	Vinyl Console 8-Track Insert w/ console Bonn and GP	Inquire

This is the piece that surrounds the 8-track on '67-'68 full size consoles.

Note: The "Select," "Volume," "Tone" and "Balance" print is not available. These inserts will be blank.



PA437A 1976 Vinyl Console Door Insert - GP (RE) \$ 8.00/ea.

COMBINATION VINYL DASH AND CONSOLE INSERTS

PA440	1967	Vinyl Dash and Console Inserts, w/o Air, Auto - Catalina, 2+2, and Executive (RE)	44.00/ea.
PA440A	1967	Vinyl Dash and Console Inserts, w/Air, Auto - Catalina, 2+2, and Executive (RE)	44.00/ea.
PA440B	1967	Vinyl Dash and Console Inserts, w/o Air, 4 Sp. - Catalina, 2+2, and Executive (RE)	44.00/ea.
PA440C	1967	Vinyl Dash and Console Inserts, w/Air, 4 Sp. - Catalina, 2+2, and Executive (RE)	44.00/ea.
PA440D	1967	Vinyl Dash and Console Inserts, w/o Air, Auto - Bonneville and GP (RE)	Inquire
PA440E	1967	Vinyl Dash and Console Inserts, w/Air, Auto - Bonneville and GP (RE)	Inquire
PA440F	1967	Vinyl Dash and Console Inserts, w/o Air, 4 Sp. - Bonneville and GP (RE)	Inquire
PA440G	1967	Vinyl Dash and Console Inserts, w/Air, 4 Sp. - Bonneville and GP (RE)	Inquire
PA441	1968	Vinyl Dash and Console Inserts, w/o Air, Auto - Catalina, Ventura, and Executive (RE)	44.00/ea.
PA441A	1968	Vinyl Dash and Console Inserts, w/Air, Auto - Catalina, Ventura, and Executive (RE)	44.00/ea.
PA441B	1968	Vinyl Dash and Console Inserts, w/o Air, 4 Sp. - Catalina, Ventura, and Executive (RE)	44.00/ea.
PA441C	1968	Vinyl Dash and Console Inserts, w/Air, 4 Sp. - Catalina, Ventura, and Executive (RE)	44.00/ea.
PA441D	1968	Vinyl Dash and Console Inserts, w/o Air, Auto - Bonneville and GP (RE)	Inquire

PA441E 1968	Vinyl Dash and Console Inserts, w/Air, Auto - Bonneville and GP (RE)	Inquire
PA441F 1968	Vinyl Dash and Console Inserts, w/o Air, 4 Sp. - Bonneville and GP (RE)	Inquire
PA441G 1968	Vinyl Dash and Console Inserts, w/Air, 4 Sp. - Bonneville and GP (RE)	Inquire

Note 1: Save money by purchasing vinyl dash and console inserts together.

Note 2: We are able to offer vinyl wood grained dash and console inserts with a new material that is far superior to that which was offered several years ago. This material will not shrink and it also has an adhesive backing for ease of installation.



DASH COMPONENTS



PA446D

PA446D 1969-72 Switch Retainer Clip (A-body) (RE) .. \$ 4.00/ea.

This clip was used to hold the following switches in the dash: 1969 Power antenna switch; 1969-71 Convertible top switch; 1969-71 S.W. rear power window switch; 1969-72 Defogger switch; 1969 Rear speaker reverb switch; and 1969-70 Power flow vent motor switch.



PA446FJ



PA446JK



PA447A

PA446FJ 1955-68 Odometer Trip Meter Knob (RE) 3.50/ea.



This knob measures 1/8" I.D. 7/16" O.D. x 1/2" tall. Black rubber.

PA446JK 1969-70 Heater Control Knobs - FS (GM) 3.00/ea.

PA446KK 1968 Ignition Bezel Nut - FS (RE) 9.50/ea.

See PM241 - PM250 for Ignition Switches.

PA447A 1967-70 Chrome Dash Knob Bezels w/White Letters - FS (RE) 18.00/set

PA447A 1969-72 Chrome Dash Knob Bezels w/White Letters - GP (RE) 18.00/set

PA447B 1967-70 Chrome Dash Knob Bezels w/Black Letters - FS (RE) 18.00/set

PA447B 1969-72 Chrome Dash Knob Bezels w/Black Letters - GP (RE) 18.00/set

Note 1: PA447A and PA447B bezels were used from 1967 to 1972. Certain bezels will not be used on later cars. This set of five bezels contains "LIGHTS," "WIPER," "LIGHTER" and radio bezels "TONE" and "SELECT."

Note 2: The "SELECT" bezel is used with AM radios only. The "WIPER" bezel is used in 1967-68 only.



PA447C



PA447D

PA447C 1966 Dash Knobs (RE) \$ 12.00/set

Note: PA447C contains 2 radio knobs and the headlight knob. These are plastic knobs whereas originals were chromed pot metal. However, once installed, appearance is excellent.

PA447D 1967-70 Dash Knobs - FS (RE) 12.00/set

PA447D 1969-72 Dash Knobs - GP (RE) 12.00/set

Note: PA447D contains 2 radio knobs and headlight knob.



PA447L



PA447M

PA447K

1959, 1964-65 Cigarette Lighter (NOS) 15.00/ea.

PA447L 1966 Cigarette Lighter (RE) 12.00/ea.

PA447M 1967-70 Cigarette Lighter - FS (RE) 15.00/ea.

PA447M 1969-72 Cigarette Lighter - GP (RE) 15.00/ea.

Note: Some cars (usually '69 models) used a different style cigarette lighter. These Casco style lighters were ejected by a stainless steel collar. Please be sure your original is the same as the photo above.



PA447N



PA447NB

PA447N Cigarette Lighter Element (Rochester) (AP) 5.00/ea.

This element fits PA447K through PA447M.

PA447NB Cigarette Lighter Element (Casco) (AP) 11.00/ea.

RADIO COMPONENTS



PA448A



PA448C

PA448A 1967-70 Chrome Speaker Bezel w/White Letters - FS (RE)..... \$ 4.50/ea.

PA448A 1971-72 Chrome Speaker Bezel w/White Letters - GP (RE)..... 4.50/ea.

PA448B 1967-70 Chrome Speaker Bezel w/Black Letters -FS (RE)..... 4.50/ea.

PA448B 1971-72 Chrome Speaker Bezel w/Black Letters - GP (RE)..... 4.50/ea.

Note: PA448A and PA448B have the word "SPEAKER" printed on them with arrows denoting "R" and "F." You must check your particular application since AM-FM stereo radios used "Balance" instead of "Speaker."

PA448C 1967-70 Chrome Radio Control Knob - FS (RE)..... 5.00/ea.

PA448C 1969-72 Chrome Radio Control Knob - GP (RE)..... 5.00/ea.

This chrome knob is an excellent reproduction that fits both the volume and select controls on your radio.




PA448J

PA448J 1965-67 AM-FM Radio Face Decal (RE) 8.00/ea.

This decal can refurbish your faded or marred dash face simply and effectively.

PA448JD



PA448JD 1963-66 AM-FM Slide Bar (RE) 19.00/ea.

This is the chrome bar on the radio face used to select desired radio band.

CONVERTIBLE TOP SWITCH & BEZEL



PA449J

PA449J 1966 Convertible Top Switch (RE) 79.00/ea.



PA449JH

PA449JH 1966 Convertible Top Switch Bezel w/Knob (RE) \$ 27.00/ea.

Comments: Bezel is low pressure casting.



PA449JP

PA449JP 1969-70 Convertible Top Switch (RP) 65.00/ea.

Note: Bezel is different from original equipment. It is stainless not diecast chrome like original.

POWER ANTENNA SWITCH & MISCELLANEOUS BEZELS



PA449KH

PA449KH 1964-66 Power Antenna Switch (RE) 79.00/ea



PA449KK

PA449KK 1964-65 Power Antenna Switch Bezel w/Knob (RE) 27.00/ea.

PA449KM 1966 Power Antenna Switch Bezel w/Knob (RE) 27.00/ea.

REVERB & SPEAKER BEZELS



PA449KP

PA449KP	1964-65 Reverb Switch Bezel w/Knob (RE) ...	\$ 27.00/ea.
PA449KR	1966 Reverb Switch Bezel w/Knob (RE) ...	27.00/ea.
PA449KX	1964-65 Speaker Switch Bezel w/Knob (RE) ..	Inquire
PA449KY	1966 Speaker Switch Bezel w/Knob (RE) ..	Inquire

Comments: Bezels are low pressure castings.

AIR CONDITIONING VENT



PA450J

PA450J	1963-77 Chrome Lap Cooler A/C Vent Deflector (GM).....	10.00/ea.
---------------	--	-----------

PA450J is plastic unlike the early diecast originals.

CARDBOARD PACKAGE TRAYS



PA455	1955-57 Cardboard Package Tray - 2 Dr. and 4 Dr. Sedan (RE)	15.00/ea.
PA455A	1955-57 Cardboard Package Tray - 2 Dr. and 4 Dr. HT (RE).....	15.00/ea.
PA456	1958 Cardboard Package Tray - ALL exc. Bonneville (RE).....	24.00/ea.
PA457	1959-60 Cardboard Package Tray - 2 Dr. and 4 Dr. Sedan (RE)	24.00/ea.
PA457A	1959-60 Cardboard Package Tray - 2 Dr. HT (RE).....	24.00/ea.
PA457B	1959-60 Cardboard Package Tray - 4 Dr. HT (RE).....	24.00/ea.
PA458	1961-62 Cardboard Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT (RE).....	24.00/ea.
PA458A	1961 Cardboard Package Tray - 2 Dr. HT (RE).....	24.00/ea.
PA459A	1962 Cardboard Package Tray - 2 Dr. HT (RE).....	24.00/ea.
PA459A	1963-64 Cardboard Package Tray - 2 Dr. HT exc. GP (RE)	24.00/ea.
PA460	1963-64 Cardboard Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT (RE).....	24.00/ea.
PA460C	1963-64 Cardboard Package Tray - GP (RE) ..	24.00/ea.
PA461AA	1965-66 Cardboard Package Tray - 2 Dr. and 4 Dr. - Sedan; 4 Dr. HT - Bonneville (RE).....	24.00/ea.

PA461BB	1965 Cardboard Package Tray - 2 Dr. HT - Bonneville (RE)	\$ 24.00/ea.
PA461	1965-66 Cardboard Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT - Catalina (RE).....	24.00/ea.
PA461A	1965-66 Cardboard Package Tray - 2 Dr. HT - Catalina (RE).....	24.00/ea.
PA461A	1966 Cardboard Package Tray - 2 Dr. HT - Bonneville (RE)	24.00/ea.
PA461C	1965-67 Cardboard Package Tray - GP (RE) ..	24.00/ea.
PA462	1967-68 Cardboard Package Tray - 2 Dr. and 4 Dr. Sedan (RE)	24.00/ea.
PA462A	1967-68 Cardboard Package Tray - 2 Dr. HT exc. GP (RE)	24.00/ea.
PA462B	1967-68 Cardboard Package Tray - 4 Dr. HT (RE).....	24.00/ea.
PA462C	1968 Cardboard Package Tray - GP (RE) ..	24.00/ea.
PA463	1969-70 Cardboard Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT (RE).....	24.00/ea.
PA463A	1969-70 Cardboard Package Tray - 2 Dr. HT exc. GP (RE)	24.00/ea.
PA464	1969-70 Cardboard Package Tray - GP (RE) ..	24.00/ea.
PA465	1971-72 Cardboard Package Tray - GP (RE) ..	24.00/ea.
PA468A	1971-72 Cardboard Package Tray - 2 Dr. HT exc. GP (RE)	24.00/ea.
PA468J	1974 Cardboard Package Tray - 4 Dr. Sedan (RE)	24.00/ea.

Please add \$8.50 shipping for Package Trays.

These trays fit between the rear seat and the rear window and are ready for installation. They are die-cut and 1959-up models come with a vinyl strip and foam rubber padding.

When ordering, specify year, model, body style, and color desired.

Colors available: Black, red, med. blue, dk. blue, aqua, green, brown, saddle, tan, gold, and maroon.

Jute padding is the insulation that goes between the package tray and body bracing. Usually original jute is rotten causing unnecessary noise and chatter.


Please specify in your order if you would like jute padding. It is available for an additional \$10.00.

GM used two styles of package trays in these full-sized automobiles. The cardboard style has a stippled appearance without a covering. The mesh package tray uses cardboard covered with a coarse mesh material. The mesh tray gives your interior a more luxurious appearance and comes with hidden rear speaker holes.

Comments: Both types of package trays are of excellent quality.

Please inquire concerning the status of 1973-up package trays. New patterns are constantly becoming available.

MESH PACKAGE TRAYS



Mesh package tray material with speaker holes.

PA469Y	1958	Mesh Package Tray - All exc. Bonneville (RE).....	\$ 39.00/ea.
PA470	1959-60	Mesh Package Tray - 2 Dr. and 4 Dr. Sedan (RE)	39.00/ea.
PA470A	1959-60	Mesh Package Tray - 2 Dr. HT (RE) .	39.00/ea.
PA470B	1959-60	Mesh Package Tray - 4 Dr. HT (RE) .	39.00/ea.
PA471	1961-62	Mesh Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT (RE)	39.00/ea.
PA471A	1961	Mesh Package Tray - 2 Dr. HT (RE) .	39.00/ea.
PA472A	1962	Mesh Package Tray - 2 Dr. HT (RE) .	39.00/ea.
PA472A	1963-64	Mesh Package Tray - 2 Dr. HT exc. GP (RE)	39.00/ea.
PA473	1963-64	Mesh Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT (RE)	39.00/ea.
PA473C	1963-64	Mesh Package Tray - GP (RE)	39.00/ea.
PA474AA	1965-66	Mesh Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT - Bonneville, S.C. (RE) .	39.00/ea.
PA474BB	1965	Mesh Package Tray - 2 Dr. HT - Bonneville, S.C. (RE)	39.00/ea.
PA474	1965-66	Mesh Package Tray - 2 Dr. and 4 Dr. Sedan - 4 Dr. HT - Catalina (RE)	39.00/ea.
PA474A	1965-66	Mesh Package Tray - 2 Dr. HT - Catalina (RE)	39.00/ea.
PA474A	1966	Mesh Package Tray - 2 Dr. HT - Bonneville (RE)	39.00/ea.
PA474C	1965-66	Mesh Package Tray - GP (RE)	39.00/ea.
PA474D	1967	Mesh Package Tray - GP (RE)	39.00/ea.
PA475	1967-68	Mesh Package Tray - 2 Dr. and 4 Dr. Sedan (RE)	39.00/ea.
PA475A	1967-68	Mesh Package Tray - 2 Dr. HT exc. GP	39.00/ea.
PA475B	1967-68	Mesh Package Tray - 4 Dr. HT (RE) .	39.00/ea.
PA475C	1968	Mesh Package Tray - GP (RE)	39.00/ea.
PA476	1969-70	Mesh Package Tray - 2 Dr. and 4 Dr. Sedan; 4 Dr. HT - FS (RE)	39.00/ea.
PA476A	1969-70	Mesh Package Tray - 2 Dr. HT, Exc. GP (RE)	39.00/ea.
PA477	1969-70	Mesh Package Tray - GP (RE)	39.00/ea.
PA478	1971-72	Mesh Package Tray - GP (RE)	39.00/ea.
PA480A	1971-72	Mesh Package Tray - 2 Dr. HT, Exc. GP (RE)	39.00/ea.



Please inquire concerning the status of 1973-up package trays. New patterns are constantly becoming available.

Please specify in your order if you would like jute padding. It is available for an additional \$10.00.

Please add \$8.50 shipping for Package Trays.



PA485	1973-77	Molded Package Tray - GP w/o Speaker Holes (RE)	99.00/ea.
PA485A	1973-77	Molded Package Tray - GP with Speaker Holes (RE)	125.00/ea.

These trays will be molded ABS panels with embossed leatherette grain and jute backing. These package trays are made from original molded style cardboard trays, and will be ready to install. They will be black and can be painted to match your interior color. Many originals are cracked or deteriorated by the sun. This should be an excellent reproduction.

Note: Please add \$8.50 additional shipping for PA485.

TRIM ADHESIVE




PA498K



PA498M

PA498K	Aerosol Trim Adhesive (AP)	\$ 12.50/ea.
PA498M	Brush-on Trim Adhesive, 1 Quart (AP)	Disc.



PA498P

PA498P	Disposable Brush (AP)	1.00/ea.
---------------	-----------------------------	----------

HEADLINERS

Perforated



Star Pattern



If you do not see your particular headliner listed, please call because we can virtually make all headliners from 1955-77 including station wagons. There are just too many different listings to show all. Please inquire on price and availability.

Note: When ordering your headliner please specify year, body style #, model, color, and type fabric. Pontiac used many different headlining materials. We have many of these patterns and colors available. Please inquire. Because of the large number of different headliners used, we will not have most of them in stock. Please allow 3-5 weeks additional shipping time.

Note: We recently purchased NOS material and can now provide '57 and '58 random raised star and pyramid pattern in several original colors

PA520	1955-60	Headliner (RE).....	Inquire
PA522	1961	Headliner (Star Pattern) - 2 Dr. HT (RE).....	\$ 91.00/ea.
PA523	1961	Headliner (Star Pattern) - Sedans (RE).....	91.00/ea.
PA524	1961	Headliner (Star Pattern) - 4 Dr. HT (RE).....	91.00/ea.
PA525	1962-64	Headliner (Star Pattern) - 2 Dr. HT, Exc. 63-64 GP (RE).....	91.00/ea.
PA526	1963-64	Headliner (Star Pattern) - GP (RE).....	91.00/ea.
PA527	1964	Headliner (Ribbed) - GP (RE).....	91.00/ea.
PA528	1963-64	Headliner (Star Pattern) - 4 Dr. HT (RE).....	91.00/ea.
PA529	1963-64	Headliner (Star Pattern) - 4 Dr. Sedan (RE).....	91.00/ea.
PA530	1965-66	Headliner (Perforated) - 2 Dr. HT, Exc. GP (RE).....	80.00/ea.
PA531	1965-67	Headliner (Perforated) - GP (RE).....	75.00/ea.
PA535	1967-68	Headliner (Perforated) - 2 Dr. HT, Exc. GP (RE).....	83.00/ea.
PA536	1968	Headliner (Perforated) - GP (RE).....	75.00/ea.
PA540	1969-72	Headliner (Perforated) - GP (RE).....	75.00/ea.
PA542	1969-70	Headliner (Perforated) - FS (RE).....	80.00/ea.

Most headliners come complete with "ear muffs" (cardboard-covered sections behind the 1/4 window) and enough material to cover sunvisors. The star pattern material is an exact match to original and is considered an excellent reproduction. The perforated material is extremely close to original for '65 up interiors.

Colors: Star pattern comes in black, white, silver, lt. blue, med. blue, aqua and red.

Perforated pattern comes in black, white, sandalwood, buckskin, red, maroon, green and blue. Samples available on request.


Other materials are available in various original colors. Samples available on request.

HEADLINER SOUND DEADENER

PA545J	1955-77	Headliner Sound Deadener (RP).....	15.00/ea.
---------------	---------	------------------------------------	-----------


This is the material glued to the roof and used as an insulation and sound deadener. These are not reproductions of the original, but a lighter material that works equally well.

WINDOW TRIM



PA546AB

PA546AB	1955-57	Windshield Inner Lower Molding Center Clip (RE).....	\$ 4.00/ea.
----------------	---------	--	-------------



PA548B	1964	Rear Window Inner Lace Kit Sedan (RE).....	53.00/kit
PA548D	1965-66	Rear Window Inner Lace Kit - Sedan (RE).....	80.00/kit

PA548B & PA548D are the three-piece kits that surround the rear window on the inside. The lace itself is molded around the corners as original. Our kits also include the molded center escutcheons.

Color available is black—paint to match.

INTERIOR GARNISH MOLDING SCREW SETS




		PA549GA	
PA549GA	1955-57	Interior Garnish Molding Screw Set - 2 Dr HT (RE).....	6.00/set
PA549GB	1955-57	Interior Garnish Molding Screw Set - Conv (RE).....	6.00/set
PA549GC	1955-57	Interior Garnish Molding Screw Set - Safari (RE).....	8.00/set
PA549GD	1955-57	Interior Garnish Molding Screw Set - S. W. (RE).....	10.00/set
PA549GF	1955	Interior Garnish Molding Screw Set - 2 Dr Sedan (RE).....	6.00/set
PA549GG	1955	Interior Garnish Molding Screw Set - 4 Dr Sedan (RE).....	6.00/set
PA549GH	1956-57	Interior Garnish Molding Screw Set - 2 Dr Sedan (RE).....	6.00/set
PA549GJ	1956-57	Interior Garnish Molding Screw Set - 4 Dr Sedan (RE).....	6.00/set
PA549GK	1956-57	Interior Garnish Molding Screw Set - 4 Dr HT (RE).....	6.00/set

Note: These sets contain enough chrome screws to attach all your interior Garnish Moldings.

PA549HS	1955-57	Windshield Pillar Molding Screws (Stainless Steel) all except Conv (RE).....	3.00/set
----------------	---------	--	----------

GLOVE BOXES



PA550	1955-56	Glove Box (RE).....	\$ 18.00/ea.
PA551	1957	Glove Box (RE).....	18.00/ea.
PA552	1958	Glove Box (RE).....	18.00/ea.
PA553	1959-60	Glove Box (RE).....	18.00/ea.
PA554	1961-62	Glove Box (RE).....	18.00/ea.
PA555	1963-64	Glove Box w/o AC (RE).....	18.00/ea.
PA556	1963-64	Glove Box w/AC (RE).....	18.00/ea.
PA557	1965-66	Glove Box w/AC, w/o (A.T.C.) Automatic Temp Control (RE).....	18.00/ea.
PA558	1965-66	Glove Box w/AC, w/A.T.C. (RE).....	18.00/ea.
PA559	1965	Glove Box w/o AC (RE).....	18.00/ea.
PA559A	1966	Glove Box w/o AC (RE).....	18.00/ea.
PA560	1967-68	Glove Box w/o AC - Exc. GP (RE)	18.00/ea.
PA561	1967-68	Glove Box w/AC - Exc. GP (RE)	18.00/ea.
PA561	1967-68	Glove Box - GP (RE).....	18.00/ea.
PA562	1969-70	Glove Box - Exc. GP (RE)	Inquire
PA563	1971-72	Glove Box w/o AC - Exc. GP (RE)	Inquire
PA564	1971-72	Glove Box w/AC - Exc. GP (RE)	Inquire
PA565	1969-72	Glove Box - GP (RE).....	18.00/ea.

Glove box cardboard is die-cut, stapled and ready for installation.

Comments: Very good.



PA568	Glove Box Light (RE)	12.00/ea.
--------------	----------------------------	-----------

This kit includes bulb, socket, switch and necessary wiring to install this glove box light. Attaches to existing dash harness and is same as original.

Comments: Excellent.

INSTRUMENT PANEL SCRIPT



		PA571	
PA571	1955	Instrument Panel Script "Star Chief " (APE).....	35.00/ea.



		PA572	
PA572	1956	Instrument Panel Script "Star Chief " (APE).....	\$ 35.00/ea.



		PA573	
PA573	1957	Instrument Panel Script "Star Chief " (APE).....	35.00/ea.

This is the script which says Star Chief on the passenger side of the instrument panel. All of these reproductions are manufactured in chrome plated plastic (originally PA571 was plastic while PA572 and PA573 were a very brittle zinc alloy).

GLOVE BOX LOCKS & BRACKET



		PA595		PA610	
PA590	1955-58	Glove Box Lock w/Late-Style Key (NOS).....	29.00/ea.		
PA591	1955-58	Glove Box Lock w/Original-Style Key (NOS)	38.00/ea.		

Note: These glove box locks do not have chromed bezels. For correct appearance you must use your original bezel.

PA592	1959-60	Glove Box Lock w/Late-Style Key (NOS).....	17.50/ea.
PA593	1959-60	Glove Box Lock w/Original-Style Key (NOS)	23.00/ea.
PA594	1961-62	Glove Box Lock w/Late-Style Key (NOS).....	18.50/ea.
PA595	1961-62	Glove Box Lock w/Original-Style Key (NOS)	23.00/ea.
PA596	1963-64	Glove Box Lock w/Late-Style Key (NOS).....	17.50/ea.
PA597	1963-64	Glove Box Lock w/Original-Style Key (NOS)	22.00/ea.
PA598	1965-66	Glove Box Lock w/Late-Style Key (NOS).....	17.50/ea.
PA599	1965-66	Glove Box Lock w/Original-Style Key (NOS)	22.00/ea.
PA600	1967	Glove Box Lock w/Late-Style Key (NOS).....	18.50/ea.
PA601	1967	Glove Box Lock w/Original-Style Key (NOS)	23.00/ea.

PA602	1968	Glove Box Lock w/Late-Style Key (NOS).....	\$ 17.50/ea.
PA603	1968	Glove Box Lock w/Original-Style Key (NOS).....	22.00/ea.
PA604	1969	Glove Box Lock w/Original-Style Key (NOS).....	29.00/ea.

Note: PA604 glove box lock does not have the chrome bezel. For correct appearance you must use your original bezel.

PA606	1970-77	Glove Box Lock w/Original-Style Key (NOS).....	12.00/ea.
PA610	1955-58, 1961-62 & 67	Glove Box Lock Retainer (RE).....	6.00/ea.

Note: Sets of locks using the same key configuration are available in Section Seventeen.

INTERIOR LAMP REFLECTORS AND BEZELS



PA620



PA621

PA620	1955-58	Dome Lamp Reflector (RE)	13.00/ea.
This is the dome lamp located in the center of the headliner.			
PA621	1955-57	Rear Quarter Lamp Reflector w/lens (2 Dr. HT, 4 Dr. HT, and Safari) (RE) .	23.00/ea.
PA621	1959-69	Rear Quarter Lamp Reflector w/lens (Station Wagon) (RE)	23.00/ea.

This is the small round reflector found on both sides at the rear of the headliner. Comes complete with lens (PA631).



PA623



PA628

PA623	1962-64	Convertible Rear Armrest Courtesy Light Bezel (RE)	26.00/ea.
PA625	1969-77	Dome Lamp Reflector (GM)	10.00/ea.
PA627	1959-62	Dome Lamp Bezel (RE).....	Inquire
PA628	1963-64	Dome Lamp Bezel, Exc. GP (RE)	8.00/ea.

INTERIOR LAMP LENSES




PA630



PA630D

PA630	1955-58	Dome Lens (Fits PA620 above) (RE)	8.00/ea.
PA630D	1958-64	Side Roofrail Dome Lens (2 required) (RE)	18.00/ea.



PA630F

PA630F	1965-68	Side Roof Accessory Lens (APE)	\$ 39.00/pr.
---------------	---------	--------------------------------------	--------------

This rare accessory lens has been unavailable from GM for years. Since used pieces are usually cracked, these lenses will greatly enhance the interior of those cars with this desirable option.



PA631



PA632

PA631	1955-57	Rear Quarter Lens - 2 Dr. and 4 Dr. HT and Safari (Fits PA621) (RE).....	5.00/ea.
PA631	1959-69	Rear Quarter Courtesy Lamp Lens - Station Wagon (Fits PA621) (RE).....	5.00/ea.
PA632	1958-61	Dome Lens Convertible - (3 1/2" x 1 9/16") (RE).....	15.00/ea.




PA635



PA636

PA635	1959-64	Dome Lens (Exc. Side Rail Lamps), Exc. 63-64 GP (GM)	4.00/ea.
PA636	1960-64	Dome Lens w/Optional Reading Lamp (APE)	12.00/ea.
PA636AA	1963-64	Dome Lens (Exc. Side Rail Lamps) GP (RP-GM)	4.00/ea.

This lens makes a good replacement; however, it is made from plastic instead of the original glass. The tabs on the bezel must be bent down more to retain this lens.



PA636A

PA636A		Courtesy Light Lens (RE).....	7.50/ea.
---------------	--	-------------------------------	----------

Note: This lens mounts on an aluminum bracket under the dash on cars equipped with the courtesy lamp accessory group. Originals are usually faded or cracked.



PA637



PA638

PA637 1962-70 Rear Quarter Armrest Courtesy Lamp Lens (Conv.) (GM)..... 8.00/pr.

PA638 1971-75 Rear Quarter Armrest Courtesy Lamp Lens (Conv.) (GM)..... 8.00/pr.



PA639

PA639 1969-77 Dome Lens - ALL (GM)..... 4.00/ea.

PA640 1969-77 Dome Lens w/Optional Reading Lamp - ALL (GM) 4.00/ea.




PA641

PA641 1969-77 Dome and Reading Lamp Housing (Double lens) (GM) 69.00/ea.




PA642

PA642 1969-77 Dome and Reading Lamp Reflector (Double lens) (GM) Disc.



PA644J

PA644J Dome Lamp Bulb Terminals (GM) .. 2.00/pr.



PA644JB

PA644JB 1969-77 Dome Lamp Mounting Kit (GM) 4.00/kit

This kit contains 2 nuts and 2 studs.




PA644JK

PA644JK Dome Lamp Bulb (GM)..... 1.50/ea.

Note 1: Replaces GE#211, 211-1, and 211-2.

Note 2: Please see Section Eleven (Electrical) for other bulbs.

RUBBER BUMPERS



PA653D



PA660



PA665

PA650 1955-58 Glove Box Door Bumpers (RE) \$ 1.50/pr.

PA663 1955-58 Glove Box Stop (GM)..... 1.50/ea.

PA653 1959-60 Glove Box Door Bumpers (RE) 1.50/pr.

PA653D 1959-62 Glove Box Door Grommet
1 3/4" x 5/8" (RE) 7800/ea.


PA654 1961-62 Glove Box Door Bumpers (RE) 1.50/pr.

PA660 1963-67 Glove Box Door Bumpers (RE) 1.50/pr.

PA661 1968-76 Glove Box Door Bumpers - FS (GM) 1.50/pr.

PA662 1969-77 Glove Box Door Bumpers - GP (RE) 1.50/pr.

PA663 Glove Box Stop (GM)..... 1.50/ea.



PA610

PA663

We have found that this stop was used on many different Pontiacs.

PA665 1962-67 Console Bumpers (GM) 4.00/pr.

PA663 1962-64 Console Door Stop (GM) 1.50/ea.

PA668 1969-77 Console Bumpers - GP (RE) 2.50/pr.

SUNSHADE COMPONENTS



PA670 1955-58 Sunshade Assembly - HT (RE)..... 90.00/pr.

PA670A 1955-58 Sunshade Assembly - Conv. (RE) 90.00/pr.

PA670D 1959-60 Sunshade Assembly - Star Vinyl
- HT (RE)..... 90.00/pr.

PA670E 1959-60 Sunshade Assembly - Conv. (RE) 90.00/pr.

PA670J 1961 Sunshade Assembly - Star Vinyl -
HT (RE) 91.00/pr.

PA670K 1961-62 Sunshade Assembly - Conv. (RE) 90.00/pr.

PA670P 1962-63 Sunshade Assembly - Star Vinyl -
HT (RE) 91.00/pr.

PA670R 1963 Sunshade Assembly - Conv. (RE) 90.00/pr.

PA670RB 1964 Sunshade Assembly - Star Vinyl
- HT (RE)..... 91.00/pr.

PA670Z 1964 Sunshade Assembly - Ribbed Vinyl
- GP (RE)..... 90.00/pr.

PA670S 1964 Sunshade Assembly - Conv. (RE) 90.00/pr.

PA671B 1965-68 Sunshade Assembly - Perforated
Vinyl - HT (RE) 75.00/pr.

PA671D 1965 Sunshade Assembly - Conv. (RE) 91.00/pr.

PA671F 1966-69 Sunshade Assembly - Conv. (RE) 85.00/pr.

PA671J 1969 Sunshade Assembly - Perforated
Vinyl - GP (RE) 79.00/pr.


PA671R	1970-72	Sunshade Assembly - Conv. (RE)	\$ 87.00/pr.
PA671S	1970-72	Sunshade Assembly - Perforated Vinyl - GP (RE)	69.00/pr.
PA672B	1973-75	Sunshade Assembly - Conv. (RE)	85.00/pr.
PA672J	1973-77	Sunshade Assembly - Perforated Vinyl - GP (RE)	83.00/pr.

Comments: These are reproductions of the sunvisor assemblies that become soiled and faded with age. The visor will mount directly into your existing sunshade support.

Note: The sunvisors are available in all the same colors as our headliners and armrest pads. Samples are available upon request. When ordering please specify year, model, body style, material and color desired.

If you do not see your particular model listed, please call because new patterns are becoming available constantly.

PA680	1955-58	Sunshade Supports (Exc. Conv.) (RE)	25.00/pr.
PA680A	1955-57	Sunshade Supports - Conv (RE)	129.00/pr.
PA680B	1955-57	Convertible Sunshade Support Mounting Screws - Stainless Steel (6 pcs. w/ washers) (RE)	2.50/set
PA684	1960-63	Sunshade Supports -All Exc. Conv. (RE)	42.00/pr.



		PA687	PA688	
PA687	1965-68	Sunshade Support (Exc. Conv.), L or R (GM)	20.00/ea.	
PA687	1969-72	Sunshade Support - L or R - GP (GM)	20.00/ea.	
PA688		Sunshade Support Screw (Fits PA687) (GM)	1.00/ea.	

Note: This is the screw that clamps the support to the visor shaft.

PA689	1971-72	Sunshade Support - L or R - FS (Exc. Conv.) (GM)	38.00/ea.
PA689	1973-77	Sunshade Support - L or R - ALL (Exc. Conv.) (GM)	38.00/ea.



		PA695	PA698	PA699	
PA692	1965-76	Sunshade Sleeves - FS (GM)			2.00/pr.
PA695	1969-77	Sunshade Sleeves - GP (GM)			2.00/pr.
PA698	1959-62	Sunshade Grommets (APE)			5.00/pr.
PA699	1963-72	Sunshade Grommets - ALL (GM)			3.50/pr.

TILT & TURN SIGNAL LEVERS



PA700

PA699J	1967-77	Tilt Wheel Release Lever - ALL (GM)	\$ 5.00/ea.
PA700	1967-72	Turn Signal Lever w/Cruise Control - GP (GM)	86.00/ea.
PA700	1967-76	Turn Signal Lever w/Cruise Control - FS (GM)	86.00/ea.
PA705	1969-75	Turn Signal Lever w/o Cruise - ALL and '76 FS (GM)	12.00/ea.



PA706J

PA706J	1969-73	Turn Signal Switch Housing - Floor Shift w/o Tilt Wheel - ALL (GM)	78.00/ea.
PA706J	1974-75	Turn Signal Switch Housing - M-40 w/o Tilt Wheel - FS (GM)	78.00/ea.

SPEAKER GRILLES



PA711

PA710	1970-72	Rear Speaker Grille - ALL exc. Station Wagon (GM)	Disc.
PA710	1973-74	Rear Speaker Grille - FS exc. SW (GM)	Disc.
PA711	1966-72	Rear Speaker Grille - ALL (RE)	15.00/ea.



PA715

PA716

PA715	1955-66	Coat Hook - Chrome - ALL exc. Conv. (RE)	10.00/pr.
PA715J	1963-66	Coat Hook - Chrome - ALL Conv. (RE)	11.00/ea.
PA716	1967-77	Coat Hook - Black Plastic - ALL exc. Conv. (GM)	6.00/pr.
PA716J	1976-77	Coat Hook Chrome - GP (GM)	4.00/ea.

INTERIOR KICK PANELS



PA751

PA750	1955	Forward Cowl Kick Panel w/o Air (RE)	\$ 15.00/pr.
PA751	1956	Forward Cowl Kick Panel w/o Air (RE)	15.00/pr.
PA752	1957	Forward Cowl Kick Panel w/o Air (RE)	15.00/pr.
PA753	1958	Forward Cowl Kick Panel w/o Air (RE)	15.00/pr.
PA754	1959	Forward Cowl Kick Panel w/o Air - Catalina (RE)	15.00/pr.
PA755	1959	Forward Cowl Kick Panel w/o Air - Bonneville (RE)	15.00/pr.
PA756	1960	Forward Cowl Kick Panel w/o Air - Catalina (RE)	15.00/pr.
PA757	1960	Forward Cowl Kick Panel w/o Air - Bonneville (RE)	15.00/pr.
PA757A	1960	Forward Cowl Kick Panel w/Air - Bonneville (RE)	15.00/pr.
PA758	1961-62	Forward Cowl Kick Panel w/o Air (RE)	15.00/pr.
PA758D	1961-62	Forward Cowl Kick Panel w/Air (RE)	15.00/pr.
PA759	1963-64	Forward Cowl Kick Panel w/o Air - Bonneville	15.00/pr.

PA759 panels are bare cardboard w/o carpeting. Carpeting may be purchased separately. See PA225. PA750 through PA759 come in black and are paint to match. Our listing is expanding constantly as new patterns become available. Please inquire if you do not see your year listed.

KICK PANEL VENT KNOBS



PA780




PA782

PA780	1966	Kick Panel Vent Knobs (RE)	5.00/ea.
PA781	1967-68	Kick Panel Vent Knobs (RE)	5.00/ea.
PA782	1969-72	Kick Panel Vent Knobs (A-body) (RE)	5.00/ea.

These knobs come ready to install with correct hole diameter.

Comments: Good to very good.

WINDLACE



PA800

PA800	1955-72	Windlace (5 ft. length) (RE)	\$ 11.25/ea.
--------------	---------	------------------------------------	--------------

This is the windlace used on door posts and door lock pillars. It is a similar replacement for the leatherette style vinyl covered windlace used on convertibles and hardtops. Colors available: Parchment and black.



PA802K

PA802K	Early '69	Door Jamb Edging - GP (RE)	18.00/pr.
---------------	-----------	----------------------------------	-----------

This is an exact reproduction of the early '69 style edging (cardboard with attached lace).

PA802M	Late 1969-72	Door Jamb Edging - GP (RE)	25.00/pr.
---------------	--------------	----------------------------------	-----------

Note: PA802K and PA802M are available in black only - paint to match.

FLOOR PANS



PA810

PA810	1955-57	Front Floor Pans (RE)	110.00/pr.
PA811	1955-57	Rear Floor Pans (RP)	110.00/pr.

Rear floor pans may be replaced by taking a pair of front floor pans and reversing them. Several customers have used this process and by trimming the panels were able to complete their floor pan restoration.

PA830L	1959-60	Front Floor Pan, LH (RE)	72.00/ea.
PA830R	1959-60	Front Floor Pan, RH (RE)	72.00/ea.
PA831L	1959-60	Rear Floor Pan, LH (RE)	72.00/ea.
PA831R	1959-60	Rear Floor Pan, RH (RE)	72.00/ea.
PA832L	1959-60	Rear Seat Pan, LH (RE)	85.00/ea.
PA832R	1959-60	Rear Seat Pan, RH (RE)	85.00/ea.
PA836L	1961-64	Rear Floor Pan, LH (RE)	69.00/ea.

PA836R	1961-64	Rear Floor Pan, RH (RE)	\$ 69.00/ea.
PA850L	1965-70	Front Floor Pan, LH - FS (RE)	72.00/ea.
PA850R	1965-70	Front Floor Pan, RH - FS (RE)	72.00/ea.
PA851L	1965-70	Rear Floor Pan, LH - FS (RE)	72.00/ea.
PA851R	1965-70	Rear Floor Pan, RH - FS (RE)	72.00/ea.
PA860L	1969-72	Front Floor Pan, LH - GP (RE)	59.00/ea.
PA860R	1969-72	Front Floor Pan, RH - GP (RE)	59.00/ea.
PA861L	1969-72	Rear Floor Pan, LH - GP (RE)	59.00/ea.
PA861R	1969-72	Rear Floor Pan, RH - GP (RE)	59.00/ea.
PA862L	1969-72	Full Floor Pan, LH - GP (RE)	99.00/ea.
PA862R	1969-72	Full Floor Pan, RH - GP (RE)	99.00/ea.



PA864

PA864	1969-72	Full Floor Pan Under Rear Seat - GP (RE)	199.00/ea.
PA870L	1973-77	Front Floor Pan, LH - GP (RE)	69.00/ea.
PA870R	1973-77	Front Floor Pan, RH - GP (RE)	69.00/ea.
PA871L	1973-77	Rear Floor Pan, LH - GP (RE)	69.00/ea.
PA871R	1973-77	Rear Floor Pan, RH - GP (RE)	69.00/ea.

Please add \$8.50 for shipping floor plans.

Note: Floor pans have been very popular items with GTO - Tempest and Firebird restoration projects for years. Now that similar panels are available for full-size Pontiacs they make repairing rusted floors much easier and much more professional.

FLOOR BRACES



PA880R

PA880L	1959-60	Front Seat Mounting Bracket LH (RE)	43.00/ea.
PA880R	1959-60	Front Seat Mounting Bracket RH (RE)	43.00/ea.

These brackets weld under the front underseat floor pan. Made from heavy gauge metal they come complete with cage nuts to bolt the bench seat down securely.

PA880AL	1959-60	Front Floor Brace LH (RE)	69.00/ea.
PA880AR	1959-60	Front Floor Brace RH (RE)	69.00/ea.
PA880BL	1959-60	Center Floor Brace LH (RE)	53.00/ea.
PA880BR	1959-60	Center Floor Brace RH (RE)	53.00/ea.

PA880DL	1959-60	Rear Partial Floor Brace End LH (RE)	\$ 49.00/ea.
PA880DR	1959-60	Rear Partial Floor Brace End RH (RE)	49.00/ea.

These braces are only the outer ends - they measure 20" long.

PA888AL	1965-70	Front Floor Brace LH-FS (RE)	55.00/ea.
PA888AR	1965-70	Front Floor Brace RH-FS (RE)	55.00/ea.
PA888BL	1965-70	Center Floor Brace LH-FS (RE)	57.00/ea.
PA888BR	1965-70	Center Floor Brace RH-FS (RE)	57.00/ea.
PA888CL	1965-70	Rear Short Floor Brace LH-FS (RE)	62.00/ea.
PA888CR	1965-70	Rear Short Floor Brace RH-FS (RE)	62.00/ea.
PA888DL	1965-70	Rear of Rear Floor Brace LH-FS (RE)	55.00/ea.
PA888DR	1965-70	Rear of Rear Floor Brace RH-FS (RE)	55.00/ea.



PA890

PA890	1969-72	Front Floor Brace - GP (RE)	100.00/ea.
PA890A	1969-72	Center Floor Brace - GP (RE)	100.00/ea.

These braces are the finishing touch for your floor problems. Practically every rusted floor has rusted floor braces. These braces are stamped using heavy 12 ga. steel and are ready to be welded in place.

Note: Seat belts attach to the center floor brace.

Please add \$8.50 shipping for PA890 and PA890A floor braces.



PA900



PA901

PA900	Seam Sealer, Black (AP)	11.00/tube
PA901	Brushable Seam Sealer, Grey 1 Quart (AP)	Disc.



PA902

PA902	Disposable Brush	1.00/ea.
--------------	------------------	-------	----------

DASH PADS



PA918

PA918 Dash Pad, Nylon Attaching Inserts (GM) .. \$ 1.00/ea.



PA920

PA920 1957 Dash Pad (Black) - Paint to Match (RE)..... 449.00/ea.



PA921

PA921 1958 Dash Pad (Black) - Paint to Match (RE).....\$449.00/ea.

Made from OEM thermo-form dash vinyl and molded closed cell high density polyethylene foam, these pads are an excellent reproduction. The '57 is made with studs along the bottom edge and a Haircell grain texture very close to original. The '58 has the factory original Seville grain texture. Both are unconditionally guaranteed against defects in workmanship and cracking for as long as you own your car. These pads are available in black (paint to match) and are drop-shipped directly from manufacturer. Please allow 4-6 weeks for delivery.

Please add \$10.00 additional shipping for dash pads.



TALK ABOUT FAST SERVICE!

Many people *talk* about fast service but Ames Performs fast service. Between 93% and 94% of *all* orders were shipped within 24 hours during 1994.

For ordering or price quotations, please call (800) 421-2637.
For questions or ordering, call (603) 876-3345
(603) 876-4656
(603) 876-4751

SECTION TWO-FRONT END TRIM



FRONT EMBLEM



PB105

PB105 1951, 53 Grille Lucite Emblem (Silver/Red) (APE)..... \$ 79.00/ea.

PB106 1952 Grille Lucite Emblem (Gold/Red) (APE)..... 79.00/ea.

Note: These emblems are also used on the wire wheel centers.



PB116

PB115	1962	Front Emblem (w/nuts) (APE).....	\$ 29.00/ea.
PB116	1963	Front Emblem (w/nuts) Exc. GP (APE)	29.00/ea.
PB117	1963	Front Emblem (w/nuts) - GP (RE)	29.00/ea.

Note: Low-pressure casting with correct satin brushed surfaces.



PB120

PB120	1965	Front Emblem (w/nuts) (RE).....	24.00/ea.
PB115 and PB116 are die-cast to all original specifications. PB115 and PB116 have the original white and gold surfaces while PB120 has the satin-brushed surfaces.			
PB122	1967	Front Emblem - GP (RE)	25.00/ea.
Using 2nd design specifications, this arrowhead was cast in a low pressure mold with correct chrome and satin brushed surfaces.			
PB122A	1967	Front Emblem - GP (APE)	25.00/ea.
Using third design specifications, this arrowhead has a steel core with a molded rubber exterior.			
PB122D	1967	Front Emblem - exc GP (RE)	25.00/ea.
PB123J	1969	Front Emblem - FS (RE)	24.00/ea.
PB123K	1970	Front Emblem - FS (RE)	24.00/ea.



PB125Y	1964	GP Grille Emblem (RE)	22.00/ea.
PB126	1966	GP Grille Emblem (RE)	22.00/ea.
PB126B	1967	GP Headlight Door Emblem (RE)	22.00/ea.
PB126D	1968	GP Grille Emblem (RE)	22.00/ea.

PB125Y through PB126D are low-pressure castings. Overall quality is good.





PB127J

PB127J	1969	428 Grille Emblem (RE)	20.00/ea.
---------------	------	------------------------------	-----------



PB130

PB130	1971-72	Front Panel Script - GP (RE)	20.00/ea.
Because of the limited market PB127J and PB130 are not die-cast. They are low-pressure castings. Overall the quality is good.			



PB131

PB131	1971-72	Header Panel Emblem - GP (APE) ...	\$ 39.00/ea.
--------------	---------	------------------------------------	--------------




PB138D



PB138G

PB138D	1976	"Grand Prix" Header Nameplate (GM)	Disc.
PB138G	1976-77	Pontiac Header Panel Crest Emblem - GP (GM)	Disc.

HEADLIGHT DOOR GASKET



PB140	1955-57	Headlight Bucket Seals (RE)	4.00/pr.
PB140J	1955-57	Headlight Outer Rim to Sealed Beam Retaining Ring Seal (RE)	14.00/pr.
PB141	1958	Headlight Door Gasket (APE)	6.00/pr.
PB141J	1958	Headlight Outer Rim to Sealed Beam Retaining Ring Seal (RE)	25.00/set
PB145	1963	Headlight Door Gasket (APE)	6.00/pr.
PB146	1964	Headlight Door Gasket (APE)	6.00/pr.
PB147	1965	Headlight Door Gasket (APE)	6.00/pr.

These fender to headlight door gaskets were reproduced to exact GM specifications. These rubber strips replace your old hard or cracked originals.

HEADLIGHT DOOR COMPONENTS




- PB150** 1966 Headlight Door Nut (long plastic) (AP)..... \$.50/ea.
- PB150B** 1967 Headlight Door Nut (square plastic) (AP)..... .50/ea.
- PB150J** 1966-67 Headlight Door Screw (AP)50/ea.

Note: These screws are difficult to locate since they have a #8-18 thread size and a #6 head. Replacements are approximately 3/8" longer than original.



- PB155** 1968 Headlamp Actuator Seals - GP and Bonneville (RE)..... 15.00/pr.

Note: This product seals the vacuum actuator and the rod; it is usually the cause of those common vacuum leaks in cars with hideaway headlights.



- PB155A** 1968 Headaway Headlamp Actuator w/cover - GP and Bonneville (APE) . 65.00/ea.

This reproduction is the complete actuator ready to bolt in and now includes the cover, case, rod, seals, and diaphragm. These actuators should finally cure those inoperative hide-away headlight doors.

- PB155AA** 1968 Actuator Covers, Pair-GP and Bonneville (APE) 15.00/pr.

Finally available, these covers are usually missing on most cars.



- PB155AK** 1968 Headlamp Actuator Dust Boots (APE)..... 18.00/pr.


Note: These boots are designed to keep the inside of the actuators free from dirt and dust.



- PB155B** 1968 Hideaway Headlamp Vacuum Canister - GP and Bonneville (RE) ... \$ 49.00/ea.

This reproduction is the vacuum can mounted on the inner fender. Many originals are missing or damaged.

- PB155BJ** 1967-68 Hideaway Headlamp Vacuum Line Check Valve - GP and Bonneville (GM)..... 3.00/ea.



- PB155C** 1968 Hideaway Headlight Bushing Kit 14 Pieces - GP and Bonneville (RE) . 18.00/set

This kit is a must for '68 hideaway owners. Many times drooping or malfunctioning hide-away doors can be rejuvenated with this kit alone. Don't spend needless money and time on actuators etc. until you've first installed these bushings. Discard unused bushings.




Note: Hideaway headlight switches for '68 GPs & Bonnevilles are available in Section Eleven part number PM229T.



- PB155D** 1968 Hideaway Actuator Bushing Retainer Clip - GP and Bonneville (RP)50/ea.

Requires 4 per car.

FRONT END HARDWARE



- PB160** 1955-61 Headlight Adjusting Screw (AP)..... 1.00/ea.
- PB159J** 1962-68 Headlight Adjusting Nut and Screw (AP)..... 1.00/ea.

PB160	1969-70	Headlight Adjusting Nut and Screw - GP (AP)	\$ 1.00/ea.
PB160D	1969	Headlight Adjusting Nut and Screw - FS (AP)	1.50/ea.
PB160D	1974-75	Headlight Adjusting Nut and Screw - GP (AP)	1.50/ea.
PB160G	1976-77	Headlight Adjusting Nut and Screw - GP (AP)	1.00/ea.



PB160T

PB160M	1955-58	Headlight Adjusting Spring (AP)	Disc.
PB160R	1965-66	Headlight Adjusting Spring (AP)	1.50/ea.
PB160T	1968-69	Headlight Adjusting Spring - FS (AP)	1.50/ea.
PB160V	1969-70	GP & 1970 FS Headlight Adjusting Spring (AP)	1.50/ea.
PB160W	1971-73	GP & 1971-72 FS Headlight Adjusting Spring (AP)	1.50/ea.
PB160X	1973	Headlight Adjusting Spring - FS (AP)	1.50/ea.
PB160Y	1974-77	Headlight Adjusting Spring - ALL (GM)	2.00/ea.

PARKING LAMP COMPONENTS



PB162



PB163

PB162	1956	Parking Lamp Lenses (RE)	25.00/pr.
PB163	1957	Parking Lamp Lenses (RE)	30.00/pr.

Comments: Excellent.



PB164J

PB164J	1958	Parking Lamp Lens Gaskets (RE)	12.00/pr.
---------------	------	--------------------------------------	-----------



PB166



PB168

PB166	1960	Parking Lamp Lens (RE)	10.00/ea.
PB168	1963	Parking Lamp Lens Clear (APE)	59.00/pr.

Finally - These highly sought after lenses have been reproduced. Quality is excellent.



PB169

PB169	1963-64	Parking Lamp Lenses - Clear exc. GP (APE)	\$ 30.00/pr.
PB170	1964	Parking Lamp Lenses - Amber exc. GP (APE)	30.00/pr.
PB171	1965	Parking Lamp Lenses - Clear exc. GP (APE)	30.00/pr.
PB172	1963-65	Parking Lamp Lenses Gaskets exc. GP (APE)	6.00/pr.

Because of the exceptional quality and customer response to our previous lenses we enlisted the same supplier to make these 1963-65 lenses.



PB175

PB175	1965	Parking Lamp Lenses - GP (APE)	40.00/pr.
--------------	------	--------------------------------------	-----------

Each lens is complete with stamped metal and cast shield assembly. Quality is excellent.



PB176

PB176	1965	Parking Lamp Gaskets - GP (APE)	6.00/pr.
--------------	------	---------------------------------------	----------

Finally you can stop the moisture from entering and condensing on the inside of your parking light lenses. Unlike stamped gaskets these are made of molded rubber, same as originals.



PB177

PB177	1965	Parking Lamp Bezels - GP (APE)	30.00/pr.
--------------	------	--------------------------------------	-----------

These chrome die-cast bezels were introduced in conjunction with PB175 and PB176. Again, quality is excellent.

PB178	1965	Parking Lamp Set - GP (APE)	65.00/set
--------------	------	-----------------------------------	-----------

Save money by purchasing all six of the above

parking lamp components. Each set contains two lenses, two lens gaskets, and two lens bezels.



PB182J

PB182A	1958	Parking Light Lens Screw (AP)	\$.50/ea.
PB182J	1969-72	Parking Light Lens and Bezel Screw - GP (AP).....	.50/ea.

These PB182J screws are very hard to find being a #8 - 18 x 4" long.



FRONT END BOLT KITS



PB185A	1955-57	Front End Bolt Kit (AP).....	Inquire
PB185C	1958	Front End Bolt Kit (AP).....	35.00/kit
PB185D	1959-60	Front End Bolt Kit (AP).....	Inquire
PB185E	1961-62	Front End Bolt Kit (AP).....	Inquire
PB185F	1963-64	Front End Bolt Kit (AP).....	35.00/kit
PB185G	1965-66	Front End Bolt Kit (AP).....	35.00/kit
PB185H	1967-68	Front End Bolt Kit (AP).....	Inquire
PB185J	1969-70	Front End Bolt Kit-FS (AP).....	Inquire
PB185K	1969-72	Front End Bolt Kit-GP (AP)	35.00/kit
PB185L	1971-75	Front End Bolt Kit-FS (AP).....	Inquire
PB185M	1973-77	Front End Bolt Kit-GP (AP)	Inquire

Note: These kits contain enough bolts and shims to assist in assembly of the front end sheet metal.



HEADLIGHTS, RINGS & SCREWS



PB190D



PB192D

PB188	1955-57	Halogen Round Headlight (AP)	12.00/ea.
		2 Headlamp System	
PB188B	1958-70	Halogen Round Low Beam Headlight - All (AP)	7.00/ea.
		4 Headlight System	
PB188D	1958-70	Halogen Round High Beam Headlight - All (AP)	7.00/ea.
		4 Headlight System	
PB188B	1971-75	Halogen Round Low Beam Headlight - FS exc. 75 Bonneville and Grandville (AP)	7.00/ea.
		4 Headlight System	

PB188D	1971-75	Halogen Round High Beam Headlight - FS exc. 75 Bonneville and Grandville (AP)	\$ 7.00/ea.
		4 Headlight System	
PB188	1971-75	Halogen Round Headlight - GP (AP).....	12.00/ea.
		2 Headlight System	
PB188F	1975-77	Halogen Square Low Beam Headlight exc. 75 Cat & GP (AP).....	7.00/ea.
		4 Headlight System	
PB188G	1975-77	Halogen Square Low Beam Headlight exc. 75 Cat & GP (AP).....	7.00/ea.
		4 Headlight System	

Note: PB188-PB188D are not correct but are inexpensive and brighter replacements for T-3 bulbs.

PB190	1956-57	"T-3" Headlight Set (RE).....	109.00/pr.
PB190B	1958-59	"T-3" Headlight Set (RE).....	109.00/set of 4
PB190D	1960-67	"T-3" Headlight Set (RE).....	109.00/set of 4

These new reproductions are the final touch for your detailed restoration. Bulbs are absolutely correct with "Guide" lettering and T-3 triangle.

PB192	1955	Headlight Retainer Ring (Requires 2) (GM).....	10.00/ea.
PB192B	1956-57	Headlight Retainer Ring (Requires 2) (GM).....	Disc.
PB192D	1958-67	Headlight Retainer Ring (Requires 4) (GM).....	10.00/ea.
PB192	1971-72	Headlight Retainer Ring - GP (Requires 2) (GM).....	9.00/ea.
PB192J	1973-75	Headlight Retainer Ring - GP (Requires 2) (GM).....	12.00/ea.
PB192M	1976-77	Headlight Retainer Ring - GP (Requires 4) (GM).....	11.00/ea.


These rings surround the headlight holding it in place.



PB192RA

PB192RA	1955-77	Headlight Retainer Ring Screw - ALL (GM)	1.00/ea.
----------------	---------	---	----------


BUMPER BOLTS



PB221

PB220	1955-63	Round Head Stainless Steel Cap Bumper Bolt (w/nut) (RE).....	1.00/ea.
PB221	1964-72	Pan Head Stainless Steel Cap Bumper Bolt (w/nut) (RE).....	1.00/ea.

LICENSE PLATE MOUNTING



PB225

- PB225** 1955-59 Front License Mounting Kit (RE)..... \$ 3.00/ea.
PB225 1963-75 Front License Mounting Kit (RE)..... 3.00/ea.
 (Includes 2 rubber bumpers, 2 nylon nuts, and 2 screws.)
PB230 1968-72 Front License Plate Bumper
 (Mounting Bracket to Valance
 Panel) (RE)75/ea.

SIDE MARKER LENS & CLIP



PB250



PB251

- PB250** 1969 Side Marker Lenses - Executive
 Station Wagon (APE) 20.00/pr.

This is an exact plastic reproduction of the two-piece lenses mounted on the sides of the front valance panel.

- PB251** 1969 Side Marker Lens Clip - Executive
 Station Wagon (RE) \$ 12.00/pr.

Comments: These are the clips used to secure side marker lens to the valance.

RADIATOR SUPPORT BAFFLE



PB301

- PB301** 1969 Radiator Support Lower Air Baffle
 - ALL w/AC and ALL GP
 (w/mounting hardware) (RE) 32.00/ea.

Comments: This is an exact reproduction of the factory installed air baffle. Constructed of hair-cell pattern plastic, it diverts additional air through the radiator for better engine cooling.

SECTION THREE-FRONT FENDER TRIM

FENDER EMBLEMS & ORNAMENTS



PC100

- PC100** 1955 Chrome Star Ornament (RE) \$ 10.00/ea.



PC105

- PC105** 1956 Front Fender V-8 Emblems (APE)..... 49.00/pr.

Note: These high quality die-cast emblems have the white border around the outside edges. '56 emblems typically did not use this border.



PC110

- PC110** 1957 Star Chief Fender Script (APE) \$ 65.00/pr.

This brand-new reproduction is die-cast in one-piece like originals.


Note: Beware of the two-piece low pressure reproductions on the market.



PC114

PC112


- PC112R** 1957 Front Fender Louver - Bonneville
 - RH (RE) 21.00/ea.
PC112L 1957 Front Fender Louver - Bonneville
 - LH (RE) 21.00/ea.
PC112 1957 Front Fender Louver Set - Bonneville
 - 14 Pieces (RE) 284.00/set
PC114 1957 Fuel Injection Emblems
 (Set of 3) (RE) 259.00/set



- PC114K** 1957 Complete Illuminated Fender Ornaments (APE)\$269.00/pr.

Note 1: These ornaments are correct for all '57 models from Chieftains through Bonneville.

Note 2: Each assembly consists of chrome ornament, lucite insert and wiring. Attaching studs are in the same position as the non-illuminated standard fender ornaments. As in original installations, one small hole must be drilled under the ornament for wiring.



- PC114L** 1957 Illuminated Fender Ornament Inserts (APE)..... 79.00/pr.

Many owners have nice ornaments but their inserts are badly cracked. These reproductions will greatly enhance your original assemblies.



- PC115** 1958 Tripower Fender Emblem (RE)..... 65.00/pr.



- PC116** 1958 Fuel Injection Fender Emblem (RE).. 69.00/ea.



- PC117** 1958 Front Fender Side Louver Set (8pcs) (RE) 479.00/set
- PC117L** 1958 Front Fender Side Louver - LH (RE)..... 70.00/ea.
- PC117R** 1958 Front Fender Side Louver - RH (RE)..... 70.00/ea.



- PC120** 1959 Tripower Fender Emblems (Gold) (RE) 65.00/pr.
- PC122** 1960 Bonneville Fender Emblems (RE)..... 40.00/pr.



- PC130** 1962-64 421 Fender Emblems (RE)..... \$ 59.00/pr.



- PC150** 1964 2+2 Fender Emblems (RE)..... 54.00/pr.



- PC152** 1964 "Grand Prix" Fender Letters (9 pieces) (RE)..... 59.00/ea.
- PC152A** 1964 "Grand Prix" Fender Letters (18 pieces) (RE)..... 105.00/set



- PC152J** 1964 Grand Prix Front Fender Emblem (RE)..... 29.00/ea.



- PC158** 1965 2+2 Louvers (RE) 11.00/ea.
- Note:* 2+2s require 10 louvers per side.



- PC158J** 1965 Catalina Fender Emblem (RE) 89.00/pr.



- PC160** 1965 421 Fender Emblems (RE)..... 99.00/pr.

PC161 1965 Grand Prix Fender Letters (RE) \$ 59.00/set



PC162

PC162 1965 Bonneville Fender Emblem (RE) 93.00/pr.

PC168 1966 Bonneville Door and Fender Letters (10 pc. set) (RE) 99.00/side



PC169

PC169 1966 Catalina Fender Emblems (RE) 109.00/pr.

PC170 1966 421 Fender Emblems (Exc. 2+2) (RE) 99.00/pr.

PC171 1966 421 Fender Emblem - 2+2 (RE) 99.00/pr.



PC171J

PC171J 1966 Grand Prix Fender Emblem (RE) 95.00/pr.

PC171L 1966 Grand Prix Fender Letters (RE) 59.00/ea.



PC178

PC172 1967 428 Fender Emblems (RE) 69.00/pr.

PC176J 1968 428 Fender Emblems (RE) 75.00/pr.



PC177

PC177 1968 "Bonneville" Fender Letters (10-piece set) (RE) 79.00/ea.

PC177A 1968 "Bonneville" Fender Letters (20-piece set) (RE) 155.00/pr.

PC178 1969 428 Fender Emblems - ALL (RE) 40.00/pr.



PC180

PC180 1969-72 Model SJ Emblems - GP (RE) \$ 45.00/pr.



PC181

PC181 1969 Model J Emblems - GP (RE) 45.00/pr.

PC200 1969 "Grand Prix" Fender Letters (9 pcs.) (RE) 67.00/ea.

PC200A 1969 "Grand Prix" Fender Letters (18 pcs.) (RE) 125.00/pr.

Comments: Because of the limited market, PC114 through PC200A are not die-cast. These pieces are low pressure castings.

Overall the quality is good.



PC220

PC220 1971-74 Fender Script Catalina (CATALINA) (RE) Inquire



PC225

PC225 1973-77 "SJ" Fender Emblems - GP (RE) 22.00/ea.



PC228

PC228 1973-77 "Grand Prix" Fender Emblem - GP (NOS) Inquire



PC240 "350" Rocker Panel Molding Emblems (RP) 43.00/pr.

PC241 "400" Rocker Panel Molding Emblems (RP) 43.00/pr.

PC242 "455" Rocker Panel Molding Emblems (RP) 43.00/pr.



Although never used on full-size Pontiacs, many customers have used these as afterproducts bolt-ons.

WHEELWELL TRIM

PC300 1964-77 Wheelwell Molding Screws (RE) \$ 5.00/set

Each set of wheelwell molding screws does one complete car (32 screws). Screws are the same as GM with the unique washer head design.



PC326L 1971-72 Front Wheelwell Molding w/Screws, LH - FS (NOS) 45.00/ea.
PC326R 1971-72 Front Wheelwell Molding w/Screws, RH - FS (NOS) 45.00/ea.
PC328L 1973-76 Front Wheelwell Molding w/Screws, LH - FS (NOS) 45.00/ea.
PC328R 1973-76 Front Wheelwell Molding w/Screws, RH - FS (NOS) 45.00/ea.
PC330L 1973-77 Front Wheelwell Molding w/Screws, LH - GP (GM) 40.00/ea.
PC330R 1973-77 Front Wheelwell Molding w/Screws, RH - GP (GM) 40.00/ea.

Please add \$7.00 for shipping on wheelwell moldings.

FRONT FENDER




PC380L

PC380L 1975-76 Front Fender, LH - FS (NOS) \$250.00/ea.

Note 1: Fenders are unpainted and may have light surface rust.

Note 2: Fenders must be prepaid and will be shipped truck freight. Please ask for a freight charge estimate. Please include \$10.00 per item packaging and handling on all freight charge items.



PC420 1955-57 Lower Front Fender Shims (RE) 5.50/set

SECTION FOUR-HOOD COMPONENTS



PD105

PD105 1955 Illuminated Indianhead Lucite - Amber (RE) \$ 69.00/ea.

PD106 1955 Illuminated Indianhead Lucite - Clear (RE) 69.00/ea.

Note: Color, clarity and design are excellent.



PD107

PD107 1956 Accessory Hood Ornament Insert - Clear (RE) 69.00/ea.

Note: This is the clear plastic insert only.

EMBLEMS




PD110

PD110 1957 Hood Emblem Lucite Insert (APE).... \$49.00/ea.

This is our own reproduction of the '57 front plastic emblem. Most originals are either cracked or faded and should be replaced by one of these excellent reproductions.



PD111B 1958 Bonneville Hood Letters (RE) 129.00/set



PD115

- PD115** 1961 Hood Arrowhead w/Nuts (APE)..... \$ 29.00/ea.
PD116 1964 Hood Arrowhead w/Nuts (APE)..... 29.00/ea.

These emblems are die-cast to all original specifications including satin-brushed surfaces.



PD117Y

- PD117Y** 1965 GP Hood Emblem (RE) 20.00/ea.



PD118

- PD118** 1965 2+2 Hood Emblem w/Nuts (RE) 39.00/ea.
PD119 1966 2+2 Hood Emblem w/Nuts (RE) 39.00/ea.
PD120 1966 Hood Arrowhead w/Nuts (RE) 25.00/ea.



PD122

- PD122** 1967 Bonneville Hood Emblem (RE) 25.00/ea.



PD130




PD131

- PD130** 1969-70 Hood Emblem - GP (APE) 18.00/ea.
PD131 1969-70 Hood Emblem Bezel - GP (APE) 18.00/ea.
PD132 1969-70 Hood Emblem and Bezel - GP (APE) .. 30.00/ea.

Note: Save money on both PD130 and PD131 by purchasing them as a set.


Comments: The 1969-70 Grand Prix hood emblem and bezel are both excellent reproductions.

COWL SCREENS & GRILLES



PD149

- PD149** 1969 Cowl Screen (GP) (RE) \$19.00/ea.
 PD149 is made from the correct wire mesh.



PD150

- PD150** 1970-72 Cowl Grille, 3 Pc. - (GP) (RE) 57.00/set

Note: These reproductions are made to replace your old broken or missing grilles. Cowl grilles are molded from a heat resistant material to resist distortion. These grilles are used on cars with or without air conditioning.

BUMPERS & SEALS



PD200



PD200A

- PD200** 1955-63 Hood Bumper Cap - Front or Rear... 2.00/ea.

Note: PD200 is the rubber cap only.


- PD200A** 1955-63 Hood Bumper Stud (RE) 3.00/ea.

- PD200B** 1955-63 Hood Bumper Assembly (RE) 4.00/ea.

PD200B consists of PD200 and PD200A.



PD204



PD205



PD206

- PD205** 1964-65 Hood Bumper w/Stud - Front Adjustable (GM) 3.00/ea.

- PD204** 1966-77 Hood Bumper Cap - Front Adjustable (RE) 2.00/ea.

This is an exact reproduction of the cone-shaped cap used on the front adjustable bumper for these years. You must reuse the original stud and nut. PD206 is an exact reproduction utilizing the rubber cap w/the stud.

- PD206** 1966-77 Hood Bumper w/Stud - Front Adjustable (RE) 3.00/ea.




PD207



PD216

- PD207** 1967-72 Hood Rear Bumper -All (GM)..... \$ 2.00/ea.
PD207 1973-76 Hood Rear Bumper - FS (GM) 2.00/ea.
 PD207 is a GM replacement that is now too tall. It must be cut for your specific application (actual height is 13/16").
- PD207C** 1967-72 Hood Rear Bumper (RE) 8.00/pr.
PD207C 1973-76 Hood Rear Bumper - FS (RE) 8.00/pr.
 These reproductions are much closer to the original design (actual height is 7/8").
- PD208** 1973-77 Bumper Hood to Cowl Round - GP Inquire
PD212 1955-57 Hood to Fender Bumper (APE) 2.00/ea.
PD214 1958 Hood to Fender Bumper (RE)..... 3.00/ea.
PD215 1959-63 Hood to Fender Bumper (RE)..... 2.50/ea.
PD216 1964-68 Hood to Fender Bumper (RE)..... 1.50/ea.
PD218 1969 Hood to Fender Bumper (APE) 1.50/ea.
PD222 1970-72 Hood to Fender Bumper (APE) 1.00/ea.
PD222 1973-76 Hood to Fender Bumper - FS (RE) 1.00/ea.
PD224 1973-77 Hood to Fender Bumper - GP Inquire
PD250 1955-56 Cowl Panel Bumpers (RE) 4.50/set

HOOD TO COWL SEALS



- PD260** 1955-56 Hood to Cowl Seal (RE) 9.00/ea.
PD261 1957-58 Hood to Cowl Seal (RE) 9.00/ea.
PD262 1959-60 Hood to Cowl Seal (RE) 9.00/ea.
PD265 1961-62 Hood to Cowl Seal (RE) 10.00/ea.
PD266 1963-64 Hood to Cowl Seal (RE) 9.00/ea.
PD268 1965-66 Hood to Cowl Seal (RE) 28.00/ea.
PD269 1967-68 Hood to Cowl Seal (RE) 19.00/ea.
PD272 1971-76 Hood to Cowl Seal (RE) 20.00/ea.

The hood to cowl seal is mounted along the upper portion of the firewall. This weatherstrip seals the rear portion of the engine compartment.



PD291


- PD290** 1955-67 Clip-Hood to Cowl Seal (GM) 1.00/ea.
PD291 1968-77 Hood to Cowl Seal Metal Clip (RE).. .75/ea.



PD293J

- PD293J** 1959-60 Cowl Side Drain Gutter
 - Sedan (RE) \$ 87.00/pr.
PD293L 1961-62 Cowl Side Drain Gutter - ALL (RE) ... 84.00/pr.

HOOD TO WINDSHIELD FRAME PAD



PD295

- PD295** 1969-72 Pad, Hood to Windshield Side
 Frame - GP (RE) 15.00/pr.

Note: These items may be the most sought after pieces needed in 1969-72 GPs. Every original seems cracked or destroyed.

Our reproductions are made of high impact plastic to keep your hood from gouging the cowl area when closing.

HOOD HINGES AND SPRINGS



PD311R

- PD311R** 1971-76 Hood Hinge, RH - FS (GM)..... Disc.
PD311L 1971-76 Hood Hinge, LH - FS (GM)..... Disc.
PD313R 1973-77 Hood Hinge, RH - GP (GM) Disc.
PD313L 1973-77 Hood Hinge, LH - GP (GM)..... Disc.



- PD330** 1969-70 Hood Hinge Spring - FS (GM)..... 13.00/ea.



PD334C

PD334B 1963-66 Hood Hinge Nut and Bolt Kit (RP)... \$ 4.00/kit
PD334C 1967-77 Hood Hinge Bolt Kit (RP)..... 4.00/kit

HOOD TACHS



PD342


PD341	1967	Hood Tach (RE).....	Inquire
PD342	1968 to Early '69	Hood Tach - 5100 Redline - ALL (RE).....	Inquire
PD342A	1968 to Early '69	Hood Tach - 5500 Redline - ALL (RE).....	Inquire
PD343	Late 1969-72	Hood Tach - 5100 Redline - GP (RE).....	Inquire
PD343A	Late 1969-72	Hood Tach - 5500 Redline - GP (RE).....	Inquire

PD342 and PD342A have steel blue faces while PD343 and PD343A have black faces. 5100 redline is original; however, we offer a 5500 redline for those performance minded enthusiasts. (Factory harnesses cannot be used with these tach.) These tachs come complete with wiring harnesses and a 2-year warranty.

Note: Before painting, lightly sand the primer on these tachs. Under no circumstances should the primer be removed.

Comments: Very good. Externally all units are now made to exact factory two-piece specifications. Tach wiring harnesses are available separately in Section Eleven.

HOOD RELEASE COMPONENTS



PD350	1971-76	Hood Release Handle w/Cable - FS (GM).....	28.00/ea.
PD350	1973-77	Hood Release Handle w/Cable - GP (GM).....	28.00/ea.
PD350J	1971-76	Hood Release Cable Retainer - FS (GM).....	1.00/ea.

PD350J 1973-77 Hood Release Cable Retainer - GP (GM)..... \$ 1.00/ea.



PD350L

PD350L	1971-76	Hood Release Cable Grommet - FS (GM).....	3.00/ea.
PD350L	1973-77	Hood Release Cable Grommet - GP (GM).....	3.00/ea.
PD352A	1971-72	Hood Pop Springs - GP (RE).....	20.00/pr.
PD352D	1971-73	Hood Pop Spring - FS (RE)	11.00/ea.
PD352J	1974-76	Hood Pop Spring - ALL (GM).....	6.00/ea.

HOOD LAMP KITS




PD360C

PD360	1963-68	Underhood Lamp Kit (RE).....	53.00/ea.
PD360C	1969-70	Underhood Lamp Kit - GP (RE).....	53.00/ea.

These kits are a reproduction of the accessory package for underhood lighting.

Please check Section Nine for trunk lamp kits.

HOOD PAD RETAINERS




PD398B

PD398	1956	Hood Pad Wire Retainer Kit (APE)...	20.00/set
This kit includes 2 stainless steel retaining wires, 4 stamped clips and 4 screws to hold your hood pad securely in place.			
PD398B	1957-58	Hood Pad Wire Retainer Kit (APE)...	20.00/set
PD398D	1959	Hood Pad Wire Retainer Kit (APE)...	20.00/set

PD398B and PD398D include 2 galvanized retaining wires, 4 stamped clips and 4 screws.

UNDERHOOD INSULATION



PD400	1956	Underhood Insulation Pad - Yellow (RE).....	\$ 25.00/ea.
PD400A	1956	Underhood Insulation Pad - Yellow w/Wire Retainer Kit (See #PD398) (RE).....	42.00/ea.
PD400C	1956	Underhood Insulation Pad - Gray (RE).....	25.00/ea.
PD400D	1956	Underhood Insulation Pad - Gray w/Wire Retainer Kit (See #PD398) (RE).....	42.00/ea.
PD401	1957	Underhood Insulation Pad - Yellow (RE).....	25.00/ea.
PD401A	1957	Underhood Insulation Pad - Yellow w/Wire Retainer Kit (See #PD398B) (RE).....	42.00/ea.
PD401C	1957	Underhood Insulation Pad - Gray (RE).....	25.00/ea.
PD401D	1957	Underhood Insulation Pad - Gray w/Wire Retainer Kit (See #PD398B) (RE).....	42.00/ea.
PD402	1958	Underhood Insulation Pad - Yellow (RE).....	25.00/ea.
PD402A	1958	Underhood Insulation Pad - Yellow w/Wire Retainer Kit (See #PD398B) (RE).....	42.00/ea.
PD402C	1958	Underhood Insulation Pad - Gray (RE).....	25.00/ea.
PD402D	1958	Underhood Insulation Pad - Gray w/Wire Retainer Kit (See #PD398B) (RE).....	42.00/ea.
PD403	1959	Underhood Insulation Pad - Yellow (RE).....	25.00/ea.
PD403A	1959	Underhood Insulation Pad - Yellow w/Wire Retainer Kit (See #PD398D) (RE).....	42.00/ea.
PD403C	1959	Underhood Insulation Pad - Gray (RE).....	25.00/ea.
PD403D	1959	Underhood Insulation Pad - Gray w/Wire Retainer Kit (See #PD398D) (RE).....	42.00/ea.
PD404	1960	Underhood Insulation Pad - Yellow (RE).....	25.00/ea.
PD405	1960	Underhood Insulation Pad Yellow w/Clips (See #PD434) (RE).....	28.00/ea.
PD405C	1960	Underhood Insulation Pad - Gray (RE).....	25.00/ea.

PD405D	1960	Underhood Insulation Pad - Gray w/Clips (See #PD434) (RE).....	\$ 28.00/ea.
PD406	1961-62	Underhood Insulation Pad - Yellow (RE).....	25.00/ea.
PD407	1961-62	Underhood Insulation Pad - Yellow w/Clips (See #PD434) (RE).....	28.00/ea.
PD407C	1961-62	Underhood Insulation Pad - Gray (RE).....	25.00/ea.
PD407D	1961-62	Underhood Insulation Pad - Gray w/Clips (See #PD434) (RE).....	28.00/ea.

There seems to be controversy over the color of original hood insulation pads for 56-62 FS Pontiacs. Many customers have found gray hood pads instead of yellow on their early cars. Therefore, we have decided to carry both yellow and gray.

PD408	1963	Underhood Insulation Pad (RE)	25.00/ea.
PD409	1963	Underhood Insulation Pad w/Clips (See #PD436) (RE).....	28.00/ea.
PD410	1964	Underhood Insulation Pad (RE)	25.00/ea.
PD411	1964	Underhood Insulation Pad w/Clips (See #PD436) (RE).....	28.00/ea.
PD412	1964	Underhood Insulation Pad w/Metal Clips (See #PD435) (RE).....	35.00/ea.

Note: For many full size Pontiacs, the Insulation Pad covers only a small portion of the hood. They are usually positioned over the engine itself.

PD413	1965	Underhood Insulation Pad (RE)	25.00/ea.
PD414	1965	Underhood Insulation Pad w/Clips (See #PD436) (RE).....	28.00/ea.
PD415	1965	Underhood Insulation Pad w/Metal Clips (See #PD435) (RE).....	35.00/ea.
PD416	1966	Underhood Insulation Pad (RE)	25.00/ea.
PD417	1966	Underhood Insulation Pad w/Clips (See #PD436) (RE).....	28.00/ea.
PD418	1966	Underhood Insulation Pad w/Metal Clips (See #PD435) (RE).....	35.00/ea.
PD419	1967	Underhood Insulation Pad (RE)	25.00/ea.
PD419A	1967	Underhood Insulation Pad w/Clips (See #PD436) (RE).....	28.00/ea.
PD420	1968	Underhood Insulation Pad (RE)	25.00/ea.
PD420A	1968	Underhood Insulation Pad w/Clips (See #PD436) (RE).....	28.00/ea.
PD421	1969-70	Underhood Insulation Pad - FS (RE).	25.00/ea.
PD422	1969-70	Underhood Insulation Pad w/Clips (See #PD436) - FS (RE)	28.00/ea.
PD423	1969-70	Underhood Insulation Pad - GP (RE).....	25.00/ea.
PD424	1969-70	Underhood Insulation Pad w/Clips (See #PD436) - GP (RE).....	28.00/ea.
PD425	1971-72	Underhood Insulation Pad - FS (RE).	25.00/ea.
PD426	1971-72	Underhood Insulation Pad w/Clips (See #PD436) - FS (RE)	28.00/ea.
PD427	1971-72	Underhood Insulation Pad - GP (RE).....	25.00/ea.
PD428	1971-72	Underhood Insulation Pad w/Clips (See #PD436) - GP (RE).....	28.00/ea.
PD428J	1973-74	Underhood Insulation Pad - FS (RE).	25.00/ea.

PD428K	1973-74 Underhood Insulation Pad w/Clips (See #PD436) - FS (RE)	\$ 28.00/ea.
PD429	1973-77 Underhood Insulation Pad - GP (RE).....	25.00/ea.
PD429A	1973-77 Underhood Insulation Pad w/Clips (See #PD436) - GP (RE).....	28.00/ea.
PD429D	1975 Underhood Insulation - FS (RE).....	25.00/ea.
PD429E	1975 Underhood Insulation w/Clips (See #PD436) - FS (RE)	28.00/ea.

Our reproduction underhood insulation pads are die-cut from material very close to original.

Comments: Very good. The outline material and hole locations are excellent. The product does not have the material compressed in the small areas around the perimeter as did the original, but does have a backing for added strength.



PD434



PD435



PD436

PD434	1960-62 Hood Insulator Pad Clip, Round Plastic (RE).....	\$.50/ea.
PD435	1964-66 Hood Insulator Pad Clip, Square Metal (RE).....	1.00/ea.
PD436	1963-77 Hood Insulator Pad Clip, Square Plastic (RE).....	.35/ea.

Finally a steel hood pad clip for those restorers seeking originality. Gauge, type of steel, and black finish are all the same as original.

SECTION FIVE-DOOR COMPONENTS

EMBLEMS



PF100

PF100	1955 Chrome Star Ornament (RE)	\$ 10.00/ea.
--------------	--------------------------------------	--------------



PF100J

PF100J	1959 Bonneville Door Crest Emblem (RE)	18.00/ea.
---------------	--	-----------



PF105

PF105	1962 Door Emblem - GP (RE).....	109.00/pr.
--------------	---------------------------------	------------

Comments: Because of the limited market PF105 is not die-cast. This piece is a low pressure casting, and overall the quality is good.



PF106J

PF106J	1966 Bonneville Door and Fender Letters (10 pc. set) (RE)	99.00/ea
---------------	---	----------

DOOR HANDLES



PF121D

PF110	1955-57 Outside Door Handle Assembly - 2 Dr. HT & Conv. (RE)	\$ 50.00/pr.
PF111	1955-57 Outside Door Handle Assembly Sedan - 4 Dr. HT (RE).....	50.00/pr.
PF115	1958 Outside Door Handle Assembly (RE).....	118.00/pr.

Note: PF115 will not fit Cheifan & Superchief 2 Dr. HT & 4 Dr. Sedan.

PF117	1959 Outside Door Handle Assembly - Front (RE).....	85.00/pr.
--------------	---	-----------

PF120	1959 Rear & 1967-68 Front or Rear Outside Door Handles (GM)	Disc.
--------------	---	-------

PF120 are handles only.

PF120D	1959 Rear & 1967-68 Front or Rear Outside Door Handle Assemblies (RE).....	70.00/pr.
---------------	--	-----------

PF110-PF120D assemblies include handles, buttons, shafts, springs, o-rings, retainers, bolts and gaskets.

PF121	1960-62 Front & 1961-62 Rear Outside Door Handles (GM)	Disc.
--------------	--	-------

PF121 are handles only.

PF121D 1960-62 Front & 1961-62 Rear
Outside Door Handle Assemblies
(RE)..... \$ 70.00/pr.

Note: Includes same components as PF120D.

PF122 1960 Rear & 1963-66 Front or Rear
Outside Door Handles (GM) Disc.
PF122 are handles only.

PF122D 1960 Rear & 1963-66 Front or Rear
Outside Door Handle Assemblies
(RE)..... 70.00/pr.

Note: Includes same components as PF120D.

Comments: PF122D exhibit outstanding quality - available now!

PF126 1969-70 Outside Door Handles - Front 4 Dr.
Models (GM)..... Disc.

PF127L 1969-70 Outside Door Handle - Front 2 Dr.
and Rear 4 Dr. Models, LH - FS PF127S
(GM)..... Disc.



PF127S 1969-72 Outside Door Handle Assembly
w/o Retainer, L or R - GP (RE) 49.00/ea.

PF127T 1969-72 Outside Door Handle Assembly,
Pair w/o Retainers - GP (RE) 89.00/pr.

See PF144A for door handle gaskets.

PF128 1971-76 Outside Door Handles, Front or
Rear - FS (GM)..... 105.00/pr.



PF129 1973-early 76
Outside Door Handles,
61/4" long - GP (GM) Disc.

PF130 Late 1976-77
Outside Door Handles, 55/8" long
- GP (GM)..... 78.00/pr.

1976 was a transition year for door handles.
Please measure your originals before ordering.



PF135

PF133 1955-57 Outside Door Handle Push Buttons
(RE)..... 9.50/pr.

PF135 1960-70 Outside Door Handle Buttons (RE).. \$ 18.00/pr.

Comments: These reproductions far exceed the current GM door handle button quality. Buttons come complete with gaskets, springs and retainers. Button shafts must be cut to fit your application.

DOOR HANDLE SHIELDS



PF140

PF140 1955-56 Accessory Door Handle Shields
(RE)..... 22.00/pr.



PF141

PF141 1957 Accessory Door Handle Shields
(RE)..... 27.00/pr.

PF141B 1958 Accessory Door Handle Shields
(RP)..... 32.00/pr.

These are the Chevrolet Accessories that many Pontiac enthusiasts have asked for.

DOOR HANDLE GASKETS



PF142 1955-57 Door Handle and Lock Gaskets
(RE)..... 3.50/set

PF143 1958 Door Handle and Lock Gaskets
(RE)..... 3.50/set

PF143A 1959 Rear and 1967-68 ALL
Door Handle and Lock Gaskets 5.00/set

PF144 1959-70 Door Handle and Lock Gaskets
(Exc. 1959 Rear, 1967-68, and
'69-'70 GP) (RE) 5.00/set

PF144A 1969-72 Door Handle and Lock Gaskets
- GP (RE)..... 6.50/set

Set includes enough gaskets for two door handles and three locks.

Comments: Excellent. Other sources sell beaded gaskets, but we've never seen these used by the factory.



PF144F

PF144F 1971-76 FS & 1973-77 GP
Outside Door Handle Escutcheon
(GM)..... \$ 3.00/ea.

This is the black plastic behind the outside door handle that serves as a gasket and a water shield.

PF144N 1955-77 Door and Deck Lid Lock Gasket
(RE)..... 1.00/ea.

DOOR BADGES



PF144TA

PF144TA 1967 Mark of Excellence Badge,
Turquoise (RE)..... 5.00/ea.

PF144TB 1968 & Newer
Mark of Excellence Badge,
Blue (RE)..... 6.50/ea.

After years of only a flat decal being available, these are the correct stamped aluminum pieces.

Comments: Quality is excellent.

DOOR LOCK ASSEMBLIES



PF145A 1955-57 Door Lock Assembly (Sedans)
w/Late-Style Key (NOS) 26.50/pr.
PF145B 1955-57 Door Lock Assembly (Sedans)
w/Original-Style Key (NOS)..... 34.00/pr.
PF146A 1955-57 Door Lock Assembly (2 Dr. HT
and Conv.) w/Late-Style Key (NOS). 26.50/pr.
PF146B 1955-57 Door Lock Assembly (2 Dr. HT and
Conv.) w/Original-Style Key (NOS). 34.00/pr.
PF147A 1956-57 Door Lock Assembly (4 Dr. HT)
w/Late-Style Key (NOS) 25.00/pr.
PF147B 1956-57 Door Lock Assembly (4 Dr. HT)
w/Original-Style Key (NOS)..... 34.00/pr.
PF148A 1958 Door Lock Assembly (Exc. Wagons)
w/Late-Style Key (NOS) 25.00/pr.

PF148B 1958 Door Lock Assembly (Exc. Wagons)
w/Original-Style Key (NOS)..... \$ 36.00/pr.
PF149A 1958 Door Lock Assembly (Wagons)
w/Late-Style Key (NOS) 26.00/pr.
PF149B 1958 Door Lock Assembly (Wagons)
w/Original-Style Key (NOS)..... 32.00/pr.
PF150A 1959 Door Lock Assembly (ALL 2 Dr.
Models) w/Late-Style Key (NOS) Disc.
PF150B 1959 Door Lock Assembly (ALL 2 Dr.
Models) w/Original-Style Key
(NOS)..... 35.00/pr.
PF151A 1959 Door Lock Assembly (ALL 4 Dr.
Models) w/Late-Style Keys (NOS).... 25.00/pr.
PF151B 1959 Door Lock Assembly (ALL 4 Dr.
Models) w/Original-Style Key
(NOS)..... 56.00/pr.
PF152A 1960 Door Lock Assembly (ALL 2 Dr.
Models) w/Late-Style Key (NOS) Disc.
PF152B 1960 Door Lock Assembly (ALL 2 Dr.
Models) w/Original-Style Key
(NOS)..... 35.00/pr.
PF153A 1960 Door Lock Assembly (ALL 4 Dr.
Models) w/Late-Style Key (NOS).... Disc.
PF153B 1960 Door Lock Assembly (ALL 4 Dr.
Models) w/Original-Style Key
(NOS)..... 35.00/pr.
PF154A 1961-64 Door Lock Assembly (Exc. 4 Dr. HT)
w/Late-Style Key (NOS) 20.00/pr.
PF154B 1961-64 Door Lock Assembly (Exc. 4 Dr. HT)
w/Original-Style Key (NOS)..... 30.00/pr.
PF155A 1961-64 Door Lock Assembly (4 Dr. HT)
w/Late-Style Key (NOS) 25.00/pr.
PF155B 1961-64 Door Lock Assembly (4 Dr. HT)
w/Original-Style Key (NOS)..... 34.00/pr.
PF156A 1965-66 Door Lock Assembly w/Late-Style
Key (NOS) 18.50/pr.
PF156B 1965-66 Door Lock Assembly w/Original-
Style Key (NOS) 25.00/pr.
PF157A 1967-68 Door Lock Assembly w/Late-Style
Key (NOS) 18.50/pr.
PF157B 1967-68 Door Lock Assembly w/Original-
Style Key (NOS) 25.00/pr.
PF158 1969-70 Door Lock Assembly w/Key - ALL
(NOS)..... 18.50/pr.
PF159 1971-73 Door Lock Assembly w/Key - FS
(NOS)..... 17.00/pr.
PF159A 1971-73 Door Lock Assembly w/Key - GP
(NOS)..... 18.50/pr.
PF161 1974-76 Door Lock Assembly w/Key - FS
(NOS)..... 17.00/pr.
PF161A 1974-77 Door Lock Assembly w/Key - GP
(NOS)..... 17.00/pr.

Note: Sets of locks using the same key configuration are available in Section Seventeen.

DOOR LOCK RETAINERS AND PAWLS



PF164A

PF164C

PF164A	1955-57 Door Lock Retainer 2 Dr HT, Conv, 4 Dr Sedan and 4 Dr Wagons (RE).....	\$ 3.00/ea.
PF164C	1955-57 Door Lock Retainer 2 Dr Sedan, 2 Dr Wagons and 4 Dr HT (RE).....	3.00/ea.



PF165

PF165	Door Lock Retainer - ALL (RP).....	.50/ea.
--------------	------------------------------------	---------

PF165 is the clip that holds the door lock assemblies in place in the door.



PF170BL

PF170L	1965-66 Door Lock Pawl, LH (ALL exc. 4 Dr.) (RE)	4.00/ea.
PF170R	1965-66 Door Lock Pawl, RH (ALL exc. 4 Dr.) (RE)	4.00/ea.
PF170BL	1965-66 Door Lock Pawl, LH (4 Dr.) (RE)	4.00/ea.
PF170BR	1965-66 Door Lock Pawl, RH (4 Dr.) (RE).....	4.00/ea.
PF171L	1967-69 Door Lock Pawl, LH - FS (ALL exc. 4 Dr.) (RE)	4.00/ea.
PF171R	1967-69 Door Lock Pawl, RH - FS (ALL exc. 4 Dr.) (RE)	4.00/ea.
PF171BL	1967-69 Door Lock Pawl, LH - FS (4 Dr. exc. 68-69 Cat.) (RE)	4.00/ea.
PF171BR	1967-69 Door Lock Pawl, RH - FS (4 Dr. exc. 68-69 Cat.) (RE)	4.00/ea.
PF171DL	1968-69 Door Lock Pawl, LH (4 Dr. Cat.) (RE).....	4.00/ea.
PF171DR	1968-69 Door Lock Pawl, RH (4 Dr. Cat.) (RE).....	4.00/ea.
PF172L	1970 Door Lock Pawl, LH - FS (ALL exc. 4 Dr.) (RE)	4.00/ea.
PF172R	1970 Door Lock Pawl, RH - FS (ALL exc. 4 Dr.) (RE)	4.00/ea.
PF172BL	1970 Door Lock Pawl, LH - FS (4 Dr.) (RE).....	4.00/ea.
PF172BR	1970 Door Lock Pawl, RH - FS (4 Dr.) (RE).....	4.00/ea.

FRONT DOOR HINGES & HARDWARE



PF191L	1971-76 Upper Door Hinge, LH - FS (GM)	\$ 97.00/ea.
PF191R	1971-76 Upper Door Hinge, RH - FS (GM)	97.00/ea.
PF192	1969-72 Upper Door Hinge, LH or RH - GP (RE)	49.00/ea.
PF192AL	1973-77 Upper Door Hinge, LH - GP (GM).....	Disc.
PF192AR	1973-77 Upper Door Hinge, RH - GP (GM).....	Disc.
PF193	1969-76 Lower Door Hinge, LH or RH - FS (GM).....	66.00/ea.
PF194L	1969-72 Lower Door Hinge, LH - GP (RE) .	59.00/ea.
PF194R	1969-72 Lower Door Hinge, RH - GP (RE) .	59.00/ea.
PF196	1973-77 Lower Door Hinge, LH or RH - GP (GM).....	97.00/ea.
PF197XB	1955-57 Door Hinge to Door Jamb A Pillar Screw Set (8 pcs.) (RE)	6.00/set
PF197XD	1955-57 Door Hinge to Door Bolt Set All 2 Dr and 4Dr Front Doors (12 pcs.) (RE)	8.00/set
PF197XF	1955-57 Door Hinge Screw Set 4 Dr Rear Doors (6 pcs.) (RE)	4.00/set

Note: This kit will do one hinge.



PF198



PF198A

PF198	Phillips Head Door Hinge Bolt (RP).	2.00/ea.
--------------	-------------------------------------	----------

This is the correct recessed phillips head bolt that attaches the hinge to the door.

PF198A	Hex Head Door Hinge Bolt (RP).....	2.00/ea.
---------------	------------------------------------	----------

This is the hex bolt that attaches the hinge to the door and/or pillar.

Note: Please check your hinges for correct application.



PF200	1955-68 Door Hinge Repair Kit (RE)	12.50/kit
PF201	1969-77 Door Hinge Repair Kit, Front (Upper & Lower) (RE).....	16.50/kit


Hinge repair kits contain enough hardened pivot pins and bushings for two upper and two lower door hinges.

PF202	1955-77 Door Hinge Bushing - 7/16" O.D. (GM).....	\$ 1.00/ea.
PF202A	1968-77 Door Hinge Bushing - 1/2" O.D. (GM).....	1.00/ea.

DOOR STRIKERS & HARDWARE



PF206

PF204	1955-59 Door Striker (RE).....	36.00/pr.
PF204AJ	1955-59 Door Striker to Body Screw Set (6 pcs.) (RE)	5.00/set
PF204AN	1955-57 Door Lock Catch Mechanism Screw Set (10 pcs.) (RE)	5.00/set
	This attaches the latch mechanism to back of door.	
PF206	1965-70 Door Striker, LH or RH - FS (GM)...	2.00/ea.
PF208	1971-76 Door Striker, LH or RH - FS (GM)...	20.00/ea.
PF206	1969-72 Door Striker - GP (GM).....	2.00/ea.

RUBBER DOOR BUMPERS

	PF226	PF225	PF228	
PF220	1955-57 Door Bumper (RE).....			1.50/ea.
PF221	1955-57 Upper Door Bumper - Sedan (Screw on) (RE)			1.00/ea.

These use a screw to attach them.

PF221A	1955-57 Upper Door Bumper - Sedan (Plug type) (RE)	1.50/ea.
---------------	--	----------

These have a molded rubber nipple that pushes into a hole.

PF225	1958 Door Bumper (GM)	1.00/ea.
PF226	1959-62 Door Bumpers (RE)	1.25/ea.
PF226A	1963-64 Door Bumper (RE).....	1.50/ea.
PF225	1959-64 Door Bumpers (GM)	1.00/ea.

Note: Many 1959-64 full-sized cars used PF225 bumpers in conjunction with PF226 (especially four-door models).

PF225	1965-66 Door Bumper (GM)	1.00/ea.
PF228	1967-70 Door Bumper - FS (RE)	2.00/ea.

Note: These 3/4" x 1" bumpers were usually used as the top bumper on two-door models and also on some four-door models.

PF225	1967-77 Door Bumper - FS (RE)	1.00/ea.
--------------	-------------------------------------	----------

Note: These 3/8" x 1" bumpers were used in conjunction with PF228.

PF225	1969-77 Door Bumper - GP (GM)	1.00/ea.
--------------	-------------------------------------	----------

DOOR WINDOW STOPS



PF245

PF245	1955-57 Door Window Stop Kit Conv and HTP (RE)	\$ 18.50/ea.
--------------	--	--------------

Note: One kit per door. Includes one long stop screw, one short stop screw, plates, rubber caps and necessary attaching hardware.

PF245B	1958 Door Window Stop Kit Conv and HTP (RE)	18.50/ea.
---------------	---	-----------

Note: One kit per door. Includes two stop screws, plates, rubber caps and necessary attaching hardware.

PF250	1955-58 Door Window Stop w/Manual Window (RE).....	1.00/ea.
--------------	--	----------

PF251	1955-60 Door Window Stops w/Power Windows (RE)	4.00/pr.
--------------	--	----------

PF251B	1959-60 Door Window Stops Sedan w/o Power Windows (RE)	4.00/pr.
---------------	--	----------

PF251D	1961-64 Door Window Stop (RE)	4.00/ea.
---------------	-------------------------------------	----------

PF251R	1955-57 Anti-Rattle Window Rollers (RE).....	4.00/ea.
---------------	--	----------

DOOR DRAIN SEALS



PF252J

PF252D	1956-58 Door Drain Seals (RE)	3.00/ea.
---------------	-------------------------------------	----------

PF252J	1962-72 Door Drain Seals (RE)	2.00/ea.
---------------	-------------------------------------	----------

Ever wonder what those slots were at the bottom of your doors? These seals pop into the holes at each end of the slots allowing water out and keeping dirt from entering the door.

DOME LIGHT SWITCHES



PF254RB



PF254RF

PF254RB	1955-56 Dome Light Door Jamb Switch - Rear Doors - 4 Drs (RE).....	13.00/ea.
----------------	--	-----------

PF254RF	1957-60 Dome Light Door Jamb Switch - Rear Doors - 4 Drs (RE).....	13.00/ea.
----------------	--	-----------

PF254RF 1961-62 Dome Light Door Jamb Switch - Rear Doors Station Wagons (RE) \$ 13.00/ea.



PF254RB & RF come complete with gaskets and screws.

PF254RR 1955-56 Dome Light Door Jamb Switch Gasket All - (RE)..... 1.00/pr.

PF254RS 1957-60 Dome Light Door Jamb Switch Gasket All - (RE)..... 1.00/pr.

PF254RS 1961-62 Dome Light Door Jamb Switch Gasket - Rear Doors S.W. (RE)..... 1.00/pr.



PF255L 1968-77 Dome Light Door Jamb Switch, 2-Terminal (GM)..... 6.00/ea.

PF255M 1968-77 Dome Light Door Jamb Switch, 1-Terminal (GM)..... 5.50/ea.

PF255P 1970-77 Dome Light Door Jamb Switch w/Electric Door Locks - FS (GM)..... Disc.

MIRRORS PADS BRACKETS



PF258



PF261J

PF258 1955-56 Outside Rearview Mirror Pad (RE) ... 3.00/ea.



PF258J

PF258J 1957-58 Outside Rearview Mirror (RE)..... 145.00/ea.

PF260 1959-60 Outside Rearview Mirror Pad (RE) ... 6.00/ea.

PF260B 1961-62 Outside Rearview Mirror Pad (Std. mirror) (RE) 6.00/ea.

PF261J 1961-64 Outside Rearview Mirror Pad (Remote) (RE) 5.00/ea.



PF269J

PF269J 1964-66 Outside Rearview Mirror w/Pad, Bracket & Screws (R or L) Std. (APE) \$ 42.00/ea.

For years we have been dissatisfied with the quality of GM's replacement mirror for the early Pontiacs. Besides having incorrect dimensions, the assemblies are loose and exhibit poor quality.

We have now produced an exact high quality reproduction of the original 1964-66 mirror part number 9770283. In-house durability and testing has proven the quality of these mirrors to be far better than that of the mirrors GM now supplies.



PF269K

PF269K 1964-66 Outside Rearview Mirror Pad (APE). 3.00/ea.

Note: This is the pad that comes with PF269J. If you are ordering a pad for an existing mirror on your car, check the casting number under the base. The original '64-'66 mirrors should have a base casting number of 1164573. Replacement mirrors should have base casting numbers of 15-1548 or 61076 (for these applications use PF270A).

PF270 1967-68 Outside Rearview Mirror w/Pad, Bracket & Screws (R or L) Std. (APE) 42.00/ea.



As discussed under PF269J, GM's inability to produce a quality mirror forced us to manufacture our own product.

Comments: PF270 is an exact reproduction of the 67-68 mirror - part number 9787901.

Note: GM mirrors are available upon request - price as of February '98 is 54.50/ea. Hardware is not included with GM mirrors.

PF270A 1967-68 Outside Rearview Mirror Pad (APE). 3.00/ea.

This is the pad that comes with PF270. If you are ordering this pad for an existing mirror check to see that the base casting numbers are either 15-1548 or 61076.



PF270F

PF270B 1964-68 Outside Rearview Mirror Bracket (Std.) (APE)..... 3.00/ea.

PF270C 1964-68 Outside Rearview Mirror Attaching Screw (Std.) (GM)..... 1.00/ea.

- PF270F** 1964-66 Mirror Hardware Combo (APE) \$ 6.50/ea.
PF270K 1967-68 Mirror Hardware Combo (APE) 6.50/ea.



PF271

- PF271** 1965-68 Outside Rearview Mirror Pad
 (Remote) (APE) 3.00/ea.



- PF271B** 1965-68 Outside Rearview Mirror Bracket
 (Remote) (RE) 17.00/ea.



PF272

- PF272** 1969-70 Outside Rearview Mirror w/Pad,
 Bracket & Screws (R or L) (Std.)
 Chrome - All (APE) 45.00/ea.
PF272 1971-72 Outside Rearview Mirror w/Pad,
 Bracket & Screws (R or L) (Std.)
 Chrome - GP (APE) 45.00/ea.

This is the third mirror we have reproduced to overcome GM's poor quality and high price. Both our PF269J and PF270 have become the standard of the industry with superb chrome, tight construction, and fair price.

This new PF272 exhibits these same qualities.

- PF272A** 1969-72 Mounting Pad for PF272 (APE) 3.00/ea.
PF272B 1969-72 Mounting Bracket for PF272 (APE) .. 3.00/ea.
PF272C 1969-72 Attaching Screw for PF272 1.00/ea.
PF272D 1969-72 Attaching Hardware Combination
 for PF272 (APE) 6.50/kit

Note: PF272D consists of PF272A, PF272B, and PF272C.

- PF272A** 1969-70 FS & 1969-72 GP
 Remote Mirror Pad (Chrome Mirror)
 (APE) 3.00/ea.
PF273 1971-72 Outside Rearview Mirror (Std.) - FS
 (GM) Disc.
PF273A 1971-72 Mounting Pad for PF273 (GM) Disc.
PF273B 1971-72 Mounting Bracket for PF273 (GM) .. 4.00/ea.
PF273C 1971-72 Attaching Screw for PF273 1.00/ea.
PF273D 1971-72 Attaching Hardware Combination
 for PF273 (GM) Disc.

Note: PF273D consists of PF273A, PF273B, and PF273C.

- PF274** 1971-72 Outside Rearview Mirror Remote
 Sport Replacement (Paint to match)
 LH - GP (GM) \$115.00/ea.
PF275 1971-72 Outside Rearview Mirror Sport
 (Paint to match) RH - ALL (GM) 77.00/ea.
PF275A 1971-72 Mounting Pad for PF275 (GM) 3.00/ea.
PF275B 1971-72 Mounting Bracket for PF275 (GM) .. 11.00/ea.
PF275C 1971-72 Mounting Screw for PF275 (GM) Disc.
PF275D 1971-72 Attaching Hardware Combination
 for PF275 (GM) Disc.
PF278 1973-76 Outside Rearview Mirror
 Chrome (Std.) L or R - FS (GM) Disc.
PF278 1973-77 Outside Rearview Mirror
 Chrome (Std.) L or R - GP (GM) Disc.



PF280

- PF280** 1973-74 Outside Rearview Mirror
 Chrome Remote LH - GP (GM) Disc.
PF280A 1973-74 Mounting Pad for PF280 (GM) Disc.
PF282 1973-77 Outside Rearview Mirror
 Chrome Remote LH - GP (GM) Disc.
PF282 1975-76 Outside Rearview Mirror
 Chrome Remote LH - FS (GM) Disc.
PF282A 1973-77 Mounting Pad for PF282 (GM) Disc.



PF284

- PF284** 1973-77 Outside Rearview Mirror - Remote
 Sport (Paint to match) LH - GP
 (GM) Disc.
PF284 1975-76 Outside Rearview Mirror - Remote
 Sport (Paint to match) LH - FS (GM). Disc.
PF284A 1973-77 Mounting Pad for PF284 (GM) Disc.
PF285 1973-77 Outside Rearview Mirror - Std.
 Sport (Paint to match) RH - GP (GM) Disc.
PF285 1975-76 Outside Rearview Mirror - Std.
 Sport (Paint to match) RH - FS (GM) Disc.
PF284A 1973-77 Mounting Pad for PF285 (GM) Disc.



WINDOW REGULATOR HANDLES



PF289A

PF289C

- PF289A** 1955-57 Front Window Regulator Handles w/Washers (RP)..... \$ 22.00/pr.
PF289C 1955-57 Front Vent Window Regulator Handles w/Washers (RP) 22.00/pr.

These handles are meant to be used as replacements only. They are chrome plated and utilize a black knob.



PF289H

PF289J

- PF289H** 1958-64 Front Window Regulator Handle, 58 exc Chieftan, 59-64 Catalina (AP)..... 5.50/ea.

Note: This handle is a replacement. It has ribs on the handle where originals did not.

- PF289J** 1958-64 Front Vent Window Regulator Handle, 58 exc Chieftan, 59-64 Catalina (AP) 5.50/ea.


See note under PF289H

- PF290** 1959-64 Front Window Regulator Handle - Exc. Catalina (RE) 12.00/ea.

- PF290B** 1959-64 Front Vent Window Regulator Handle - Exc. Catalina (RE) 12.00/ea.

PF290 and PF290B are excellent reproductions.

- PF291** 1965-66 Front Window Regulator Handle - ALL (GM) 24.00/ea.



PF292

- PF292** 1967-77 Front Window Regulator Handle, Black Knob - ALL (GM)..... 18.00/ea.
PF292K 1967-77 Front Window Regulator Handle, Black Knob - ALL (AP)..... 4.50/ea.
PF293 1967-77 Front Window Regulator Handle, Clear Knob - ALL (GM) 17.00/ea.
PF293K 1967-77 Front Window Regulator Handle, Clear Knob - ALL (AP) 4.50/ea.

Note: Although not an exact replacement, we have found the GM window regulator handles

to be the best quality handles produced. We also offer PF292K and PF293K as an inexpensive alternative.



PF295

- PF295** 1967-77 Window Regulator Handle Replacement Knob (RE) \$ 6.50/pr.

Although colored knobs are not original for '68 and up, these are an attractive accessory for daily driver cars.

Colors available are: White, Red, Brown, Buckskin, and Medium Blue.

All regulator handles come with a retainer clip.



PF299



PF299D

PF299DB

- PF299** 1955-77 Window Regulator Handle Washer - ALL (GM) 1.00/ea.

- PF299D** 1961-77 Window Regulator Handle Spring . 1.00/ea.

These are the springs behind the window regulator handles and door handles.

- PF299DB** 1961-77 Window Regulator Handle Retainer Clip (RP)50/ea.



WINDOW ROLLERS



PF299DJ

- PF299DJ** 1955-57 Window Regulator Roller (RE)..... 3.00/ea.

Commonly worn, the rollers can now be replaced. Complete with rivets.



PF299DZ

- PF299DZ** 1955-57 Front Door Window Anti-Rattle Roller HTP, Conv, Safari (RE)..... 9.00/ea.



PF299J

- PF299J** 1969-70 Front Window Regulator Rear Roller
- GP (GM)..... \$ 11.00/ea.



PF300

- PF300** 1959-77 Regulator and Door Handle Spring
Clip Removal Tool (AP) 5.00/ea.




PF302JA

- PF302JA** 1955-57 Front Window Regulator Gear
Plate 2 Dr HT - Conv (RE) 22.00/ea.

- PF302JJ** 1955-64 Window Regulator to Door Frame
Screws (8 pcs.) (RE) 5.00/set

These correct style screws mount the window
regulator to the door.

POWER WINDOW MOTORS



- PF305R** 1955-58 Front Power Window Motor
- RH (RP) 129.00/ea.

- PF305L** 1955-58 Front Power Window Motor
- LH (RP)..... 129.00/ea.

Note: These motors are replacements for 1955
to 1958 Pontiacs with 12-tooth drive gears.

- PF306R** 1959-71 Front Power Window Motor
- RH (RE)..... 129.00/ea.

- PF306L** 1959-71 Front Power Window Motor
- LH (RE) 129.00/ea.

- PF307R** 1972-77 Front Power Window Motor
- RH (RE)..... 129.00/ea.

- PF307L** 1972-77 Front Power Window Motor
- LH (RE) 129.00/ea.

Note: PF306 & PF307 motors have a 12-tooth
drive gear. Please check your gear before or-
dering since some full-size cars used a different
number of drive gear teeth.

POWER WINDOW HARNESS BOOT



PF308J

- PF308J** 1965-68 Power Window Harness Boot (RE).. \$ 75.00/set

INSIDE DOOR HANDLES



PF309N

- PF309N** 1955-58 Inside Door Handles w/Washers
(RE-RP)..... 23.00/pr.

Excellent quality.

Note: These are meant to be used as replace-
ments. They are not exact.

- PF309NA** 1955-58 Inside Door Handles (AP - RP) 5.50/ea.

See note under PF309N. These are less expen-
sive lesser quality pieces that do not include
the washer.

- PF309N** 1959-64 Inside Door Handles - Cat only
w/Washers (RE-RP) 23.00/pr.

Excellent quality.

Note: These are meant to be used as replace-
ments. They are not exact.

- PF309NA** 1959-64 Inside Door Handles - Cat only
(AP - RP)..... 5.50/ea.

See note under PF309N. These are less expen-
sive lesser quality pieces that do not include
the washer.



PF310X

- PF310X** 1965-67 Inside Door Handle - GP and
Bonneville (RE)..... 52.00/pr.

Comments: Excellent.



PF311

PF311 1965-67 Inside Door Handle
- Exc. Bonneville -GP (GM)..... \$ 9.00/ea.



PF315R & PF315L

PF315L 1968-70 Inside Door Handle - Exc. GP and
Bonneville, LH (GM) 17.00/ea.

PF315R 1968-70 Inside Door Handle - Exc. GP and
Bonneville, RH (GM) 17.00/ea.

PF321L 1973-77 Inside Door Handle, LH - GP (GM). Disc.


PF330 1955-67 Inside Door Handle Washer - ALL
(GM)..... 1.00/ea.



PF330CL

PF330CL 1955-59 Inside Door Latch Mechanism - LH
(RE)..... 16.00/ea.

PF330CN 1955-59 Inside Door Latch Mechanism
Mounting Screws (8 pcs.) 6.00/set



PF330NL

PF330NL 1968-69 Inside Door Latch Mechanism
- Bonneville, LH (RE)..... 31.00/ea.

This will also fit '68 Catalina w/Custom Trim.

PF330NR 1968-69 Inside Door Latch Mechanism
- Bonneville, RH (RE) 31.00/ea.

This will also fit '68 Catalina w/Custom Trim.

VACUUM OPERATED DOOR LOCK COMPONENTS



PF333JA



PF333JC

PF333JA 1965 Vacuum Operated Door Lock
Vacuum Canister (RE) \$ 49.00/ea.

PF333JA 1966-67, 69
Vacuum Operated Door Lock
Vacuum Canister, Exc. GP (RE) 49.00/ea.

PF333JC 1965-69 Vacuum Operated Door Lock
Vacuum Line Valve - ALL (GM)..... 3.00/ea.

LOCK PULLS AND FERRULES



PF351

PF353

PF353B

PF355

PF335 1955-60 Door Lock Pulls - Black (RE) 5.00/pr.

PF336 1955-60 Door Lock Pulls - Red (RE) 5.00/pr.

PF337 1955-60 Door Lock Pulls - Green (RE) 5.00/pr.

PF338 1955-60 Door Lock Pulls - Blue 5.00/pr.

PF339 1955-60 Door Lock Pulls - Aqua (RE)..... 5.00/pr.

PF340 1955-60 Door Lock Pulls - Copper (RE) 5.00/pr.

PF341 1961-62 Door Lock Pulls - Black (RP) 4.00/pr.

PF341A 1961-62 Door Lock Pulls - Red (RE) 4.00/pr.

PF341B 1961-62 Door Lock Pulls - Blue (RE) 4.00/pr.

PF341C 1961-62 Door Lock Pulls - Off-White (RE)..... 4.00/pr.

PF341D 1961-62 Door Lock Pulls - Light Saddle (RE).. 4.00/pr.

PF341E 1961-62 Door Lock Pulls - Brown (RE) 4.00/pr.

PF350 1963-66 Door Lock Pulls - Chrome (RE) 5.00/pr.

Note: PF350 is an exact reproduction of the 1965-66 door lock pull. It is the same shape and length as the original. It also replaces the 1963-64 chrome metal door lock pulls.

PF351 1963-66 Door Lock Pull - Chrome (RP) 3.00/pr.

Note: PF351 is an excellent replacement; the shape is very close to original. However, it is 7/16" longer.

PF352 1967 Door Lock Pull - Chrome (RE)..... 6.00/pr.

PF353 1968-70 Door Lock Pull - Fluted Chrome 5.00/pr.

PF353B 1968-77 Door Lock Pull - Chrome (GM) 4.00/pr.

Note: We have found 1968-70 Pontiacs to use two different styles of door lock pulls. Please refer to diagrams above of PF353 and PF353B before ordering.

PF353C 1968 Colored Door Lock Pulls (RE) 4.00/pr.


PF353C Can also be used on 69-77 cars.




Colors available are: Red, Blue, White, Brown, Saddle, and Black.

PF354J	1961-64	Door Lock Pull Ferrules (RE)	\$ 7.00/pr.
PF354L	1965-67	Door Lock Pull Ferrules (RE)	Inquire
PF355	1968-77	Door Lock Pull Ferrule (RE).....	.75/ea.

WEATHERSTRIP



ROOF RAIL WEATHERSTRIP AND COMPONENTS



PF358T

PF358T	1969-72	Window Guides - GP (RE)	11.00/ea.
---------------	---------	-------------------------------	-----------

These clip under the drip rail molding escutcheons and guide the glass into the weatherstrip.

PF360	1955-57	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	14.00/pr.
PF361	1955-57	Roof Rail Weatherstrip - Safari (RE)..	109.00/pr.
PF362	1956-57	Roof Rail Weatherstrip - 4 Dr. HT (RE).....	239.00/pr.
PF363	1958	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	22.00/pr.
PF364	1958	Roof Rail Weatherstrip - 4 Dr. HT (RE).....	99.00/pr.
PF366	1959-60	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	69.00/pr.
PF367	1959-60	Roof Rail Weatherstrip - 4 Dr. HT (RE).....	99.00/pr.
PF369	1961	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	69.00/pr.
PF370	1961-62	Roof Rail Weatherstrip - 4 Dr. HT (RE).....	80.00/pr.
PF371	1962	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	69.00/pr.

PF373



PF373	1963-64	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	\$ 69.00/pr.
PF374	1963-64	Roof Rail Weatherstrip - 4 Dr. HT (RE).....	59.00/pr.
PF374A	1963-64	Roof Rail Weatherstrip - GP (RE).....	90.00/pr.
PF375	1965-66	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	59.00/pr.
PF376	1965-66	Roof Rail Weatherstrip - 4 Dr. HT (RE).....	59.00/pr.
PF378	1967-68	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	59.00/pr.
PF378A	1967-68	Roof Rail Weatherstrip - 4 Dr. HT (RE).....	99.00/pr.
PF379	1969-70	Roof Rail Weatherstrip - 2 Dr. HT (RE).....	59.00/pr.
PF384	1969-72	Roof Rail Weatherstrip - GP (RE).....	59.00/pr.
PF385J	1971-73	Roof Rail Weatherstrip - FS, 2 Dr. HT exc. Grandville (RE)	59.00/pr.
PF386	1971-75	Roof Rail Weatherstrip - Grandville, 2 Dr. HT (RE).....	86.00/pr.
PF386	1974-76	Roof Rail Weatherstrip - Bonneville and Catalina, 2 Dr. HT (RE)	86.00/pr.
PF387	1971-74	Roof Rail Weatherstrip - 4 Dr. HT exc. Grandville (RE)	132.00/pr.
PF388	1971-74	Roof Rail Weatherstrip - Grandville, 4 Dr. HT (RE).....	132.00/pr.
PF389A	1973-77	Roof Rail Weatherstrip - GP (RE).....	75.00/pr.
PF389L	1973-77	Roof Rail Weatherstrip, LH - GP (GM).....	Disc.
PF389R	1973-77	Roof Rail Weatherstrip, RH - GP (GM).....	Disc.



PF395

PF395J

PF395	1955-57	Upper Chrome Flipper Stop at Rear - 2 Dr. HT (RE).....	10.00/pr.
PF395J	1955-57	Front Side Roof Rail Filler - 2 Dr. HT (RE).....	22.00/pr.

This filler goes in front of the flipper.



PF395T



PF395TD


PF395T	1955	Flipper Spring Set 2 Dr. HT (RE)	\$ 10.00/set
PF395TA	1956-57	Flipper Spring Set 2 Dr. HT (RE)	9.00/set
Each set of flipper springs will do one car.			
PF395TD	1955-57	Flipper Contact Plastic Cover 2 Dr. HT (RE)	5.00/pr.
Note: This is the piece that slips over the flipper lever that contacts the top of the vent window frame that closes and opens the flipper.			
PF395TJ	1955-57	Flipper and 1/4 Window Rooftrack Mounting Screws 2 Dr. HT (40 pcs.) (RE)	5.00/set

GLASS CHANNEL WEATHERSTRIP

PF400	1955-57	Glass Channel Weatherstrip - 2 Dr. HT (AP)	54.00/set
PF401	1955-57	Glass Channel Weatherstrip - Conv. (AP)	54.00/set
PF402	1955-57	Glass Channel Weatherstrip - 2 Dr. Sedan (AP)	90.00/set
PF403	1955-57	Glass Channel Weatherstrip - 4 Dr. Sedan or Wagon (AP)	90.00/set
PF404	1955-57	Glass Channel Weatherstrip - Safari (AP)	99.00/set
PF405	1956-57	Glass Channel Weatherstrip - 4 Dr. HT (AP)	54.00/set
PF406	1958	Glass Channel Weatherstrip - Bonneville HT (AP)	49.00/set
PF407	1958	Glass Channel Weatherstrip - Bonneville Conv. (AP)	49.00/set
Note: PF400 through PF407 come complete with vertical sash channel weatherstrips.			
PF411	1959-60	Glass Channel Weatherstrip - 2 Dr. HT (AP)	49.00/set
PF412	1959-60	Glass Channel Weatherstrip - Conv. (AP)	49.00/set
PF413	1959-60	Glass Channel Weatherstrip - 2 Dr. Sedan (AP)	49.00/set

Note: PF411 through PF413 are not exact replacements for the original weatherstrip. The stainless steel on the exterior strips is much smaller diameter than original and the original mounting clips are not available.

In the 1992 season we purchased over 1000 original 61-64 GM glass channel clips. With these clips we were able to manufacture exact reproduction glass channel weatherstrip for 1961-64 models. Our supply is now exhausted but we will continue to search for more clips. Please inquire concerning the status of these exact reproduction weatherstrips.



PF415

PF415	1961	Glass Channel Weatherstrip - 2 Dr. HT, 8 pcs. (AP)	\$ 54.00/set
PF415A	1961	Glass Channel Weatherstrip - Conv., 8 pcs. (AP)	54.00/set
PF416	1962-64	Glass Channel Weatherstrip - 2 Dr. HT, 8 pcs. exc. 63-64 GP (AP)	54.00/set
PF416A	1962	Glass Channel Weatherstrip - Conv., 8 pcs. (AP)	54.00/set
PF416B	1963-64	Glass Channel Weatherstrip - Conv., 8 pcs. (AP)	54.00/set
PF416C	1963-64	Glass Channel Weatherstrip - GP, 8 pcs. (AP)	54.00/set


PF415 through PF416C do not have the same design as original equipment. Cars will have to be drilled to install these weatherstrips.

PF425	1965-66	Outer Glass Channel Weatherstrip - 2 Dr. HT exc. GP, 4 pcs. (RE)	Disc.
PF425A	1965-66	Outer Glass Channel Weatherstrip - Conv., 4 pcs. (RE)	Disc.
PF435	1965-66	Glass Channel Weatherstrip - 2 Dr. HT exc. GP, 8 pcs. (AP)	54.00/set
PF435A	1965-66	Glass Channel Weatherstrip - Conv., 8 pcs. (AP)	54.00/set
PF435C	1965-66	Glass Channel Weatherstrip - GP, 8 pcs. (AP)	54.00/set
PF435J	1967-68	Glass Channel Weatherstrip - 2 Dr. HT exc. GP, 8 pcs. (AP)	54.00/set
PF436	1967-68	Glass Channel Weatherstrip - Conv. exc. GP, 8 pcs. (AP)	54.00/set
PF437	1967	Glass Channel Weatherstrip - 2 Dr. HT - GP, 8 pcs. (AP)	54.00/set
PF437A	1967	Glass Channel Weatherstrip - Conv. - GP, 8 pcs. (AP)	54.00/set
PF438	1968	Glass Channel Weatherstrip - GP, 8 pcs. (AP)	54.00/set
PF445	1969-72	Glass Channel Weatherstrip - GP, 8 pcs. (AP)	54.00/set

Note: As other weatherstrips become available we will evaluate them and include them in future catalogs. Please inquire if you do not see your car listed.

These weatherstrip kits contain eight horizontal weatherstrips that seal the bottom of the door glass and rear quarter glass. Both inside and outside weatherstrips are included and sold only as a complete kit (no individual pieces may be purchased separately).

Comments: These weatherstrips do not always have the same design as original equipment. However, they are a good replacement when originals have deteriorated.




- PF460** 1971-76 Inner Window Glass Channel w/s L or R - 2 Dr. HT, FS (GM)..... Disc.
- PF466L** 1973-77 Outer Window Glass Channel w/s LH, GP (NOS)..... Inquire
- PF466R** 1973-77 Outer Window Glass Channel w/s RH, GP (NOS)..... Inquire

GLASS CHANNEL GUIDE PLATES & STAPLES



PF478J

- PF478J** Glass Channel Weatherstrip Attaching Staples - 20 Pack (RE)..... \$ 3.00/set



PF480



PF480D

- PF480** 1962-64 Glass Channel Guide Plate (RE)..... 6.50/ea.
- PF480D** 1962-64 Glass Channel Guide Plate (RE)..... 5.00/ea.

DOOR WEATHERSTRIP FASTENERS




PF498J



PF498L

- PF498J** 1955-60 Door Weatherstrip Fastener (RE)..... 1.00/ea.
1/2" long w/13/32" head.
- PF498L** 1955-60 Door Weatherstrip Spring Clip Retainer w/Oval Screw Hole (RE).... 1.50/ea.

DOOR WEATHERSTRIPS



- PF500** 1955-57 Door Weatherstrip - 2 Dr. HT & Conv. (RE)..... \$ 69.00/pr.
- PF501** 1955-57 Door Weatherstrip - Safari (RE)..... 59.00/pr.
- PF502** 1955-60 Door Weatherstrip - 2 Dr. Sedan (RE)..... 49.00/pr.
- PF503** 1955-57 Front Door Weatherstrip - 4 Dr. Sedan (RE)..... 68.00/pr.
- PF503A** 1955-57 Rear Door Weatherstrip - 4 Dr. Sedan (RE)..... 71.00/pr.
- PF504** 1956-57 Front Door Weatherstrip - 4 Dr. HT (RE)..... 82.00/pr.
- PF504A** 1956-57 Rear Door Weatherstrip - 4 Dr. HT (RE)..... 82.00/pr.
- PF505** 1958 Door Weatherstrip - 2 Dr. HT & Conv. (RE)..... 69.00/pr.
- Note: This weatherstrip fits Bonneville 2 Dr. HT and Conv. and Chieftain Conv. only!*
- PF506** 1958 Front Door Weatherstrip - 4 Dr. Sedan (RE)..... 75.00/pr.
- PF506A** 1958 Rear Door Weatherstrip - 4 Dr. Sedan (RE)..... 68.00/pr.
- PF510** 1959-60 Door Weatherstrip - 2 Dr. HT & Conv. (RE)..... 69.00/pr.
- PF511** 1959-60 Front Door Weatherstrip - 4 Dr. Sedan (RE)..... 72.00/pr.
- PF511A** 1959-60 Rear Door Weatherstrip - 4 Dr. Sedan (RE)..... 76.00/pr.
- PF512** 1959-60 Front Door Weatherstrip - 4 Dr. HT (RE)..... 84.00/pr.
- PF512A** 1959-60 Rear Door Weatherstrip - 4 Dr. HT (RE)..... 84.00/pr.
- PF515** 1961-62 Door Weatherstrip - 2 Dr. HT & Conv. (RE)..... 69.00/pr.
- PF516** 1961-64 Door Weatherstrip - 2 Dr. Sedan (RE)..... 59.00/pr.
- PF517** 1961-64 Front Door Weatherstrip - 4 Dr. Sedan & Wagon (RE)..... 59.00/pr.
- PF517A** 1961-64 Rear Door Weatherstrip - 4 Dr. Sedan (RE)..... 59.00/pr.
- PF517D** 1961-64 Rear Door Weatherstrip - Wagon (RE)..... 59.00/pr.
- PF518** 1961-62 Front Door Weatherstrip - 4 Dr. HT (RE)..... 84.00/pr.
- PF518B** 1963-64 Front Door Weatherstrip - 4 Dr. HT (RE)..... 84.00/pr.
- PF518D** 1961-64 Rear Door Weatherstrip - 4 Dr. HT (RE)..... 84.00/pr.
- PF520** 1963-64 Door Weatherstrip - 2 Dr. HT & Conv. exc. GP (RE)..... 69.00/pr.
- PF522** 1963-64 Door Weatherstrip - GP (RE)..... 69.00/pr.
- PF525** 1965-66 Door Weatherstrip - 2 Dr. Sedan (RE)..... 59.00/pr.
- PF525A** 1965-66 Front Door Weatherstrip - 4 Dr. Sedan and Wagon (RE)..... 59.00/pr.
- PF525B** 1965-66 Rear Door Weatherstrip - 4 Dr. Sedan (RE)..... 59.00/pr.
- PF525D** 1965-66 Rear Door Weatherstrip - Wagon (RE)..... 59.00/pr.



PF526

PF526	1965-66	Door Weatherstrip - 2 Dr. HT & Conv. (RE)	\$ 59.00/pr.
PF530	1967-68	Door Weatherstrip - 2 Dr. Sedan (RE)	59.00/pr.
PF530A	1967-68	Front Door Weatherstrip - 4 Dr. Sedan (RE)	59.00/pr.
PF530B	1967-68	Rear Door Weatherstrip - 4 Dr. Sedan (RE)	59.00/pr.
PF530D	1967-68	Front Door Weatherstrip - 4 Dr. HT (RE)	82.00/pr.
PF530F	1967-68	Rear Door Weatherstrip - 4 Dr. HT (RE)	82.00/pr.
PF531	1967-68	Door Weatherstrip - 2 Dr. HT & Conv. (Exc. GP) (RE)	59.00/pr.
PF533A	1969-70	Front Door Weatherstrip - 4 Dr. Sedan (RE)	82.00/pr.
PF533B	1969-70	Rear Door Weatherstrip - 4 Dr. Sedan (RE)	82.00/pr.
PF535	1969-70	Door Weatherstrip - 2 Dr. HT & Conv., FS (RE)	59.00/pr.
PF540	1969-72	Door Weatherstrip - GP (RE)	59.00/pr.
PF542	1971-76	Door Weatherstrip - 2 Dr. HT & Conv., FS (RE)	132.00/pr.

This reproduction is extruded rubber weatherstripping. It is somewhat stiffer than GM's skin coated latex but it makes a good alternative.

PF544	1971-76	Front Door Weatherstrip - 4 Dr. HT - FS (RE)	118.00/pr.
PF544A	1971-76	Rear Door Weatherstrip - 4 Dr. HT - FS (RE)	90.00/pr.

PF545L	1971-76	Front Door Weatherstrip - 4 Dr. Sedan & Wagon, LH - FS (GM)	Disc.
PF545R	1971-76	Front Door Weatherstrip - 4 Dr. Sedan & Wagon, RH - FS (GM)	Disc.
PF547	1973-77	Door Weatherstrip - GP (RE)	\$ 85.00/pr.
PF547L	1973-77	Door Weatherstrip - GP, LH (GM) ...	Disc.

SASH CHANNEL WEATHERSTRIP

PF549J	1955-62	Sash Channel Weatherstrip - 2 Dr. HT & Conv. (RE)	15.00/pr.
---------------	---------	--	-----------

Note: 1955-62 Sash Channels use a two piece weatherstrip. The lower is a galvanized channel while the upper has stainless steel beads. You will receive one of each style which can be cut in half to renew each side.

PF549K	1963	Sash Channel Weatherstrip - 2 Dr. HT & Conv. (RE)	15.00/pr.
PF549L	1964	Sash Channel Weatherstrip - 2 Dr. HT & Conv. (RE)	15.00/pr.
PF550	1965-68	Sash Channel Weatherstrip - 2 Dr. HT & Conv. (RE)	22.00/pr.

PF550 comes with a molded tip like factory originals.

Comments: Very good.


PF550G	1955-68	Front Door Side Glass Rear Sash Channel Weatherstrip - 2 Dr. HT and Conv. (RE)	7.50/pr.
---------------	---------	--	----------

This is the flocked weatherstrip used to reline the rear channel on the front door glass.

SASH CHANNEL SIDE WINDOW BUMPERS



PF552	1955-58	Sash Channel Side Window Bumper - 2 Dr. HT, Conv. & Safari (RE)	10.00/pr.
--------------	---------	--	-----------



DON'T BE HELD UP BY PRICE INCREASES.

This may be the most important note you'll read in our catalog: We have kept our price increases to a bare **minimum**. Several products have even decreased in price.

For ordering or price quotations, please call (800) 421-2637 (AMES).
For questions or ordering, call (603) 876-3345
(603) 876-4656
(603) 876-4751

PF552AJ	1959-60	Sash Channel Side Window Bumper - ALL HT (RE).....	\$ 28.00/pr.
PF552CJ	1961-62	Sash Channel Side Window Bumper - 2 Dr. HT (RE).....	26.00/pr.
PF552CK	1961-62	Sash Channel Side Window Bumper - Conv. (RE).....	30.00/pr.
PF552D	1963-64	Sash Channel Side Window Bumper - 2 Dr. HT (RE).....	20.50/pr.
PF552E	1963-64	Sash Channel Side Window Bumper - Conv. (RE).....	20.50/pr.

These bumpers go at the top of the sash channel w/s at the vent window frame. They seal the top of the sash channel w/s.

DOOR GLASS SETTING CHANNELS

PF559	1955-57	Door Glass Setting Channel - 2 Dr. Sedan (RE).....	18.00/set
PF560	1955-57	Door Glass Setting Channel - 2 Dr. HT (RE).....	19.00/set
PF561	1955-57	Door Glass Setting Channel - Safari (RE).....	14.00/set
PF562	1958-72	Door Glass Setting Channel - .032" (GM).....	.50/ft.
PF563	1958-72	Door Glass Setting Channel - .047" (GM).....	.50/ft.

Note: PF560 through PF563 are the rubber channels that hold the glass in the lower sash channel.



PF569	1965	Door Glass Lower Sash Weatherstrip (RE).....	3.50/ft.
--------------	------	---	----------

For use with cars with bolt-on sash channels.

SASH CHANNELS AND SCREWS



PF591

PF587L	1955-57	Door Window Glass Lower Sash Channel - 2 Dr. HT & Conv., LH (RE).....	19.00/ea.
PF587R	1955-57	Door Window Glass Lower Sash Channel - 2 Dr. HT & Conv., RH (RE).....	19.00/ea.
PF587AL	1955-57	Door Window Glass Lower Sash Channel - 2 Dr. Sedan, LH (RE)....	19.00/ea.
PF587AR	1955-57	Door Window Glass Lower Sash Channel - 2 Dr. Sedan, RH (RE)....	19.00/ea.



Note: PF587L-PF587AR are zinc-plated to prevent rust and corrosion.

PF587BL	1955-57	Door Window Glass Lower Sash Channel - Safari, LH (RE).....	\$ 14.00/ea.
PF587BR	1955-57	Door Window Glass Lower Sash Channel - Safari, RH (RE).....	14.00/ea.
PF587DL	1955-57	Front Door Window Glass Lower Sash Channel - 4 Dr. Sedan/S.W. LH (RE).....	11.00/ea.
PF587DR	1955-57	Front Door Window Glass Lower Sash Channel - 4 Dr. Sedan/S.W. RH (RE).....	11.00/ea.
PF587FL	1955-57	Rear Door Glass Lower Sash Channel - 4 Dr. Sedan/S.W. LH (RE).....	11.00/ea.
PF587FR	1955-57	Rear Door Glass Lower Sash Channel - 4 Dr. Sedan/S.W. RH (RE).....	11.00/ea.

Note: PF587BL-PF587FR are all painted steel channels.

PF588L	1958	Door Window Glass Lower Sash Channel - Bonneville, LH (RE).....	65.00/ea.
PF588R	1958	Door Window Glass Lower Sash Channel - Bonneville, RH (RE)....	65.00/ea.
PF588AL	1958	Door Window Glass Lower Sash Channel - Star Chief 2 Dr. HT, LH (RE).....	56.00/ea.
PF588AR	1958	Door Window Glass Lower Sash Channel - Star Chief 2 Dr. HT, RH (RE).....	56.00/ea.
PF589L	1959-60	Door Window Glass Lower Sash Channel - 2 Dr. HT & Conv., LH (RE).....	65.00/ea.
PF589R	1959-60	Door Window Glass Lower Sash Channel - 2 Dr. HT & Conv., RH (RE).....	65.00/ea.
PF589AL	1959-60	Door Window Glass Lower Sash Channel - 2 Dr. Sedan, LH (RE).....	Inquire
PF589AR	1959-60	Door Window Glass Lower Sash Channel - 2 Dr. Sedan, RH (RE).....	Inquire

Note: PF588L through PF589AR are all triple-plated chrome.

PF591L	1961-64	Door Window Glass Lower Sash Channel, LH (RE).....	65.00/ea.
PF591R	1961-64	Door Window Glass Lower Sash Channel, RH (RE).....	65.00/ea.


PF591L and PF591R lower sash channels fit 61-64 cars including GP with a 32 5/8" sash channel.



PF593J	1955-57	Glass Track to Regulator Arm Mounting Screws (10 pcs.) (RE).....	3.00/set
---------------	---------	---	----------

These are the correct style plated phillips head w/ attached star washer.

DOOR WINDOW FRAMES AND COMPONENTS




PF595L	1955-57 Door Window Frame - 2 Dr. HT & Conv., LH (RE)	\$ 68.00/ea.
PF595R	1955-57 Door Window Frame - 2 Dr. HT & Conv., RH (RE)	68.00/ea.
PF595DL	1958 Door Window Frame - Bonneville 2 Dr. HT, LH (RE)	68.00/ea.
PF595DR	1958 Door Window Frame - Bonneville 2 Dr. HT, RH (RE)	68.00/ea.
PF595F	1958 Door Window Frame - Bonneville Conv., LH or RH (RE)	68.00/ea.
PF595HL	1958 Door Window Frame - Star Chief 2 Dr. HT, LH (RE)	68.00/ea.
PF595HR	1958 Door Window Frame - Star Chief 2 Dr. HT, RH (RE)	68.00/ea.
PF595KL	1959 Door Window Frame - 2 Dr. HT, LH (RE)	68.00/ea.
PF595KR	1959 Door Window Frame - 2 Dr. HT, RH (RE)	68.00/ea.
PF595M	1959 Door Window Frame - Conv., LH or RH (RE)	68.00/ea.
PF595PL	1960 Door Window Frame - 2 Dr. HT, LH (RE)	68.00/ea.
PF595PR	1960 Door Window Frame - 2 Dr. HT, RH (RE)	68.00/ea.
PF595S	1960 Door Window Frame - Conv., LH or RH (RE)	68.00/ea.
PF595XL	1961-64 Door Window Frame - 2 Dr. HT, LH (RE)	68.00/ea.
PF595XR	1961-64 Door Window Frame - 2 Dr. HT, RH (RE)	68.00/ea.
PF595Y	1961-64 Door Window Frame - Conv., LH or RH (RE)	68.00/ea.



PF596J

- PF596J** 1955-57 Window Frame Screw Sets - HT & Conv. (RE) \$ 5.00/set
Contains enough screws to put 4 frames together or one complete car.



PF599J

- PF599J** 1961-62 Front Door Hinge Pillar at Beltline Seal - 2 Dr. HT (RE) 20.00/pr.

DOOR HINGE "J" WEATHERSTRIP



PF601

- PF600** 1955-57 Door Hinge "J" Weatherstrip (RE) 10.00/pr.
PF601 1958 Door Hinge "J" Weatherstrip (RE) 14.00/pr.
PF602 1959-60 Door Hinge "J" Weatherstrip (RE) 14.00/pr.

Note: This weatherstrip is used on the front of the door under the windshield pillar post. It keeps water coming off the windshield from entering the interior of the car.

VENT WINDOW WEATHERSTRIP AND SCREWS



- PF605** 1955-57 Vent Window Weatherstrip - ALL HT, Conv. & Safari (RE) 49.00/set
PF606 1955-57 Vent Window Weatherstrip - Sedans & Wagons (RE) 49.00/set || **PF607** 1958 Vent Window Weatherstrip - ALL HT & Conv. exc. Bonneville (RE) | 52.00/set |
| **PF607A** 1958 Vent Window Weatherstrip - Bonneville (RE) | 85.00/set |
| **PF607C** 1958 Vent Window Weatherstrip - Station Wagon (RE) | 111.00/set |
| **PF609** 1959-60 Vent Window Weatherstrip - ALL HT & Conv. (RE) | 52.00/set |

PF609B	1959	Vent Window Weatherstrip - Sedan & Wagon (RE)	\$ 95.00/set
PF609D	1960	Vent Window Weatherstrip - Sedan & Wagon (RE)	95.00/set
PF611	1961-62	Vent Window Weatherstrip - ALL HT & Conv. (RE)	52.00/set
PF611B	1961-62	Vent Window Weatherstrip - Sedan & Wagon (RE)	106.00/set
PF613	1963-64	Vent Window Weatherstrip - 2 Dr. HT & Conv. (exc. GP) (RE)....	52.00/set
PF613B	1963-64	Vent Window Weatherstrip - 4 Dr. HT, GP (RE)	108.00/set
PF615	1965-68	Vent Window Weatherstrip - ALL HT & Conv. (RE)	74.00/set



PF620

PF620	1955-57	Vent Window Assembly Screws All Exc. Sedans (60 pcs.) (RE)	11.00/set
--------------	---------	---	-----------



This kit contains enough chrome plated screws to install vent moldings, rubber and regulators.

DOOR SILL PLATES AND SCREWS



PF640	1955-57	Door Sill Plates - ALL 2 Dr. (RE)	59.00/pr.
PF641	1955-57	Door Sill Plates - 4 Dr. Sedan (RE)....	99.00/set
PF642	1956-57	Door Sill Plates - 4 Dr. HT (RE)	185.00/set
PF643	1958	Door Sill Plates - ALL 2 Dr. (RE)	69.00/pr.

Note: These plates were reproduced for the '58 Chevrolet Impala. Physical dimensions are exactly the same; however, the print design is not exactly the same.

Comments: This is a very acceptable replacement.

PF646	1959-60	Door Sill Plates - ALL 2 Dr. (RE)	100.00/pr.
PF648	1961-64	Door Sill Plates - ALL 2 Dr. (RE)	52.00/pr.
PF648D	1961-64	Door Sill Plates - ALL 4 Dr. (RE)	115.00/set of 4

Note: The 1955-57 and 1959-64 door sill plates are excellent reproductions.

PF650L	1965-70	Door Sill Plate - LH - FS(GM)	35.00/ea.
PF650R	1965-70	Door Sill Plate - RH - FS (GM)	35.00/ea.
PF650T	1965-70	Door Sill Plates - All 4 Dr. (RE)	129.00/set of 4

PF651	1971-76	Door Sill Plate - ALL 2 Dr. R or L - FS (GM)	25.00/ea.
--------------	---------	---	-----------

PF654L	1969-72	Door Sill Plate - LH - GP (GM)	\$ 32.00/ea.
PF654R	1969-72	Door Sill Plate - RH - GP (GM)	32.00/ea.
PF655L	1973-77	Door Sill Plate - LH - GP (GM)	Disc.
PF655R	1973-77	Door Sill Plate - RH - GP (GM)	Disc.



PF656T

PF656T	1955-77	Door Sill Plate Screw Set (Set of 8) (RE)	2.50/set
---------------	---------	--	----------

Note: Order 1 set for 2 door cars and 2 sets for 4 door cars.

ROCKER PANEL MOLDING & CLIPS



PF680

PF680	1957	Rocker Panel Moldings - Bonneville and Star Chief (APE)	169.00/pr.
--------------	------	--	------------

See PF714 & PF714A for clips.



PF680A

PF680A	1957	Rocker Panel Molding - Safari (APE)	169.00/pr.
---------------	------	-------------------------------------	------------

Comments: Excellent.

Many customers have used these Safari moldings to dress up their Chieftain bodies. Although not original equipment they look excellent.

See PF714 and PF714A for clips.



PF681

PF681	1958	Rocker Panel Moldings - Bonneville (APE)	199.00/pr.
--------------	------	---	------------

Comments: Excellent.

See PF715 and PF715A for clips.



		PF695	PF696		
PF695	1969	Rocker Panel Moldings			
		(Stainless Steel) - GP (APE)		135.00/pr.	
PF696	1970-72	Rocker Panel Moldings			
		(Aluminum) - GP (APE)		125.00/pr.	

Note: Both stainless steel and anodized aluminum rocker panel moldings were used on 1969-72 GPs. Please be sure to check your original molding material or call for information.

See PF745 & PF745B for clips.

Please add \$8.50 shipping for rocker panel moldings.



PF714


PF714	1957	Rocker Panel Molding Clip (RE)	3.00/ea.
PF714A	1957	Rocker Panel Molding Clip Set	
		- 14 pcs. (RE)	37.00/set

Product is excellent.

PF715	1958	Rocker Panel Molding Clip	
		(AP-GM)	2.00/ea.
PF715A	1958	Rocker Panel Molding Clip Set	
		- 12 clips (AP-GM)	20.00/set


PF715 and PF715A are plastic aftermarket clips which securely hold the rocker panel molding in place. These clips require drilling new holes for mounting.

Comments: Excellent replacement.



PF720

PF720	1962-64	Rocker Panel Molding Clip (Exc. '64	
		Bonneville) (1st Design) (RE)	Inquire
PF720A	1962-64	Rocker Panel Molding Clip Set	
		(Exc. '64 Bonneville) (12 Clips)	
		(1st Design) (RE)	Inquire



PF721

PF721	1962-64	Rocker Panel Molding Clip (Exc. '64	
		Bonneville) (2nd Design) (RE)	1.75/ea.

PF721A	1962-64	Rocker Panel Molding Clip Set	
		(Exc. '64 Bonneville) (12 Clips)	
		(2nd Design) (RE)	\$ 18.00/set

Note: Since two styles of rocker panel molding clips were used in 1962-64, be sure to identify your needs using the clip diagrams provided. If you have the first design clips on your car and PF720 and PF720A are not available, please call on how to convert to 2nd design clips.

PF743	1968	Rocker Panel Molding Clip (RE)	3.00/ea.
PF745	1969-72	Rocker Panel Molding Clip	
		- GP (AP)	1.00/ea.

Note: These clips mount on the face of the rocker panel and are similar in design to PF721.

PF745A	1968-72	Rocker Panel Molding Clip	
		- Lower (RE)	3.00/ea.

These are the 8 1/2" long clips that bolt under the rocker panel and hold the bottom of the molding.

PF745B	1969-72	Rocker Panel Molding Clip Set	
		- GP (RE)	21.00/set

This clip set includes 12 - PF745 and 4 - PF745A clips.

ROCKER PANELS




PF751L	1955-57	Inner Rocker Panel, LH - 2 Dr. (RE) .	59.00/ea.
PF751R	1955-57	Inner Rocker Panel, RH - 2 Dr. (RE) .	59.00/ea.
PF752L	1955-57	Outer Rocker Panel, LH - 2 Dr. (RE)	75.00/ea.
PF752R	1955-57	Outer Rocker Panel, RH - 2 Dr. (RE)	75.00/ea.
PF753L	1955	Outer Rocker Panel, LH - 4 Dr. (RP)	39.00/ea.
PF753R	1955	Outer Rocker Panel, RH - 4 Dr. (RP)	39.00/ea.
PF754L	1956-57	Outer Rocker Panel, LH - 4 Dr.	
		Sedan/S.W. (RE)	95.00/ea.
PF754R	1956-57	Outer Rocker Panel, RH - 4 Dr.	
		Sedan/S.W. (RE)	95.00/ea.
PF756L	1958	Inner Rocker Panel, LH - 2 Dr. (RE) .	65.00/ea.
PF756R	1958	Inner Rocker Panel, RH - 2 Dr. (RE) .	65.00/ea.
PF757L	1958	Outer Rocker Panel, LH - 2 Dr. (RE)	86.00/ea.
PF757R	1958	Outer Rocker Panel, RH - 2 Dr. (RE)	86.00/ea.
PF758L	1958	Outer Rocker Panel, LH - 4 Dr. (RE)	29.00/ea.
PF758R	1958	Outer Rocker Panel, RH - 4 Dr. (RE)	29.00/ea.
PF760L	1959-60	Outer Rocker Panel, LH - 2 Dr. (RP)	33.00/ea.
PF760R	1959-60	Outer Rocker Panel, RH - 2 Dr. (RP)	33.00/ea.
PF761L	1959-60	Outer Rocker Panel, LH - 4 Dr. (RE)	29.00/ea.
PF761R	1959-60	Outer Rocker Panel, RH - 4 Dr. (RE)	29.00/ea.
PF765L	1965-68	Outer Rocker Panel, LH - 2 Dr. (RE)	35.00/ea.
PF765R	1965-68	Outer Rocker Panel, RH - 2 Dr. (RE)	35.00/ea.
PF766L	1965-68	Outer Rocker Panel, LH - 4 Dr. (RE)	29.00/ea.
PF766R	1965-68	Outer Rocker Panel, RH - 4 Dr. (RE)	29.00/ea.
PF770L	1969-72	Rocker Panel, LH - GP (RE)	89.00/ea.
PF770R	1969-72	Rocker Panel, RH - GP (RE)	89.00/ea.

Note 1: These rocker panels are the steel panels painted body color under the doors. Many people confuse these with the stainless steel

rocker panel moldings.

Note 2: Please add \$8.50 shipping for rocker panels.



PF802R

PF802L	1955-57	Door Skin 2 Dr. HT/Conv. - LH (RE).....	\$209.00/ea.
PF802R	1955-57	Door Skin 2 Dr. HT/Conv. - RH (RE)	209.00/ea.
PF802AL	1955-57	Door Skin 2 Dr. Sedan - LH (RE) ...	209.00/ea.
PF802AR	1955-57	Door Skin 2 Dr. Sedan - RH (RE) ...	209.00/ea.

Note 1: PF802AL and PF802AR do not include the window frame.

Note 2: Please add \$12.00 for shipping Door Skins.


PF802GL	1955-57	Lower Door Skin Outer-All 2 Dr. - LH (RE)	\$ 53.00/ea.
PF802GR	1955-57	Lower Door Skin Outer-All 2 Dr. - RH (RE)	53.00/ea.

Please add \$7.00 shipping for Lower Door Skins.



PF802RL

PF802RL	1955-57	Inner Door Bottom Patch - 2 Dr. HT/Conv. -LH (RE).....	112.00/ea.
PF802RR	1955-57	Inner Door Bottom Patch - 2 Dr. HT/Conv. -RH (RE)	112.00/ea.
PF802SL	1955-57	Inner Door Bottom Patch - 2 Dr. Sedan/Safari -LH (RE).....	69.00/ea.
PF802SR	1955-57	Inner Door Bottom Patch - 2 Dr. Sedan/Safari -RH (RE)	69.00/ea.



DON'T BACKORDERS MAKE YOU HOPPING MAD?

Needless backorders are aggravating, costly, and time-consuming. Each year we've become more efficient reaching an unbelievably low backorder rate. 95.2% of all invoices were shipped without backorders and 98.6% of all parts ordered were shipped without backorders.

If you want your parts NOW (and we mean *all* your parts) our order line is (800) 421-2637 (AMES).

For questions or ordering, call (603) 876-3345
(603) 876-4656
(603) 876-4751

SECTION SIX WINDSHIELD & REAR WINDOW RELATED

WINDSHIELD REVEAL MOLDINGS



PG170



PG170B

PG170	1955-57	Upper Front Windshield Reveal Escutcheon All except Conv. (RE)....	\$ 5.00/ea.
PG170B	1955-57	Lower Front Windshield Reveal Escutcheon (RE)	5.00/ea.



PG220	1969-72	Upper Windshield Reveal Molding - GP (GM).....	32.00/ea.
PG221L	1969-72	Side Windshield Reveal Molding, LH - GP (GM)	38.00/ea.
PG221R	1969-72	Side Windshield Reveal Molding, RH - GP (GM)	38.00/ea.


PG230	1973-77 Upper Windshield Reveal Molding - GP (GM).....	Disc.
PG231L	1973-77 Side Windshield Reveal Molding, LH - GP (GM).....	\$ 39.50/ea.
PG231R	1973-77 Side Windshield Reveal Molding, RH - GP (GM)	Disc.

REAR WINDOW REVEAL MOLDINGS



	PG238	PG239
PG238	1955-57 Upper Rear Window Reveal Corner Molding w/Clips - 2 DRHT (RE).....	15.00/pr.
PG238B	1955-57 Upper Rear Window Reveal Corner Molding w/Clips - Sedan (RE)	15.00/pr.
PG239	1955-57 Lower Rear Window Reveal Escutcheon - 2DRHT - Sedan (RE)...	5.00/ea.
PG239B	1956-57 Lower Rear Window Reveal Escutcheon - 4DRHT (RE).....	5.00/ea.
PG250L	1969-70 Upper Rear Window Reveal Molding, LH - GP (GM)	51.00/ea.
PG250R	1969-70 Upper Rear Window Reveal Molding, RH - GP (GM).....	51.00/ea.
PG251L	1969-70 Lower Rear Window Reveal Molding, LH - GP (GM)	36.00/ea.

FRONT DRIP RAIL MOLDINGS



PG280	1969-72 Front Drip Rail Molding - GP (RE)....	22.00/pr.
PG281	1969-72 Front Drip Rail Molding Escutcheon - GP (RE).....	10.00/pr.



REVEAL MOLDING CLIPS



	PG289AB	PG289AF
PG289AB	1955-57 Front Lower Reveal Molding Clip Set (RE).....	9.00/set

PG289AF	1955-57 Front Windshield Reveal Corner Molding Clips (RE).....	\$ 9.00/pr.
PG289AM	1955-58 Rear Reveal Molding Clip Set w/o Corner Molding Clips (set 15) (RE).....	4.00/set
PG289AP	1955-57 Rear Reveal Corner Molding Clips (RE).....	6.00/pr.



	PG290	PG290B	PG290F
PG290	1965-68 Front Reveal Molding Clip 3/4"W x 1 3/16"H (AP)50/ea.
PG290B	1965-68 Rear Reveal Molding Clip 1" W x 7/8"H (AP)50/ea.
PG290F	1969-72 Front and Rear Reveal Molding Clip - GP 17 1/16"W x 1 3/16"H (AP)50/ea.
PG290F	1969-76 Front and Rear Reveal Molding Clip - FS 17 1/16"W x 1 3/16"H (AP)50/ea.

Note: Because different assembly plants used different numbers of clips, you may want to determine how many you need before placing your order.

INSTALLATION KITS

PG300	1965-77 Windshield Installation Kit - ALL (AP).....	10.00/ea.
PG301	1965-77 Rear Window Installation Kit - ALL (AP).....	10.00/ea.

These kits include enough sealant rubber for the installation of either the front or rear window.

WINDSHIELD CHANNELS



PG400	1955-57 Windshield Glass Channel - Exc. Conv. (RE).....	35.00/ea.
PG401	1955-57 Windshield Glass Channel - Conv. (RE)	35.00/ea.
PG402	1958 Windshield Glass Channel - 2 Dr. HT & Conv. Bonne (RE)	35.00/ea.
PG403	1958 Windshield Glass Channel - Star Chief ALL (RE)	76.00/ea.
PG404	1959-60 Windshield Glass Channel - ALL HT & Conv. (RE)	45.00/ea.
PG405	1959-60 Windshield Glass Channel - ALL Sedan & Station Wagon (RE) ..	45.00/ea.

PG406	1961-62	Windshield Glass Channel - Exc. Conv. & 1962 2 Dr. HT (RE) ..	\$ 45.00/ea.
PG407	1961-62	Windshield Glass Channel - Conv. (RE)	45.00/ea.
PG408	1962	Windshield Glass Channel - 2 Dr. HT (RE)	45.00/ea.
PG409	1963-64	Windshield Glass Channel - 2 Dr. HT & Conv. exc. GP (RE)	45.00/ea.
PG409A	1963-64	Windshield Glass Channel - GP (RE)	45.00/ea.
PG410	1963-64	Windshield Glass Channel - Sedan and Station Wagon (RE)	45.00/ea.
PG411	1963-64	Windshield Glass Channel - 4 Dr. HT (RE)	45.00/ea.

Note: PG400 through PG411 are the heavy rubber channels that hold the windshield in place.



PG416

PG415	1955	Windshield Gutter Inner Cowl Panel Drain (RE)	8.50/pr.
PG416	1956-57	Windshield Gutter Inner Cowl Panel Drain (RE)	8.50/pr.

Customers have reported that PG416 works equally well on 59-60 Pontiacs.

PG417	1955-64	Outer Corner Cowl Plug (RE)	1.00/ea.
PG418	1963-64	Side Cowl Panel Plug (RE)	2.50/ea.

REAR GLASS CHANNELS

PG420	1955	Rear Glass Channel - Sedan (RE)	35.00/ea.
PG421	1955-57	Rear Glass Channel - 2 Dr. HT (RE) ..	35.00/ea.
PG422	1956-57	Rear Glass Channel - Sedan (RE)	45.00/ea.
PG423	1956-57	Rear Glass Channel - 4 Dr. HT (RE) ..	35.00/ea.
PG424	1955-57	Rear Glass Channel - Dr. Safari (RE) ..	35.00/ea.
PG425	1958	Rear Glass Channel - Bonneville (RE) ..	35.00/ea.
PG426	1958	Rear Glass Channel - ALL exc. Bonneville (RE)	80.00/ea.
PG427	1959-60	Rear Glass Channel - Sedan w/o Inside Garnish Molding (RE)	118.00/ea.
PG428	1959-60	Rear Glass Channel - Sedan w/Inside Garnish Molding (RE)	45.00/ea.
PG428A	1959-60	Rear Glass Channel - 2 Dr. HT w/o Inside Garnish Molding (RE)	105.00/ea.
PG429	1959-60	Rear Glass Channel - 2 Dr. HT w/Inside Garnish Molding (RE)	86.00/ea.
PG429B	1959-60	Rear Glass Channel - 4 Dr. HT (RE) ..	150.00/ea.
PG430	1961	Rear Glass Channel - 2 Dr. HT (RE) ..	45.00/ea.
PG431	1961	Rear Glass Channel - Sedan (RE)	106.00/ea.

PG432	1961-62	Rear Glass Channel - 4 Dr. HT (RE)	\$108.00/ea.
PG433	1962-64	Rear Glass Channel - 2 Dr. HT exc. 63-64 GP (RE)	45.00/ea.
PG433A	1963-64	Rear Glass Channel - GP (RE)	55.00/ea.
PG434	1962-64	Rear Glass Channel - Sedan (RE)	45.00/ea.
PG435	1963-64	Rear Glass Channel - 4 Dr. HT (RE) ..	102.00/ea.

Note: PG420 through PG435 are the heavy rubber channels that hold the rear window in place.



PG440


PG440	1955-59	Rear Glass Channel Drain (RE)	9.00/pr.
--------------	---------	-------------------------------------	----------

WINDSHIELD WIPER ESCUTCHEON COMPONENTS



PG500

PG500	1955-56	Windshield Wiper Escutcheons w/nuts (RE)	25.00/kit
--------------	---------	---	-----------



PG500A

PG500A	1955-56 & '58	Wiper Escutcheon Nut Removal Tool (AP)	7.00/ea.
---------------	---------------	---	----------

Note: This tool is used in conjunction with a screwdriver to remove that inaccessible escutcheon nut.



PG500AD

PG500AD	1955-56 & '58	Wiper Escutcheon Nuts (RE)	5.00/pr.
----------------	---------------	----------------------------------	----------

WINDSHIELD WIPER ARMS & LINK ASSEMBLIES



PG540L	1955-57	Wiper Arm, Bayonet Style LH (RE) ..	17.00/ea.
PG540R	1955-57	Wiper Arm, Bayonet Style RH (RE) ..	17.00/ea.

PG550L	1969-72 Windshield Wiper Arm, LH - GP (GM).....	Disc.
PG550R	1969-72 Windshield Wiper Arm, RH - GP (GM).....	Disc.
PG551L	1971-76 Windshield Wiper Arm, LH - FS (GM).....	51.00/ea.
PG551R	1971-76 Windshield Wiper Arm, RH - FS exc. Conv. (GM).....	Disc.
PG552L	1973-77 Windshield Wiper Arm, LH - GP (GM).....	41.00/ea.
PG552R	1973-77 Windshield Wiper Arm, RH - GP (GM).....	Disc.
PG570L	1969-72 Wiper Housing and Link Assembly, LH - GP (GM).....	99.00/ea.
PG570R	1969-72 Wiper Housing and Link Assembly, RH - GP (GM).....	Disc.

WINDSHIELD WIPER BLADES



PG580D

PG580D	1955-57 Wiper Blade, Bayonet Style (RP).....	17.00/ea.
---------------	--	-----------

These are polished stainless steel blades without any Trico markings. Excellent replacement.



PG580J

PG580J	1959-64 Wiper Blade w/o Overlap Blades exc. GP, L or R Trico (AP)	12.50/ea.
PG580L	1959-64 Wiper Blade w/Overlap Blades exc. GP, L or R Trico (AP)	13.00/ea.
PG580J	1962-68 Wiper Blade - GP, L or R Trico (AP).	12.50/ea.
PG580N	1965-66 Wiper Blade - Exc. GP, L or R Trico (AP)	Inquire
PG580L	1967-77 Wiper Blade - Exc. GP, L or R Trico (AP)	13.00/ea.
PG580P	1969-77 Wiper Blade - GP, L or R Trico (AP).	13.00/ea.

These blades are almost exactly like originals, although they do not have the "Trico" trade-mark stamping.

WINDSHIELD WIPER MOTORS & COMPONENTS



PG623

PG614	1959-62 Wiper Motor - 2 Speed (AP).....	Disc.
PG615	1960-61 Wiper Motor - Single Speed (AP)	Disc.
PG616	1963-64 Wiper Motor (AP).....	Disc.
PG620	1968-72 Wiper Motor - FS (GM)	\$202.00/ea.
PG621	1969-72 Wiper Motor - GP (GM).....	99.00/ea.
PG623	1973-77 Wiper Motor - ALL (GM)	109.00/ea.



PG630

PG630	Electric Wiper Motor Grommets w/ Screws (RE).....	7.00/set
--------------	--	----------

Note: This set includes three grommets and three attaching bolts.

See engine compartment (Section Thirteen) for windshield washer components.



PG650

PG640	1963-77 Windshield Wiper Motor Mounting Bolts (Set of 3) (RE)	3.00/set
PG650	1962 Windshield Wiper Transmission Pad (RE)	4.50/ea.
PG655	1959-62 Windshield Wiper Motor Crank Cap (2 speed wiper only) (RE)	16.00/ea.



Visit us on the


World Wide Web

<http://www.amesperf.com>

email: customerservice@amesperf.com

SECTION SEVEN-CONVERTIBLE TOPS

CONVERTIBLE TOP BOOTS



IMPORTANT NOTICE: Because of new efficient manufacturing techniques and high quantity purchasing, we have been able to slash top boot prices. These are the same high quality boots we have sold for years.

PH101	1955-57	Convertible Top Boot (RE)\$120.00/ea.
PH102	1958	Convertible Top Boot (RE) 120.00/ea.
PH103	1959-60	Convertible Top Boot (RE) 120.00/ea.
PH104	1961-64	Convertible Top Boot (RE) 120.00/ea.
PH105	1965-68	Convertible Top Boot (RE) 120.00/ea.
PH105D	1969-70	Convertible Top Boot (RE) 120.00/ea.
PH105F	1971	Convertible Top Boot (RE) 120.00/ea.
PH105G	1972-75	Convertible Top Boot (RE) 120.00/ea.


Boot material is die-cut and stitched like original. Vinyl is correct and comes in a variety of colors—please carefully note if your car needs a white or parchment (off-white) boot. In trying to match parchment interiors several customers have mistakenly ordered a white boot.

Boot bag comes with top boot.


CONVERTIBLE TOP BOOT COMPONENTS

PH106	1955-75	Convertible Top Boot Bag (RE) 4.00/ea.
--------------	---------	-------------------------------	----------------

This is an exact reproduction of GM's discontinued black 6 mil boot bag.



PH109



PH109D

PH109	1955-70	Convertible Top Boot Retainer Channel (RE) 69.00/ea.
--------------	---------	--	-----------------



This Channel is used on the back of the rear seat. The top boot slides into this channel. Measures 3/4" x 42 1/4".

PH109D	1955-57	Convertible Top Well Molding Snaps (RE) 59.00/set.
---------------	---------	---	------------------

CONVERTIBLE TOP KITS

PH120	1955-57	Convertible Top Kit w/Plastic Window and Pads (RE)\$199.00/ea.
PH121	1958	Convertible Top Kit w/Plastic Window and Pads (RE) 199.00/ea.
PH122	1959-60	Convertible Top Kit w/Plastic Window and Pads (RE) 199.00/ea.
PH123	1961	Convertible Top Kit w/Plastic Window and Pads (RE) 199.00/ea.
PH124	1962-64	Convertible Top Kit w/Plastic Window and Pads (RE) 199.00/ea.
PH125	1965-66	Convertible Top Kit w/Glass Window and Pads (RE) 299.00/ea.
PH126	1967-68	Convertible Top Kit w/Glass Window and Pads (RE) 299.00/ea.
PH127	1969-70	Convertible Top Kit w/Glass Window and Pads (RE) 299.00/ea.
PH128	1971-75	Convertible Top Kit w/Glass Window and Pads (RE) 339.00/ea.

Note: Tops are quality stitched using only top of the line 38-ounce vinyl. These kits come complete with items necessary to refurbish your top (pads, top, and window). Top components have a two-year warranty on materials and workmanship. We recommend professional installation of convertible tops. For colors other than black or white please request samples.

Please add \$8.50 shipping when ordering 1965-75 tops with glass rear windows.

REAR WINDOW KITS



PH135	1955-57	Plastic Rear Window w/Vinyl (RE) 99.00/ea.
PH136	1958	Plastic Rear Window w/Vinyl (RE) 99.00/ea.
PH137	1959-60	Plastic Rear Window w/Vinyl (RE) 99.00/ea.
PH138	1961	Plastic Rear Window w/Vinyl (RE) 99.00/ea.
PH139	1962-64	Plastic Rear Window w/Vinyl (RE) 99.00/ea.
PH140	1965-66	Glass Rear Window w/Vinyl (RE) 150.00/ea.
PH141	1967-68	Glass Rear Window w/Vinyl (RE) 150.00/ea.
PH142	1969-70	Glass Rear Window w/Vinyl (RE) 150.00/ea.
PH143	1971-75	Glass Rear Window w/Vinyl (RE) 210.00/ea.

Note: All rear windows will fit original tops.

Please add \$8.50 shipping when ordering PH140-PH143.

CONVERTIBLE TOP PADS

PH150 1955-75 Convertible Top Pads (RE) \$ 22.00/pr.



CONVERTIBLE TOP WELL

PH161 1955-56 Convertible Top Well (RE) 57.00/ea.
PH164 1959-60 Convertible Top Well (RE) 54.00/ea.
PH165 1961-64 Convertible Top Well (RE) 45.00/ea.
PH166 1965-68 Convertible Top Well (RE) 45.00/ea.
PH167 1969-70 Convertible Top Well (RE) 57.00/ea.
PH168 1971-75 Convertible Top Well (RE) 60.00/ea.

Wells are not made from original material, but fit and look fine.

Comments: Excellent.

TACK STRIPS



PH180D

PH180D 1955-57 Convertible Top Rear Tack Strip w/ Bow (3 pcs) (RE) 199.00/set

Comes with mounting hardware.

Please add \$8.50 shipping for PH180D.

PH180K 1955-75 Convertible Top Tacking Strip, Front, 1/8"x5/8" (RE) 1.50/ft.

This 5/8" tacking strip is thinner than original GM. Using two strips results in approximately the correct thickness.

PH180M 1955-75 Convertible Top Tacking Strip, Rear, 3/8"x1/2" (RE) 1.50/ft.

Note: PH180K and PH180M are plastic strips that replace your original cardboard pieces. Most cars use 5 to 6 feet at each location.

CONVERTIBLE REAR MOLDING CLIPS



PH187 1955-57 Convertible Rear Molding Clips (RE) 30.00/set

PH190 1961-64 Convertible Rear Molding Clips (RE) Inquire

PH190B 1965-66 Convertible Rear Molding Clips (RE) Inquire

PH190D 1967-68 Convertible Rear Molding Clips (RE) 3.75/ea.

These are the clips that hold the molding secure around the rear of the top well. (The top boot snaps to this molding.)

CONVERTIBLE PINCH RAIL PADS



PH192B

PH192B 1955-57 Pinch Rail Pads (RE) \$ 12.00/kit

Note: 18 pads /kit

PH192D 1958-64 Pinch Rail Pads (RE) 14.50/kit

Note: 24 pads /kit

PH192B and PH192D are located in the trunk area between the rear pinch rail and body.

CONVERTIBLE LATCHING & TOP FRAME COMPONENTS



PH199 1955-57 Convertible Top Hardware and Bolt Kit (RE) 119.00/set

This kit contains over 300 peices to replace and install a convertible top frame and top cylinders. Comes with complete instructions and pictures.

Comments: Excellent kit.



PH199D

PH199G

PH199D 1955-57 Convertible Top Front Guide Pin - Stainless Steel - (RE) 6.50/ea.

PH199G 1955-57 Convertible Top Side Rail Adjuster Bolt (RE) 6.50/ea.

This is the square headed bolt above the door glass on the top side rail.



PH200

PH201

PH200 1955-57 Convertible Striker Plates - Chrome (RE) 44.00/pr.

PH200A 1955-57 Convertible Striker Plates Screw Kit - Stainless Steel - w/ star washers - (RE) 2.00/set





PH200D

PH200D 1955-57 Latch Plates (RE) \$ 17.00/pr.

These are the latch plates that go around the latch handles. They come w/ mounting hardware.

PH201 1955-58 Convertible Sunvisor Hooks (RE) ... 31.00/pr.



PH202

PH202 1955-60 Convertible Top Handles (RE)..... 54.00/pr.

Note: PH200 through PH202 are excellent quality reproductions.

PH202A 1955-60 Convertible Top Handle Mounting Screws (Stainless Steel) (RE)..... 2.00/pr.





PH204AL

PH204 1961-64 Convertible Top Handles (RE)..... 40.00/pr.

PH204AL 1961-64 Convertible Top Latch LH (RE)..... 135.00/ea.

PH204AR 1961-64 Convertible Top Latch RH (RE) 135.00/ea.



PH204BB

PH204BB 1961-64 Convertible Top Latch Bushings with Snap Rings (RE)..... 15.00/pr.

These are the bushings that the convertible top latch pin slides into.



PH208

PH208 1965-70 Convertible Latch Hook Knuckle w/Pin (RE)..... \$ 28.00/pr.

Many times latch knuckles break around the pin. This new reproduction is stronger and uses a slightly larger pin. In order to use these knuckles the top bracket must be enlarged about .009 inch using a 15/64 drill.



PH210

PH210 1965-75 Front Roof Rail Hook (RE) 5.00/ea.

PH212

PH212 1965-70 Front Roof Rail Guide Pin (RE) 5.00/ea.

PH214

Note: This is the pin that guides the convertible top frame into the windshield header.

PH214 1955-75 Convertible "Wire-on" Caps 4.50/ea.



PH230L

PH230L 1971-75 Front Roof Rail Lock - LH (NOS)..... 125.00/ea.

PH230R 1971-75 Front Roof Rail Lock - RH (NOS) Inquire

Note: PH230R and PH230L are the mechanisms which hold the top frame to the windshield header.



PH235L

PH235L 1971-75 Front Roof Rail Lock Knuckle - LH (NOS)..... Disc.

PH235R 1971-75 Front Roof Rail Lock Knuckle - RH (NOS)..... 10.00/ea.

CONVERTIBLE TOP MAINTENANCE



PH238B "Koala®" Convertible Top Cleaner (32 oz.) (AP) 12.50/ea.

PH238D "Koala - Kamikaze®" Yearly Cleaner (32 oz.) (AP) 13.00/ea.

PH238F "Koala®" Convertible Top Sealer
(16 oz.) (AP) \$ 15.00/ea.

Note: PH238F must be used after cleaning top with PH238D.

PH238H "Koala®" Plastic Window Polish
(2 oz.) (AP)..... 8.00/ea.


CONVERTIBLE CYLINDERS AND HARDWARE



PH245 1955-57 Convertible Top Cylinder
- LH or RH (RP) 135.00/ea.
PH246 1958 Convertible Top Cylinder
- LH or RH (RP) 135.00/ea.
PH247 1959-60 Convertible Top Cylinder
- LH or RH (RP) 135.00/ea.
PH248 1961 Convertible Top Cylinder
- LH or RH (RP) 135.00/ea.
PH249 1962 Convertible Top Cylinder
- LH or RH (RP) 135.00/ea.
PH250 1963-64 Convertible Top Cylinder
- LH or RH (RP) 135.00/ea.
PH251 1965-70 Convertible Top Cylinder
- LH or RH (RP) 135.00/ea.


Note: These top cylinders are not rebuilt units, but are newly manufactured.

Comments: The finest available.



PH255 1955-61 Convertible Top Cylinder Support
Spacers (RE)..... 3.00/pr.

Note: Requires 2 pair per car.



PH256

PH256 1955-57 Convertible Top Cylinder Braces
(RE)..... 17.50/pr.



PH256L

PH256L 1955-57 Convertible Top Cylinder Bracket
with Hardware LH (RE) \$ 53.00/ea.

PH256R 1955-57 Convertible Top Cylinder Bracket
with Hardware RH (RE) 53.00/ea.



PH256X

PH256X 1955-57 Convertible Top Cylinder Mounting
Kit (RE)..... 12.00/kit

CONVERTIBLE TOP PUMP & MOTORS



PH259

PH259 1955-57 Convertible Top Pump and Motor
Cover..... 75.00/ea.

PH260 1955-63 Convertible Top Pump and Motor
(RP)..... 229.00/ea.

PH261 1964 Convertible Top Pump and Motor
(RP)..... 219.00/ea.

PH263 1965-70 Convertible Top Pump and Motor
(RP)..... 229.00/ea.

Note 1: These pump-motor assemblies are meant as replacements. The existing reservoir may be swapped. Hoses need no alteration.

Note 2: As with any top hydraulic system, do not fill reservoir more than 75% of capacity.

PH264 1971-75 Actuator Motor (GM) 235.00/ea.

PH264K 1971-75 Actuator Motor Relay(GM) 20.00/ea.

CONVERTIBLE TOP CABLES AND HOSES



	PH265L	PH267	
PH265L	1971-75 Actuator Cable, LH - FS (GM)	\$ 31.00/ea.	
PH265R	1971-75 Actuator Cable, RH - FS (GM)	36.00/ea.	
PH267	1955-70 Convertible Top Pump Motor Grommet (RE)	2.00/ea.	
PH270	1955-61 Convertible Top Hose Kit (RP)	105.00/kit	
PH271	1962-70 Convertible Top Hose Kit (RP)	105.00/kit	

Note: These hoses will finish your convertible top rebuild. Kit comes complete with hose and fittings. Since these are universal kits, excess hose may be coiled to complete the installation.



	PH271D	PH271DB	
PH271D	1955-66 Convertible Top Hose Retaining Clip (screw-on) (RE)	3.00/ea.	
PH271DB	1955-66 Convertible Top Hose Retaining Clip (push-in) (RE)	4.00/ea.	

Note: These clips hold the hose in place for clean routing. Four are required on most cars.

PH275	Convertible Top Bleeder System ...	17.00/ea.
--------------	------------------------------------	-----------

Note: This kit comes complete with filler plug adapter, hose and most importantly, complete instructions. Bleeder system was copied from the GM Fisher Body Manual.



	PH276	
PH276	1969-70 Convertible Top Switch (RP)	65.00/ea.

Note: The bezel on PH276 is made from stainless, not diecast chrome like the original.

CONVERTIBLE TOP HOLD-DOWN CABLES



	PH290	
PH289	1961-64 Convertible Top Hold-Down Cables (RE)	\$ 45.00/pr.
PH290	1965-70 Convertible Top Hold-Down Cables (RE)	30.00/pr.
PH291L	1971-75 Convertible Top Hold-Down Cable, LH (GM)	33.00/ea.
PH291R	1971-75 Convertible Top Hold-Down Cable, RH (GM)	33.00/ea.

CONVERTIBLE TOP WEATHERSTRIP



PH300	1955-57 Convertible Top Weatherstrip Set (RE)	255.00/set
PH301	1958 Convertible Top Weatherstrip Set (RE)	269.00/set
PH302	1959-60 Convertible Top Weatherstrip Set (RE)	239.00/set
PH303	1961-64 Convertible Top Weatherstrip Set (RE)	239.00/set
PH304	1965-66 Convertible Top Weatherstrip Set (RE)	219.00/set
PH305	1967-70 Convertible Top Weatherstrip Set (RE)	249.00/set
PH306	1971-75 Convertible Top Weatherstrip Set (RE)	239.00/set

The above top weatherstrip sets include all weatherstrips needed for your convertible top. All pieces have been duplicated from originals including the steel inserts.

Note: Pillar Post Weatherstrips are not included in PH300 through PH306. See PH350 through PH358.

Comments: Using limited production techniques it is impossible to hold exact tolerances of complicated weatherstrips. These are closer than we expected and can be classified as very good.

- PH308A** 1955-57 Front Windshield Header Seal (RE).....\$ 12.00/ea.
PH308B 1955-57 Rear Windshield Header Seal (RE) 10.00/ea.



PH308BA

- PH308BA** 1955-57 Convertible Top Header Strips (RE)..... 49.00/pr.

Note: These strips are used to secure convertible top and weather stripping where the header and convertible top contact over the front windshield.

- PH308C** 1955-57 Quarter Window Stops (RE)..... 10.00/pr.
PH308D 1955-57 Rear Quarter Drain Seals and Roof Rail Stops (RE) 42.00/set
PH308F 1955-57 Convertible Top Side Roof Rail Slat Iron Bumpers (RE) 25.00/pr.
PH309 1958-64 Windshield Header Seal (RE)..... 10.00/ea.
PH309AA 1965-66 Windshield Header Seal (RE)..... 18.00/ea.
PH309A 1967-70 Rubber Windshield Header Seal w/molded corners (RE)..... 45.00/ea.

PH309A is the rubber weatherstrip that seals the convertible top frame to the windshield header. May also be used on '65-'66 models if molded corners are desired.

- PH320** 1971-75 Windshield Header Seal (GM) 94.00/ea.
PH320A 1971-75 Windshield Header Seal (RE)..... 99.00/ea.

CONVERTIBLE PILLAR POST WEATHERSTRIP



- PH350** 1955-58 Windshield Pillar Post Weatherstrips, also HT and Safari (RE)..... 18.00/pr.

Note: There are less expensive alternatives (see PH350A) on the market for this application; however, we feel this product offers the best quality available. It is made from extruded rubber not foam and has all correct push pins.

- PH350A** 1955-58 Windshield Pillar Post Weatherstrips, also HT and Safari (RE)..... \$ 6.00/pr.

Note: This weatherstrip functions fine as a less expensive alternative.

- PH352** 1959-60 Windshield Pillar Post Weatherstrips (RE)..... 50.00/pr.
PH353 1961-62 Windshield Pillar Post Weatherstrips (RE)..... 50.00/pr.
PH354 1963-64 Windshield Pillar Post Weatherstrips (RE)..... 50.00/pr.
PH355 1965 Windshield Pillar Post Weatherstrips (RE)..... 50.00/pr.
PH356 1966-68 Windshield Pillar Post Weatherstrips (RE)..... 50.00/pr.
PH357 1969-70 Windshield Pillar Post Weatherstrips (RE)..... 50.00/pr.
PH358 1971-75 Windshield Pillar Post Weatherstrips (RE)..... 50.00/pr.

Note: Pillar post weatherstrip runs along the side of the windshield. These reproductions have the correct molded ends and fit well.


Comments: Very good—since they are extruded rubber these weatherstrips are harder than original but soon conform to shape.

VINYL TOPS



- PH400** 1969-72 Vinyl Top, GP (RE) 59.00/ea.

Note: These vinyl tops are universal fit. They fit all '69-72 GP, but the grain and seams may not look exactly like the original top. Colors available are black and white.



ALARMED BY SUDDEN INCREASES?

Some suppliers have raised prices so dramatically many customers think it is industry-wide. This is absolutely not the case. While we've seen other catalog prices jump significantly, Ames Performance has been able to hold price increases to a bare minimum.

For ordering or price quotations, please call (800) 421-2637.
 For questions or ordering, call (603) 876-3345
 (603) 876-4656
 (603) 876-4751

SECTION EIGHT-REAR 1/4 TRIM

EMBLEMS AND ORNAMENTS



PJ101 1955 Rear 1/4 V-8 Emblems (APE)..... \$ 49.00/pr.

Note 1: PJ101 will also fit 1956 front fender; however, 1956 did not use the white border found on 1955s.

Note 2: These are high quality die-cast pieces.



PJ101G

PJ101G 1955,57 Chrome Star Ornament
- 2 prong (RE) 11.00/ea.

Note: This ornament has two mounting prongs as used until early 1957.

PJ101H 1957-58 Chrome Star Ornament
- 3 prong (RE) 13.00/ea.

Note: This ornament has three mounting holes as used in late 1957 through 1958.



PJ103

PJ103 1963 Grand Prix 1/4 Panel Emblems (RE).. 58.00/pr.



PJ104Y

PJ104Y 1965 Grand Prix Rear 1/4 Panel Emblems (RE)..... 105.00/pr.



PJ105

PJ105 1965 2+2 1/4 Panel Emblems (RE)..... 109.00/pr.



PJ106

PJ106 1966 2+2 1/4 Panel Emblems (RE)..... \$ 99.00/pr.



PJ107J

PJ107J 1967 Rear 1/4 Panel "Bonneville" Letters (10-piece set) (RE) 79.00/set


PJ107K 1967 Rear 1/4 Panel "Bonneville" Letters (20-piece set) (RE) 155.00/2 sets



PJ107P

PJ107P 1967-68 Rear 1/4 Panel "Grand Prix" Letters (9-piece set) (RE) 75.00/set

PJ107R 1967-68 Rear 1/4 Panel "Grand Prix" Letters (18-piece set) (RE) 145.00/2 sets



PJ109J

PJ109J 1969 Sail Panel Louvers - GP (RE)..... 6.50/ea.

PJ109K 1969 Sail Panel Louvers (10-piece set) (RE) 60.00/set

It appears there were two styles of louvers used on '69 GPs. The PJ109J and PJ109K measure 4" long with a center to center pin distance of 27/8". We are still looking for an NOS louver that is 4" long with a center to center pin distance of 33/8". Please let us know if you can help us.



PJ110

PJ110 1971-72 "Grand Prix" Pillar Emblems (RE) \$ 41.00/pr.

Note: Because of the limited market, PJ103 through PJ110 are not die-cast. These pieces are low pressure castings. Overall the quality is good.



PJ115

PJ115 Rear 1/4 Panel Emblem Plastic Nut (RE) 1.50/ea.

These are used for emblems with $\frac{3}{16}$ " stud size.

BEZELS AND LENSES



PJ120

PJ120 1968 Rear Side Marker Bezels - Exc. GP (RE) 42.00/pr.

Note: PJ120 are die-cast reproductions.



PJ121

PJ120A 1968 Rear Side Marker Bezel - Exc. GP (RE) 37.00/pr.

Note: PJ120A are low-pressure castings.



PJ121C

PJ121 1968 Rear Side Marker Lens - Exc. GP (RE) 15.00/pr.

Comments: Reproductions are excellent.



PJ121D

PJ121C 1968 Rear Side Marker Gaskets exc. GP - (RE) 4.00/pr.

PJ121D 1968 Rear Side Marker Light Ground Strap exc. GP - (RE) 8.00/pr.

1/4 WINDOW REGULATOR COMPONENTS



PJ178 1955-57 Window Regulator Handle w/ Washer (RE) \$ 23.00/pr.

These handles are meant to be used as replacements. They are chrome plated and utilize a black knob.



PJ179 1958-64 Window Regulator Handle, 58 exc Chieftain, '59-'64 Catalina - (AP) 5.50/ea.

PJ180 1959-64 Window Regulator Handle (Exc. Catalina) (RE) 12.00/ea.

PJ181 1965-66 Window Regulator Handle (GM) 24.00/ea.

PJ185 1967-77 Window Regulator Handle (Blk. Knob) (GM) 18.00/ea.

PJ185A 1967-77 Window Regulator Handle (Blk. Knob) (AP) 4.50/ea.

PJ186 1967-77 Window Regulator Handle (Clear Knob) (GM) 17.00/ea.

PJ186A 1967-77 Window Regulator Handle (Clear Knob) (AP) 4.50/ea.



PJ190 1967-77 Window Regulator Handle Replacement Knob (RE) 6.50/pr.

Although colored knobs are not original for '68 and up, these are an attractive accessory for daily driver cars.

Colors available are: White, Red, Brown, Buckskin, and Medium Blue.

Note 1: All regulator handles come with locking spring clips.

Note 2: Although not an exact replacement, the GM window regulator handles are the best quality handles available. PJ185A and PJ186A are offered as inexpensive alternatives.



PJ195

PJ195 1955-77 Window Regulator Handle Washer (GM) 1.00/ea.



PJ195C

PJ195C 1961-77 Window Regulator Handle Spring (GM) 1.00/ea.

These are the springs behind the window regulator handle.

PJ195F


PJ195F 1955-77 Window Regulator Handle Clip - ALL (RE)50/ea.



PJ195R

PJ195R 1959-77 Regulator and Door Handle Spring
Clip Removal Tool (AP) \$ 5.00/ea.

POWER WINDOW MOTORS




PJ196L 1955-58 Rear Power Window Motor
- LH (RP) 129.00/ea.
PJ196R 1955-58 Rear Power Window Motor
- RH (RP) 129.00/ea.

Note: These motors are replacements for 1955 to '58 Pontiacs with 12-tooth drive gears.

PJ197L 1959-71 Rear Power Window Motor
- LH (RE) 129.00/ea.
PJ197R 1959-71 Rear Power Window Motor
- RH (RE) 129.00/ea.
PJ198L 1972-76 Rear Power Window Motor
- LH (RE) 129.00/ea.
PJ198R 1972-76 Rear Power Window Motor
- RH (RE) 129.00/ea.

Note: PJ197 & PJ198 motors have a 12-tooth drive gear. Please check your gear before ordering since some full-size Pontiacs used a different number of drive gear teeth.

QUARTER WINDOW WEATHERSTRIPS



PJ200 1955-57 Quarter Window Weatherstrips
(Cloth covered w/steel insert) (RE) ... 18.00/pr.
PJ201 1955-57 Quarter Window Weatherstrips
(Rubber w/o steel insert) (RE) 8.00/pr.
PJ201A 1955-57 Quarter Window Weatherstrips
- 2 Dr. Sedan (RE) 22.00/pr.
PJ201C 1955-57 Quarter Window Weatherstrips
- Safari (RE) 15.00/pr.

These are made specifically for the slide-open side windows on Safaris.

PJ201J 1958 Quarter Window Weatherstrips
(Cloth covered w/steel insert)
Conv. (RE) \$ 18.00/pr.
PJ201K 1958 Quarter Window Weatherstrips
(Cloth covered w/steel insert)
2 Dr. HT (RE) 18.00/pr.
PJ202 1958-64 Quarter Window Weatherstrips
(Rubber w/o steel insert) ALL (RE) 7.00/pr.
PJ202J 1959-60 Quarter Window Weatherstrips
(Rubber w/steel insert) Conv. (RE) 18.00/pr.
PJ202K 1959-60 Quarter Window Weatherstrips
(Rubber w/steel insert) 2 Dr. HT
(RE) 18.00/pr.
PJ202M 1959-60 Quarter Window Weatherstrips
- 4 Dr. HT (RE) 22.00/pr.
PJ203 1965-66 Quarter Window Weatherstrips
(Rubber w/steel insert) 2 Dr.'s (RE) ... 18.00/pr.
PJ204 1965-66 Rear Door Window Front
Weatherstrips (Rubber w/o steel
insert) 4 Dr. HT (RE) 11.00/pr.
PJ206 1967-68 Quarter Window Weatherstrips
(Rubber w/o steel insert) 2 Dr.'s (RE) 11.00/pr.
Note: This weatherstrip does not fit '67 GP Conv.
PJ206J 1967-68 Quarter Window Weatherstrips
(Rubber w/steel insert) Conv. (RE) 19.00/pr.
Note: This weatherstrip does not fit '67 GP Conv.
PJ209 1969-70 Quarter Window Weatherstrips
(Rubber w/steel insert) FS (RE) 21.00/pr.
PJ209L 1969-70 Quarter Window Weatherstrips,
LH - (Rubber w/steel insert) FS (GM) 25.00/ea.
PJ209R 1969-70 Quarter Window Weatherstrips,
RH - (Rubber w/steel insert) FS (GM) 25.00/ea.
PJ210 1969-72 Quarter Window Weatherstrips
- GP (Rubber w/steel insert) (RE) 20.00/pr.
PJ210L 1969-72 Quarter Window Weatherstrips - LH
(Rubber w/steel insert) (GP) (GM) 23.00/ea.
PJ210R 1969-72 Quarter Window Weatherstrips - RH
(Rubber w/steel insert) (GP) (GM) 23.00/ea.
PJ211A 1971-74 Quarter Window Weatherstrips
- (Rubber w/steel insert)
- Grandville 2 Dr. HT (RE) 30.00/pr.
Note: PJ211A will work on '71-'73 Grandville convertibles but must be cut down in length.
PJ212A 1971-73 Quarter Window Weatherstrips
(Rubber w/steel insert) - 2DRHT,
Conv. exc. Grandville (RE) 25.00/pr.
PJ212A 1974-75 Quarter Window Weatherstrips
(Rubber w/steel insert)
Grandville Conv. (RE) 25.00/pr.
PJ212L 1971-73 Quarter Window Weatherstrips
- LH (Rubber w/steel insert)
- 2DRHT, Conv. exc. Grandville
(GM) 23.00/ea.
PJ212R 1971-73 Quarter Window Weatherstrips
- RH (Rubber w/steel insert)
- 2DRHT, Conv. exc. Grandville
(GM) 23.00/ea.

- PJ212L** 1974-75 Quarter Window Weatherstrips
 - LH (Rubber w/steel insert)
 - Grandville Conv. (GM) \$ 22.50/ea.
- PJ212R** 1974-75 Quarter Window Weatherstrips
 - RH (Rubber w/steel insert)
 - Grandville Conv. (GM) 22.50/ea.

Note: Several of these reproduction quarter window weatherstrips do not have steel reinforcements. Although not as rigid as the originals, they seal well.

SASH CHANNELS



PJ220L & R


- PJ219** 1955-57 Rear 1/4 Window Sash Channel
 - 2 Dr. HT - Conv., LH or RH (RE) 22.00/ea.
- PJ219D** 1958 Rear 1/4 Window Sash Channel
 - 2 Dr. HT - Conv., LH or RH (RE) 22.00/ea.
- PJ219F** 1959-60 Rear 1/4 Window Sash Channel
 - 2 Dr. HT - Conv., LH or RH (RE) 22.00/ea.

These channels are riveted to the quarter glass assembly to hold the 1/4 window weatherstripping.

- PJ220L** 1969-72 Rear 1/4 Window Sash Channel
 - LH (GP) (RE) 42.00/ea.
- PJ220R** 1969-72 Rear 1/4 Window Sash Channel
 - RH (GP) (RE) 42.00/ea.

PJ220L & R are the chrome strips that attach to the front of the rear quarter window and hold the rear 1/4 window weatherstrip.

Note: Original GM sash channels are available upon request. Price as of February '98 is \$76.50/ea.




PJ222BL

- PJ222BL** 1955-57 Rear 1/4 Window Adjusting Plate
 - Conv. LH (RE) 12.00/ea.
- PJ222BR** 1955-57 Rear 1/4 Window Adjusting Plate
 - Conv. RH (RE) 12.00/ea.

These are the knurled plates that adjust the rear 1/4 window in and out.

CHROME WINDOW FRAMES



PJ225A

- PJ225** 1955-57 Upper Quarter Window - Chrome Frame - 2 Dr. HT, LH or RH (RE) \$ 68.00/ea.
- PJ225A** 1955-57 Upper Quarter Window - Chrome Frame - Conv., LH or RH (RE) 85.00/ea.
- PJ225D** 1958 Upper Quarter Window - Chrome Frame - Bonneville 2 Dr. HT, LH or RH (RE) 62.00/ea.
- PJ225F** 1958 Upper Quarter Window - Chrome Frame - Bonneville Conv., LH or RH (RE) 93.00/ea.
- PJ225J** 1959-60 Upper Quarter Window - Chrome Frame - 2 Dr. HT, LH or RH (RE) Inquire
- PJ225K** 1959-60 Upper Quarter Window - Chrome Frame - Conv., LH or RH (RE) 85.00/ea.



SETTING CHANNEL

- PJ228J** Window Glass Setting Channel, Rubber - .032" (GM)50/ft.
- PJ228K** Window Glass Setting Channel, Rubber - .047" (GM)50/ft.

REAR SIDE GLASS CHANNELS



PJ233

- PJ230** 1955-57 Side Glass Channels
 - 2 Dr. Safari (RE) 90.00/pr.
- PJ231** 1955-57 Side Glass Channels - 2 Dr. SW (RE) 60.00/pr.
- PJ232** 1955-57 Side Glass Channels - 4 Dr. SW (RE) 60.00/pr.
- PJ233** 1955-57 Side Glass Channels
 - 4 Dr. Sedan (RE) 49.00/pr.

Note: PJ230 through PJ233 are the rubber channels that hold the rear side glass in place.

- PJ234** 1955-57 Safari Rear Curved Glass Stops (RE). 3.00/pr.



- PJ234C** 1955-57 Rear 1/4 Window Stops - Conv. (RE). 6.00/pr.

QUARTER WINDOW MOLDINGS




PJ240L

PJ242

PJ240	1973-77 Quarter Window Molding w/Vinyl Top, PR - GP (NOS).....	Inquire
PJ242	1973-77 Quarter Window Molding Escutcheon w/ or w/o Vinyl Top, LH or RH (GM)	Disc.

LOCK PILLAR WEATHERSTRIPS



PJ247	1955-57 Lock Pillar Weatherstrip - 2 Dr. HT (RE)	\$ 18.00/pr.
PJ248	1955-57 Lock Pillar Weatherstrip - Conv. (RE)	10.00/pr.
PJ249	1956-57 Lock Pillar Weatherstrip - 4 Dr. HT (RE)	25.00/set
PJ250	1958 Lock Pillar Weatherstrips - 2 Dr. HT (RE)	18.00/pr.
PJ251	1958 Lock Pillar Weatherstrips - Conv. (RE)	18.00/pr.
PJ252	1959-60 Lock Pillar Weatherstrips - 2 Dr. HT (RE)	18.00/pr.
PJ253	1959-60 Lock Pillar Weatherstrips - Conv. (RE)	18.00/pr.
PJ254	1959-60 Lock Pillar Weatherstrips - 4 Dr. HT Front Door (RE)	22.00/pr.
PJ254A	1959-60 Lock Pillar Weatherstrips - 4 Dr. HT Rear Door (RE)	28.00/pr.
PJ255	1961-64 Lock Pillar Weatherstrips - 2 Dr. HT (RE)	18.00/pr.
PJ256	1961-64 Lock Pillar Weatherstrips - Conv. (RE)	18.00/pr.
PJ257	1961-64 Lock Pillar Weatherstrips - 4 Dr. HT Front Door (RE)	7.00/pr.
PJ257A	1961-64 Lock Pillar Weatherstrips - 4 Dr. HT Rear Door (RE)	22.00/pr.
PJ260	1965-66 Lock Pillar Weatherstrips 2 Drs (RE)	19.00/pr.
PJ260B	1965-66 Lock Pillar Weatherstrips - 4Dr. HT/Sedan (RE)	22.00/pr.
PJ265	1967-68 Lock Pillar Weatherstrips (RE)	22.00/pr.

1967-68 used two different lock pillar weatherstrips. PJ265 measures 23/4" x 33/4" and PJ265A measures 23/4" x 43/4". Please measure your original before placing your order.

PJ265A	1967-68 Lock Pillar Weatherstrips (RE)	\$ 21.00/pr.
PJ268	1969-70 Lock Pillar Weatherstrips -FS (RE)	22.00/pr.
PJ270	1969-72 Lock Pillar Weatherstrips - GP (RE) ..	19.00/pr.
PJ272	1971-75 Lock Pillar Weatherstrips - FS (RE) ...	21.00/pr.

Note: Lock pillar weatherstrip seals the bottom of the quarter window at the lock pillar. These reproductions are manufactured with steel like the originals.

DOOR JAMB LOUVERS



PJ280	1969-72 Door Jamb Louver - GP (RE)	13.00/ea.
--------------	--	-----------

Note: This louver does not have the one-way flapper attached to it.

SHEET METAL PLUGS



PJ300



PF302



PJ304

PJ300	3/4-Inch Sheet Metal Body Plug (Plastic) (AP)	1.00/ea.
PJ301	3/4-Inch Sheet Metal Body Plug (Rubber) (RP)	2.00/ea.
PJ302	1-Inch Sheet Metal Body Plug (Rubber) (RP)	1.00/ea.
PJ303	1-Inch Sheet Metal Plug (Plastic) (AP)	1.00/ea.
PJ304	Rocker Panel Drain Plug (RE)	1.00/ea.


This rectangular plug is found in the inner rocker panel in front of the rear wheelwell.



PJ320	1960-63 Rear 1/4 and Tailgate Wiring Grommet - SW (RE)	10.00/ea.
--------------	--	-----------

These were used to pass wiring from the 1/4 panel to the tailgate on station wagons.

FENDER SKIRT COMPONENTS



- PJ350** 1955-57 Fender Skirt to Body Gasket (RE)..... \$ 9.00/pr.
PJ351 1958-64 Fender Skirt to Body Gasket (RE)..... 9.00/pr.
PJ353 1967-68 Fender Skirt to Body Gasket (RE)..... 32.00/pr.




- PJ380
- PJ380** 1965-66 Fender Skirt Bracket Set (RE) 15.00/set
of 4

These are the brackets used to attach the skirts to the rear quarter. Usually bent, rusted, or even missing these brackets will facilitate your fender skirt restoration.

SEAM SEALER



- PJ400** PJ400 Seam Sealer, Black (AP) 9.50/tube
PJ402 PJ402 Brushable Seam Sealer, Grey
1 Hazmat Quart (AP) Disc.



- PJ404
- PJ404** Disposable Brush (AP) 1.00/ea.

B-PILLAR PATCH PANELS



- PJ510L
- PJ510L** 1955-57 B-Pillar Brace - Conv. LH (RE).....\$ 79.00/ea.
PJ510R 1955-57 B-Pillar Brace - Conv. RH (RE) 79.00/ea.



- PJ518L
- PJ518L** 1955-57 Complete B-Pillar Panel - 2DRHT
- Conv. - LH (RE) 99.00/ea.
PJ518R 1955-57 Complete B-Pillar Panel - 2DRHT
- Conv. - RH (RE) 99.00/ea.

PJ518L and PJ518R will replace the rear of the front door opening at the front of the quarter panel. They extend from the top of the quarter panel down to the rocker panel and include the cutouts for the striker latch mechanisms.




- PJ520L
- PJ520L** 1955-57 B-Pillar Lower Patch Panel
- 2DRHT/Conv. LH (RE)..... 65.00/ea.
PJ520R 1955-57 B-Pillar Lower Patch Panel
- 2DRHT/Conv. RH (RE) 65.00/ea.

PJ520L and PJ520R will replace just the lower portion of the B-Pillar.

SECTION NINE-TRUNK COMPONENTS

TRUNK MATS



Pontiac used many colors and designs for its truck mats from 1955-77. We have several new patterns and colors. We should be able to match most original trunk component materials with our product line.

The following trunk mat materials are available for the years listed:

Tan and Brown Chainlink (1955-56), TBC Gray and Black Crowsfoot (1955-57), GBC Gray and Red Crowsfoot (1955-57), GRC Gray and White Crosshatch (1958), GWC Gray and Black Houndstooth (1959), GHT Red and Black Houndstooth (1960), RHT Red, Fawn, and Black Herringbone (1961), RFB

Red and Black Herringbone (1962-64), RBH Aquamarine and Black Herringbone (1962-64), AHB

Gray and Green Gator (1965-66), GAT Gray and Black Herringbone (1967-68), GHB Gray Green Felt (1969-77), FGG Black Felt (1969-70), BF

Matching trunk mats, side panels, and spare tire covers will be available in these new colors and patterns.

Note: Please see inside front cover for color samples.

Important Note: Colors shown on inside front cover are approximate color matches. As dye lot changes and different materials are used, colors may vary. Side panels, trunk mats, spare tire covers and trunk dividers will not always be exact matches since all are made from different materials (ex. cardboard, rubber, and vinyl).



PK100J

PK100J 1955-56 (TBC) Chainlink Trunk Mat Material - ALL (RE)..... \$ 38.00/yd.

This material just became available. It has the correct printing and is made from the original style cloth. We are selling this by the yard and most cars require 3 - 3 1/2 yards. The roll is 56" wide and in most cars, must be used with a backing for proper appearance.

PK101 1955-56 Trunk Mat, Star Chief - 2 Dr. HT - GBC - Rubber (RP)..... 58.00/ea.


PK101A 1955-56 Trunk Mat, Star Chief - Conv. - GBC - Rubber (RP)..... 55.00/ea.

PK102 1957 Trunk Mat, Star Chief - 2 Dr. HT (RE)..... 99.00/ea.

Note: This mat can be trimmed to fit 4 Dr. HT Star Chiefs.

PK102A 1957 Trunk Mat, Star Chief & Bonneville - Conv. (RE) 99.00/ea.

PK102C 1957 Trunk Mat, Chieftain - 2 Dr. HT (RE)..... 99.00/ea.




Note: 1957 mats are available in either Gray & Black Crowsfoot or Gray & Red Crowsfoot. Please specify when ordering.

These mats (PK102-PK102C) are excellent! They are made correctly with the horsehair backing and silkscreened face. These should be the finishing touch to your trunk compartment.

PK104 1958 Trunk Mat, Bonneville, Chieftain - 2 Dr. HT (RE)..... 99.00/ea.

PK104A 1958 Trunk Mat, Bonneville, Chieftain - Conv. (RE) 99.00/ea.

PK104C 1958 Trunk Mat, Star Chief & Superchief - 2 Dr. HT (RE)..... 99.00/ea.



These mats are made by the same supplier as our '57's and are excellent. They have the correct horsehair backing and silkscreened cross-hatch face. For years, only vinyl mats were available. Although they had the correct print, they lacked the originality of the horsehair backing. These new mats are an excellent value.

PK106	1959	Trunk Mat, Catalina - GHT (RE)	\$ 55.00/ea.
PK107	1959	Trunk Mat, Bonneville, Star Chief - GHT (RE)	55.00/ea.
PK108	1960	Trunk Mat, Catalina, Ventura - 2 Dr. HT & Conv. - RHT (RE)	54.00/ea.
PK108B	1960	Trunk Mat, Catalina, Ventura - 4 Dr. Sedan - RHT (RE)	54.00/ea.
PK109	1960	Trunk Mat, Bonneville, Star Chief - RHT (RE)	54.00/ea.
PK110	1961	Trunk Mat, Catalina, Ventura - HT - RFB (RE)	49.00/ea.
PK110A	1961	Trunk Mat, Catalina, Ventura - Conv. - RFB (RE)	49.00/ea.
PK111	1961	Trunk Mat, Bonneville, Star Chief - 2 Dr. HT & Conv. - RFB (RE)	49.00/ea.
PK111B	1961	Trunk Mat, Bonneville, Star Chief - 4 Dr. HT - RFB (RE)	58.00/ea.

Note: 1962-64 trunk mats are available in red and black herringbone or aquamarine and black herringbone. Please specify color when ordering.

PK112	1962	Trunk Mat, Catalina - GP - 2 Dr. HT - Sedan (RE)	49.00/ea.
PK112A	1962	Trunk Mat, Catalina - Conv. (RE)	49.00/ea.
PK113	1962	Trunk Mat, Bonneville, Star Chief - 2 Dr. HT & Conv. (RE)	49.00/ea.
PK114	1963-64	Trunk Mat, Catalina - 2 Dr. HT (RE)	49.00/ea.
PK114A	1963-64	Trunk Mat, Catalina - Conv. (RE)	49.00/ea.
PK114B	1963-64	Trunk Mat, Catalina - 4 Dr. HT (RE)	49.00/ea.
PK114C	1963-64	Trunk Mat, Catalina - 4 Dr. Sedan (RE)	49.00/ea.
PK115	1963-64	Trunk Mat, Bonneville, Star Chief - 2 Dr. HT - Conv. (RE)	49.00/ea.
PK115B	1963-64	Trunk Mat, Bonneville, Star Chief - 4 Dr. HT (RE)	49.00/ea.
PK119	1963	Trunk Mat, GP (RE)	49.00/ea.
PK119A	1964	Trunk Mat, GP (RE)	49.00/ea.
PK120	1965-66	Trunk Mat, Catalina - GP - 2+2 - HT - GAT (RE)	49.00/ea.
PK120A	1965-66	Trunk Mat, Catalina - 2+2 - Conv. - GAT (RE)	49.00/ea.
PK121	1965	Trunk Mat, Bonneville, Star Chief - Exc. Conv. - GAT (RE)	49.00/ea.
PK121A	1965	Trunk Mat, Bonneville, Star Chief - Conv. - GAT (RE)	49.00/ea.
PK122C	1965-66	Trunk Mat, Catalina - 4 Dr. Sedan - GAT (RE)	49.00/ea.
PK123	1966	Trunk Mat, Bonneville, Star Chief - GAT (RE)	49.00/ea.
PK126	1967-68	Trunk Mat, Catalina, GP - 2+2 - GHB (RE)	49.00/ea.
PK126B	1967-68	Trunk Mat, Catalina - 4 Dr. HT - GHB (RE)	49.00/ea.
PK126C	1967-68	Trunk Mat, Catalina - 4 Dr. Sedan - GHB (RE)	49.00/ea.
PK127	1967-68	Trunk Mat, Bonneville, Executive - 2 Dr. HT - GHB (RE)	49.00/ea.
PK127A	1967	Trunk Mat, Bonneville, Executive - Conv. - GHB (RE)	49.00/ea.

PK128A	1968	Trunk Mat, Bonneville, Executive - Conv. - GHB (RE)	\$ 49.00/ea.
PK134	1969-70	Trunk Mat, Catalina - 2 Dr. HT - FGG (RE)	32.00/ea.
PK134A	1969-70	Trunk Mat, Catalina - Conv. - FGG (RE)	32.00/ea.
PK134C	1969-70	Trunk Mat, Catalina - 4 Dr. Sedan - FGG (RE)	45.00/ea.
PK135	1969-70	Trunk Mat, Bonneville - 2 Dr. HT (RE)	Inquire
PK135A	1969-70	Trunk Mat, Bonneville - Conv. - Black Felt (RE)	58.00/ea.
PK137	1969	Trunk Mat, GP - FGG (RE)	32.00/ea.
PK138	1970	Trunk Mat, GP - FGG (RE)	32.00/ea.
PK140	1971-72	Trunk Mat, Catalina - 2 Dr. HT - FGG (RE)	Inquire
PK140A	1971-72	Trunk Mat, Catalina - Conv. - FGG (RE)	32.00/ea.
PK141	1971-72	Trunk Mat, Bonneville - 2 Dr. HT - FGG (RE)	32.00/ea.
PK141A	1971-72	Trunk Mat, Bonneville - Conv. - FGG (RE)	Inquire
PK141C	1971-72	Trunk Mat, Bonneville - 4 Dr. Sedan - FGG (RE)	42.00/ea.
PK142	1971-72	Trunk Mat, GP - FGG (RE)	32.00/ea.
PK148A	1973-75	Trunk Mat, Grandville - Conv. - FGG (RE)	34.00/ea.
PK149D	1973-75	Trunk Mat, Grandville - 4 Dr. HT - FGG (RE)	34.00/ea.
PK150	1973-77	Trunk Mat, GP - FGG (RE)	32.00/ea.

If you do not find your trunk mat listed above, please inquire. We are looking for new patterns to complete our listing.

Please add \$7.00 shipping for rubber trunk mats.

C
L
E
A
R
A
N
C
E

Note: We still have a quantity of old style trunk components being sold at reduced prices. We have many years and colors available for people not requiring an exact color match. Please inquire with your year and model for prices.

C
L
E
A
R
A
N
C
E


TRUNK SIDE PANELS AND CLIPS



PK195

PK195	1963-77	Trunk Side Panel Clip (GM)	1.00/ea.
--------------	---------	----------------------------------	----------

This is the little spring clip that is used to secure side panels to the inner trunk framework. GM has superceded this part to a plastic push pin now.



In most applications, side panels are available with our trunk mats. We can coordinate design and material in order to complete the total restoration of your trunk area.

Trunk side linings are now printed cardboard like originals and are available in the same colors as trunk mats.

PK203	1958	Trunk Side Panels, Bonneville - 2 Dr. HT - GWC (RE)	Inquire
PK203A	1958	Trunk Side Panels, Bonneville - Conv. - GWC (RE)	Inquire
PK204	1959	Trunk Side Panels, Catalina - 2 Dr. HT - GHT (RE)	\$ 54.00/pr.
PK204A	1959	Trunk Side Panels, Catalina - Conv. - GHT (RE)	54.00/pr.
PK204B	1959	Trunk Side Panels, Catalina - 4 Dr. HT - GHT (RE)	54.00/pr.
PK205	1959	Trunk Side Panels, Bonneville - 2 Dr. HT - GHT (RE)	49.00/pr.
PK205A	1959	Trunk Side Panels, Bonneville - Conv. - GHT (RE)	55.00/pr.
PK205B	1959	Trunk Side Panels, Bonneville - 4 Dr. HT - 4 Dr. Sed GHT (RE)	49.00/pr.
PK207	1960	Trunk Side Panels, Catalina, Ventura - 2 Dr. HT - RHT (RE)	49.00/pr.
PK207A	1960	Trunk Side Panels, Catalina, Ventura - Conv. - RHT (RE)	49.00/pr.
PK207B	1960	Trunk Side Panels, Catalina, Ventura - 4 Dr. HT - RHT (RE)	49.00/pr.
PK208	1960	Trunk Side Panels, Bonneville, Star Chief - 2 Dr. HT - RHT (RE)	49.00/pr.
PK208A	1960	Trunk Side Panels, Bonneville, Star Chief - Conv. - RHT (RE)	49.00/pr.
PK208B	1960	Trunk Side Panels, Bonneville, Star Chief - 4 Dr. HT & Sedan - RHT (RE)	49.00/pr.
PK209	1961	Trunk Side Panels, Catalina, Ventura - HT - RFB (RE)	49.00/pr.
PK209A	1961	Trunk Side Panels, Catalina, Ventura - Conv. - RFB (RE)	54.00/pr.
PK210	1961	Trunk Side Panels, Bonneville, Star Chief - 2 Dr. HT - RFB (RE)	49.00/pr.
PK210A	1961	Trunk Side Panels, Bonneville, Star Chief - Conv. - RFB (RE)	71.00/pr.

Note: 1962-64 side panels are available in red and black herringbone or aquamarine and black herringbone. Please specify color when ordering.

PK211	1962	Trunk Side Panels, Catalina, GP - 2 Dr. HT - 4 Dr. Sed (RE)	\$ 49.00/pr.
PK211A	1962	Trunk Side Panels, Catalina - Conv. (RE)	49.00/pr.
PK212	1962	Trunk Side Panels, Bonneville, Star Chief - 2 Dr. HT - 4Dr. Sedan (RE) ...	54.00/pr.
PK212A	1962	Trunk Side Panels, Bonneville, Star Chief - Conv. (RE)	54.00/pr.
PK213	1963	Trunk Side Panels, Catalina, GP, Ventura - 2 Dr. HT (RE)	49.00/pr.
PK213B	1963-64	Trunk Side Panels, Catalina, Ventura - Conv. (RE)	Inquire
PK214	1963-64	Trunk Side Panels, Bonneville, Star Chief - HT (RE)	54.00/pr.
PK214A	1963-64	Trunk Side Panels, Bonneville, Star Chief - Conv. (RE)	54.00/pr.
PK215C	1964	Trunk Side Panels, Catalina, GP, Ventura - 2 Dr. HT (RE)	49.00/pr.
PK217	1965-66	Trunk Side Panels, Catalina - 2+2 - GP - 2 Dr. HT & 4 Dr. HT - GAT (RE)	49.00/pr.
PK217A	1965-66	Trunk Side Panels, Catalina - 2+2 - Conv. - GAT (RE)	49.00/pr.
PK218	1965-66	Trunk Side Panels, Bonneville, Star Chief - 2 Dr. HT - GAT (RE)	59.00/pr.
PK218A	1965-66	Trunk Side Panels, Bonneville, Star Chief - Conv. - GAT (RE)	49.00/pr.
PK218B	1965-66	Trunk Side Panels, Bonneville, Star Chief - 4 Dr. HT - GAT (RE)	49.00/pr.
PK219	1967	Trunk Side Panels, Catalina - 2+2 - 2 Dr. HT - GHB (RE)	49.00/pr.
PK219A	1967	Trunk Side Panels, Catalina - 2+2 - Conv. - GHB (RE)	49.00/pr.
PK219B	1967	Trunk Side Panels, Catalina - 4 Dr. Sedan - GHB (RE)	54.00/pr.
PK219C	1967	Trunk Side Panels, HTP and Conv. - GHB (RE)	49.00/pr.
PK220	1967	Trunk Side Panels, Bonneville, Executive - 2 Dr. HT - GHB (RE)	52.00/pr.
PK220A	1967	Trunk Side Panels, Bonneville, Executive - Conv. - GHB (RE)	49.00/pr.
PK220B	1967	Trunk Side Panels, Bonneville, Executive - 4 Dr. HT - GHB (RE)	49.00/pr.
PK222	1968	Trunk Side Panels, Catalina, Ventura - 2 Dr. HT - GHB (RE)	52.00/pr.
PK222A	1968	Trunk Side Panels, Catalina, Ventura - Conv. - GHB (RE)	Inquire
PK222C	1968	Trunk Side Panels, GP - GHB (RE) ...	49.00/pr.
PK223	1968	Trunk Side Panels, Bonneville, Executive - 2 Dr. HT - GHB (RE)	49.00/pr.
PK223A	1968	Trunk Side Panels, Bonneville, Executive - Conv. - GHB (RE)	54.00/pr.
PK224A	1969	Trunk Side Panels, Catalina - Conv. - FGG (RE)	52.00/pr.
PK225	1969	Trunk Side Panels, Bonneville, Executive - 2 Dr. HT, Black Only (RE)	49.00/pr.
PK225A	1969	Trunk Side Panels, Bonneville, Executive - Conv., Black Only (RE) ..	49.00/pr.
PK226A	1970	Trunk Side Panels, Catalina - Conv. FGG (RE)	49.00/pr.

PK227	1970	Trunk Side Panels, Bonneville, Executive - 2 Dr. HT - FGG (RE)	\$ 49.00/pr.
PK227A	1970	Trunk Side Panels, Bonneville, Executive - Conv., Black Only (RE)..	57.00/pr.
PK227B	1970	Trunk Side Panels, Bonneville, Executive - 4 Dr. HT - FGG (RE)	49.00/pr.
PK228	1969-70	Trunk Side Panels, GP - FGG (RE) ...	49.00/pr.
PK228D	1971	Trunk Side Panels, Catalina - Conv. - FGG (RE)	52.00/pr.
PK229	1971	Trunk Side Panels, GP - FGG (RE) ...	49.00/pr.
PK231B	1972	Trunk Side Panels, Bonneville, Executive - 4 Dr. Sedan - FGG (RE)..	54.00/pr.
PK235A	1972	Trunk Side Panels, Grandville, Catalina - Conv. - FGG (RE)	72.00/pr.
PK239C	1973	Trunk Side Panels, Bonneville - 4 Dr. Sedan - FGG (RE)	49.00/pr.
PK240	1973-75	Trunk Side Panels, GP - FGG (RE) ...	49.00/pr.
PK244A	1973	Trunk Side Panels, Grandville - Conv. - FGG (RE)	72.00/pr.
PK249A	1974	Trunk Side Panels, Grandville - Conv. - FGG (RE)	57.00/pr.
PK249B	1974	Trunk Side Panels, Grandville - 4 Dr. HT - FGG (RE)	57.00/pr.
PK256	1976-77	Trunk Side Panels, GP, 6 pcs. - FGG (RE)	56.00/set

PK224A-PK256 (excluding PK225, PK225A and PK227A) side panels have green-grey felt trunk mat material adhered to their face.

Please add \$8.50 shipping for trunk side panels.

SPARE TIRE COVERS



PK330	1959	Spare Tire Cover, Gray and Black Houndstooth (RE)	29.00/ea.
PK332	1960	Spare Tire Cover, Red and Black Houndstooth (RE)	34.00/ea.
PK332A	1961	Spare Tire Cover, Red, Fawn and Black Herringbone (RE)	34.00/ea.
PK332B	1962-64	Spare Tire Cover, Red and Black Herringbone (RE)	34.00/ea.
PK332C	1962-64	Spare Tire Cover, Aquamarine and Black Herringbone (RE)	34.00/ea.
PK332D	1965-66	Spare Tire Cover, Gator (RE)	34.00/ea.


PK333	1967-68	Spare Tire Cover, Gray and Black Herringbone (RE)	\$ 34.00/ea.
PK334	1969-up	Spare Tire Cover, Gray-Green Felt (RE)	29.00/ea.
PK334D	1969-70	Spare Tire Cover, Black Felt (RE)	29.00/ea.

Note: These covers are die-stamped and sewn in the same manner as factory originals. Samples available on request.

Comments: Very good—the only difference we see is a slightly smoother surface on the reproduction.




JACK PACKS




PK335A

PK335A	Jack Pack, Gray and Black Houndstooth (AP)	8.00/ea.
PK335B	Jack Pack, Red and Black Houndstooth (AP)	8.00/ea.
PK335C	Jack Pack, Red, Fawn and Black Herringbone (AP)	8.00/ea.
PK335D	Jack Pack, Red and Black Herringbone (AP)	8.00/ea.
PK335E	Jack Pack, Aqua and Black Herringbone (AP)	8.00/ea.
PK335F	Jack Pack, Gator (AP)	8.00/ea.
PK335D	Jack Pack, Gray and Black Herringbone (AP)	8.00/ea.

Although never offered by Pontiac, the jack pack will help prevent scratching and marring of your trunk area. Large enough to store your jack and lug wrench. Available in the same colors as your trunk mats, side panels and spare tire covers.



TRUNK DIVIDERS



PK336	1955-57	Trunk Divider, Star Chief - 2 Dr. HT (RE)	18.00/ea.
PK336A	1955-57	Trunk Divider, Star Chief - 2 Dr. HT w/Lute (RE)	28.00/ea.
PK337	1955-57	Trunk Divider, Chieftain, Superchief - 2 Dr. HT (RE)	18.00/ea.
PK337A	1955-57	Trunk Divider, Chieftain, Superchief - 2 Dr. HT w/Lute (RE)	28.00/ea.
PK338	1955-57	Trunk Divider, Sedan - 4 Dr. HT (RE)	18.00/ea.

PK338A	1955-57	Trunk Divider, Sedan - 4 Dr. HT w/Jute (RE)	\$ 28.00/ea.
PK339	1958	Trunk Divider, Bonneville - 2 Dr. HT, Crosshatch (RE)	Inquire
PK339A	1958	Trunk Divider, Bonneville - 2 Dr. HT, Crosshatch w/Jute (RE) ...	Inquire
PK339B	1958	Trunk Divider, Bonneville - 2 Dr. HT, Plain Cardboard (RE)	18.00/ea.
PK339C	1958	Trunk Divider, Bonneville - 2 Dr. HT, Plain Cardboard w/Jute (RE)	28.00/ea.

PK339 and PK339A have the correct design printed on the cardboard while PK339B and PK339C offer an inexpensive alternative utilizing plain black cardboard.

PK340	1959	Trunk Divider, Catalina - 2 Dr. HT - GHT (RE)	25.00/ea.
PK340A	1959	Trunk Divider, Catalina - 2 Dr. HT - GHT w/Jute (RE)	35.00/ea.
PK340C	1959	Trunk Divider, Bonneville - 2 Dr. HT - GHT (RE)	25.00/ea.
PK340D	1959	Trunk Divider, Bonneville - 2 Dr. HT - GHT w/Jute (RE)	35.00/ea.
PK340F	1959	Trunk Divider, ALL Sedan and 4 Dr. HT - GHT (RE)	25.00/ea.
PK340G	1959	Trunk Divider, ALL Sedan and 4 Dr. HT - GHT w/Jute (RE)	35.00/ea.
PK341	1960	Trunk Divider, Catalina - 2 Dr. HT - RHT (RE)	25.00/ea.
PK341A	1960	Trunk Divider, Catalina - 2 Dr. HT - RHT w/Jute (RE)	35.00/ea.
PK341C	1960	Trunk Divider, Bonneville - 2 Dr. HT - RHT (RE)	25.00/ea.
PK341D	1960	Trunk Divider, Bonneville - 2 Dr. HT - RHT w/Jute (RE)	35.00/ea.
PK341F	1960	Trunk Divider, ALL Sedan and 4 Dr. HT - RHT (RE)	25.00/ea.
PK341G	1960	Trunk Divider, ALL Sedan and 4 Dr. HT - RHT w/Jute (RE)	35.00/ea.

Note: All 1959 trunk dividers come printed with the gray and black houndstooth pattern. All 1960 trunk dividers come printed with red and black houndstooth pattern. 1961 and newer dividers are black cardboard.

PK342	1961	Trunk Divider, HT (RE)	18.00/ea.
PK342A	1961	Trunk Divider, HT w/Jute (RE)	28.00/ea.
PK342F	1961-64	Trunk Divider, ALL Sedan and '62-'64 4 Dr. HT (RE)	18.00/ea.
PK342G	1961-64	Trunk Divider, ALL Sedan and '62-'64 4 Dr. HT w/Jute (RE)	28.00/ea.
PK343	1962-64	Trunk Divider, 2 Dr. HT (RE)	18.00/ea.
PK343A	1962-64	Trunk Divider, 2 Dr. HT w/Jute (RE)	28.00/ea.
PK344	1965-66	Trunk Divider, ALL exc. Conv. (RE)	18.00/ea.
PK344A	1965-66	Trunk Divider, ALL exc. Conv. w/Jute (RE)	28.00/ea.
PK345	1967-68	Trunk Divider, ALL exc. Conv. (RE)	18.00/ea.
PK345A	1967-68	Trunk Divider, ALL exc. Conv. w/Jute (RE)	28.00/ea.

Note: These panel boards were factory equipment between the rear seat and trunk in hard-

tops and sedans. This divider gives your trunk that final touch.

Comments: Excellent.

Please add \$7.00 shipping for seat dividers.

WEATHERSTRIP



PK350

PK350	3M Black Weatherstrip Adhesive (AP)	\$ 7.00/ea.
--------------	--	-------------



PK378

PK360	1955-56	Trunk Weatherstrip - ALL (RE)	18.00/ea.
PK362	1957	Trunk Weatherstrip - Chieftain (RE) ..	28.00/ea.
PK363	1957	Trunk Weatherstrip - Star Chief (RE) ..	22.00/ea.
PK364	1958	Trunk Weatherstrip (RE)	22.00/ea.
PK366	1959-60	Trunk Weatherstrip - Catalina (RE) ..	22.00/ea.
PK367	1959-60	Trunk Weatherstrip - Star Chief & Bonneville (RE)	22.00/ea.
PK369	1961-62	Trunk Weatherstrip - Catalina - GP ..	22.00/ea.
PK370	1961-62	Trunk Weatherstrip - Star Chief & Bonneville (RE)	22.00/ea.
PK373	1963-64	Trunk Weatherstrip - Catalina - GP (RE)	22.00/ea.
PK374	1963-64	Trunk Weatherstrip - Star Chief & Bonneville (RE)	22.00/ea.
PK378	1965-70	Trunk Weatherstrip - Catalina & '65-'68 GP (RE)	22.00/ea.
PK379	1965-70	Trunk Weatherstrip - Star Chief & Bonneville (RE)	22.00/ea.
PK383	1969-72	Trunk Weatherstrip - GP (RE)	20.00/ea.
PK384	1971-76	Trunk Weatherstrip - FS (RE)	22.00/ea.
PK385	1973-77	Trunk Weatherstrip - GP (RE)	22.00/ea.

All above trunk weatherstrips come from what we feel is the best weatherstrip on the market. We have studied samples from four manufacturers of reproduction extruded trunk weatherstrip. The product we've chosen to handle illustrates the best shape, texture, cell structure, and compressibility.

Comments: Very good. More costly than some but the best extruded product on the market.

PK387	1969-72	Trunk Weatherstrip - Skin Coated Latex, GP	59.00/ea.
--------------	---------	---	-----------

This is the original GM style weatherstrip (the finest available).



TRUNK PAINT & CLEAR COAT




- PK400** Trunk Spatter Paint, Grey & White
14 oz. Aerosol Can (GM)..... 10.00/ea.
- PK401** Trunk Spatter Paint, Black & Aqua
14 oz. Aerosol Can (GM)..... 10.00/ea.

This is GM's own trunk paint. Afterproduct spatter paint contains approximately 50% water which usually runs when the trunk area sweats. GM paint contains 30% and is far superior.

Comments: None of the products available is an exact match with the original. This is not perfect but the best we've seen in paint of this quality.

Note: Occasionally customers that order PK401 feel they have received PK400. As far as color goes, the grey in PK400 is very light, similar to concrete. The black in PK401 is actually a charcoal shade while the spatter is a very light aqua (at times the spatter almost appears white).


- PK405**  Trunk Spatter Paint, Clear Coat (AP) 6.50/ea.
We highly recommend this product because when the trunk area sweats the spatter paint tends to run. Two cans required for most trunks.

TRUNK LAMP KIT



- PK410** 1964-68 Trunk Lamp Kit (RE) 30.00/ea.
This is a reproduction of the accessory option available for '64-'68 Pontiacs. Many customers have used this on earlier cars by adapting the harness.

HOLD-DOWN ASSEMBLY



- PK415** 1965-66 Jack Handle and Jack Hold-Down Assembly - HTP (RE) \$12.00/asm.



This highly sought-after bracket is usually missing, discarded years ago. The assembly comes complete with bolt, bracket, washer, and wing nut. Excellent detail item.

MISCELLANEOUS



- | | PK424 | PK486 | |
|---------------|---|-------|-----------|
| PK420 | 1955-57 Trunk Bumper, Lower (RE)..... | | 2.00/ea. |
| PK422 | 1955-57 Trunk Bumper, Upper (RE) | | 2.00/ea. |
| PK424 | 1958-66 Trunk Bumper (RE)..... | | 1.50/ea. |
| PK440 | 1967-68 Trunk Bumper (RE)..... | | 1.00/ea. |
| PK441 | 1969-76 Trunk Bumper - FS (RE)..... | | 1.00/ea. |
| PK442 | 1969-77 Trunk Bumper - GP (RE)..... | | 1.00/ea. |
| PK460 | 1969-77 Jack Handle - GP (GM)..... | | 12.00/ea. |
| PK461 | 1971-76 Jack Handle - FS (GM) | | 11.50/ea. |
| PK465 | 1965-70 Blue Paint (For Jack Handle and Base) 11 oz. Aerosol Can (AP) | | 8.00/ea. |
| PK468 | 1955 Trunk Wiring Harness Grommet (RE)..... | | 4.50/ea. |
| | Requires 2. Fits 7/8" hole w/3/16" center hole. | | |
| PK470 | 1956 Rear Body Bolt Access Plug (RE)..... | | 4.50/pr. |
| PK473 | 1955-57 Trunk Access Plug (RE) | | 2.00/ea. |
| PK474 | 1955-57 Spare Tire Well Plug (RE) | | 2.00/ea. |
| PK480 | 1959-70 Rubber 1" Trunk Plug (RE)..... | | 1.00/ea. |
| PK481 | 1959-70 Rubber 3/4" Trunk Plug (GM) | | 2.00/ea. |
| PK485 | 1959-77 Spare Tire Hold-Down Rod | | |
| | - ALL (GM) | | 5.00/ea. |
| PK486 | 1959-77 Spare Tire Hold-Down Nut | | |
| | - ALL (GM) | | 3.50/ea. |
| PK486J | 1959-77 Spare Tire Anchor Bracket (RE)..... | | 5.50/ea. |

Note: The PK485 Hold-Down Rod loops through this bracket holding the rod to the trunk floor.



PK487

PK487 1960-68 Eight-Lug Hold-Down Plate (RE) \$ 30.00/ea.

Note: This plate is manufactured like original. It is made from the same thickness stock, has the correct crimped notches, and is stamped to have the original convex shape. The plate was used not only to anchor the eight-lug spare in the trunk, but also to hold the rim securely when mounting and dismounting tire.

Comments: Excellent. Beware of other less expensive products on the market. All the reproductions we've seen are flame cut from 3/16" or 1/4" flat stock. They exhibit none of the original crimped or contoured surfaces.

PK495 1967-77 Automatic Trunk Release Switch - ALL (GM) 6.00/ea.



PK497K

PK497J

PK497J 1966 Vacuum Check Valve for Vacuum Operated Automatic Trunk Release (GM) 4.00/ea.

PK497K 1966 Vacuum Reserve Tank w/Vacuum Operated Automatic Trunk Release (AP) 49.00/ea.

This canister serves as a replacement. Dimensions are not the same as original.



PK499J

PK499J 1971-72 Trunk Torsion Spring (RE) 37.00/pr.

Replace your worn weak springs with these new high carbon spring steel reproductions.

DECK LID LOCK SHAFTS



PK510

PK510 1955-66 Deck Lid Lock Shaft (GM) \$ 2.00/ea.

PK511 1967 Deck Lid Lock Shaft - Catalina & Executive (GM) Disc.

PK512 1967 Deck Lid Lock Shaft - Bonneville & GP (GM) Disc.

PK514 1968-72 Deck Lid Lock Shaft - ALL (GM) Disc.

DECK LID KEY BLANKS



PK525

PK525 1955-66 Deck Lid Key Blank (NOS) 3.50/ea.

PK526 1967 Deck Lid Key Blank (B) (NOS) 3.50/ea.

PK527 1968 Deck Lid Key Blank (D) (NOS) 3.50/ea.

Note: PK525, PK526, and PK527 have the original round head design. PK525 has knockout removed while PK526 and PK527 have the knockout in place.



PK528

PK528 1968 Deck Lid Key Blank (D) (GM) 1.50/ea.

Note: PK528 has an oval style head without knockout like the following later-style keys.

PK529 1969 Deck Lid Key Blank (H) (GM) 1.50/ea.

PK530 1970 Deck Lid Key Blank (K) (GM) 1.50/ea.

PK531 1971 Deck Lid Key Blank (B) (GM) 1.50/ea.

PK532 1972 Deck Lid Key Blank (D) (GM) 1.50/ea.

PK533 1973 Deck Lid Key Blank (H) (GM) 1.50/ea.

PK534 1974 Deck Lid Key Blank (K) (GM) 1.50/ea.

PK535 1975 Deck Lid Key Blank (B) (GM) 1.50/ea.

PK536 1976 Deck Lid Key Blank (D) (GM) 1.50/ea.

PK537 1977 Deck Lid Key Blank (H) (GM) 1.50/ea.

DECK LID LOCK ASSEMBLIES AND COMPONENTS



PK561

PK550 1955-58 Deck Lid Lock Assembly w/Late-Style Key (NOS) 11.00/ea.

PK550A 1955-58 Deck Lid Lock Assembly w/Original-Style Key (NOS) 17.00/ea.

PK551 1959 Deck Lid Lock Assembly w/Late-Style Key (NOS) 12.00/ea.

PK551A 1959 Deck Lid Lock Assembly w/Original-Style Key (NOS) 17.00/ea.

PK552 1960 Deck Lid Lock Assembly w/Late-Style Key (NOS) 12.00/ea.

PK552A 1960 Deck Lid Lock Assembly w/Original-Style Key (NOS) 17.00/ea.


PK553	1961-62	Deck Lid Lock Assembly w/Late-Style Key (NOS)	\$ 12.00/ea.
PK553A	1961-62	Deck Lid Lock Assembly w/Original-Style Key (NOS)	17.00/ea.
PK554	1963-64	Deck Lid Lock Assembly w/Late-Style Key (NOS)	12.00/ea.
PK554A	1963-64	Deck Lid Lock Assembly w/Original-Style Key (NOS)	17.00/ea.
PK555	1965	Deck Lid Lock Assembly w/Late- Style Key - ALL exc. GP (NOS)	11.00/ea.
PK555A	1965	Deck Lid Lock Assembly w/Original- Style Key - ALL exc. GP (NOS)	17.00/ea.
PK555C	1966	Deck Lid Lock Assembly w/Late- Style Key - ALL exc. GP (NOS)	12.00/ea.
PK555D	1966	Deck Lid Lock Assembly w/Original- Style Key - ALL exc. GP (NOS)	17.00/ea.
PK556	1967	Deck Lid Lock Assembly w/Late- Style Key - ALL exc. Bonneville & GP (NOS)	11.00/ea.
PK556A	1967	Deck Lid Lock Assembly w/Original- Style Key - ALL exc. Bonneville & GP (NOS)	17.00/ea.
PK557	1967	Deck Lid Lock Assembly w/Late- Style Key - Bonneville & GP (NOS) .	17.00/ea.
PK557A	1967	Deck Lid Lock Assembly w/Original- Style Key - Bonneville & GP (NOS) .	23.00/ea.
PK558	1968	Deck Lid Lock Assembly w/Late-Style Key (NOS)	12.00/ea.
PK558A	1968	Deck Lid Lock Assembly w/Original-Style Key (NOS)	17.00/ea.
PK559	1969-77	Deck Lid Lock Assembly w/Original- Style Key - FS & GP (NOS)	11.00/ea.
PK561	1955-77	Deck Lid Lock Gasket (RE)	1.00/ea.
See Section Seventeen for complete lock sets.			



PK570

PK570	1968-72	Trunk Lock Retainer Gasket - GP (RE)	1.00/ea.
PK570	1969-70	Trunk Lock Retainer Gasket - FS (RE)	1.00/ea.
PK571	1971-76	Trunk Lock Retainer Gasket - FS (GM)	1.00/ea.
PK571	1973-77	Trunk Lock Retainer Gasket - GP (GM)	1.00/ea.

These are the gaskets that seal the lock retain-
er to the deck lid.



PK575


PK575	1955-57	Trunk Lock Retainer All except SW (RE)	\$ 3.50/ea.
--------------	---------	---	-------------

TRUNK FLOOR SHEETMETAL

PK670	1965-69	Trunk Floor, LH - FS (RE)	Inquire
PK671	1965-69	Trunk Floor Center - FS (RE)	Inquire
PK672	1965-69	Trunk Floor, RH - FS (RE)	Inquire

Note: We have found a stamper capable of
producing these desperately needed trunk
floors. At this time we do not have a delivery
date. Please inquire concerning their status.

PK674 PK676 PK675



PK677



PK678

PK673	1969-72	Full Trunk Floor, Body Braces, and Fuel Tank Braces - GP (RE)	339.00/set
PK674	1969-72	Trunk Floor, LH w/Body Brace - GP (RE)	110.00/ea.
PK675	1969-72	Trunk Floor, RH w/Body Brace - GP (RE)	115.00/ea.
PK676	1969-72	Trunk Floor Center - GP (RE)	75.00/ea.
PK677	1969-72	Fuel Tank Braces - GP (RE)	35.00/ea.
PK678	1969-72	Body Brace, LH - GP (RE)	55.00/ea.
PK679	1969-72	Body Brace, RH - GP (RE)	55.00/ea.

It is recommended that the customer fully in-
vestigate the extent of the trunk rust. In almost
all cases the body brace is needed (body
braces are included in the price of the LH and
RH trunk floor sections). Other companies may
sell just the floor pan at reduced prices, but it is
seldom sufficient.

Please add \$8.50 shipping.

TRUNK LIP PANELS



PK730

PK730 1958 Trunk Opening Bottom Lip Patch Panels (RE) \$119.00/pr.

These patch panels will cure the commonly rusted area on 58 trunk openings. The bottom lip comes in two pieces (upper and lower) ready to replace the weatherstrip channel and dropleg from weatherstrip channel to trunk floor.



PK750

PK750 1961-77 Floor Drain Plug (RE) 4.00/ea.

This is the steel drain plug found in both the body and trunk floors.

SEAM SEALER



PK770

PK770
PK771

Seam Sealer, Black (AP) 9.50/tube



PK771

Brushable Seam Sealer, Grey

1 Quart (AP) Disc.




PK772

PK772

Disposable Brush (AP) 1.00/ea.

SECTION TEN-REAR END TRIM

EMBLEMS



PL102

PL102 1956 Deck Lid Star - Star Chief (RE) \$ 18.00/ea.

Requires 3 pieces.

PL103J 1957 Safari Deluxe Pontiac Letters (RE) 65.00/set

PL103K 1957 Safari Standard Pontiac Letters (RE).. 65.00/set




PL104

PL104 1958 Rear Deck Lid Plate Fuel Injection (RE) 69.00/ea.



PL104D 1958 Bonneville Trunk Letters (RE) 129.00/set



PL110

PL110 1961 Rear Deck Lid Arrowhead (APE)..... \$ 29.00/ea.



PL110J 1961 Bonneville Tail Panel Letters (Gold) (RE) 160.00/set



PL111

PL111 1962 Rear Deck Lid Arrowhead (APE)..... 29.00/ea.



PL111D

PL111D 1962 Rear End Panel Emblem - GP (RE) ... \$ 55.00/ea.

Note: This emblem is a little thicker than original.

PL112 1963 Rear Deck Lid Arrowhead - Exc. GP (APE)..... 29.00/ea.

PL112A 1963 Rear Deck Lid Arrowhead - GP (RE) 29.00/ea.



PL113

PL113 1963 Rear Deck Lid Plate - GP (RE) 29.00/ea.

PL114 1964 Rear Deck Lid Arrowhead (APE)..... 29.00/ea.



PL114D 1964 "Grand Prix" Deck Lid Letters (9 pcs.) (RE)..... 59.00/set



PL114Y

PL114Y 1965 GP Deck Lid Emblem (RE) 20.00/ea.



PL115

PL115 1965 Rear Deck Lid Arrowhead (APE)..... 29.00/ea.

PL116 1966 Rear Deck Lid Arrowhead (APE)..... 29.00/ea.



PL116B

PL116BA

PL116B 1966 "Bonneville" Deck Lid Letters (10 pcs) (RE) \$109.00/set

PL116BA 1966 Bonneville Tail Panel Emblem (RE) . 89.00/ea.

PL116J 1967 Rear Deck Lid Arrowhead - Cat/2+2 (RE) 25.00/ea.

PL116K 1967 Rear Deck Lid Arrowhead - ALL exc. Cat/2+2 (RE) 25.00/ea.



PL116M

PL116M 1967 Bonneville Deck Lid Emblem (RE) ... 25.00/ea.



PL117

PL117 1965-66 Rear Deck Lid Emblem 2+2 (RE).... 21.00/ea.



PL123J

PL123J 1969-70 "Grand Prix" Deck Lid Letters (9 pcs.) (RE)..... 65.00/set



PL123N

PL123M 1970 "Model J" Deck Lid Emblem - GP (RE)..... 19.00/ea.

PL123N 1970 "Model SJ" Deck Lid Emblem - GP (RE)..... 19.00/ea.



PL125

PL125 1971-72 "Grand Prix" Deck Lid Emblem (RE) 20.00/ea.



PL128

- PL128** 1973-77 "Grand Prix" Deck Lid Emblem (RE)..... Inquire



PL134

- PL134** 1976-77 Deck Lid Lock Dust Cover Lucite (GM)..... \$13.00/ea.



PL135

- PL135** Hurst Equipped Emblem (AP) 29.00/ea.
Many customers have requested this emblem as it is a nice add-on.

REAR BUMPER END CAPS



PL150

- PL150** 1957 Rear Bumper Caps (Open) w/Bolts (RE)..... 269.00/pr.



PL151

- PL151** 1957 Rear Bumper Caps (Closed) w/Bolts (RE)..... 269.00/pr.

Note: Rear bumper end caps are high quality reproductions. NOS pairs have brought \$600-\$700/pr. at swap meets making this product an excellent value.



TAILGATE COMPONENTS



PL190

- PL190** 1955-57 Lower Tailgate Cable - Safari (RE) \$ 22.00/ea.

- PL190B** 1955-57 Lower Tailgate Cable - SW (RE) 22.00/ea.

- PL190D** 1955-57 Lower Tailgate Cable Reel (RE) 44.00/ea.



PL190D



PL193

- PL193** 1955-57 Upper Tailgate Support Arm Rebuild Kit - Safari & SW (RE) 14.00/kit



PL195

- PL195** 1955-57 Inner Lower Tailgate Hinge Covers - Safari (RE) 25.00/pr.

- PL195A** 1955-57 Inner Lower Tailgate Hinge Covers - SW (RE) 25.00/pr.

These covers are zinc-plated to resist rust and corrosion.



PL200

- PL200** 1955-57 Outer Tailgate Bar Set- Safari (6 pcs)
(RE).....\$349.00/set
- PL200A** Late 1955-57 Center Tailgate Bar Safari (RE).. 149.00/ea.
- PL200AC** 1955-57 Center Tailgate Bar Handle
- Safari (RE) 50.00/ea.



PL200AG

- PL200AF** 1955-57 Tailgate Bar Clip (RE) 3.00/ea.
- PL200AG** 1955-57 Tailgate Bar Clip Set (33 pcs) (RE) 76.00/ea.
- PL201** 1955-57 Lower Tailgate Weatherstrip - Safari
(RE)..... 45.00/ea.
- PL202** 1955-57 Upper Tailgate Weatherstrip - Safari
(RE)..... 21.00/ea.
- PL203** 1955-57 Lower Tailgate Weatherstrip - SW
(RE)..... 49.00/ea.
- PL204** 1955-57 Upper Tailgate Weatherstrip - SW
(RE)..... 49.00/ea.



PL205

- PL205** 1955-57 Lower Tailgate Bumpers - Safari
(RE)..... 5.00/pr.
- PL206** 1955-57 Lower Tailgate Bumpers - SW (RE) .. 4.00/ea.




PL208

- PL208** 1955-57 Upper Tailgate Tabs - Safari (RE)..... 13.00/pr.
- Note: These are located on the ends of the upper tailgate.*



PL210G

- PL210** 1955-57 Lower Tailgate Hinge Screw Set
- SW, 6 pcs. (RE) \$ 4.00/set
- Contains enough screws to do one hinge.
- PL210D** 1955-57 Liftgate Inner Window Frame Screw
Set - Safari (RE)..... 10.00/set
- PL210G** 1955-57 Upper & Lower Tailgate Fastener
Kit - stainless steel - 126 pcs. (RE)..... 19.00/set



PL211

- PL211** 1955-57 Tailgate Hinge Repair Kit (RE) 12.00/kit
- This contains 2 new pins and 4 bushings to refurbish your worn hinges.

EXHAUST HANGERS & CLAMPS



PL220C

- PL220C** 1969-72 Muffler Hanger (dual exh.), LH - GP
(AP)..... 8.00/ea.
- PL220D** 1969-72 Muffler Hanger (dual exh.), RH - GP
(AP)..... 8.00/ea.


These hangers are located just behind the muffler. Both hangers are excellent replacements.



PL220F

PL220F 1969-72 Tail Pipe Hangers (Rear) - GP (AP)... \$ 12.00/pr.

These hangers are similar to original except the design of the pipe to bottom hanger bracket. Originally the pipe was positioned beside the bracket while with PL220F the pipe is clamped below the bracket.



PL220F

PL220G



PL220G


PL220G Exhaust Band Clamp (Rear - 2" dia.)(APE) 12.00/pr.

PL220H Exhaust Band Clamp (Rear - 2 1/4" dia.)(APE) 12.00/pr.

These unique clamps were used on many Pontiacs with dual exhaust. Use with PL220F for final exhaust detailing.



PL220M



PL220N

PL220M 1966-73 Original GM Style Muffler Clamp, 2" (APE) 6.00/ea.

PL220N 1966-73 Original GM Style Muffler Clamp, 2 1/4" (APE)..... 6.00/ea.

Since Pontiac restorations began, no one has ever located the unique muffler clamps used by the factory. Since these were not serviced by GM parts departments, afterproduct flat sided clamps have always been used, even by the most conscientious restorer.

These clamps were reproduced using samples from low mileage original exhaust cars and NOS accessory exhaust extension kits from 1966.

Comments: These exact clamps with the circular style outer profile are for the serious restorer.

Note: We are unsure about '64 and '65 cars, but believe these clamps were used and this style clamp was dropped in either 1974 or 1975.

TAILLAMP COMPONENTS



PL258



PL258A

PL258 1955-56 Taillamp Lens - ALL exc. 870 and Star Chief (RE)..... \$ 29.00/pr.

PL258A 1955-56 Taillamp Lens Trim Ring - ALL 870 and Star Chief (RE)..... 20.00/pr.

PL258B 1955-56 Taillamp Lens w/Trim Ring - ALL 870 and Star Chief (RE) 47.00/set

Note: PL258 and PL258A are nice reproductions. Lenses do not have GUIDE or guidex imprints. Trim ring must be epoxied onto lens to make deluxe lens. Ring will fit reproduction or original lenses.

PL258G 1955-56 Taillamp to Rear 1/4 Seal - Chieftain Wagons only (RE)..... 3.00/pr.



PL260



PL260A

PL260 1957 Taillamp Lens - Chieftain - Superchief (RE)..... 59.00/pr.

This lens is not correct for Star Chief or Bonneville; however, it will fit. The lens has the reflector in it that was not on original Star Chiefs and Bonneville.

PL260A 1957 Taillamp Lens Gaskets (RE) 8.50/pr.



PL262A

PL262A 1958 Taillamp Lens Gasket Set (4 pcs.) (RE)..... 15.00/set

PL262AB 1958 Taillamp Lens Screws (AP)..... .50/ea.



PL264

PL264 1960 Taillamp Lens - Bonneville and Star Chief exc. SW (RE) \$ 13.00/ea.

Requires 4.

PL264B 1960 Taillamp Lens - All exc. Bonneville and Star Chief (RE)..... 13.00/ea.

Requires 4.



PL267J

PL267J 1963 Taillamp Assembly to Body Seal (RE)..... 4.00/pr.


PL267M 1963 Taillamp Lens Gasket (RE) 6.00/pr.



PL267X


PL267X 1968 Taillamp Lens Gaskets - exc. SW (RE)..... 21.00/pr.

BACK UP LENSES AND GASKETS



PL275

PL275 1955-56 Back-Up Lenses (RE) Inquire




PL276

PL276 1957 Back-Up Lenses (RE) 62.00/pr.




PL276A

PL276A 1957 Back-Up Lens Gaskets (RE)..... 7.00/pr.



PL276E

PL276E 1958 Back-Up Lens Gaskets (RE)..... 8.00/pr.



PL276EB

PL276EB 1958 Back-Up Lens Screws (AP)..... .50/ea.



PL276J

PL276J 1959 Back-Up Lenses (RE) \$ 32.00/pr.

PL276R 1961 Back-Up Lens Gaskets - Star Chief (RE)..... 11.50/pr.



PL280

PL280 1964-66 Back-Up Lenses - Exc. '64 GP (APE) 22.00/pr.

PL280A 1964-66 Back-Up Lens Gaskets - Exc. '64 GP (APE)..... 6.00/pr.



PL280A

Both lenses are high quality reproductions.



PL280C

PL280C 1964-66 Back-Up Lamp Housing - Exc. '64 GP (RE) 33.00/ea.

PL280D 1964-66 Back-Up Lamp Assembly - Exc. '64 GP (RE) 45.00/asm.

PL280D consists of housing, lens, lens gasket, bulb and screws.



PL281

PL281 1967 Back-Up Lenses (APE)..... 26.00/pr.

PL281 1968 Back-Up Lenses (SW Only) (APE).... 26.00/pr.

PL281A 1967-68 Back-Up Lens Gaskets for PL281 (APE)..... 6.00/ea.


PL290 1961-68 Back-Up Lens Screw (APE) 1.00/ea.



PL281A

This is the special long-shanked screw used exclusively for Pontiac back-up lenses.

TAILLIGHT BEZEL GASKETS



PL300 Taillight Bezel Gaskets (APE) \$ 1.00/ft.

For those years requiring taillight bezel gaskets, we have released this U-shaped gasket.

FUEL TANKS AND INSULATION



PL316 1969-70 Fuel Tank - GP (RE) 199.00/ea.

Note: This new reproduction tank comes without a sending unit and filler neck. You must use your original filler neck. New sending units and sending unit retainers are available. See below.

Additional \$8.50 shipping on fuel tanks.

PL325 1961-77 Fuel Tank Insulation (AP) 21.50/ea.

FUEL GAUGE SENDING UNITS & RETAINERS



PL330 1969-70 Fuel Gauge Sending Unit - GP (GM) 47.00/ea.

Note: This fits '70 GPs w/o E.E.S. except the 3/8" and 1/4" lines are reversed from the original design.

PL331 1971-72 Fuel Gauge Sending Unit - FS exc. AC, SW, or HD Cooling (GM) 76.00/ea.

PL332 1971-72 Fuel Gauge Sending Unit w/AC, FS exc. SW, or HD Cooling (GM).... 74.00/ea.

PL334C 1973-76 Fuel Gauge Sending Unit w/AC, FS exc. SW (GM) \$ 77.00/ea.

Note: Fuel gauge sending units do not come with locking retainers. Please order below.

PL338 1961-72 Fuel Gauge Sending Unit Retainer, 25/8" (GM) 2.00/ea.

This retainer fits 61-64 SW, 65-66 FS, 69-70 FS, and 69-72 GP or any fuel gauge sending unit with a 25/8" lock ring.

PL338B 1967-77 Fuel Gauge Sending Unit Retainer, 37/8" (GM) 3.00/ea.

This retainer fits 67-68 FS, 71-76 FS, and 73-77 GP or any fuel gauge sending unit with a 37/8" locking ring.



PL338D 1955-64 Fuel Gauge Sending Unit Gasket (GM) 2.00/ea.

This is the flat gasket with five mounting holes.

PL338F 1961-72 Fuel Gauge Sending Unit Gasket -23/8" (GM) 2.00/ea.

PL338H 1967-77 Fuel Gauge Sending Unit Gasket -31/2" (GM) 2.00/ea.



PL338J 1961-77 Fuel Gauge Sending Unit Filter (GM) 10.00/ea.

This "sock" style filter goes on the sending unit inside the fuel tank.

GAS TANK STRAPS AND HARDWARE



PL339 1957 Gas Tank Strap (RE) 15.00/ea.

PL339A 1958 Gas Tank Strap (RE) 15.00/ea.

PL339AJ 1961-64 Gas Tank Strap (RE) 15.00/ea.

PL340 1969-70 Gas Tank Support Strap - GP (GM) .. 9.00/ea.

PL342U 1969-70 Gas Tank Strap Hardware Kit (AP) ... Inquire

GAS TANK CAPS



PL345

PL345	1965-70	Gas Tank Cap - Exc. SW (GM).....	\$ 7.00/ea.
PL346	1970	Gas Tank Cap - SW exc. Evaporative Emission System (GM) .	8.00/ea.
PL346H	1975-77	Gas Tank Cap (GM)	6.00/ea.

FUEL TANK RELATED



PL350

PL350	1965-77	Gas Tank Filler Door - ALL exc. SW (GM).....	24.50/ea.
--------------	---------	--	-----------

LICENSE PLATE COMPONENTS



PL350BG

PL350BG	1955-56	License Plate Lamp Assemblies - Safari & SW (RE).....	33.00/pr.
----------------	---------	---	-----------

Each set comes complete with a pair of lenses, gaskets, housings, bulbs and wirings.

PL350BH	1955-56	License Plate Lamp Lens - Safari and SW (RE)	6.00/pr.
----------------	---------	--	----------



PL350BJ	1955-56	License Plate Lamp Lens Gaskets (RE).....	4.00/pr.
----------------	---------	---	----------



PL350D

License Plate Lamp Assembly - ALL exc. SW (GM/RE)..... \$ 25.00/ea.

This assembly is very similar to many we've seen on early Pontiacs; however, there are some minor differences. The lens is completely clear (no gray shielding) and the wire exits the right side instead of the left side. See photo above.



PL350DB

PL350DB	1964-72	License Plate Lamp Lens (RE).....	7.50/ea.
----------------	---------	-----------------------------------	----------

GM offered several different style lenses through the years. This lens may differ slightly in appearance but it makes a good replacement.

PL350DD	1964-72	License Plate Lamp Lens Gasket (GM).....	2.00/ea.
----------------	---------	--	----------



PL350F

PL350F	1974-77	License Plate Lamp Lens - ALL exc. SW (GM)	9.50/ea.
---------------	---------	--	----------

LICENSE PLATE POCKETS



PL350H	1969-70	Rear Bumper License Plate Pocket - GP (RE).....	65.00/ea.
---------------	---------	---	-----------

PL350J	1971-72	Rear Bumper License Plate Pocket - GP (RE).....	65.00/ea.
---------------	---------	---	-----------

These pockets are rigid fiberglass reproductions. They do not have the molded clips like originals but are installed using the gas door bolts. Once installed they look like originals.

Comments: Customers have found these fit very well.

GAS DOOR BUMPERS



PL356


PL368

PL352	1955-56	Gas Door Bumper (RE)	\$ 3.00/pr.
PL353	1957	Gas Door Bumper Set - Exc. SW (RE).....	6.00/kit
PL354	1957	Gas Door Bumpers - SW (RE)	3.00/pr.
PL355	1958	Gas Door Bumpers - Exc. SW (RE)...	3.00/pr.
PL356	1958	Gas Door Bumpers (RE).....	3.00/pr.
PL357	1959	Gas Door Bumpers - Exc. SW (RE)...	3.00/pr.
PL359	1960	Gas Door Bumpers - Exc. SW (RE)...	3.00/pr.
PL365	1963-64	Gas Door Bumpers - Exc. SW.....	3.00/pr.

We have found these fit '61-'62 applications as well.

PL368	1965-77	Gas Door Bumpers - Exc. SW (GM)	3.00/pr.
PL369	1965-77	Gas Door Bumpers - SW	3.00/pr.

BUMPER BOLTS & LICENSE PLATE MOUNTING PACKAGE



PL371

PL370	1955-63	Stainless Capped Round Head Bumper Bolt w/Nut (RE).....	\$ 1.00/ea.
PL371	1964-72	Stainless Capped Pan Head Bumper Bolt w/Nut	1.00/ea.
PL380	1963-72	Rear License Plate Mounting Package (RE)	4.50/ea.

REAR VALANCE



PL385

PL385	1969-70	Rear Valance-GP Fiberglass (RE)	Disc.
--------------	---------	---------------------------------------	-------

REAR BODY PANEL TO BUMPER SEAL



PL390	1955-56	Rear Body Panel to Bumper Seal (RE).....	10.00/pr.
PL391	1957	Rear Body Panel to Bumper Seal (RE).....	8.00/pr.
PL395	1960	Rear Body Panel to Bumper Seal (RE).....	11.00/ea.

Note: PL390 through PL395 are the rubber seals between the body and the rear bumper.

SECTION ELEVEN - ELECTRICAL RELATED

POWER ANTENNAS



PM102	1952-54	Power Antenna Mast w/Cord (RE) ...	\$ 99.00/ea.
PM102B	1955-Early '57	Power Antenna Mast w/Cord (RE) ...	99.00/ea.

Note: This is a Casco style mast with diamond-shaped cord.

PM102D	Late 1957-58	Power Antenna Mast w/Cord (RE) ...	99.00/ea.
---------------	--------------	------------------------------------	-----------

Note: This is a Pioneer style mast with round cord.


PM102F	1959-60	Power Antenna Mast w/Cord (RE) ...	99.00/ea.
PM102H	1961	Power Antenna Mast w/Cord (RE).....	99.00/ea.

PM102J	1962-66	Power Antenna Mast w/Cord (RE) ...	\$ 99.00/ea.
---------------	---------	------------------------------------	--------------


These recent reproductions have all correct contours and look excellent. Until now, power masts have been almost impossible to find.

Note: Power antenna switches and bezels can be found in Section One PA449KK-PA449KM.

ANTENNA COMPONENTS



ANTENNA MASTS




1955-64

- PM105** 1955-64 Antenna Mast (Round Manual Mast w/Male Nut and Spherical Tip) (RP) \$ 20.00/ea.

This replacement mast is similar to originals; however, there are a few differences. It has four sections instead of three, a bigger overall diameter, a check nut instead of the correct stationary nut, and it doesn't have the ring around the upper mast. We have a few NOS masts available see PM105A.

- PM105A** 1955-64 Antenna Mast (Round Manual Mast w/Male Nut and Spherical Tip) NOS..... 50.00/ea.

Note: If your '64 Pontiac has a forked end instead of male nut please refer to PM107-PM107B.



1964-66


- PM107** 1964-66 Antenna Mast (Oval Manual Mast w/Female Nut, Forked End and Spherical Tip) (RP)..... Inquire

- PM107A** 1964-66 Antenna Mast (Oval Manual Mast w/Female Nut, Forked End and Oval Tip) (RP)..... 65.00/ea.

- PM107B** 1964-66 Antenna Mast (Oval Manual Mast w/Female Nut, Forked End and Oval Grooved Tip) (RP) 75.00/ea.

At this time, we are offering three styles of '64-'66 masts: (1) the correct oval mast with oval grooved tip (PM107B); (2) a replacement mast (PM107A) that looks like PM107B except without groove in the oval; (3) for an inexpensive alternative we offer PM107 which has a spherical tip.

Note: Supplies are limited.



1967-69

- PM109** 1967-69 Antenna Mast (Oval Manual Mast w/Female Nut, Plug End and Spherical Tip) (RP)..... Inquire

- PM109A** 1967-69 Antenna Mast (Oval Manual Mast w/Female Nut, Plug End and Oval Tip) (RP)..... 65.00/ea.

- PM109B** 1967-69 Antenna Mast (Oval Manual Mast w/Female Nut, Plug End and Oval Grooved Tip) (NOS)..... \$ 75.00/ea.

At this time we are offering three styles of '67-'69 masts: (1) the correct oval mast with oval grooved tip (PM109B); (2) a replacement mast (PM109A) that looks like PM109B except without the groove in the oval tip; (3) for an inexpensive alternative we offer PM107 which has a spherical tip.

Note: Supplies are limited.

- PM110** 1967-69 Manual Antenna Mast Replacement (GM)..... 12.00/ea.

GM discontinued the telescoping three-section mast in favor of this replacement one-piece whip style.

ANTENNA MOUNTING PADS



PM120

- PM120** 1955-56 Manual Antenna Mast Pad (RE) 2.50/ea.



PM120A

- PM120A** 1957-58 Manual Antenna Mast Pad (RE) 6.50/ea.



PM120BA

- PM120BA** 1957 Mounting Pad - Power Antenna, Upper (RE)..... 12.00/ea.

- PM120BB** 1957 Mounting Pad - Power Antenna, Lower (RE)..... 8.00/ea.

- PM127** 1965-66 Manual Antenna Mast Pad (RE) Inquire

- PM131** 1969 Mounting Pad - Manual Antenna (RE)..... 3.00/ea.

- PM132** 1969 Mounting Pad - Power Antenna, Upper & Lower (RE) 6.00/pr.



PM120BB

Please inquire concerning antenna mast pads if your year is not listed. New reproductions are constantly becoming available.

ANTENNA NUTS, ADAPTERS & LEAD WIRES



PM135



PM140B

PM135	1960-69	Manual Antenna Base Nut (RE)	\$ 12.00/ea.
PM140	1961	Manual Antenna Adapter (RE)	18.00/ea.
PM140B	1962	Manual Antenna Adapter (RE)	29.00/ea.
PM140D	1963-64	Manual Antenna Adapter (RE)	18.00/ea.
PM140F	1965-66	Manual Antenna Adapter (RE)	20.00/ea.
PM140J	1967-68	Manual Antenna Adapter (RE)	18.00/ea.
PM140L	1969	Manual Antenna Adapter (RE)	12.00/ea.



PM150



PM155

PM150	1961	Power Antenna Base Nut (RE)	15.00/ea.
PM150	1962-66	Power Antenna Base Nut (RE)	15.00/ea.

It has always been hard to rechrome those slotted antenna base nuts. This part is ready to screw on for less than most rechroming jobs and without the hassle.



PM153J	1964	Power Antenna Adapter (RE)	27.00/ea.
PM155		Antenna Lead Firewall Grommet (RE)	3.00/ea.

Note: This grommet fits cars with a 9/16" firewall hole and lead diameter of 7/32".

PM155H	1962-64	Antenna Lead Wire w/Grommet (RE)	15.00/ea.
PM155J	1965-69	Antenna Lead Wire w/Grommet (RE)	15.00/ea.

MANUAL ANTENNA BODIES



PM164

PM162	1963-64	Antenna Body w/o Lead (w/Screw-in style mast) (RE)	37.00/ea.
--------------	---------	--	-----------

PM163	1964	Antenna Body w/o Lead (w/Fork style mast) (RE)	\$ 37.00/ea.
PM164	1965-66	Antenna Body w/o Lead (RE)	39.00/ea.
PM165	1967-68	Antenna Body w/o Lead (RE)	37.00/ea.
PM166	1969	Antenna Body w/o Lead - FS (RE)	37.00/ea.

Note: These are the bodies mounted under the fender that the antenna screws into. Most originals are broken or missing.



PM170D

PM170	1970-72	Antenna Lead w/Windshield Antenna - GP (GM)	8.00/ea.
PM170D	1969-72	Cowl Panel to Hold Antenna Ground Clip - GP (GM)	1.00/ea.

Note: This also fits 1970 FS.

DIRECTIONAL SIGNAL SWITCHES



PM200	1967-68	Directional Signal Switch (Exc. Cornering Lamps) (Boyne) (GM)	69.00/ea.
PM201	1967-68	Directional Signal Switch (Exc. Cornering Lamps) (Delco) (GM)	59.00/ea.
PM202	1967-68	Directional Signal Switch (w/Cornering Lamps) (Boyne) (GM)	105.00/ea.
PM203	1969-77	Directional Signal Switch (w/Cornering Lamps) - ALL (GM)	39.00/ea.
PM204	1969-77	Directional Signal Switch (Exc. Cornering Lamps) - ALL (GM)	39.00/ea.

These original GM directional switches come complete with switch, wires, and plug. Boyne switches are usually blue while Delco are white. You must know your application and type before ordering since Delco and Boyne switches are seldom compatible.


PM210	1965-66	Directional Signal Switch Repair Kit (Boyne Switches) (AP)	20.50/ea.
PM211	1967-77	Directional Signal Switch Repair Kit (Delco Switches) (AP)	20.50/ea.

Note: PM210 and PM211 are kits to repair Boyne and Delco directional signal switches. Boyne switches are usually blue plastic and Delco switches are white plastic.

HAZARD LIGHT KNOB

PM214J	1967-77	Hazard Light Knob (GM)	2.00/ea.
---------------	---------	------------------------------	----------

COLUMN CANCEL CAMS



PM216

PM216 1965-66 Tilt Column Cancel Cam (RE) \$ 25.00/ea.

This cam operates the turn signal switch and activates the horn relay. The shape of the reproduction is not like original but operation is the same.

PM216D 1967-68 Tilt Column Cancel Cam (GM) 6.00/ea.

PM216G 1969-75 Non-Tilt Column Cancel Cam (GM) 12.50/ea.

PM216H 1969-75 Tilt Column Cancel Cam (GM) 12.50/ea.

PM216K 1976-77 Non-Tilt Column Cancel Cam (GM) 12.50/ea.

PM216L 1976-77 Tilt Column Cancel Cam (GM) 12.50/ea.




PM220

PM220 1967-77 Turn Signal Cancel Springs, Pr. (GM) 1.50/pr.

In some cases, a "broken" turn signal switch may be fixed inexpensively with these springs.

SWITCHES & RELAYS



PM229T

PM229 1960-62 Headlight Switch (RP) 39.00/ea.

PM229E 1963-67 Headlight Switch w/o Hideaway Headlights (GM/RE) 35.00/ea.

PM229T 1967-68 Headlight Switch w/Hideaway Headlights - GP - Bonneville (GM-RE) 53.00/ea.

Although not an exact replacement, this combination GM-reproduction works well. This unique switch, which has vacuum fittings for hideaway headlight control, has been difficult to locate for years.

PM230 1968-74 Headlight Switch - FS w/o Hideaways (GM) 25.00/ea.

PM231 1969-72 Headlight Switch - GP (GM) 23.00/ea.

PM230 1973-74 Headlight Switch - GP (GM) 25.00/ea.

PM231 1975-77 Headlight Switch - ALL (GM) 23.00/ea.

PM235 1955-57 Headlight Dimmer Switch (AP) 15.00/ea.

PM238 1961-77 Headlight Dimmer Switch - ALL w/Floor Mounted (GM) 9.50/ea.

PM238K 1973-77 Headlight Dimmer Switch Column Mounted w/Tilt (GM) Disc.

PM239B 1969-73 Neutral Safety Switch - ALL Auto (AP) \$ 24.50/ea.

PM239D 1974-77 Neutral Safety Switch - ALL Auto (AP) 20.00/ea.

PM239L 1965-75 Stop Light Switch, Exc. Cruise (GM-RP) 8.00/ea.

PM239N 1967-77 Stop Light Switch w/Cruise (GM-RP) 13.00/ea.

PM239P 1976-77 Stop Light Switch, P.B. exc. Cruise (GM-RP) 8.50/ea.

PM239R 1967-77 Transmission Kickdown Switch, AT (GM-RP) 10.00/ea.



PM239TA



PM239TC

PM239TA 1961-75 Power Seat Relay (GM) 24.00/ea.

PM239TC 1970 FS & 1970-72 GP Power Accessory Relay (GM) 29.00/ea.

Different years used this relay for various accessories including power tops, power windows, power seats, power locks, etc. (Refer to the PM239TC photo for identification.)

PM239TF 1971-75 Power Accessory Relay - FS (GM) . 24.00/ea.

PM239TF 1976-77 Power Window and Power Sunroof Relay (GM) 24.00/ea.



PM240AB

PM240AB 1967 Convertible Firewall Junction Block (AP) 5.00/ea.

LIGHT BULBS



LB0067 #67 Light Bulb 1.00/ea.

LB0089 #89 Light Bulb 1.00/ea.

LB0090 #90 Light Bulb 1.00/ea.

LB0093 #93 Light Bulb 1.00/ea.

LB0194 #194 Light Bulb 1.00/ea.

LB0194A #194A Amber Light Bulb 1.50/ea.

LB0211 #211 Light Bulb 1.50/ea.

LB1003 #1003 Light Bulb 1.00/ea.

LB1155 #1155 Light Bulb 1.50/ea.

LB1156 #1156 Light Bulb 1.00/ea.

LB1157 #1157 Light Bulb 1.00/ea.

LB1157A	#1157A Amber Light Bulb.....	\$ 1.50/ea.
LB1445	#1445 Light Bulb	1.50/ea.
LB1893	#1893 Light Bulb	1.50/ea.
LB1895	#1895 Light Bulb	1.50/ea.

Note: When ordering light bulbs, please look at originals and take the part number off of it. The bulbs above use the standardized numbering system.

PM268A	1968 Ignition Lock Cylinder w/Late-Style Key (NOS)	\$ 12.00/ea.
PM269	1969-77 Ignition Lock Cylinder w/Key - ALL (NOS).....	12.00/ea.

Note: See Section Seventeen for matched sets of locks.

IGNITION SWITCHES



PM241	1955-56 Ignition Switch (NOS).....	Inquire
PM242	1957-58 Ignition Switch (NOS).....	Inquire
PM243	1959-61 Ignition Switch (NOS).....	Inquire
PM244	1962 Ignition Switch (NOS).....	Inquire
PM245	1963-64 Ignition Switch w/AC (NOS).....	50.00/ea.
PM246	1963-64 Ignition Switch w/o AC (NOS).....	50.00/ea.
PM247	1965 Ignition Switch (NOS).....	Inquire
PM248	1966 Ignition Switch (NOS).....	39.00/ea.
PM249	1967 Ignition Switch (NOS).....	39.00/ea.
PM250	1968 Ignition Switch (NOS).....	Inquire
PM251	1969-70 Ignition Switch (Exc. Tilt Wheel) - ALL (NOS).....	35.00/ea.
PM252	1971-77 Ignition Switch (Exc. Tilt Wheel) - ALL (GM)	21.00/ea.
PM253	1971-77 Ignition Switch (w/Tilt Wheel) - ALL (GM)	18.00/ea.

Many ignition switches have been discontinued for several years; please inquire concerning stock.

IGNITION LOCK CYLINDERS



PM260	1955-64 Ignition Lock Cylinder w/Original-Style Key (NOS).....	12.00/ea.
PM260A	1955-64 Ignition Lock Cylinder w/Late-Style Key (NOS)	9.00/ea.
PM265	1965 Ignition Lock Cylinder w/Original-Style Key (NOS).....	25.00/ea.
PM265A	1965 Ignition Lock Cylinder w/Late-Style Key (NOS)	Disc.
PM266	1966 Ignition Lock Cylinder w/Original-Style Key (NOS).....	Disc.
PM266A	1966 Ignition Lock Cylinder w/Late-Style Key (NOS)	Disc.
PM267	1967 Ignition Lock Cylinder w/Original-Style Key (NOS).....	Disc.
PM267A	1967 Ignition Lock Cylinder w/Late-Style Key (NOS)	Disc.
PM268	1968 Ignition Lock Cylinder w/Original-Style Key (NOS).....	16.00/ea.

RADIO SPEAKERS



PM305	1965-68 Radio Speaker, Front (NOS).....	Inquire
PM306	1969-70 Radio Speaker, Front - FS (GM).....	31.00/ea.
PM307	1971-72 Radio Speaker, Front - FS exc. SW (GM).....	Disc.
PM308	1971-72 Radio Speaker, Front - Exc. Stereo or Tape Player - FS (GM)	Disc.
PM309	1971-72 Radio Speaker w/Tape Player or Stereo - FS (GM)	11.00/ea.
PM310	1971-72 Radio Speaker, Rear - FS SW (GM) ..	22.00/ea.
PM311	1973-77 Radio Speaker, Rear (1 leadwire) (GM).....	Disc.
PM312	1976-77 Radio Speaker, Rear (2 leadwires) (GM).....	Disc.
PM320	1964-67 Reverb Mounting Bracket (RE).....	Disc.


This is the bracket that mounts the reverb unit behind the rear seat.

REAR SPEAKER ENCLOSURES



PM330

PM330	1964-65 Rear Speaker Enclosure, Exc. Conv. (RE).....	18.00/ea.
PM331	1966-70 Rear Speaker Enclosure - ALL exc. Conv. (RE)	18.00/ea.



PM331D

PM331D	1968-72 Rear Speaker Housing Bolt - Conv. (RE).....	5.00/ea.
PM332	1971-72 Rear Speaker Enclosure - GP (RE)	18.00/ea.

- PM333** 1971-77 Rear Speaker Enclosure - FS exc.
Conv. (GM) \$ 9.00/ea.
- PM333A** 1971-77 Rear Speaker Enclosure Bracket
- FS exc. Conv. (GM) Disc.
- PM333B** 1971-77 Rear Speaker Enclosure Retainer
- FS exc. Conv. (GM) 1.00/ea.

Most original cars equipped with rear speakers have long since lost their speaker enclosures. These reproductions are exact down to the special spring clip used for attachment. 1964-67 cars need one per car while the '68-'77 models used two.

ENGINE SENDING UNITS



PM353

- PM350** 1959-65 Oil Pressure Sending Unit
w/o Rally Gauges (GM) 4.50/ea.
- PM351** 1966-77 Oil Pressure Sending Unit
w/o Rally Gauges - ALL (GM) 4.50/ea.
- PM352** 1965-66 Oil Pressure Sending Unit
w/Rally Gauges 0-60 PSI - ALL (RP) 34.00/ea.
- PM353** 1967-77 Oil Pressure Sending Unit w/Rally
Gauges 0-80 PSI - ALL (GM) 35.00/ea.
- PM354** 1967-77 Oil Pressure Sending Unit
w/Rally Gauges (AP) 19.00/ea.
- Note:* At least one Pontiac year pre-1967 used a 0-80 psi Rally oil pressure gauge. PM353 or PM354 will serve as replacements for these cars.
- PM354K** 1959-72 Temperature Sending Unit w/o Rally
Gauges (Correct Single Terminal)
(NOS) 29.00/ea.
- PM355** 1959-69 Temperature Sending Unit w/o Rally
Gauges (Incorrect Double Terminal)
(AP) 15.00/ea.
- PM356** 1963-77 Temperature Sending Unit
w/Rally Gauges - ALL (GM) 14.50/ea.

IGNITION KEYS



PM366

- PM360** 1955-66 Ignition Key 1.50/ea.
Note: PM360 is original-style with the knockout removed. These no longer have Briggs & Stratton logo.
- PM362** 1967 Ignition Key - A 1.00/ea.
Note: PM362 uses late key design similar to PM366.
- PM363** 1967 Ignition Key - A (NOS) 3.50/ea.
Note: PM363 is original-style with knockout. These no longer have Briggs & Stratton logo.

- PM364** 1968 Ignition Key - C (GM) \$ 1.50/ea.
Note: PM364 uses the late key design similar to PM366.



PM365

- PM365** 1968 Ignition Key Blank - C (NOS) 3.50/ea.
Note: PM365 is original-style with knockout. These no longer have Briggs & Stratton logo.
- PM366** 1969 Ignition Key - E (GM) 1.50/ea.
- PM367** 1970 Ignition Key - J (GM) 1.50/ea.
- PM368** 1971 Ignition Key - A (GM) 1.50/ea.
- PM369** 1972 Ignition Key - C (GM) 1.50/ea.
- PM370** 1973 Ignition Key - E (GM) 1.50/ea.
- PM371** 1974 Ignition Key - J (GM) 1.50/ea.
- PM372** 1975 Ignition Key - A (GM) 1.50/ea.
- PM373** 1976 Ignition Key - C (GM) 1.50/ea.
- PM374** 1977 Ignition Key - E (GM) 1.50/ea.

HORNS AND RELAYS

- PM380** 1955-77 LH Horn (High Note) (GM) 35.00/ea.
- PM383** 1955-77 RH Horn (Low Note) (GM) 27.00/ea.
- PM400** 1955-56 Horn Relay (AP) 20.00/ea.
- PM401** 1957-58 Horn Relay (AP) 16.50/ea.
- PM402** 1959-62 Horn Relay (AP) 16.50/ea.

Note: This relay does not have the battery cable junction connection. For that style relay see PM403.



PM403

- PM403** 1961-64 Horn Relay (AP) 20.00/ea.
- PM401** 1966-67 Horn Relay (AP) 16.50/ea.
- PM406** 1968 Horn Relay (AP) 23.00/ea.
- PM407** 1969-71 Horn Relay (AP) 15.00/ea.
- PM408** 1972-76 Horn Relay (AP) 21.50/ea.
- PM409** 1977 Horn Relay (AP) 14.00/ea.

VOLTAGE REGULATORS



PM420

- PM420** 1955-62 Voltage Regulator (NOS) 49.00/ea.
This is an NOS Delco piece with correct inside adjustments and Delco Script cover.

PM423A 1969-70 "Delco Remy" Voltage Regulator, All exc. Internal Regulated Alternator (CSI option) (GM) \$ 32.00/ea.

DELCO REMY is stamped straight across cover unlike the original which was staggered.



BATTERIES



PM450 1955-60 Model 2SMR53 Tar Top Battery , 450 CCA (RE) 109.00/ea.

Note: PM450 does not have the exact original case configuration for 1955.

PM451 1961-65 Model DC12 (w/o Flange) Tar Top Battery, 500 CCA (RE) 109.00/ea.

PM452 1966 Model DC12 (w/Flange) Tar Top Battery, 500 CCA (RE) 109.00/ea.

Note: 1966 is a transition year between PM452 and PM453.

PM453 1966-71 Model R59 Energizer, 450 CCA (RE) 119.00/ea.

PM453B 1966-71 Model R59HC Energizer, 650 CCA (RE) 129.00/ea.

Very few 1971 applications used PM453 or PM453B (most cars were equipped with PM453D side terminal battery).

PM453D 1971-75 Model R89HC Side Terminal Battery 700 CCA (RE) 160.00/ea.

Note 1: These batteries all have group 24 dimensions (L = 10¹/₂", W = 6⁷/₈" and H = 8³/₄").

Note 2: Batteries must be prepaid and will be drop-shipped "dry-charged" from our distributor.

Note 3: Discounts do not apply to batteries.

Note 4: Please add \$14.00 shipping for batteries.

BATTERY CABLES



PM499J 1955 Top Post Battery Cables (RE) 47.00/pr.

PM499L 1956-57 Top Post Battery Cables (RE) 47.00/pr.

PM499N 1958 Top Post Battery Cables (RE) 47.00/pr.

PM500 1959-60 Battery Cables (RE) Inquire

PM503 1961-62 Battery Cables w/AC (RE) 53.00/pr.

PM505 1961-62 Battery Cables w/o AC (RE) 53.00/pr.

PM507 1963 Battery Cables, ALL exc. GP (RE) \$ 53.00/pr.

PM507A 1963 Battery Cables, GP (RE) 53.00/pr.

PM509 1964 Battery Cables w/Black Positive Lead (RE) 53.00/pr.

PM509A 1964 Battery Cables w/Red Positive Lead (RE) 53.00/pr.

It seems '64 could have either black or red positive lead wires. Please check your originals before ordering.

PM511 1965-66 Battery Cables (RE) Inquire

PM513 1967 Battery Cables (RE) Inquire

PM511 and PM513 are available with only one accessory lead. It appears a few '65-'67 cars had two accessory leads. Because of limited production, these cables are not available.

PM515 1968 Battery Cables (RE) Inquire

PM517 1969 Battery Cables - FS (RE) 53.00/pr.

PM519 1969 Battery Cables - GP (RE) Inquire

PM521 1970 Battery Cables - FS exc. 455 or HD Battery (RE) Inquire

PM523 1970 Battery Cables - FS w/455 or HD Battery (RE) Inquire

PM525 1970 Battery Cables - GP w/o HD Battery (RE) Inquire

PM527 1971 Battery Cables - GP w/o High Perf Engine (RE) Inquire

Comments: These cables have been researched using GM blueprints and scarce originals. The spring-ring casting has been used on concourse Corvettes for years.

Very good—Outside head diameter somewhat larger than original.

SIDE TERMINAL BATTERY CABLES



PM530H

PM530 1970 Negative Battery Cable - 455 HD (25" long) - FS (GM) 21.00/ea.

PM530C 1971 Negative Battery Cable - ALL 455 or HD (30" long) - FS (GM) 21.00/ea

PM530F 1971 Negative Battery Cable (35" long) - GP (GM) 18.00/ea.

PM530H 1972-77 Negative Battery Cable - ALL (GM) . 18.00/ea.

PM531B 1970 Positive Battery Cable - ALL 455 HD (55" long) (GM) 34.00/ea.

PM531D 1970 Positive Battery Cable - 350/400 Std. (63" long) - FS (GM) 34.00/ea.

PM531E 1970 Positive Battery Cable - 350/400 HD (53" long) - FS (GM) 21.00/ea.

PM531G 1971	Positive Battery Cable (45" long) - FS (GM).....	\$ 20.00/ea.
PM531B 1971	Positive Battery Cable (55" long) - GP (GM).....	34.00/ea.
PM531B 1972	Positive Battery Cable - 400 HD & 455 (55" long) - GP (GM).....	34.00/ea.
PM531J 1972	Positive Battery Cable - 400 Std. (55" long) - GP (GM).....	23.00/ea.
PM531K 1972-74	Positive Battery Cable - 350/400 Std. (50" & 24" Wire) - ALL (GM).....	21.00/ea.
PM531M 1973-74	Positive Battery Cable - 350/400 HD/ 455 (50" & 10" Wire) - ALL (GM).....	20.00/ea.
PM531J 1975-76	Positive Battery Cable (55" long) - ALL exc. HD Battery (GM).....	23.00/ea.
PM531B 1975-76	Positive Battery Cable (55" long) - ALL w/HD Battery (GM).....	34.00/ea.
PM531P 1977	Positive Battery Cable (65" long) - GP (GM).....	24.00/ea.

JUNCTION BLOCK STARTER CABLES



PM550

PM550	1959-60 Junction Block Starter Cable (40 inches long) (RE)	18.00/ea.
PM550	1961-62 Junction Block Starter Cable, Super Duty Only (40 inches long) (RE)	18.00/ea.
PM551	1961 Junction Block Starter Cable (30 inches long) (RE)	18.00/ea.
PM552	1962-64 Junction Block Starter Cable (24 inches long) (RE)	18.00/ea.

PM550 through PM552 is the black 4-gauge positive cable that connects the junction block to the starter. It comes complete with the correct fabric shielding.

WIRE LOOM AND WRAP



PM580	1/4" I.D. Split Ribbed Flexible Plastic Wire Loom (RE).....	1.00/ft.
PM581	3/8" I.D. Split Ribbed Flexible Plastic Wire Loom (RE).....	1.00/ft.

PM582	1/2" I.D. Split Ribbed Flexible Plastic Wire Loom (RE).....	\$ 1.00/ft.
PM583	3/4" I.D. Split Ribbed Flexible Plastic Wire Loom (RE).....	1.00/ft.
PM587	1/4" I.D. Tar Wire Loom (RE).....	1.00/ft.
PM588	3/8" I.D. Tar Wire Loom (RE).....	1.00/ft.
PM589	1/2" I.D. Tar Wire Loom (RE).....	1.00/ft.

PRINTED DASH CIRCUITS



PM620

PM620	1969-72 Printed Dash Circuit w/Rally Gauges - GP (RE).....	79.00/ea.
PM621	1969-72 Printed Dash Circuit w/o Rally Gauges - GP (RE).....	79.00/ea.



PM630

PM630	Wiring Harness Vinyl Wrap (RE)	12.00/100 ft. roll
--------------	--------------------------------------	-----------------------

This is the original style non-adhesive vinyl wrap commonly used on all GM cars. This is non-electrical tape.



Visit us on the

World Wide Web

<http://www.amesperf.com>

email: customer.service@amesperf.com

WIRING HARNESSES



We carry an extensive line of wiring harnesses to solve your electrical problems. These harnesses are made to exact original specifications making installation a simple plug-in operation.

Please refer to the following abbreviations when ordering wiring harnesses.

UNIT. DIST. = UNITIZED DISTRIBUTOR
 TI = TRANSISTORIZED IGNITION
 RA = RAM AIR
 AC = AIR CONDITIONING
 AT = AUTOMATIC TRANSMISSION
 MT = MANUAL TRANSMISSION
 DEF = DEFROSTER

EXT. REG. = EXTERNAL REGULATOR (VOLTAGE REGULATOR MOUNTED ON CORE SUPPORT)
 INT. REG. = INTERNAL REGULATOR (VOLTAGE REGULATOR IN ALTERNATOR)
 HD = HEAVY DUTY
 PW = POWER WINDOWS
 ATC = AUTOMATIC TEMPERATURE CONTROL

We carry an extensive line of wiring harnesses for 1964-74 full size and 1969-74 Grand Prix models. We can provide engine, forward light, dash and air conditioning harnesses for most 1955-63 models. Please inquire with specific needs and for prices.

Harnesses will be shipped directly to you from our west coast manufacturer. Allow 4-6 weeks for delivery.

ENGINE HARNESSES

For 1955-63 Engine Harnesses look in Dash Harness section.

04555	1964	Engine Harness, V-8	\$ 89.00/ea.
05190	1964	Engine Harness, V-8	
		w/AC.....	94.00/ea.
05925	1965	Engine Harness, V-8	89.00/ea.
05930	1965	Engine Harness, V-8	
		w/Std. AC	94.00/ea.
06050	1965	Engine Harness, V-8	
		w/ATC-AC.....	94.00/ea.
09345	1966	Engine Harness, V-8	89.00/ea.
09545	1966	Engine Harness, V-8	
		w/Std. AC	94.00/ea.
09550	1966	Engine Harness, V-8	
		w/ATC-AC.....	94.00/ea.
10230	1967	Engine Harness, V-8	89.00/ea.
10235	1967	Engine Harness, V-8	
		w/Std. AC	94.00/ea.
10240	1967	Engine Harness, V-8	
		w/ATC-AC.....	94.00/ea.
10290	1967	Engine Harness, V-8	
		w/TI.....	104.00/ea.
10295	1967	Engine Harness, V-8	
		w/TI & Std. AC.....	104.00/ea.
10300	1967	Engine Harness, V-8	
		w/TI & ATC-AC	104.00/ea.
11355	1968	Engine Harness, V-8	125.00/ea.
11350	1968	Engine Harness, V-8	
		w/AC.....	125.00/ea.
12175	1968	Engine Harness, V-8	
		w/Int. Reg.	125.00/ea.
12180	1968	Engine Harness, V-8	
		w/Int. Reg. & AC.....	125.00/ea.

Note 1: Please specify when ordering 64-68 engine harnesses if you have a 2-wire or 4-wire voltage regulator.

Note 2: Please send original firewall harness plug when ordering 64-68 engine harnesses.

13290A	1969	Engine Harness,	
		V-8.....	\$129.00/ea.
12845	1969	Engine Harness, V-8	
		w/Gauges.....	125.00/ea.
12850	1969	Engine Harness, V-8	
		w/Int. Reg.	125.00/ea.
12855	1969	Engine Harness, V-8	
		w/Int. Reg. & Gauges ...	125.00/ea.
12860	1969	Engine Harness, V-8	
		w/HD Alt. (62 amp).....	125.00/ea.
13480	1969	Engine Harness, V-8	
		w/HD Alt. (62 amp)	
		& Gauges.....	125.00/ea.
13650	1970	Engine Harness, V-8,	
		MT-FS.....	135.00/ea.
13690	1970	Engine Harness, V-8,	
		MT, w/Gauges-FS,	
		B-body.....	135.00/ea.
13710	1970	Engine Harness, V-8,	
		MT w/HD Alt. (62 amp)	
		-FS.....	135.00/ea.
13705	1970	Engine Harness, V-8,	
		AT-FS.....	135.00/ea.
13700	1970	Engine Harness, V-8,	
		AT w/Gauges-FS.....	135.00/ea.
15580	1970	Engine Harness, V-8,	
		AT w/HD Alt. (62 amp)	
		-FS.....	135.00/ea.
15560	1970	Engine Harness, V-8,	
		MT-GP.....	139.00/ea.
15565	1970	Engine Harness, V-8,	
		AT-GP.....	139.00/ea.
16070	1971	Engine Harness, V-8,	
		350, AT-FS.....	135.00/ea.
15915	1971	Engine Harness, V-8,	
		350, MT-FS.....	135.00/ea.

16705	1971	Engine Harness, V-8,	
		ALL w/Unit. Dist.-FS.....	\$135.00/ea.
16065	1971	Engine Harness, V-8,	
		AT-GP.....	139.00/ea.
16060	1971	Engine Harness, V-8,	
		MT-GP.....	139.00/ea.
16075	1971	Engine Harness, V-8,	
		ALL w/Unit. Dist.-GP ...	135.00/ea.
16955	1972	Engine Harness, V-8	
		-FS.....	145.00/ea.
16970	1972	Engine Harness, V-8	
		w/Unit. Dist.-FS.....	145.00/ea.
16945	1972	Engine Harness, V-8	
		-GP.....	145.00/ea.
16950	1972	Engine Harness, V-8	
		w/Unit. Dist.-GP.....	149.00/ea.
17030	1973	Engine Harness, V-8	149.00/ea.
17085	1973	Engine Harness, V-8	
		w/Unit. Dist.	145.00/ea.
17060	1974	Engine Harness, V-8	149.00/ea.
17110	1974	Engine Harness, V-8	
		w/Unit. Dist.	149.00/ea.

AIR CONDITIONING HARNESSES

02270	1956	Air Conditioning	
		Harness.....	95.00/ea.
02595	1957	Air Conditioning	
		Harness.....	95.00/ea.
02780	1958	Air Conditioning	
		Harness.....	95.00/ea.
02870	1959	Air Conditioning	
		Harness w/Circulaire ...	95.00/ea.
02915	1959	Air Conditioning	
		Harness w/Cool Pack ..	45.00/ea.
03220	1960	Air Conditioning	
		Harness w/Circulaire ...	95.00/ea.
03170	1960	Air Conditioning	
		Harness w/Cool Pack ..	45.00/ea.

03605	1961	Air Conditioning Harness w/Circulaire ...	\$ 95.00/ea.
03585	1961	Air Conditioning Harness w/Cool Pack ..	45.00/ea.
03835	1962	Air Conditioning Harness w/Cool Pack (Universal).....	45.00/ea.
04425	1963	Air Conditioning Harness, Field Installed.	95.00/ea.
04585	1964	Air Conditioning Harness, Field Installed.	95.00/ea.
05180	1964	Air Conditioning Harness, Factory Installed.....	95.00/ea.
05820	1965	Air Conditioning Harness, Field Installed.	95.00/ea.
05725	1965	Air Conditioning Harness, Std.	95.00/ea.
05880	1965	Air Conditioning Harness w/ATC.....	95.00/ea.
06260	1958	Air Conditioning Extension Harness, Clutch Wire w/Cool Pack.....	12.00/ea.
06260	1959	Air Conditioning Extension Harness, Clutch Wire w/Cool Pack.....	12.00/ea.

DASH HARNESES

02210	1955	Dash & Engine Compt. Harness w/Directional Signals.....	452.00/ea.
02265	1956	Dash & Engine Compt. Harness w/Directional Signals.....	452.00/ea.
02420	1957	Dash & Engine Compt. Harness.....	452.00/ea.

Note: Please send us original fuse blocks when ordering 58-64 dash harnesses. New blocks are not available.

02675	1958	Dash & Engine Compt. Harness.....	452.00/ea.
02795	1959	Dash & Engine Compt. Harness.....	485.00/ea.
00985	1959	Dash & Engine Compt. Harness w/AC.....	485.00/ea.
03225	1960	Dash & Engine Compt. Harness w/Manual Control Heater	485.00/ea.
03055	1960	Dash & Engine Compt. Harness w/Push Button Control Heater .	485.00/ea.
03060	1960	Dash & Engine Compt. Harness w/AC.....	485.00/ea.
03440	1961	Dash Instrument Cluster Extension Harness	59.00/ea.
03445	1961	Dash & Engine Compt. Harness w/Manual Control Heater.....	485.00/ea.
03450	1961	Dash & Engine Compt. Harness w/Push Button Control Heater .	485.00/ea.

03455	1961	Dash & Engine Compt. Harness w/AC.....	\$485.00/ea.
03440	1962	Dash Instrument Cluster Extension Harness	59.00/ea.
03775	1962	Dash & Engine Compt. Harness w/Push Button Control Heater .	485.00/ea.
04040	1962	Dash & Engine Compt. Harness w/AC and Alt.	485.00/ea.
03780	1962	Dash & Engine Compt. Harness w/AC and Gen.....	485.00/ea.
04065	1963	Dash & Engine Harness.....	429.00/ea.
04310	1963	Dash & Engine Harness w/AC.....	429.00/ea.
04545	1964	Dash Harness, Col. Shift, AT or ALL MT....	429.00/ea.
04550	1964	Dash Harness, Col. Shift, AT or ALL MT w/AC.....	429.00/ea.
05120	1964	Dash Harness, Console Shift, AT	429.00/ea.
05125	1964	Dash Harness, Console Shift, AT w/AC	429.00/ea.

Note: Please send us original fuse blocks when ordering 58-64 dash harnesses. New blocks are not available.

00975	1965	Dash Harness, Col. Shift, AT or ALL MT.....	429.00/ea.
05980	1965	Dash Harness, Col. Shift, AT or ALL MT w/Std. AC	429.00/ea.
09265	1965	Dash Harness, Col. Shift, AT or ALL MT w/ATC-AC.....	429.00/ea.
05990	1965	Dash Harness, Console Shift, AT	429.00/ea.
05985	1965	Dash Harness, Console Shift, AT w/Std. AC	429.00/ea.
00980	1965	Dash Harness, Console Shift, AT w/ATC-AC.....	429.00/ea.
09335	1966	Dash Harness, Col. Shift, AT or ALL MT.....	429.00/ea.
09350	1966	Dash Harness, Col. Shift, AT or ALL MT w/Gauges.....	429.00/ea.
09340	1966	Dash Harness, Console Shift, AT	429.00/ea.
09355	1966	Dash Harness, Console Shift, AT w/Gauges	429.00/ea.
10360	1967	Dash Harness, Col. Shift, AT or ALL MT.....	429.00/ea.
10515	1967	Dash Harness, Col. Shift, AT or ALL MT w/Gauges.....	429.00/ea.
10365	1967	Dash Harness, Console Shift, AT	429.00/ea.
10520	1967	Dash Harness, Console Shift, AT w/Gauges	429.00/ea.
11330	1968	Dash Harness, Col. Shift, AT or ALL MT.....	429.00/ea.

11340	1968	Dash Harness, Col. Shift, AT or ALL MT w/Gauges.....	\$429.00/ea.
11335	1968	Dash Harness, Console Shift, AT	429.00/ea.
11345	1968	Dash Harness, Console Shift, AT w/Gauges.....	429.00/ea.
12810	1969	Dash Harness-FS.....	429.00/ea.
12815	1969	Dash Harness-FS w/Gauges.....	429.00/ea.
13530	1969	Dash Harness-GP	429.00/ea.
13535	1969	Dash Harness-GP w/Gauges.....	429.00/ea.
15835	1970	Dash Harness-FS.....	429.00/ea.
15840	1970	Dash Harness-FS w/Gauges.....	429.00/ea.
15845	1970	Dash Harness-GP	429.00/ea.
15850	1970	Dash Harness-GP w/Gauges.....	429.00/ea.
16215	1971	Dash Harness-FS, ALL .	429.00/ea.
16225	1971	Dash Harness-GP	429.00/ea.
16670	1971	Dash Harness-GP w/Gauges.....	429.00/ea.
17295	1973	Dash Harness-GP w/Gauges.....	429.00/ea.
17305	1974	Dash Harness-GP w/Gauges.....	429.00/ea.

Note: Discounts do not apply to dash harnesses.

FORWARD LAMP HARNESES

04060	1963	Forward Lamp Harness.....	125.00/ea.
04560	1964	Forward Lamp Harness.....	139.00/ea.
05615	1965	Forward Lamp Harness.....	139.00/ea.
09360	1966	Forward Lamp Harness.....	139.00/ea.
10305	1967	Forward Lamp Harness-FS.....	139.00/ea.
10310	1967	Forward Lamp Harness-GP.....	149.00/ea.
11360	1968	Forward Lamp Harness-FS.....	139.00/ea.
11365	1968	Forward Lamp Harness-GP.....	149.00/ea.

Note: Please send original firewall harness plug when ordering 64-68 forward lamp harnesses.

13400	1969	Forward Lamp Harness-FS.....	139.00/ea.
12905	1969	Forward Lamp Harness-GP.....	139.00/ea.
13695	1970	Forward Lamp Harness-FS.....	139.00/ea.
13620	1970	Forward Lamp Harness-GP.....	139.00/ea.
13625	1970	Forward Lamp Harness-GP w/Cornering Lamps	139.00/ea.
15895	1971	Forward Lamp Harness-FS.....	139.00/ea.

15900 1971 Forward Lamp
Harness-GP.....\$139.00/ea.

LAMP EXTENSION HARNESSSES

04270 1963 Lamp Extension
Harness, Dash Harness
to Ammeter, Clock &
Gas Gauge Lamps 15.00/ea.
05765 1965 Lamp Extension
Harness, Dash Harness
to Clock..... 9.00/ea.
06185 1965 Lamp Extension
Harness, Dash Harness
to Vacuum Gauge 9.00/ea.
09595 1966 Lamp Extension
Harness, Dash Harness
to Heater or AC Con-
trol Panel Indicator 9.00/ea.

TACHOMETER HARNESSSES

04000 1962 Tachometer Harness.... 25.00/ea.
04250 1963 Tachometer Harness.... 25.00/ea.
04320 1963 Tachometer Harness
w/TI..... 29.00/ea.
04605 1964 Tachometer Harness.... 25.00/ea.
04610 1964 Tachometer Harness
w/TI..... 29.00/ea.
06245 1965 Tachometer Harness.... 25.00/ea.
06250 1965 Tachometer Harness
w/TI..... 29.00/ea.
06245 1966 Tachometer Harness.... 25.00/ea.
10050 1966 Tachometer Harness
w/TI..... 29.00/ea.
11040 1967 Tach. Harness, Hood
Mounted..... 15.00/ea.
12380 1968 Tach. Harness, Dash
Mounted..... 12.00/ea.
12375 1968 Tach. Harness, Dash
Mounted..... 15.00/ea.
12380 1969 Tach. Harness, Dash
Mounted-GP..... 12.00/ea.
17250 1969 Tach. Harness, Hood
Mounted-GP..... 15.00/ea.

15645 1970 Tach. Harness, Dash
Mounted-GP..... \$ 12.00/ea.
17250 1970 Tach. Harness, Hood
Mounted-GP..... 15.00/ea.
15645 1971 Tach. Harness, Dash
Mounted w/o Unit. Dist.
-GP..... 12.00/ea.
17360 1971 Tach. Harness, Dash
Mounted w/Unit. Dist.
-GP..... 12.00/ea.
17250 1971 Tach. Harness, Hood
Mounted-GP..... 15.00/ea.
16885 1972 Tach. Harness, Dash
Mounted w/o Unit. Dist.
-GP..... 12.00/ea.
16890 1972 Tach. Harness, Dash
Mounted w/Unit. Dist.
-GP..... 12.00/ea.
17250 1972 Tach. Harness, Hood
Mounted-GP..... 15.00/ea.

These tach harnesses work only with original
tachometers.

CONSOLE HARNESSSES

05595 1964 Console Harness, AT ... 59.00/ea.
06190 1965 Console Harness, AT ... 59.00/ea.
00970 1965 Console Harness, MT .. 14.00/ea.
10045 1966 Console Harness, AT ... 39.00/ea.
09555 1966 Console Harness, MT .. 14.00/ea.
10045 1967 Console Harness, AT ... 39.00/ea.
11135 1967 Console Harness, MT .. 14.00/ea.
10045 1968 Console Harness, AT ... 39.00/ea.
11135 1968 Console Harness, MT .. 14.00/ea.

TAILLIGHT HARNESSSES

08980 1963 Rear Lamp Harness
-GP..... 95.00/ea.
06500 1963 Rear Lamp Harness,
Intermediate-GP..... 95.00/ea.
06840 1964 Rear Lamp Harness
-GP..... 95.00/ea.
06500 1964 Rear Lamp Harness,
Intermediate-GP..... 95.00/ea.

SPEED WARNING HARNESSSES

09560 1966 Speed Warning
Harness..... \$ 19.00/ea.
09560 1967 Speed Warning
Harness..... 19.00/ea.
09560 1968 Speed Warning
Harness..... 19.00/ea.
13500 1969 Speed Warning
Harness..... 12.00/ea.
13645 1970 Speed Warning
Harness..... 12.00/ea.

GAUGE HARNESSSES

07105 1964 Auxiliary Gauge Panel
Harness w/Aux.
Gauges..... 39.00/ea.
06240 1965 Auxiliary Gauge Panel
Harness w/Aux.
Gauges..... 39.00/ea.

MISCELLANEOUS HARNESSSES

WHEN PLACING AN ORDER FOR WIRING
HARNESSSES, PLEASE INCLUDE THE FOLLOW-
ING INFORMATION:

YEAR
ENGINE SIZE
TRANSMISSION
WITH OR WITHOUT FACTORY GAUGES
TACHOMETER (IN DASH OR HOOD MOUNT-
ED)
CONSOLE OR COLUMN SHIFT
COUPE OR CONVERTIBLE
AIR CONDITIONING
NON-FACTORY COMPONENTS
POWER OPTIONS
INTEGRAL REGULATOR WITH ALTERNATOR
UNITIZED DISTRIBUTOR



DON'T GET TRAPPED!

Don't get trapped by high prices in the Pontiac industry. Some suppliers continue to charge unrealistic prices for their products while we here at Ames Performance have tried to keep the lid on price increases.

For ordering or price quotations, please call (800) 421-2637.
For questions or ordering, call (603) 876-3345
(603) 876-4656
(603) 876-4751

SECTION TWELVE - ENGINE COMPONENTS

TRI-POWER AIR CLEANERS

Important Note: The following Tri-Power air cleaner components are correct for some 1965 and all '66 units. We have listed complete sets and components for earlier models for those people who want the three single air cleaner setup.



- PN100** 1957-58 Tri-Power Air Cleaners, Complete w/GM A220C Paper Elements (RE) . \$109.00/set
- PN101** 1959-65 Tri-Power Air Cleaners, Complete w/GM A220C Paper Elements (RE) . 109.00/set
- PN102** 1966 Tri-Power Air Cleaners, Complete w/GM A220C Paper Elements (RE) . 109.00/set



- PN103** 1957-58 Tri-Power Air Cleaners, Complete w/Reproduction A193C Foam Elements and Screens (RE) 149.00/set
- PN104** 1959-65 Tri-Power Air Cleaners, Complete w/Reproduction A193C Foam Elements and Screens (RE) 149.00/set
- PN105** 1966 Tri-Power Air Cleaners, Complete w/Reproduction A193C Foam Elements and Screens (RE) 149.00/set
- PN105P** 1959-65 Tri-Power Air Cleaners, Complete - California Only w/GM A220C Paper Elements (RE) 175.00/set
- PN105R** 1966 Tri-Power Air Cleaners, Complete - California Only w/GM A220C Paper Elements (RE) Disc.
- PN105S** 1959-65 Tri-Power Air Cleaners, Complete - California Only w/Reproduction A193C Foam Elements and Screens (RE)..... 215.00/set
- PN105T** 1966 Tri-Power Air Cleaners, Complete - California Only w/Reproduction A193C Foam Elements and Screens (RE)..... Disc.

We have supplied these reproduction air cleaner sets with A220C and foam elements for years. During this time, Pontiac enthusiasts nationwide have received fine cover chrome and exact detailing of both covers and bases.

Comments: Excellent.

Note: See PN212 and PN214 for wing nuts and carb studs.



- PN106** 1957-66 Tri-Power Chrome Cover (RE) \$ 20.00/ea.
- PN107** 1957-58 Tri-Power Air Cleaner Base - ALL, Small (RE) 15.00/ea.
- PN107** 1959-65 Tri-Power Air Cleaner Base, Center, Small (RE) 15.00/ea.
- PN108** 1959-66 Tri-Power Air Cleaner Base, Large, 1959-65 End, 1966 ALL (RE) 15.00/ea.



PN108K

- PN108K** 1959-65 Tri-Power Air Cleaner Bases, California Only (Set of 3) (RE) 120.00/set
- PN108L** 1966 Tri-Power Air Cleaner Bases, California Only (Set of 3) (RE) Disc.
- PN109** 1957-66 Tri-Power Paper Air Cleaner Elements A220C (Set of 3) (GM) 18.00/set
- PN109B** 1957-58 Tri-Power Lids & Bases Only (RE).... 95.00/set
- PN110** 1959-65 Tri-Power Lids & Bases Only (RE).... 95.00/set
- PN111** 1966 Tri-Power Lids & Bases Only (RE).... 95.00/set



- PN112** 1957-66 Tri-Power Foam Air Cleaner Elements A193C (*Note:* NOS is used in photo) (Set of 3) (RE) 30.00/set

Although this foam does not have the AC logo it does have the correct cell structure and is embossed with the A193C imprint. The only other

difference between these and originals is they are manufactured without the thin inner lip around the top and bottom. This is not noticeable when the air cleaners are assembled.

Comments: Good.

- PN113** 1957-66 Tri-Power Air Cleaner Screens for use w/Foam Elements (*Note:* NOS is used in photo) (Set of 3) (RE) \$ 30.00/set

These screens are used with the PN112 foam elements to complete the four-piece air cleaner assembly.

Comments: Very close to original. We are using similar steel and original style fine wire screen to keep large particles from piercing the foam and entering the engine.

TRI-POWER FUEL LINES



PN118

- PN114** 1957 Tri-Power Fuel Lines (RE) 35.00/set
PN114A 1958 Tri-Power Fuel Lines (Steel) w/4-Way Fuel Block and 3-90° Fittings (RE)..... 60.00/set
PN115 1959-60 Tri-Power Fuel Lines (Steel) w/4-Way Fuel Block and 3-90° Fittings (RE)..... 60.00/set
PN115A 1959-60 Tri-Power Fuel Lines (Steel) w/4-Way Fuel Block, Front and Rear 105° Fittings and 90° Center Fittings (RE)..... 70.00/set
PN116 1961-62 Tri-Power Fuel Lines (Aluminum) w/4-Way Fuel Block and 3-90° Fittings (RE)..... 55.00/set
PN116A 1961-62 Tri-Power Fuel Lines (Aluminum) w/4-Way Fuel Block, Front and Rear 105° Fittings and 90° Center Fitting (RE) 70.00/set
PN117 1963 Tri-Power Fuel Lines (Aircraft Aluminum) w/4-Way Fuel Block and 3-90° Fittings (RE)..... 55.00/set
PN117A 1963 Tri-Power Fuel Lines (Aircraft Aluminum) w/4-Way Fuel Block, Center and Rear 90° Fittings and Front 105° Fitting (RE) 60.00/set
PN118 1964-65 Tri-Power Fuel Lines w/3-Way Fuel Block, Center 45° Fitting and Rear 90° Fitting (RE) 48.00/set
PN118A 1964-65 Tri-Power Fuel Lines w/3-Way Fuel Block, Center 45° Fitting and Rear 105° Fitting (RE) 55.00/set

- PN119** 1966 Tri-Power Fuel Lines w/Front Carb. Fuel Block, Center and Rear 90° Fittings (RE)..... \$ 48.00/set
PN119A 1966 Tri-Power Fuel Lines w/Front Carb. Fuel Block, Center and Rear 105° Fittings (RE)..... 62.00/set

We are making many of our own fuel lines to insure highest quality and fit. All fuel line kits use the original design fuel blocks (made by Weatherhead and authentic down to the logo). The PN115, PN116, PN117, PN118, and PN119 kits use the Weatherhead replacement 90° fitting where applicable. This is the same fitting we've used satisfactorily for years. For the serious restorer we offer the correct 105° fitting to be used in the PN115A, PN116A, PN117A, PN118A, and PN119A kits.

Comments: Excellent. With the 105° fitting we can offer the ultimate in fuel line kits.

- PN123** 1958 Tri-Power Fuel Lines w/o Fittings (RE)..... 35.00/set
PN124 1959-60 Tri-Power Fuel Lines w/o Fittings (RE)..... 35.00/set
PN125 1961-62 Tri-Power Fuel Lines w/o Fittings (RE)..... 35.00/set
PN125A 1963 Tri-Power Fuel Lines w/o Fittings (RE)..... 35.00/set
PN126 1964-65 Tri-Power Fuel Lines w/o Front Carb Fuel Block but w/45° and 90° Fittings (RE)..... 35.00/set
PN127 1966 Tri-Power Fuel Lines w/o Front Carb. Fuel Block but w/Two 90° Fittings (RE)..... 35.00/set



PN128

- PN128** 1966 Tri-Power Center Carb. Fitting (RE) .. 15.00/ea.
This is an inexpensive way to save your center carb when the fitting threads become stripped.

FUEL LINE FITTINGS



PN136

PN135

- PN133** 1958-60 Tri-Power 4-Way Fuel Block (Weatherhead)..... 30.00/ea.
PN134 1961-63 Tri-Power 4-Way Fuel Block (Weatherhead)..... 27.00/ea.
PN135 1964-66 Tri-Power Fuel Block (Weatherhead)..... 20.00/ea.
PN136 1958-66 Fuel Line Fitting—105° (Weatherhead)..... 10.00/ea.

PN137	1959-66 Fuel Line Fitting—90° (Weatherhead).....	\$ 1.50/ea.
PN138	1964-65 Fuel Line Fitting—45° (Weatherhead).....	1.50/ea.

2-BARREL AND 4-BARREL FUEL LINES



PN139T	1955-56 4-Barrel Fuel Line (RE)	23.00/ea.
PN141	1957 Bonneville Fuel Line - FI (RE)	Disc.
PN142	1957 4-Barrel Fuel Line - 2 pc. (RE).....	23.00/pr.
PN147	1961 2-Barrel Fuel Line (RE)	23.00/ea.
PN148	1961-62 4-Barrel Fuel Line (RE)	23.00/ea.
PN148C	1962 SD 2- 4-Barrel Fuel Line Set w/ Brass "T" (RE)	39.00/set
PN149C	1963 SD 2- 4-Barrel Fuel Line Set w/ Brass "T" (RE)	39.00/set
PN150	1964 4-Barrel Fuel Line (RE)	15.00/ea.
PN151	1965 4-Barrel Fuel Line (RE)	15.00/ea.
PN152	1966 4-Barrel Fuel Line (RE)	10.00/ea.
PN154	1967 2-Barrel Fuel Line (RE)	23.00/ea.
PN154D	1967 Carter AFB 4-Barrel Fuel Line (RE) ...	23.00/ea.
PN155	1967 Rochester 4-Barrel Fuel Line w/o AC or 428 (RE)	23.00/ea.
PN156	1967 Rochester 4-Barrel Fuel Line w/AC or 428 (RE)	45.00/ea.
PN159	1968-72 2-Barrel Fuel Line (RE)	23.00/ea.
PN160	1968 4-Barrel Fuel Line (RE)	23.00/ea.
PN163	1969-Early '70 4-Barrel Fuel Line (RE)	23.00/ea.

This line runs past the thermostat housing on the driver's side and is compatible with bottom outlet fuel pumps.

PN164	1969-Early '70 4-Barrel Fuel Line (RE)	23.00/ea.
--------------	---	-----------

This line runs past the thermostat housing on the passenger's side and is compatible with bottom outlet fuel pumps.

PN165	Late 1970-72 4-Barrel Fuel Line (RE)	23.00/ea.
--------------	---	-----------

This line runs past the thermostat housing on the driver's side and is compatible with side outlet fuel pumps.

PN165K	Late 1970-72 4-Barrel Fuel Line (RE)	23.00/ea.
---------------	---	-----------

This line runs past the thermostat housing on the passenger's side and is compatible with side outlet fuel pumps.

PN166	Late 1970-74 4-Barrel Fuel Line w/Pont. V-8 (RE) .	23.00/ea.
--------------	---	-----------

This line is usually associated with standard horsepower engines. It runs up the driver's side, then over and has a 5 1/2" straight into the front of the carburetor. It is compatible with side outlet fuel pumps.

PN170	1971-74 4-Barrel Fuel Line w/Pont. V-8 (RE) . \$	23.00/ea.
--------------	--	-----------

This fuel line enters into the front of the bowl on the carburetor.




PN171	1975-77 4-Barrel Fuel Line w/o Foam Cover w/Pont. V-8	23.00/ea.
--------------	--	-----------

FUEL PUMPS AND FITTINGS



PN173MA	1959-66 Brass Fuel Pump 90° Fitting (RP)	5.00/ea.
PN173PD	1959-65 Fuel Pump - ALL exc. 65 w/421 (AC-Delco).....	25.00/ea.
PN173PG	1966 Fuel Pump - ALL & 65 421 (AC-Delco).....	25.00/ea.
PN173PJ	1967 Fuel Pump - 400 w/o AC (AC-Delco).....	25.00/ea.
PN173PK	1967 Fuel Pump - 400 w/AC or 428 (AC-Delco).....	27.00/ea.
PN173PM	1968 Fuel Pump - 400 w/o AC (AP).....	28.00/ea.
PN173PN	1968 Fuel Pump - 400 w/AC or 428 (AC-Delco).....	25.00/ea.
PN173PP	1969 Fuel Pump w/o Vapor Return (AC-Delco).....	25.00/ea.
PN173PR	1969 Fuel Pump w/Vapor Return (AC-Delco).....	25.00/ea.
PN173PR	1970 Fuel Pump - GP, 2 BBL (AC-Delco)	25.00/ea.



PN173PT	1970 Fuel Pump - GP, 4 BBL w/Vapor Return, 1st Design (AP)	25.00/ea.
PN173PV	1970 Fuel Pump - GP, 4 BBL w/Vapor Return, 2nd Design (AC-Delco).....	29.00/ea.
PN173PZ	1971 Fuel Pump, 4 BBL w/AC (AP).....	27.00/ea.
PN173RC	1972-74 Fuel Pump, 4 BBL w/AC (AC-Delco).....	26.00/ea.
PN173RF	1973 Fuel Pump, 2 BBL w/AC (AC-Delco).....	25.00/ea.



PN174BG

PN174BG	1963-67 Fuel Pump to Timing Chain Cover Bolt Kit with Correct 12 Point Heads, ALL V-8 (RP)	\$ 5.50/kit
PN174BN	1968-77 Fuel Pump to Timing Chain Cover Bolt Kit, ALL V-8 (RP)	2.50/kit

Note: PN174BG and PN174BN are replacement bolts that will not have the same markings as original.



RUBBER FUEL HOSE



PN174DB


PN174DB	"Gas, Gas" Printed Rubber Fuel Hose, 3/8" (RE).....	3.00/ft
This is the correct printed fuel hose used on various years.		
PN174DJ	Replacement 5/16" Rubber Fuel Hose (RE) ..	1.00/ft
PN174DK	Replacement 3/8" Rubber Fuel Hose (RE)...	1.00/ft

VACUUM AND FUEL LINE CLAMPS



PN175K	3/8" O.D. Hose Clamp (Black)(AP)...	.50/ea.
PN175L	7/16" O.D. Hose Clamp (Green)(AP)50/ea.
PN175M	1/2" O.D. Hose Clamp (Red)(AP)50/ea.
PN175N	9/16" O.D. Hose Clamp (Black)(AP)50/ea.
PN175P	5/8" O.D. Hose Clamp (Green)(AP)50/ea.
PN175R	1 1/16" O.D. Hose Clamp (Red)(AP) ..	.50/ea.
PN175S	3/4" O.D. Hose Clamp (Black)(AP)...	.75/ea.

FRONT TO REAR FUEL LINES AND RETURN LINES



Note: 55-60 Fuel Lines will soon be available. Please inquire if you don't see your application listed.

PN177JA	1961-62 Front to Rear Fuel Line - Cat/GP 3/8" steel (RE)	\$ 65.00/ea.
PN177JB	1961-62 Front to Rear Fuel Line - Cat/GP 3/8" stainless steel (RE)	99.00/ea.
PN177JE	1961-62 Front to Rear Fuel Line - Ventura 3/8" steel (RE)	65.00/ea.
PN177JF	1961-62 Front to Rear Fuel Line - Ventura 3/8" stainless steel (RE)	99.00/ea.
PN177JJ	1961-62 Front to Rear Fuel Line - Bonne 3/8" steel (RE)	65.00/ea.
PN177JK	1961-62 Front to Rear Fuel Line - Bonne 3/8" stainless steel (RE)	99.00/ea.
PN177JN	1963-64 Front to Rear Fuel Line - Cat/GP 3/8" steel (RE)	65.00/ea.
PN177JP	1963-64 Front to Rear Fuel Line - Cat/GP 3/8" stainless steel (RE)	99.00/ea.
PN177JQ	1963-64 Return Line - Cat/GP - 1/4" steel (RE)	65.00/ea.
PN177JR	1963-64 Return Line - Cat/GP - 1/4" stainless steel (RE)	99.00/ea.
PN177JV	1963-64 Front to Rear Fuel Line - Bonne 3/8" steel (RE)	65.00/ea.
PN177JW	1963-64 Front to Rear Fuel Line - Bonne 3/8" stainless steel (RE)	99.00/ea.
PN177JX	1963-64 Return Line - Bonne 1/4" steel (RE)	65.00/ea.
PN177JY	1963-64 Return Line - Bonne 1/4" stainless steel (RE)	99.00/ea.
PN177KE	1965-66 Front to Rear Fuel Line - Cat/GP 3/8" steel (RE)	65.00/ea.
PN177KF	1965-66 Front to Rear Fuel Line - Cat/GP 3/8" stainless steel (RE)	99.00/ea.
PN177KJ	1965-66 Front to Rear Fuel Line - Bonne 3/8" steel (RE)	65.00/ea.
PN177KK	1965-66 Front to Rear Fuel Line - Bonne 3/8" stainless steel (RE)	99.00/ea.
PN177KQ	1967-68 Front to Rear Fuel Line - Cat 3/8" steel (RE)	65.00/ea.
PN177KR	1967-68 Front to Rear Fuel Line - Cat 3/8" stainless steel (RE)	99.00/ea.
PN177KV	1967-68 Front to Rear Fuel Line - GP 3/8" steel (RE)	65.00/ea.
PN177KW	1967-68 Front to Rear Fuel Line - GP 3/8" stainless steel (RE)	99.00/ea.
PN177LC	1967-68 Front to Rear Fuel Line - Bonne 3/8" steel (RE)	Inquire
PN177LD	1967-68 Front to Rear Fuel Line - Bonne 3/8" stainless steel (RE)	Inquire
PN177LL	1969 Front to Rear Fuel Line - GP 3/8" steel (RE)	65.00/ea.
PN177LM	1969 Front to Rear Fuel Line - GP 3/8" stainless steel (RE)	99.00/ea.
PN177LN	1969 Return Line - GP - 1/4" steel (RE)	65.00/ea.
PN177LP	1969 Return Line - GP 1/4" stainless steel (RE)	99.00/ea.
PN177LS	1970-72 Front to Rear Fuel Line - GP 3/8" steel (RE)	65.00/ea.

PN177LT	1970-72 Front to Rear Fuel Line - GP 3/8" stainless steel (RE)	\$ 99.00/ea.
PN177LV	1970-72 Return Line - GP - 1/4" steel (RE)	65.00/ea
PN177LW	1970-72 Return Line - GP 1/4" stainless steel (RE)	99.00/ea
PN177ME	1971-72 Front to Rear Vapor Line - GP w/ EES - 5/16" steel (RE)	65.00/ea.
PN177MF	1971-72 Front to Rear Vapor Line - GP w/ EES - 5/16" stainless steel (RE)	99.00/ea.
PN177MJ	1971-72 Emission Tank Line Set (3 pc set) - GP w/ EES steel (RE)	29.00/set
PN177MK	1971-72 Emission Tank Line Set (3 pc set) - GP w/ EES stainless steel (RE)	36.00/set
PN177NJ	1973-77 Front to Rear Fuel Line - GP 3/8" steel (RE)	65.00/ea.
PN177NK	1973-77 Front to Rear Fuel Line - GP 3/8" stainless steel (RE)	99.00/ea.
PN177NL	1973-77 Return Line - GP 1/4" steel (RE)	65.00/ea.
PN177NM	1973-77 Return Line - GP 1/4" stainless steel (RE)	99.00/ea.
PN177NN	1973-77 Front to Rear Vapor Line - GP 5/16" steel (RE)	65.00/ea.
PN177NP	1973-77 Front to Rear Vapor Line - GP 5/16" stainless steel (RE)	99.00/ea.

Please add \$8.50 for shipping fuel lines.

FUEL LINE CLIPS

		PN179SF	
PN179S	PN179SB	PN179SD	
PN179S	Steel Line Clip, Double Line Fits 1/4" and 3/8" Lines, (Green) (GM)		1.75/ea.
PN179SB	Steel Line Clip, Fits 1/4" and 5/16" Lines, (Black) (GM)		1.75/ea.
PN179SD	Steel Line Clip, Fits 5/16" and 5/16" Lines, (Black) (AP)		1.75/ea.
PN179SF	Steel Line Clip, Fits 1/4" and 3/8" Lines (AP)		1.75/ea.

PN179SH	PN179SH - PN179SN Steel Line Clip, Fits Single 3/16" Line, Silver (3/16" Bolt Hole) (AP)	1.75/ea.
PN179SJ	Steel Line Clip, Fits Single 1/4" Line, Silver (1/4" Bolt Hole) (AP)	1.75/ea.
PN179SL	Steel Line Clip, Fits Single 5/16" Line, Silver (3/16" Bolt Hole) (AP)	1.75/ea.
PN179SN	Steel Line Clip, Fits Single 3/8" Line, Silver (3/16" Bolt Hole) (AP)	1.75/ea.

PN179SP

PN179SS

PN179SV

PN179SP - PN179SV	Steel Line Clip w/ Tab, Fits Single 1/4" Line, Blue (5/32" Bolt Hole) (AP) ..	\$ 1.75/ea.
PN179SS	Steel Line Clip w/ Tab, Fits Single 3/8" Line, Blue (5/16" Bolt Hole) (AP) ..	1.75/ea.
PN179SV	Steel Line Clip w/ Tab, Fits Single 3/16" Line, Yellow Zinc (5/32" Bolt Hole) (AP)	1.75/ea.

PN179SX

PN179TB

PN179SX	PN179TB
Steel Line Clip, Double Line, Fits 3/8" and 1/4" Lines, Silver (5/16" Bolt Hole) (AP)	1.75/ea.
Steel Line Clip, Double Line, Fits 3/16" and 1/4" Lines, Silver (5/16" Bolt Hole) (AP)	1.75/ea.

PN179TD

PN179TF

PN179TD	PN179TF
Steel Line Clip, Fits 5/8" Single Line, Silver (5/32" Bolt Hole) (AP)	1.75/ea.
Steel Line Clip w/ Tab, Fits 3/8" Single Line, Blue (5/32" Bolt Hole) (AP)	2.00/ea.

Note: PN179SB thru PN179SF are shown actual size. All others are about 50%.

FUEL FILTERS

PN180	1955-57 Fuel Filter w/o FI w/5/16" Fuel Line - Glass-bowl type (GM)	12.00/ea.
PN181	1957-60 Fuel Filter w/o FI w/3/8" Fuel Line, Cad-Plated GF-61-P - ALL (GM)	7.50/ea.
PN181A	1957-60 Fuel Filter w/o FI w/3/8" Fuel Line, GF-61-P - ALL (RE)	Inquire

Note: This is a reproduction with original style blue paint and red script.

- PN181** 1961-66 Fuel Line Filter w/o AC, Cad-Plated
GF-61-P - ALL (GM)..... \$ 7.50/ea.
- PN181A** 1961-66 Fuel Line Filter w/o AC, GF-61-P
- ALL (RE)..... Inquire

Note: This is a reproduction with original style blue paint and red script.

- PN184** 1961-66 Fuel Line Filter w/AC, Cad-Plated
GF-98 - ALL (GM) 8.50/ea.

Note: This is now smaller in diameter and will not fit tightly in original style bracket.

- PN184A** 1961-66 Fuel Line Filter w/AC, GF-414
- ALL (RE)..... Disc.

Note: This is a reproduction with original style blue paint and red script.

- PN184** 1967 Fuel Line Filter w/428 Cad-Plated
GF-98 (GM) 8.50/ea.

Note: This is now smaller in diameter and will not fit tightly in original style bracket.

- PN185** 1967 Fuel Line Filter w/428 GF-98 (RE) Disc.

Note: This is a reproduction with original style blue paint and red script.

- PN190** 1964-67 Fuel Filter, 4 BBL w/o AC or 428
(GM)..... 3.00/ea.

Note: This is for cars equipped with fuel inlet sintered bronze filters.

- PN192** 1968-74 Fuel Filter, 4 BBL Paper Element
(GM)..... 3.00/ea.

- PN190** 1971-74 Fuel Filter, 2 BBL (Sintered Bronze)
(GM)..... 3.00/ea.

- PN194** 1975-77 Fuel Filter, 4 BBL (GM) 5.00/ea.



PN196

- PN196** 1971-77 Vapor Canister (GM-RP) 49.00/ea.

- PN196B** 1971-77 Vapor Canister Filter (GM)..... 3.00/ea.

TRI-POWER & 4BBL COMPONENTS



PN210

- PN210** Tri-Power Thermostatic Vacuum
Block-Off Plate (RE) 7.00/ea.

This plate is used when vacuum-operated tri-power setups are converted to progressive linkage. The plate replaces the thermostatic vacuum control assembly mounted on the front of the intake.



PN211A

- PN211A** 1966 Tri-Power Choke Pull-Off Assembly
(White like original) (RE) \$ 16.00/ea.

- PN211B** 1966 Tri-Power Choke Pull-Off
w/o Bracket (White like original)
(RE)..... 7.00/ea.

- PN211C** 1966 Tri-Power Choke Pull-Off Bracket
Only (RE)..... 10.00/ea.



PN211G

- PN211G** 1966 Tri-Power Center Carb Choke Lever
(RE)..... 6.50/ea.

- PN211J** 1964-66 Tri-Power Center Carb Vacuum
Advance Fitting (RE)..... 3.00/ea.

This is the hard to find fitting that screws into the back of the center carb and supplies vacuum to the distributor advance.



PN213

- PN212** 1957-66 Tri-Power Wing Nuts (Set of 3) (RE). 5.00/set
- PN213** 4-Barrel Wing Nut (RE) 2.00/ea.

Nuts are pressed steel and chrome-plated same as original.

- PN214** Tri-Power Carburetor Studs
(Set of 3) (RE) 7.50/set

Studs have correct thread and length to be used with PN101 through PN105A.



PN214

- PN212** 1957-66 Tri-Power Wing Nuts (Set of 3) (RE). 5.00/set
- PN213** 4-Barrel Wing Nut (RE) 2.00/ea.

- PN214** Tri-Power Carburetor Studs
(Set of 3) (RE) 7.50/set

Studs have correct thread and length to be used with PN101 through PN105A.



PN214A

- PN214A** Air Cleaner Carb Stud (GM)..... 4.00/ea.

This universal stud is 9 inches long and must be cut for your particular application.



PN216

- PN216** 1961-72 Yellow Throttle Return Spring
All (RE) 4.00/ea.

- PN218** 1961-72 Blue Throttle Return Spring
All (RE) 4.00/ea.

CHOKE HOUSING



- PN228** 1966 Tri-Power Choke Thermostat Housing, Coil and Rod (AP)..... \$ 30.00/ea.
- PN229** 1967 4-Barrel Choke Thermostat Housing, Coil and Rod (AP)..... 30.00/ea.
- PN230** 1968-70 4-Barrel Choke Thermostat Housing, Coil, and Rod (AP)..... 30.00/ea.

These units bolt to the intake manifold and include the control rod and correct clip.



PN232

- PN232** 1959-65 Tri-Power Choke Cover & Coil (RE). 25.00/ea.

VACUUM LINE COMPONENTS



PN235

- PN235** 1961-66 Tri-Power Brake Vacuum Line (RE) . 25.00/ea.

This steel line connects the front carb fitting to the power brake vacuum hose.

Note: This correct line and fitting is excellent.

- PN235A** 1961-66 Tri-Power Brake Vacuum Line Fitting (RE) 15.00/ea.

- PN235AD** 1964-65 4-Barrel Power Brake Line (RE) 6.50/ea.

This line connects the carburetor to the power brake vacuum hose.

- PN235J** Power Brake Vacuum Hose (GM-RP)..... 1.00/ft.

- PN235JC** Power Brake Vacuum Hose Clamp (RP)..... .50/ea.



PN238J



PN238L

- PN238J** 1961-66 Power Brake Vacuum Line Bracket (RE)..... 6.00/ea.

- PN238L** 1967,69 Power Brake Vacuum Line Bracket (RE)..... \$ 6.00/ea.

TRI-POWER THERMOSTAT HOUSINGS



PN245



PN246

- PN245** 1957 Tri-Power Thermostat Housing (RE) 40.00/ea.

- PN246** 1958 Tri-Power Thermostat Housing (RE) 45.00/ea.



PN247



PN248

- PN247** 1959 Tri-Power Thermostat Housing (RE) 45.00/ea.

- PN248** 1960 Tri-Power Thermostat Housing (RE) 45.00/ea.

Note: PN245 through PN248 are done in cast iron and have original shape and design.

- PN249** 1961-63 Tri-Power Thermostat Housing (RE) 45.00/ea.

Note: This is an exact reproduction of the 1961 to 1963 aluminum water neck. They are cast with the correct casting numbers.

- PN250** 1964 Tri-Power Thermostat Housing (RE) 45.00/ea.

- PN251** 1965-66 Tri-Power Thermostat Housing (RE) 35.00/ea.

Note: PN250 and PN251 are done in cast iron and have original shape with all casting numbers.

Comments: All our Tri-Power thermostat housings are very good to excellent.

2 B.C. & 4 B.C. THERMOSTAT HOUSINGS AND THERMOSTATS



PN255

- PN253** 1958-60 Thermostat Housing, 2 B.C and 4 B.C. (AP)..... 12.00/ea.

- PN255** 1965-70 Thermostat Housing, 2 B.C and 4 B.C. (AP)..... 14.00/ea.

- PN256** 1971-77 Thermostat Housing, 2 B.C. and 4 B.C. (w/Pont. V-8) (AP)..... 16.00/ea.



- PN256AM 1955-77 Thermostat w/ Gasket, 180°, All Pontiac V-8 exc. 301 (RP) \$ 6.00/ea.
- PN256AN 1955-77 Thermostat w/ Gasket, 195°, All Pontiac V-8 exc. 301 (RP) 6.00/ea.
- PN256AP 1955-77 Thermostat Housing Gasket (RP) 2.00/ea.
- PN256AR 1963-72 Thermostat Housing Bolt w/ Washer, All Pontiac (GM) 4.00/ea.

This is the hard to find bolt with the alternator bracket stud.

WATER PUMPS AND DIVIDER PLATES



- PN256B 1955-63 4 Bolt Water Pump w/ Gasket, All Pontiac V-8 (RP) 40.00/ea.
- PN256C 1963-68 Water Pump w/ Gasket, All Pontiac V-8 w/ 8 Mounting Bolts (RP) 29.00/ea.
- PN256F Early 1969 Water Pump w/ Gasket, All Pontiac V-8 (RP) 29.00/ea.

This is the hard to find short 4" hub used on early production '69 cars. This measurement is taken from the face of the hub to the surface that mounts to the timing cover.

- PN256J 1969-77 Water Pump w/ Gasket, All Pontiac V-8 exc. 301 (RP) 29.00/ea.

Note: PN256B - PN256J are remanufactured water pumps that carry a 90-day warranty.

- PN257B 1963-68 New Water Pump w/ Gasket, All Pontiac V-8 w/ 8 Mounting Bolts (RP) 79.00/ea.

- PN257E Early 1969 New Water Pump w/ Gasket, All Pontiac V-8 (RP) 79.00/ea.

Please refer to PN256F for identifying this pump.

- PN257H 1969-77 New Water Pump w/ Gasket, All Pontiac V-8 exc. 301 (RP) 49.00/ea.

Note: PN257B - PN257H are new water pumps. These carry a 90-day warranty.



- PN258PF 1963-68 Water Pump Divider Plates - Stainless Steel (APE) \$ 45.00/set

Note: Using stainless steel, we are now able to supply the ultimate in rust resistant divider plates.

Note: Since these plates are used in many different housings, slight contouring may be necessary in your application.

- PN258PJ 1969-77 Water Pump Divider Plate (GM) 7.00/ea.
- PN258PT 1969-77 Water Pump Sleeve w/ seal (GM) 12.00/pr.

FUEL FILTER BRACKETS




- PN260 1961-62 Fuel Filter Bracket (RE) 12.00/ea.
- PN260A 1963-64 Fuel Filter Bracket (RE) 12.00/ea.
- PN260B 1965-66 Fuel Filter Bracket (RE) 10.00/ea.


PN260B is not used for 1966 Tri-Power applications. See PN262

- PN260C 1967 Fuel Filter Bracket (RE) 15.00/ea.
- PN262 1966 Tri-Power Fuel Filter Bracket, Zinc-Plated (RE) 10.00/ea.

ALTERNATOR GENERATOR BOOTS AND CAPS



- PN267J 1961-62 Generator and Ignition Coil Electrical Connection Boot (RE) 11.00/ea.



- PN268K 1962-74 Alternator Plastic End Cap - Red (RE) 7.50/ea.
- PN268L 1962-74 Alternator Plastic End Cap - Black (RE) 7.50/ea.

PN268M 1975-77 Alternator Plastic End Cap - Black (GM)..... \$ 2.00/ea.

PN268K and PN268L are exact reproductions of the plastic caps used on all alternators. Cap covers positive lead and is a necessity for detailed restorations.

PN270D 1965-66 Rear Alternator Strap - ALL V-8 w/PS exc. Tri-Power (RE)..... \$ 19.00/ea.

This strap mounts to the front thermostat housing bolt.

PN270E 1967-69 Rear Alternator Strap - ALL V-8 w/PS (RE)..... 18.00/ea.

This strap mounts to the front thermostat housing bolt.

STARTER GENERATOR DISTRIBUTOR TAG FASTENERS



PN269J

PN269J Starter, Generator, and Distributor Tag Fasteners (RE) 1.00/ea.

These are the little round-headed, fluted shank rivets that attach various tags to starters, generators, and early distributors. A must detail item for the purist.

ALTERNATOR MOUNTING BRACKETS



PN270

PN270 1965-66 Tri-Power Rear Alternator Strap w/PS (RE) 26.00/ea.

This strap is an auxiliary strap that attaches to the driver's side water neck bolt and connects with the water pump to alternator strap.

It is used in conjunction with PN270AA.

PN270AA 1965-66 Front Alternator Strap - ALL V-8 w/PS (RE) 20.00/ea.

This strap bolts to the top water pump bolt.

PN270A 1965-67 Front Alternator Strap-All V-8 w/o PS (RE) 18.00/ea.

This strap bolts to the upper lefthand water pump bolt.

PN270B 1967-68 Front Alternator Strap - ALL V-8 w/PS (RE) 20.00/ea.


This strap bolts to the top water pump bolt.

PN270C 1969 Front Alternator Strap - ALL V-8 w/PS (RE) 18.00/ea.

This strap bolts to the top driver's side water pump bolt.



PN270D



PN270J 1969-70 Alternator Bracket w/Bolts and Sleeve w/o PS (RE)..... 39.00/ea.



PN270L

PN270N

PN270L 1967-70 Alternator Pivot Bracket - ALL V-8 w/PS (RE) 14.00/ea.

PN270N 1963-70 Air Conditioning Compressor Rear Mounting Bracket - ALL V-8 exc. 1965 (RE) 15.00/ea.



PN270P

PN270P 1967-70 Power Steering Mounting Bracket - ALL V-8 (RE)..... 24.00/ea.

FUEL LINE TUBING & SHIELDING

PN278 1955-77 3/8" Steel Fuel Line Tubing (25 ft. roll) (AP) 27.00/ea.

PN280 1955-77 5/16" Steel Fuel Line Tubing (25 ft. roll) (AP) 21.00/ea.


PN282 1961-77 1/4" Steel Vapor Return Tubing (25 ft. roll) (AP) 19.00/ea.



PN282J 3/8" Fuel Line Coiled Shielding (10 ft. length) (GM)..... 12.00/ea.

This is the special armor shielding that surrounds the fuel line as it runs along the frame.

INTAKE MANIFOLD COMPONENTS



PN285JB

PN285JB 1961-77 Intake Manifold Bolt Kit, All Pontiac V-8 Exc. RAIV and 455HO (AP)..... \$ 11.00/kit

These bolts do not have the same head markings as originals. Kit does not come with stud bolts for AC or alternator brackets for later years.



PN285P

PN286A

PN285L	1955-56 Intake Manifold Gasket Set, All Pontiac V-8 (RP)	16.00/set
PN285N	1957-60 Intake Manifold Gasket Set, All Pontiac V-8 (RP)	16.00/set
PN285P	1961-64 Intake Manifold Gasket Set, All Pontiac V-8 (RP)	16.00/set
PN285R	1965-71 Intake Manifold Gasket Set, All Pontiac V-8 Exc. RAIV and 1971 455HO (RP)	17.00/set
PN285T	1969-71 Intake Manifold Gasket Set, All RAIV and 1971 455HO (RP) ..	17.00/set
PN285V	1972-77 Intake Manifold Gasket Set, All Pontiac V-8 Exc. 301, 455HO and 455SD(RP)	17.00/set
PN286A	1961-64 Valley Pan Gasket (RP)	7.00/set
PN286B	1965-67 Valley Pan Gasket (RP)	7.00/set
PN286C	1968-77 Valley Pan Gasket (RP)	7.00/set

TRI-POWER CHOKE LINES



PN291

PN290 1961-63 Complete Choke Line Kit w/Manifold Plate and Manifold Lines (RE)..... \$ 50.00/kit

PN291 1964 Complete Choke Line Kit w/Manifold Plate and Manifold Lines (RE)..... 50.00/kit

These kits are to be used where the manifold plate and tubes are missing completely or where the manifold tubes have rusted and broken from the plate.

PN292 1961-64 Manifold Plate Gasket (RE) 3.00/ea.

PN292A 1961-64 Manifold Plate w/Gasket (RE) 27.00/ea.

Note: This is the plate that mounts to the manifold where the choke lines insert for hot air.

PN292C 1957-60 Choke Line (RE)..... 9.50/ea.

PN294 1961-63 Choke Lines w/o Spacers Under Carbs (RE) 25.00/set

PN294A 1961-63 Choke Lines w/Spacers Under Carbs (RE) 18.00/set

PN295 1964 Choke Lines (RE) 25.00/set

PN294 through PN295 are to be used only if the manifold tubes are in good shape and attached firmly to the plate. If the manifold tubes fall off, unfiltered air and rust particles may be drawn into the carburetor.

PN296 1965 Choke Lines (RE) 18.00/set

Comments: Very good

4 BBL CHOKE LINES



PN299A

PN299 1964 4 BBL Choke Lines (RE)..... 18.00/set

PN299A 1965-66 4 BBL Choke Lines (RE)..... 18.00/set

THROTTLE CABLE BRACKETS



PN305

PN306

PN305 1969-71 4 BBL Throttle Cable Bracket - GP (RE)..... 42.00/ea.

PN306 1972-74 4 BBL Throttle Cable Bracket - ALL (RE)..... 19.00/ea.

THROTTLE CONTROL CABLES



- PN310** 1969-71 Throttle Control Cable - GP (2 BBL) (GM)..... Disc.
- PN311** 1969-71 Throttle Control Cable - GP (4 BBL) (GM)..... \$ 30.00/ea.

THROTTLE SHAFT BRACKETS



PN325

- PN325** 1959-66 Tri-Power Carburetor Linkage Lever, RH Front (RE) 6.00/ea.

This linkage lever is used on the passenger side of all '59-'66 front carburetors. It has the necessary slotted hole for the passenger side linkage.

- PN325A** 1959-66 Tri-Power Carburetor Linkage Lever, RH Rear (RE) 6.00/ea.



PN328

- PN328** 1969-72 Quadrajete Throttle Shaft Lever - GP w/Idle Solenoid (RE)..... 16.00/ea.

- PN328B** 1969-72 Quadrajete Throttle Shaft Lever - GP w/o Idle Solenoid (RE)..... 16.00/ea.

TRI-POWER ACCELERATOR LINKAGE



PN331

- PN329** 1958 Tri-Power Mechanical Linkage (RE) Inquire
- PN329A** 1959-60 Tri-Power Mechanical Linkage (RE) 55.00/kit
- PN330** 1961-63 Tri-Power Mechanical Linkage (RE) 55.00/kit
- PN331** 1964-65 Tri-Power Mechanical Linkage (RE) 50.00/kit
- PN332** 1966 Tri-Power Mechanical Linkage (RE) 50.00/kit

These kits include necessary hardware to convert to or replace driver's side mechanical linkage on your Tri-Power.

We recommend purchasing PN341A (rear accelerator pump rod) when converting vacuum to mechanical linkages. This rod is necessary because original rods will interfere with linkage operation.

Comments: Very good.



PN340

- PN340** 1959-66 Tri-Power Carburetor Linkage w/Clips—Passenger Side (Connects front and rear carburetors) (RE) \$ 7.00/set

TRI-POWER CARBURETOR COMPONENTS



PN340K

PN341B

- PN340J** 1959-66 Tri-Power Secondary Rod Springs (RE)..... 3.50/pr.
- PN340K** 1959-66 Tri-Power Secondary Rod Springs - Heavy Duty (RE) 4.00/pr.
- PN341** 1959-66 Tri-Power Accelerator Pump Rod (Front Carb) (RE) 7.50/ea.
- PN341A** 1959-66 Tri-Power Accelerator Pump Rod (Rear Carb) (RE) 7.50/ea.
- PN341B** 1959-66 Tri-Power Accelerator Pump Rod Set (Front & Rear Carbs) (RE) 14.00/set



PN342

- PN342** 1961-63 Tri-Power Vacuum Control Rod and Clip (RE) 10.00/ea.

This is the rod & clip that connect the front carburetor to the vacuum pot.



PN343KK

- PN343KK** 1960-65 Tri-Power Throttle Shaft - Center Carb (RE)..... 35.00/ea.
- PN343KM** 1966 Tri-Power Throttle Shaft - Center Carb (RE)..... 35.00/ea.
- PN343KP** 1959-66 Tri-Power Throttle Shaft - End Carbs (RE)..... 35.00/ea.

All throttle shafts come with necessary screws and are of the highest quality.

AIR HORN REPAIR KITS



PN345L

- PN345K** 1957-65 Air Horn Repair Kit 1957-58 ALL Carbs & '59-'65 Tri-Power Center Carb Only (RP)..... Disc.
- PN345L** 1959-66 Air Horn Repair Kit - 1959-65 Tri-Power End Carbs, 1966 Center and End Carbs\$ 12.00/ea.

Note: These air horn repair kits are stamped replacements. They are not like original but will allow you to save Tri-Power carburetors with broken air horns.

AIR FILTER ELEMENTS



PN349X

- PN349X** 1957-65 Air Filter Element, 3/2 BBL (AP) 20.00/ea.
This is the large filter for the original 1-piece air cleaner for Tri-Powers.
See "Tri-Power Air Cleaners" heading in front of this section for 3-piece Tri-Power air cleaners.
- PN350** 1958-67 Air Filter Element, 2 BBL and 4 BBL (GM)..... 13.00/ea.
- PN351** 1959-60 Air Filter Element, 2 BBL Heavy Duty (GM)..... 13.00/ea.
- PN352** 1965-67 Air Filter Element, 2+2 4 BBL exc. HO (GM)..... 13.00/ea.
- PN353** 1965-66 Air Filter Element, 2 BBL or 4 BBL w/AIR (GM)..... Disc.
- PN355** 1965-67 Air Filter Foam Element, 2+2 4 BBL (RE)..... 32.00/ea.

Note: To be used with an original screen.

- PN356** 1967 Air Filter Element, 428 4 BBL - Std. (GM)..... 15.00/ea.
- PN357** 1967 Air Filter Element, 428 4 BBL - HD (GM)..... 22.00/ea.
- PN356** 1967 Air Filter Element, 428 4 BBL - HO (GM)..... 15.00/ea.
- PN356** 1968-75 Air Filter Element - 4 BBL exc. HD (GM)..... 15.00/ea.
- PN357** 1968-75 Air Filter Element - 4 BBL - HD (GM)..... 22.00/ea.
- PN359** 1967-76 Air Filter Element - 2 BBL - ALL (GM)..... 11.00/ea.

- PN356** 1976 Air Filter Element - 4 BBL - FS (GM).....\$ 15.00/ea.
- PN357** 1976 Air Filter Element - 4 BBL - GP (GM)..... 22.00/ea.
- PN356** 1977 Air Filter Element w/350R, 403 GP (GM)..... 15.00/ea.
- PN357** 1977 Air Filter Element w/350P, 400 GP (GM)..... 22.00/ea.
- PN360** 1977 Air Filter Element w/301 (GM)..... 13.00/ea.

K & N AIR FILTER ELEMENTS



- PN365** 1957-66 Tri-Power Air Filter Element Set (AP) 79.00/set
Note: Set of 3.

- PN365D** 1967 Air Filter Element, 428 4BBL Std & HO (AP)..... 49.00/ea.
- PN365G** 1968-75 Air Filter Element, 4BBL exc. HD (AP)..... 49.00/ea.
- PN365G** 1976 Air Filter Element, 4BBL - FS (AP)..... 49.00/ea.
- PN365G** 1977 Air Filter Element, w/ 350R, 403 GP (AP)..... 49.00/ea.

Get the ultimate in air intake capabilities. These filters can add up to 4-5 HP and they never need replacing. They can be cleaned and recharged using PN365M.



- PN365M** K & N Air Filter Recharge Kit (AP).... 15.00/kit

AIR CLEANERS



PN370

PN370 1965-66 Air Cleaner Assembly, 2+2 and
421 4 BBL (RE)\$275.00/ea.

Note: This is the chrome-louvered air cleaner with 4" hole for the Carter AFB carburetor. It includes paper air cleaner element.

PN370N 1967 4 Barrel Louvered Air Cleaner
Assembly (RE) 285.00/ea.

Note: This is the chrome-louvered air cleaner with 5" hole for the Rochester Quadrajets carburetor. It includes an AC paper element. See Page 116 for replacement foam or paper filters.

PN370R 1965-67 Louvered Air Cleaner Chrome Lid
(RE)..... 190.00/ea.

Note: This is the chrome lid only.

PN370T 1967 Louvered Air Cleaner Base for
Quadrajets Carburetor (RE) 65.00/ea.



PN371

PN371 1967 Air Cleaner Assembly, 428 HO (RE) 65.00/ea.

Note: This reproduction assembly consists of chrome cover, aluminum base, and paper element.

PN372 1967 Air Cleaner Cover (RE) 40.00/ea.

Note: PN372 consists of chrome air cleaner cover only (14" O.D.).



PN373

PN373 1967-75 Air Cleaner Cover - Chrome (RP)..... 55.00/ea.

This is a replacement and is not an exact match to originals (17" O.D.).



PN379

PN379 1957-58 ALL & 1959-65 Center
Tri-Power Carb to Air Cleaner
Gasket (AP) 2.00/ea.

PN379A 1959-65 Ends & 1966 ALL
Tri-Power Carb to Air Cleaner
Gasket (AP) \$ 2.00/ea.

PN379AJ 1959-66 Carb to Air Cleaner Gasket -
AFB Four-Barrel 4" Base (AP) 2.00/ea.

PN379AM 1967-77 Carb to Air Cleaner Gasket -
Quadrajets Four-Barrel 5" Base (AP) 2.00/ea.

EXHAUST PRE-HEATER COMPONENTS



PN380J

PN380J 1968-77 Air Cleaner Pre-heater Vacuum
Diaphragm (GM-RP)..... Disc.



PN386R

PN386R 1968-77 Pre-heater Shroud to Air Cleaner
Duct and Elbow (GM)..... 8.00/ea.

This duct comes complete with elbow. The duct is of the correct black accordion-style material.



PN386X

PN386X 1968-77 Pre-heater Shroud to Air Cleaner
Elbow (GM)..... 8.00/ea.



PN387

PN387 1968-77 Pre-heater Elbow to Air Cleaner
Clamp..... 1.50/ea.

OIL FILTERS



PN390L

PN390K 1960-66 Correct PF7 Oil Filter (RE) Inquire

PN390L 1967-74 Correct PF24 Oil Filter (RE) Inquire

PN390P 1960-77 Replacement AC PF24 Oil Filter
All Pontiac V-8 (GM) 6.00/ea.

OIL DIPSTICKS & TUBES



- PN392A** 1968-77 Oil Dipstick, ALL w/Pont. V-8 exc. AC (GM) \$ 6.00/ea.
- PN392C** 1968-77 Oil Dipstick, ALL w/Pont. V-8 w/AC (GM)..... 6.00/ea.
- PN392E** 1966-77 Oil Dipstick Tube to Block, ALL w/Pont. V-8 w/o AC (GM) 7.00/ea.
- PN392F** 1966-77 Oil Dipstick Tube to Block, ALL w/Pont. V-8 w/AC (GM) 7.00/ea.

Note: The oil pan must be removed to install both PN392E and PN392F. These tubes are visible on the outside of the block but are pushed up through from the inside.

- PN392G** 1970-77 Oil Dipstick Tube, Upper w/AC - ALL w/Pont. V-8 (GM) 7.00/ea.



Note: PN392G fits into PN392F.

- PN392J** 1965-68 Oil Dipstick Tube in Pan, ALL w/Pont. V-8 (RE) 10.00/ea.
- PN392K** 1969-73 Oil Dipstick Tube in Pan w/o Mounting Bracket - ALL w/Pont. V-8 (GM)..... 15.00/ea.
- PN392L** 1972-77 Oil Dipstick Tube in Pan w/Mounting Bracket - ALL w/Pont. Engine (GM) 4.00/ea.
- PN392N** 1977 V-8 Oil Dipstick Tube, 305U (GM). 4.00/ea.

OIL PANS & COMPONENTS



PN394

- PN394** 1976-77 Oil Pan - ALL w/Pont. V-8 (GM) 149.00/ea.

Note: PN394 will fit 1964-75 engines but there are a few minor differences. PN394 has a baffle spot-welded in the bottom, a side drain, a small dimple in front not seen on earlier models and it has five slots for the rear pan seal. Earlier models had 2 slots and a round hole. All year gaskets are available using PN394J and PN394K.



PN394B



PN394C

- PN394B** 1955-77 Oil Pan Drain Plug, All Pontiac V-8 (GM)..... \$ 2.00/ea.

Note: This has a 9/16" Hex head unlike the original 11/16".

- PN394C** 1955-77 Oil Pan Drain Plug Seal, All Pontiac V-8 (RP) 1.00/ea.



PN394E

- PN394E** 1964-77 Oil Pan Mounting Reinforcement Brackets, 2 Piece set (RE) 9.00/set
- PN394F** 1964-77 Oil Pan Bolt Kit, All Pontiac V-8 (RP)..... 13.00/kit

This replacement does not have correct head size or markings as originals.




PN394J

- PN394J** 1964-Early '76 Oil Pan Gasket - ALL w/Pont. V-8 (AP)..... 20.00/set
- PN394K** Late 1976-77 Oil Pan Gasket - ALL w/Pont. V-8 (AP)..... 20.00/set

These gasket sets contain the three types of rear pan seals. '64-'71 uses the cork gasket (PN394J); '72-'76 (early) uses the three pronged seal (PN394J); and '76 (late)-'77 uses the five prong seal (PN394K).

COMPLETE EXHAUST SYSTEMS



After researching several suppliers, we now offer complete exhaust systems for your classic Full Size Pontiac.

The systems come complete, either aluminized or in stainless steel. All systems come with clamps. Non HO systems come with flanges.

Please call for information concerning your particular application. Dual Exhaust prices start at \$270.00 per system.

Please add \$25.00 shipping for exhaust systems.

FLOWMASTER PERFORMANCE EXHAUST COMPONENTS



42453

Flowmaster mufflers use a fully aluminized 16 gauge steel welded case which is virtually indestructible. These mufflers greatly improve combustion efficiency and offer optimum street performance.

42453 1955-77 2 1/4" Three chamber Muffler, All Pontiac V-8 (AP) \$ 95.00/ea.

42553 1955-77 2 1/2" Three chamber Muffler, All Pontiac V-8 (AP) 95.00/ea.

Three chamber mufflers give a mellow more conservative tone over two chamber mufflers without sacrificing performance.

42443 1964-72 2 1/4" Two chamber Muffler, All Pontiac V-8 (AP) 76.00/ea.

42543 1964-72 2 1/2" Two chamber Muffler, All Pontiac V-8 (AP) 76.00/ea.

For those seeking the more aggressive sound we suggest using these two chamber mufflers.

EXHAUST MANIFOLDS & FLANGES



PN403

PN403 1965-68 HO Exhaust Manifold - ALL (RE) 399.00/pr.

Note: Please contact us concerning 1962-64 and 69-72 full-size applications.

PN403 1969 HO Exhaust Manifold - GP (RE) \$399.00/pr.

Note: PN403 will also fit 1970-72 GP although they are not original equipment.

All exhaust manifolds are manufactured using high quality ductile iron. Manifolds have passed heat testing from 52°F to 1400°F and also passed the difficult quench test. Manifolds are warranted for one year on materials and workmanship.

Manifolds are supplied with steel studs and brass nuts. Stainless studs are available (see PN422 and PN422A).

Please add \$14.00 shipping for exhaust manifolds.



PN403A

PN403A HO Exhaust Flange (2-Bolt) (RE) 20.00/ea.

Note: This 2-bolt flange must be used with PN403 exhaust manifolds.

Comments: Excellent.

PN406J 1968-74 Exhaust Flange - ALL V-8 Models exc. HO (AP) 6.00/ea.

EXHAUST COATING



PN407

PN407 1955-72 Exhaust Manifold Coating (AP) 19.00/pt.

This high-quality Eastwood product is an excellent dressing for original manifolds as well as these new reproductions. Fortified with 25% stainless steel, this high-temperature coating will give your manifolds new cast-iron appearance for thousands of miles.

EXHAUST MANIFOLD INSTALLATION KITS



PN410J

PN408 1965-69 HO Exhaust Manifold Installation Kit (RP) \$ 26.00/kit

Note: PN408 contains one pair of Fel-Pro high-performance sandwich gaskets and grade 8 high-tensile bolts.

PN410J D-Port Standard Exhaust Manifold Installation Kit (RP) 26.00/kit

Please tell us how many and what size your bolts are when ordering this kit since there are many different combinations.

Note: Same components as PN408 above.

PN411 1959-77 D-Port Exhaust Manifold Gasket (AP) 24.00/pr.

EXHAUST COMPONENTS



PN413

PN413 1955-77 Exhaust Manifold Bolt Lock (APE).... 1.25/ea.
This lock was used on all V-8 exhaust manifold bolts.



PN415

PN415 1956-58 Exhaust Elbow - LH (RE) 55.00/ea.

PN415 was used on all 1956 cars w/dual exhaust and 1957-58 cars w/dual exhaust but w/o fuel injection. This piece is often cracked or broken.

Comments: Excellent reproduction.

PN415C 1958 Exhaust Elbow w/ T395A Motor - RH (RE) 95.00/ea.



This elbow fits only 330HP Tri-Power cars w/ dual exhaust. Casting # 530966.

PN416 1961-64 Exhaust Elbow - RH (RE) 75.00/ea.

This was used on 1961-62 cars equipped with the 425A motor and 1963-64 421 HOs.



PN422

PN422 1955-77 Exhaust Manifold Stud and Nut exc. Long Branch Manifolds (RE) 3.00/ea.

PN422A 1965-69 Long Branch Manifold Stud and Nut (RE) 4.00/ea.

These studs and nuts should be used with new exhaust flanges or when your HO or RA head-

er pipe is changed. With these stainless steel studs and bronze nuts you will rid yourself of broken flange studs and exhaust manifolds.


HEAT SHIELDS



PN423

PN423 Solenoid Heat Shield (RE) \$ 10.00/ea.

Originally designed for the '67 HO and RA applications, this stainless shield helps insulate your starter solenoid from exhaust manifold heat. Shield can be used on any Pontiac to help reduce hot start problems and prolong solenoid life.



PN423J

PN423K

PN423J Battery Cable Heat Shield (4" Long) (RE) 10.00/ea.

PN423K Battery Cable Heat Shield (4 1/2" Long) (RE) 10.00/ea.

These original-style heat shields bolt to the driver's side head and run down behind the exhaust manifold.

Note: These cable shields fit a variety of V-8 full-size cars.



PN423NB

PN423NB 1969 GP HO Positive Battery Cable Shield (APE) 29.00/ea.

All '69 GP HO positive cables were routed originally through a tube attached to the LH motor mount (Part #9789780). They are a necessity for both the restored and street driven HO cars since they keep the cable away from the hot exhaust manifolds.

STARTER AND COMPONENTS



PN424

- PN423P** 1965-77 High Torque Starter (w/Pont V-8)
w/ Long Branch HO Manifolds
(AP).....\$209.00/ea.
- PN424** 1965-77 High Torque Starter (w/Pont V-8)
exc. Long Branch HO Manifolds
(AP)..... 209.00/ea.

As we all know, Pontiacs have a common hot start problem. We have found a cure. These high torque, light weight, compact designs produce in excess of 525 ft. lbs of torque (Stock is about 190 ft. lbs) The special heat dissipating solenoid makes for easy and consistent starts. These starters come with bolts and shims.



PN425D



PN425G

- PN425D** 1965-77 Starter Mounting Bolt (GM) 4.00/ea.
- PN425G** Starter Shim (Use as required) (RP)... 1.00/ea.

OIL FILTER ADAPTERS



PN427

- PN427** 1965-68 Oil Filter Adapter w/HO Exhaust
- FS (RE) 75.00/ea.
- PN428** 1969 Oil Filter Adapter w/HO Exhaust
- GP (RE) 50.00/ea.

Note: These reproduction adapters are cast aluminum. They must be used when installing HO exhaust manifolds PN403 on your engine.

ENGINE PAINT



- PN429** 1955-57 Engine Paint, 12 oz. Aerosol Can
(AP)..... Disc.
- PN429A** 1958 Engine Paint - Also '57 Bonneville,
16 oz. Aerosol Can (RE) 12.00/ea.
- PN430** 1959-65 Pontiac Blue Engine Paint,
11 oz. Aerosol Can (AP)..... 5.00/ea.
- PN430A** 1959-65 Pontiac Blue, Pint (AP) Disc.

- PN431** 1966-70 Pontiac Blue Engine Paint,
Metallic 11 oz. Aerosol Can (AP)..... \$ 5.00/ea.
- PN431A** 1966-70 Pontiac Blue Engine Paint, Metallic,
Pint (AP) Disc.
- PN431T** 1971-74 Pontiac Blue Non-Metallic, 11 oz.
Aerosol Can (AP)..... 5.00/ea.
- PN432** 1971-74 Pontiac Blue Engine Paint,
Non-Metallic, Pint (AP)..... Disc.
- PN432B** 1975-77 Pontiac Blue Engine Paint, Pint (AP) Disc.

For years controversy has raged concerning these paints. We hope our research has finally answered most of the questions.

Many people feel the paint should be blue-green. After baking our paint at 250-300°F the green became apparent and matched two of our high-mileage original engine cars.

CARBURETOR COMPONENTS



PN455J

- PN455J** 1960-67 Dash Pot All Carter AFB (AP) 21.00/ea.



PN455N



PN455T

- PN455N** 1968-72 Idle Stop Solenoid (AP) Inquire

The original solenoids for these cars have been discontinued. Most replacements do not have the correct bracket. With engine detailing becoming more critical, this exact solenoid is a must for the serious restorer.

Note: Correct applications for this piece include 1968 ALL, 1971 ALL 4 B.C.-MT and 1972 ALL 4 B.C.

- PN455T** 1968-70 Idle Stop Solenoid Bracket (RE) 15.00/ea.

Note: PN455T will work on 1971-72 cars with some modifications needed.

CARB REBUILDING KITS



PN460	1955-56 2-Barrel (AP).....	\$ 16.00/ea.
PN460	1957-65 Tri-Power Center Carb (AP)	16.00/ea.
PN461	1955 Rochester 4-Barrel (AP).....	27.50/ea.
PN462	1955-56 Carter 4-Barrel (AP).....	37.00/ea.
PN463	1956 Rochester 4-Barrel (AP).....	Disc.
PN464	1957 2-Barrel (AP).....	Disc.
PN465	1957 Rochester 4-Barrel (AP).....	34.00/ea.
PN466	1957-58 Tri-Power End Carbs (AP)	19.00/ea.
PN467	1957-58 Carter 4-Barrel (AP).....	31.00/ea.
PN468	1958-69 2-Barrel (AP).....	16.00/ea.
PN468	1959-66 Tri-Power End Carbs (AP)	16.00/ea.
PN460	1957-65 Tri-Power Center Carb (AP)	16.00/ea.
PN468	1966 Tri-Power Center Carb (AP)	16.00/ea.
PN471	1961-65 Carter 4-Barrel (AP).....	35.00/ea.
PN467	1966-67 Carter 4-Barrel (AP).....	31.00/ea.
PN472	1967 Rochester 4-Barrel (AP).....	24.50/ea.
PN473	1968 Rochester 4-Barrel (AP).....	25.00/ea.
PN474	1969-71 Rochester 4-Barrel w/o Ram Air (AP).....	25.00/ea.
PN475	1970-74 Rochester 2-Barrel (AP).....	26.00/ea.
PN476	1972-74 Rochester 4-Barrel exc. Hi Alt (AP) ..	25.00/ea.

1975-77 carb kits are also available. Please inquire.

Note: Of the many standard carburetor kits on the market, the Echlin kit is considered the best.

DELUXE CARB REBUILDING KITS

We are now handling two other carb rebuilding kits manufactured by "The Carburetor Shop."

These kits are more comprehensive than our standard line and come in two styles. The Level 1 kits come complete with all gaskets, pumps, springs, etc. that our standard kits contain. Besides the above, Level 1 two barrel kits include the pump return spring, main jets, the center power valve, and idle screws. In addition to the standard kit, the AFB Level 1 kits include primary jets, vacuum piston and spring, plus idle screws. Quadrajet Level 1 kits additionally have the power piston spring, primary jets and idle screws.

Level 2 carburetor kits contain all components found in Level 1 kits plus all new philister head screws, choke plate screws, and throttle plate screws.

Prices for these kits are:

	Level 1 kits	Level 2 kits
2 Barrel	\$40/kit	\$50/kit
3-2-Barrel	110/3 kits	135/3 kits
4-Barrel-4-GC	44/kit	59/kit
4-Barrel WCFB	44/kit	59/kit
4-Barrel-AFB	44/kit	59/kit
4-Barrel-AFB	44/kit	59/kit
Super-duty	45/kit	60/kit
4-Barrel-Q Jet	48/kit	63/kit

Application, type of carburetor and carb # must be given with order.

These kits are available for '55-'75 cars only.

Note: Tri-Power kits must be ordered in sets of 3.

Note: For carburetor jets please inquire.

CARBURETOR FLOATS



PN477D	1957-65 3x2 Center Carb Float (AP)	\$ 6.50/ea.
PN477F	1966 3x2 Center Carb Float (AP)	6.50/ea.
PN477H	1959-66 3x2 Front or Rear Carb Float (AP)	6.50/ea.
PN477M	1957-67 Carter AFB Carb Float (AP).....	6.50/ea.

Note: Requires 2 per carb.

PN478B	1967-68 Rochester Q-jet 4bbl. Carb Float (AP).....	6.50/ea.
PN478G	1969-74 Rochester Q-jet 4bbl. Carb Float (AP).....	6.50/ea.
PN478L	1975-77 Rochester Q-jet 4bbl. Carb Float (AP).....	6.50/ea.
PN478R	1964-72 Rochester 2bbl. Carb Float (AP)	6.50/ea.
PN478T	1973-76 Rochester 2bbl. Carb Float (AP)	6.50/ea.

CARBURETOR TO MANIFOLD GASKETS



PN479AF



PN479AN

PN479AF	1959-66 Tri-Power Outer Carb to Manifold Gasket (RP)	3.50/ea.
PN479AH	1957-65 Tri-Power Center Carb to Manifold Gasket (RP)	3.50/ea.
PN479AF	1966 Tri-Power Center Carb to Manifold Gasket (RP)	3.50/ea.
PN479AL	1957-67 AFB Carb to Manifold Gasket (RP).	10.50/ea.
PN479AN	1967 Q-jet Carb to Manifold Gasket (RP)	4.00/ea.
PN479AP	1967 Q-jet Carb Baffle, Stainless Steel (RP).....	8.50/ea.


- PN479AR** 1968-74 Q-jet Carb to Manifold Gasket (RP) \$ 6.00/ea.
PN479AT 1975-77 Q-jet Carb to Manifold Gasket (RP) 10.50/ea.

Note: Carburetor rebuild kits come with carb to manifold base gaskets.

PCV COMPONENTS

- PN480** 1963-65 4-Barrel and 1964-65 Tri-Power Crankcase Vent Hose Connector Nylon (RE) 18.00/ea.

This is a very detailed reproduction of the small nylon F-shaped PCV connector. Usually missing, this piece has been impossible to find and is necessary for complete restoration of your engine.



PN480A PN481A

- PN480A** 1963-65 4-Barrel and 1964-65 Tri-Power Crankcase Vent Hose Connector Steel (RE) 15.00/ea.


This plated steel connector is an excellent alternative to PN480. Although most cars were equipped with nylon connectors, some had steel.

- PN481** 1966 Tri-Power Crankcase Vent Hose Connector Nylon (RE) 18.00/ea.

This hose connector seems to have been used on most '66 models. It is different from PN480 in that all connections take 3/8" I.D. hose.

- PN481A** 1966 Tri-Power Crankcase Vent Hose Connector Steel (RE) 15.00/ea.

See *Note* under PN480A.



PN482

- PN482** 1966 4-Barrel and ALL 1967 V-8 Crankcase Vent Hose Connector Nylon (RE) \$ 16.50/ea.
PN482K 1966-67 V-8 Crankcase Molded Vent Hose, 2 & 4 BBL (APE) 7.50/ea.


This small molded hose is a fine detail item. Using standard straight hose results in a large incorrect loop.

- PN485** 1957-77 PCV Valve Grommet (GM) 3.00/ea.

This grommet fits in the back of the valley cover and houses the PCV valve.



PN485B



PN485E

- PN485B** 1957-77 PCV Valve (GM) 3.50/ea.
PN485D PCV Hose 3/8" (AP) 1.00/ft.



- PN485DC** PCV Hose 3/8" w/ Correct "Gas" Print (RE) 3.00/ft.

There has been much controversy as to whether this was used by the Factory for PCV hose. We have researched Factory photos and low mileage original cars and found this "GAS GAS" printed hose for the PCV system.

- PN485E** PCV Hose Clamps (RE)50/ea.


- PN485J** 1957-64 Crankcase Vent Hose Bracket (RE) .. 13.00/ea.

- PN485JB** 1965-Early '66 Crankcase Vent Hose Bracket (RE) .. 15.00/ea.

- PN485JD** Late '66-67 Crankcase Vent Hose Bracket (RE) .. 15.00/ea.

These new vent hose brackets are improved since they no longer are welded but rolled as original.

See diagram above PN480 for vent hose brackets.



- PN486J** 1968-77 Crankcase Ventilation Filter (RE) 5.00/ea.

PN486J mounts inside the air cleaner and connects to the crankcase vent pipe.

PN486L 1968-77 Crankcase Ventilation Filter Clip (GM)..... \$ 2.00/ea.

This clip holds PN486J in place.

PN486N 1965 Crankcase Vent Pipe, 421 HO w/Closed Crankcase (RE) 40.00/ea.

PN486P 1968-73 Crankcase Vent Pipe (RE)..... 29.00/ea.

PN486T Vent Pipe to Filter Hose w/ Correct Ribbed Design (RE) 2.00/ea.



PN487J

PN487P

PN487J 1968-72 Air Inlet Thermal Vacuum Sensor (GM)..... 16.00/ea.

PN487K 1973-77 Air Inlet Thermal Vacuum Sensor (GM)..... 16.00/ea.

Note: These are the cold start sensors usually mounted on the air cleaner base. They regulate the amount of exhaust manifold preheated air allowed to the engine during warm-up.

PN487P 1968-69 Thermostatic Vacuum Control Switch (GM)..... 35.00/ea.

This switch mounts on the front of the intake manifold. It is imperative for the correct operation of your car that this unit function properly.

Note: Applications for this part are as follows: 1968 ALL and 1969 ALL AT.

VACUUM ADVANCE LINES



PN488T

PN488P 1967 Vacuum Advance Lines (Calif. Only) - AT (RE)..... 24.00/set

This is a steel two-piece set.


PN488R 1967 Vacuum Advance Line (Exc. Calif.) - MT (RE) 12.00/ea.

This is a steel one-piece line.

PN488T 1969 Vacuum Advance Line - 4 BBL - MT (RE) 12.00/ea.

This steel line mounts on the driver's side of the carburetor routing ported vacuum to the distributor.

VACUUM HOSE KITS



PN489K 1968 Vacuum Hose Kit w/ Thermostatic Switch Plug, 5 Port Design (RE) \$ 54.00/kit

PN489N 1969 Vacuum Hose Kit w/ Thermostatic Switch Plug, 3 Port Design (RE)..... 39.00/kit

These kits contain the rubber plug with color coded vacuum hoses that connect the switch to all the components, instructions included. The vacuum switch is not included. For switch use PN487P.

Since new federal laws mandate 1968 and newer cars be equipped with original pollution control devices, these kits are a must.



PN489RJ

PN489RJ Vacuum Port Plug Kit (AP) 3.00/kit

This kit contains 1/4", 1/8", and 3/16" plugs for various locations where the port is not used.

MISCELLANEOUS



PN495

PN495 1958-66 Valve Cover Wire and/or Vacuum Hose Retainer (RE) 12.00/ea.

These retainers were used in 1958-60 cars w/AC, 1961 ALL, 1962 cars w/AT and ALL 1963-66 cars.



PN495B

PN495B 1968-69 Switch Harness Support (RE).....\$ 22.00/ea.

This support mounts to the two center intake manifold bolts on the passenger side.

Note: Applications for this part are 1968 ALL, and 1969 ALL AT.



PN495J

PN495J 1968-77 Valve Cover Wire Clips (RE) 8.00/pr.

These are the cad-plated clips that are held in place by the valve cover bolts. PP101 plastic straps snap into these clips and retain the engine wire harness.



PN500

PN500 1963-65 & '67 Valve Cover Plug (RE) 3.50/ea.



PN501

PN501 1968-77 Valve Cover Vent Pipe Grommet (GM)..... 1.50/ea.

SPARK PLUG WIRE LOOMS



PN520 1962-63 Spark Plug Wire Loom Brackets and Retainers (RE) 40.00/set

Note: Consists of two brackets and three retainers.

PN520A 1964 Spark Plug Wire Loom Brackets and Retainers, 2 and 4 BBL (RE)..... 33.00/set

Note: Consists of two brackets and three retainers.

PN520AA 1964 Spark Plug Wire Loom Brackets and Retainers, Tri-Power (RE) 50.00/set

Note: Consists of two brackets and three retainers.

PN520B 1965 Spark Plug Wire Loom Brackets and Retainers (RE) 52.00/set

Note: Consists of two brackets and three retainers.

PN520C 1966 Spark Plug Wire Loom Brackets and Retainers (RE) \$ 52.00/set

Note: Consists of two brackets and three retainers.

PN520D 1967 Spark Plug Wire Loom Brackets and Retainers (RE) 42.00/set

Note: Consists of two brackets and three retainers.

PN520E 1968-69 (exc. '69 w/AC) Spark Plug Wire Loom Brackets (RE) 60.00/set

Note: Consists of six neoprene coated brackets.

PN520F 1969 (w/AC) Spark Plug Wire Loom Brackets (RE) 60.00/set

Note: Consists of six neoprene coated brackets.

PN520H 1970 Spark Plug Wire Loom Brackets (RE)..... 60.00/set

Note: Consists of six neoprene coated brackets.

PN520J 1971-77 Spark Plug Wire Loom Retainers (RE)..... 9.00/set

Note: This kit is for cars w/o HEI systems. Consists of four retainers.



PN523J

PN523J 1955-56 Spark Plug Wire Retainer (RE)..... 6.00/ea.



PN525

PN524 1965-67 Spark Plug Wire Retainer (2-Wire) (GM)..... Disc.

PN525 1961-67 Spark Plug Wire Retainer (4-Wire) (GM)..... Disc.



SPARK PLUG WIRES

PN525AA 1955-56 Spark Plug Wire Set All w/o 2-4bbl. (RE)..... 59.00/set

PN525AC 1956-57 Spark Plug Wire Set w/ 2-4bbl. or 3-2bbl. (RE)..... 59.00/set

PN525AE 1957 Spark Plug Wire Set w/ Fuel Injection (RE) 59.00/set

PN525AG 1957 Spark Plug Wire Set w/ Single Carb (RE)..... 59.00/set

PN525AJ 1958 Spark Plug Wire Set w/ Fuel Injection (RE) 59.00/set

PN525AL 1958 Spark Plug Wire Set w/o Fuel Injection (RE) 59.00/set

PN525AN 1959-60 Spark Plug Wire Set w/ Single Carb (RE)..... 59.00/set

PN525AP 1959-60 Spark Plug Wire Set w/ 3-2bbl. (RE) 59.00/set

PN525AR 1961 Spark Plug Wire Set All (Not Dated) (RE)..... 59.00/set

Note: PN525AA thru PN525AR are not available with date codes.



Note: The following original-style plug wires have just become available. Using dated plug wires will greatly affect people in the restoration field. Packard used this dated wire from 1961 through 1974.



Dating Information: Original wires were printed like the above example. "TVRS" means Television Radio Suppression. The date code consists of a number designating the quarter, "Q" denoting quarter, and the last two digits indicate the year. The wire photographed above was made in the second quarter of 1963. Original wires were manufactured 6 months to 1 year AHEAD of the actual automobile assembly date. Order your correctly dated wires by subtracting six to twelve months from your car's assembly date. This date is stamped on the cowl tag. Example: a 1966 car with "04C" (third week of April) on the tag can use wires with either 4Q65 or 2Q65 codes.



PN525A T	Spark Plug Wire Set 1-Q-61 (RE)	\$ 59.00/set
PN525A V	Spark Plug Wire Set 3-Q-61 (RE)	59.00/set
PN525A W	Spark Plug Wire Set 1-Q-62 (RE)	59.00/set
PN525A X	Spark Plug Wire Set 3-Q-62 (RE)	59.00/set
PN525A Z	1962-63	
	Spark Plug Wire Set - (Not Dated)	
	Super Duty (RE)	59.00/set

Note: PN525AZ uses solid core wires that will result in radio interference.

PN525A	Spark Plug Wire Set 2-Q-63 (RE)	59.00/set
PN525B	Spark Plug Wire Set 4-Q-63 (RE)	59.00/set
PN525C	Spark Plug Wire Set 2-Q-64 (RE)	59.00/set
PN525D	Spark Plug Wire Set 4-Q-64 (RE)	59.00/set
PN525E	Spark Plug Wire Set 2-Q-65 (RE)	59.00/set
PN525F	Spark Plug Wire Set 4-Q-65 (RE)	59.00/set
PN525G	Spark Plug Wire Set 2-Q-66 (RE)	59.00/set
PN525H	Spark Plug Wire Set 4-Q-66 (RE)	59.00/set
PN525J	Spark Plug Wire Set 2-Q-67 (RE)	59.00/set
PN525K	Spark Plug Wire Set 4-Q-67 (RE)	59.00/set

Note: 2Q66 or 4Q66 wires should be used on all '67 model cars to insure proper fit and correct length wires. 2Q67 wires are used only on early production '68 models.

PN525L	Spark Plug Wire Set 2-Q-68 (RE)	\$ 59.00/set
PN525M	Spark Plug Wire Set 4-Q-68 (RE)	59.00/set
PN525N	Spark Plug Wire Set 2-Q-69 (RE)	59.00/set
PN525O	Spark Plug Wire Set 4-Q-69 (RE)	59.00/set

Note: 1969 model year applications with air conditioning require different wire sets - please inquire.

PN525P	Spark Plug Wire Set 2-Q-70 (RE)	59.00/set
PN525Q	Spark Plug Wire Set 4-Q-70 (RE)	59.00/set
PN525R	Spark Plug Wire Set 2-Q-71 (RE)	59.00/set
PN525S	Spark Plug Wire Set 4-Q-71 (RE)	59.00/set
PN525SAC	Spark Plug Wire Set 1-Q-72 (RE)	59.00/set
PN525SAE	Spark Plug Wire Set 3-Q-72 (RE)	59.00/set
PN525SAG	Spark Plug Wire Set 1-Q-73 (RE)	59.00/set
PN525SAJ	Spark Plug Wire Set 3-Q-73 (RE)	59.00/set
PN525SAL	Spark Plug Wire Set 1-Q-74 (RE)	59.00/set

Note: These plug wire sets are custom cut to the correct lengths and do not fit cars with unitized distributors. They are a must for the purist.

HEI PLUG WIRES

PN525SAT	1974-77 HEI Ignition Plug Wire Set (AC Delco)	35.00/set
-----------------	---	-----------



These Packard wires are Delco replacements. They may not have the same configurations or markings as originals.

AC-DELCO SPARK PLUGS



PN525SC	1959-66 Spark Plug, All 389ci (AC-Delco) ..	1.75/ea.
PN525SF	1962-66 Spark Plug, All 421ci (AC-Delco) ..	1.75/ea.
PN525SJ	1967-69 Spark Plug, All 400ci (AC-Delco) ..	1.75/ea.
PN525SM	1967-69 Spark Plug, All 428ci (AC-Delco) ..	1.75/ea.
PN525SP	1970-71 Spark Plug, All Pont. 350ci and 400ci 4bbl. (AC-Delco)	1.75/ea.
PN525SS	1970-71 Spark Plug, All 400ci 2bbl. (AC-Delco)	1.75/ea.
PN525SV	1970-71 Spark Plug, All 455ci (AC-Delco) ..	1.75/ea.
PN525SY	1972-74 Spark Plug, All Pont. 350ci and 400ci 2bbl. (AC-Delco)	1.75/ea.
PN525TA	1972-74 Spark Plug, All 400ci 4bbl. and 455ci (AC-Delco)	1.75/ea.
PN525TD	1975-77 Spark Plug, All Pont. 350ci 2bbl. and 400ci 2bbl. (AC-Delco)	1.75/ea.

- PN525TG** 1975-77 Spark Plug, All Pont. 350ci 4bbl. and 400ci 4bbl. (AC-Delco) \$ 1.75/ea.
PN525TJ 1975-76 Spark Plug, All 455ci (AC-Delco) .. 1.75/ea.

DISTRIBUTORS AND COMPONENTS



- PN526AD** 1963-73 Points Type Remanufactured Distributor, All Pont. V-8 exc. TI or Unitized (RP) 65.00/ea.

This distributor comes complete with vacuum advance, points set, condensor, lead wire and advance weights. Cap and rotor are not included.

- PN526AG** 1974-77 HEI Remanufactured Distributor, All Pont. V-8 (RP) 139.00/ea.

This distributor comes complete with vacuum advance, module, lead wires and advance weights. Cap, rotor and coil are not included.

Note: PN526AD and PN526AG are replacement distributors. They will not have correct date codes or part numbers. These distributors carry a 90-day warranty.



PN526AJ

- PN526AJ** 1957-73 Points Set, Clip-on Type Terminal, All Pont. V-8 (AC-Delco) 8.00/ea.



PN526AM

- PN526AM** 1957-73 Condensor, All Pont. V-8 exc. TI or Unitized (AC-Delco) 3.50/ea.



PN526AQ

- PN526AQ** 1957-73 Rotor, All Pont. V-8 exc. TI or Unitized (AC-Delco) 4.00/ea.



PN526BF

- PN526BC** 1974-77 Rotor, All Pont. V-8 w/ HEI (AC-Delco) \$ 5.50/ea.
PN526BF 1957-73 Distributor Cap, All Pont. V-8 exc. TI or Unitized and 1957 3x2 (AC-Delco) 10.50/ea.

Although these Delco caps are visually correct, they do not have the same markings as originals.

- PN526BJ** 1974-77 Distributor Cap, All Pont. V-8 w/ HEI (AC-Delco) 15.00/ea.



PN526BM

- PN526BM** 1960-73 Ignition Coil, All Pont. V-8 exc. TI or Unitized (AC-Delco) 27.00/ea.

This is a Delco replacement coil. It is visually correct except it does not have the same markings as originals.

- PN526BP** 1974-77 HEI Ignition Coil, All Pont. V-8 (AC-Delco) 35.00/ea.

- PN526BR** 1974-77 HEI Ignition Coil Cover, All Pont. V-8 (AC-Delco) 14.50/ea.

- PN526BS** 1974-77 HEI Ignition Distributor Module, All Pont. V-8 (AC-Delco) 27.00/ea.



PN526BP

VALVE COVERS AND COMPONENTS



PN526E

- PN526C** 1959-64 Chrome Valve Covers w/push on style cap (Covers only) (APE) 119.00/set

These are offered because many customers have asked for this style chrome cover as an excellent dress up item.

- PN526D** 1964 Chrome Valve Covers w/twist in style cap (Covers only) (APE) 119.00/set

- PN526E** 1965 Chrome Valve Covers (APE) 119.00/set


- PN526F** 1966 Chrome Valve Covers (APE) 119.00/set

- PN526G** 1967-77 Chrome Valve Covers (APE) 99.00/set

Comments: Excellent

Comments: Both stamping and chrome quality are good to excellent.

Note: Valve covers do not come with gaskets or bolts.



PN527F

PN527F 1955-77 Zinc-Plated Valve Cover Bolts
(8 pcs.) (APE) \$ 15.00/set

These are identical to original GM valve cover bolts (5/16" thread x 9/16" long with a 7/16" hex head).


PN527G 1955-77 Standard Valve Cover Gaskets
(GM) 18.00/pr.

These gaskets are original GM neoprene approximately .140" thick. Use for all applications except modified valve trains.

PN527H 1955-77 Hi-Performance Valve Cover
Gaskets (AP) 20.00/pr.

These Hi-Performance cork gaskets are 1/4" thick for use with those engines modified with extreme valve trains or extensive baffle assemblies.

VALVE COVER KITS



PN527K

PN527K 1955-77 Standard Valve Cover Gaskets
& Bolts (GM) 30.00/kit

Note: Contains 1 pr. of PN527G gaskets and 1 set of PN527F bolts.

PN527M 1955-77 Hi-Performance Valve Cover
Gaskets & Bolts (AP) 32.00/kit

Note: Contains 1 pr. of PN527H gaskets and 1 set of PN527F bolts.

PN527N 1967-77 Valve Covers, Standard Gaskets
& Bolts 126.00/kit

Note: Contains 1 pr. of PN526G valve covers, 1 pr. of PN527G gaskets and 1 set of PN527F bolts.

PN527P 1967-77 Valve Covers, Hi-Performance
Gaskets & Bolts 131.00/kit

Note: Contains 1 pr. of PN526G valve covers, 1 pr. PN527H gaskets and 1 set of PN527F bolts.

OIL BREATHER CAPS



PN530

PN534Y

PN535

PN530 1955-57 Valve Cover Oil Breather Cap
(Exc. '57 F1 and 3x2 BBL)
(Painted) (RP) \$ 15.00/ea.

PN531 1957 Valve Cover Oil Breather Cap
w/F1 or 3x2 BBL (Painted) (RP) 10.00/ea.

PN531 1958 Valve Cover Oil Breather Cap
(Painted) (RP) 10.00/ea.

PN530 1959-64 Valve Cover Oil Breather Cap
(Exc. '63-'64 3x2 BBL, 421 HO,
and SD) (Painted) (RP) 15.00/ea.

PN531 1963-64 Valve Cover Oil Breather Cap
w/3x2 BBL, 421 HO, and SD
(Painted) (RP) 10.00/ea.

PN530 1965-67 Valve Cover Oil Breather Cap
(Painted) (RP) 15.00/ea.

Note: PN530 and PN531 are replacement parts from GM that do not match the original equipment. They are painted gray with smooth tops. They fit and function fine.

PN534Y 1964 Valve Cover Oil Breather Cap
(421 Tri-Power) (Type FC-45
Chrome - Calif.) (RE) 40.00/ea.

PN535 1964-67 Valve Cover Oil Breather Cap
(Chrome) (Twist-On) (APE) 30.00/ea.

PN535 is a chrome-plated reproduction of the original part with the correct double dimples and embossed AC-OIL logo. Quality is excellent.



PN536



PN536B

PN536 1967-77 Valve Cover Oil Filler Cap (RE) Inquire

This project has not gone well. We have not given up but must improve the spot-welding method before it is released. For an inexpensive replacement, see PN536B.

PN536B 1968-77 Valve Cover Oil Filler Cap (AP) 5.00/ea.

This is not the original design cap but is an excellent chrome afterproduct replacement.

ENGINE MOUNTS



PN548

PN548 1955-57 Engine Rear Support Mount (RE) 70.00/pr.

PN550A 1959-64 Engine Mount - LH (AP) 15.00/ea.

PN550B 1959-64 Engine Mount - RH (AP) 15.00/ea.

PN550 1965-70 Engine Mount - FS, LH or RH (AP) ... 15.00/ea.

PN550A	1969	Engine Mount - GP, LH (AP)\$ 15.00/ea.
PN550B	1969	Engine Mount - GP, RH (AP) 15.00/ea.
PN551L	1970-73	Engine Mount - GP, LH (AP) 18.00/ea.
PN551R	1970-73	Engine Mount - GP, RH (AP) 18.00/ea.
PN551L	1971-72	Engine Mount - FS w/HD Frame, LH (AP) 18.00/ea.
PN551R	1971-72	Engine Mount - FS w/HD Frame, RH (AP) 18.00/ea.
PN553	1973-76	Engine Mount - FS, L or R (AP) 25.50/ea.
PN555	1974-77	Engine Mount - GP, L or R (AP) 15.50/ea.

VALVE TRAIN COMPONENTS



PN596

PN594	1964-66	1.5 Ratio Rocker Arm w/ Ball, All Pontiac V-8 (RP) 9.00/ea.
--------------	---------	---	----------------

Note: Also fits 1967 326 and 400 2bbl.

PN596	1967-77	1.5 Ratio Rocker Arm w/ Ball & 3/8" Nut, All Pontiac V-8 exc. 1967 326, 1967 400 2bbl., RAIV, 301 (RP) 5.00/ea.
--------------	---------	--	----------------

PN598	1967-77	1.65 Ratio Rocker Arm w/ Ball & 3/8" Nut, All Pontiac V-8 exc. 301 or 1967 400 2bbl. (RP) Inquire
--------------	---------	---	---------------

PN600	1967-77	1.65 Ratio Rocker Arm Set w/ Balls & 3/8" Nuts, All Pontiac V-8 exc. 301 or 1967 400 2bbl. (Set of 16) (RP) Inquire
--------------	---------	---	---------------

We have found PN598 and PN600 to be a true 1.65 ratio rocker arm, which increases valve lift considerably over the stock 1.5 ratio.

Comments: Easy bolt on performance. The best pressed steel rockers on the market.

PN602	1967-77	Rocker Arm Nut, 3/8", All Pontiac V-8 exc. RAIV or 1967 400 2bbl. (RP)75/ea.
--------------	---------	--	---------------



PN604



PN606

PN604	1967-77	Screw In Rocker Arm Stud, 3/8" Bottleneck, All Pontiac V-8 exc. RAIV (RP) 4.00/ea.
--------------	---------	---	----------------

PN605	1959-60	Pushrod, All 389 V-8 (RP) \$ 2.50/ea.
--------------	---------	---------------------------	-------------------

Note: Diameter: .315" Length: 9.145"

PN606	1961-66	Pushrod, All Pontiac V-8 (RP) 2.50/ea.
--------------	---------	-------------------------------	----------------

Note 1: Also fits 1967 400 2bbl.

Note 2: Diameter: .315" Length: 8.715"

PN608	1967-77	Pushrod, All Pontiac V-8 exc. 1967 400 2bbl., RAIV & RAIV (RP) 2.50/ea.
--------------	---------	---	----------------

Note: Diameter: .315" Length: 9.145"

PN609	1968	RAIV Pushrod (RP) 3.00/ea.
--------------	------	-------------------	----------------

Note: Diameter: .340" Length: 9.137"

Caution: Pushrod to guide hole interference may occur if PN609 is used with non RAIV heads.

PN609B	1969-70	RAIV Pushrod (RP) 4.00/ea.
---------------	---------	-------------------	----------------

Note: Diameter: .340" Length: 9.205"

Caution: Pushrod to guide hole interference may occur if PN609B is used with non RAIV heads.



PN610

PN610	1967-77	Pushrod Guideplate, All Pontiac V-8 exc. RAIV, RAIV, and 301 (GM) 3.00/ea.
--------------	---------	--	----------------

Note: Requires 4 per car.



PN612

PN612		Valve Spring Set for PN614, PN616 and PN618 Camshafts (RP) 95.00/set
--------------	--	---	-----------------

PN613	1963-77	Cylinder Head to Block Alignment Pin (GM) 1.00/ea.
--------------	---------	--	----------------

4 Required per engine block.



PN613

CAMSHAFTS AND COMPONENTS



Ames Performance now offers camshafts for your restoration. A variety of cams are available for hundreds of different piston, head and valve train combinations, but we concentrate on factory specifications.

Our cams have stock duration, lift, overlap, and profiles for your original engine configuration and are all supplied by Crane—the nation's leader in cam technology.

Stock cams can also enhance performance. Please refer to the description of each shaft for your particular needs.

- PN614** 1959-77 Hydraulic Camshaft, OEM Replacement for GM # 9779066 (RP)..... \$ 89.00/ea.

This camshaft replaces the standard horsepower workhorse cams from 1959 to 1976. The actual grind is a blueprint of the 9779066 (since the 067 is almost identical, Crane recommends the 066 in those applications).

Performance Note: PN614 can be used in 326, 350, and low compression 400 engines if a modest performance increase is desired.

- PN616** 1959-77 Hydraulic Camshaft, OEM Replacement for GM # 9779068 (RP)..... 109.00/ea.

This is an exact profile for some of the finest stock street engines Pontiac ever engineered (1967-68 HO, 1968 Ram Air I, 1969-70 RA III, 1971-72 455 HO etc.).

Performance Note: Certainly the best for exact restoration, but also our choice for those individuals seeking horsepower increases from standard horsepower engines.

- PN618** 1959-77 Hydraulic Camshaft, OEM Replacement for GM # 9794041 (RP)..... 109.00/ea.

This is the famous RAII and RAIV shaft used in 1968-70 and originally scheduled for the 1973 Super Duty engines. This cam is the best choice for correct restorations.

Performance Note: This cam can produce large horsepower gains when installed in standard horsepower engines. However, be aware that the horsepower and torque bands are such that this cam is less streetable than the PN616.

- PN620** Camshaft Installation Tool (AP)..... 25.00/ea.

This tool allows easy installation of the camshaft without causing severe damage to cam bearings.



PN621

PN624

- PN621** 1969-70 RAIV Lifter Set (RP)..... \$ 89.00/set

These are the special "Low Ball" lifters used on RAIV applications to minimize valve float and gain maximum RPM.

Note: RAIV applications only.

- PN622** 1959-77 Hydraulic Lifters, OEM Replacement, All Pontiac V-8 exc. RAIV & 301 (RP) 49.00/set
- PN624** 1959-77 Camshaft Thrust Plate, All Pontiac V-8 (RP) 23.00/ea.
- PN626** 1959-77 Camshaft Timing Gear Key, All Pontiac V-8 (RP) 1.00/ea.

TIMING CHAINS AND COMPONENTS



PN628

- PN628** 1959-77 Timing Chain and Gear Set, All Pontiac V-8 exc. 301 (RP) 39.00/set
- PN630** 1959-77 Double Roller Timing Chain & Gear Set, All Pontiac V-8 exc. 301 (RP) 89.00/set

These Cloyes timing chain sets are the best on the market for the price.

Performance Note: For more precise timing and durability we recommend going with the PN630 double roller timing chain set.



PN632



PN634




PN636

- PN632** 1959-77 Fuel Pump Eccentric, All Pontiac V-8 (GM) 10.00/ea.
- PN634** 1959-77 Camshaft Timing Gear Bolt, All Pontiac V-8 (GM) 2.00/ea.
- PN636** 1959-77 Camshaft Timing Gear Bolt Washer, All Pontiac V-8 (GM) 3.50/ea.



TIMING CHAIN COVER AND COMPONENTS



- PN638** 1969-77 Timing Chain Cover, All Pontiac V-8 exc. 301 (GM) \$ 97.00/ea.

For years, the various timing chain covers for 1964-1968 Pontiacs have been in high demand.

As this catalog goes to press we are receiving quotes to retool these covers. If costs are feasible we will proceed with manufacture. Please inquire.

- PN638C** 1959-62 Timing Chain Cover Gasket Set, All Pontiac V-8 (RP) 18.00/set
- PN638F** 1963 Timing Chain Cover Gasket Set, All Pontiac V-8 with 4 Bolt Water Pump (RP) 19.00/set
- PN638J** 1963-77 Timing Chain Cover Gasket Set, All Pontiac V-8 exc. 4 Bolt Water Pump (RP) 19.00/set
- PN639** 1959-77 Timing Chain Cover Bolt Kit, All Pontiac V-8 (RP) 9.00/kit
- PN640** 1959-77 Timing Chain Cover Stud, All Pontiac V-8 (RP) 2.00/ea.

Measures 3/8" x 3 11/16" 2 required per car.



- PN641** 1962-77 Engine Hoist Bracket (RE) 7.00/ea.

It's difficult to believe the extent to which correct restorations have evolved. However, even this hoist bracket is a necessity. Mounted on the upper right hand timing chain cover bolt, it was originally used when lowering the engine into the chassis.

- PN642** 1962-77 Intake Manifold to Timing Chain Cover Bolt and Clamp (RE) 7.00/ea.



ENGINE BEARINGS AND CAPS



PN646

- PN643** 1959-77 Cam Bearing Set, All Pontiac V-8 exc. 301 (RP) \$ 18.00/set
- PN644** 1959-77 Standard Connecting Rod Bearing Set, All Pontiac V-8 exc. 301 (RP) 49.00/set
- PN646** 1959-77 Standard Main Bearing Set, All Pontiac V-8 exc. 421, 428 and 455 (RP) 69.00/set
- PN647** 1961-77 Standard Main Bearing Set, All Pontiac 421, 428 and 455 (RP) 79.00/set

We have found Clevite 77 bearings to be by far the best rod and main bearings on the market. Because of their tri-metal construction they withstand the friction, dirt, wear, and heat that chew away bearing and journal life.


Please Note: If you need undersized bearings, please contact us with your application.



- PN650** Plastigage, .001-.003 Clearance (AP) 2.00/ea.
- Plastigage is used to measure bearing clearances. This is an absolute necessity when rebuilding an engine.



- PN651** 1963-77 Connecting Rod Bolt 3/8", All Pontiac V-8 exc. 455 Super Duty (GM) 4.50/ea.
- PN651G** 1963-77 Connecting Rod Nut 3/8", All Pontiac V-8 exc. 455 Super Duty (AP) Disc.



- PN651J** 1963-77 Heavy Duty Connecting Rod Bolt Set with Nuts, 3/8", All Pontiac V-8 exc. 455 Super Duty (AP) 89.00/set



- PN652** 1959-77 4 Bolt Main Bearing Cap Set, All Pontiac V-8 exc. 421, 428 and 455 (AP) 320.00/set

- PN653** 1962-76 4 Bolt Main Bearing Cap Set , All Pontiac 421, 428 and 455 (AP)\$ 320.00/set

When non 4-bolt main blocks are fitted with PN652 - PN653 they must be drilled and tapped. All blocks must be line bored.



OIL PUMPS AND COMPONENTS



PN654



PN658

- PN654** 1959-77 Standard 60 PSI Oil Pump w/ Screen, All Pontiac V-8 exc. 301 and RAIV (RP)..... 39.00/ea.
- PN656** 1959-77 80 PSI High Pressure Oil Pump w/ Screen, All Pontiac V-8 exc. 301 (RP)..... 54.00/ea.


We strongly recommend using the PN660 heavy duty oil pump drive rod with the PN656 high pressure oil pump.

- PN658** 1959-77 Oil Pump Drive Rod, All Pontiac V-8 exc. 301, RAIV, 455 HO and 455SD - OE Replacement (RP)..... 9.00/ea.
- PN660** 1959-77 Heavy Duty Oil Pump Drive Rod, All Pontiac V-8 exc. 301 (RP)..... 15.00/ea.

PN660 was originally used on RAIV, 455 HO, and 455 SD. We suggest using this in any high performance application. PN660 may be used in place of standard shaft.



PISTON RINGS



- PN662** 1959-66 389 ci Piston Ring Set, Standard (RP)..... 49.00/set
- PN664** 1963-66 421 ci Piston Ring Set, Standard (RP)..... 49.00/set
- PN666** 1968-77 Pontiac 350 ci Piston Ring Set, Standard (RP)..... 49.00/set

- PN668** 1967-77 Pontiac 400 ci Piston Ring Set, Standard (RP)..... \$ 49.00/set
- PN670** 1967-69 Pontiac 428 ci Piston Ring Set, Standard (RP)..... 49.00/set
- PN672** 1970-76 Pontiac 455 ci Piston Ring Set, Standard (RP)..... 49.00/set

For years Sealed Power Rings have been the best OEM replacement out there. They have a unique top ring design which helps seal against blow-by and provides excellent oil control.

Please Note: If you need oversized piston rings, please contact us with your application.




FREEZE PLUGS



- PN674** 1959-77 Steel Freeze Plug Set, All Pont. V-8 (RP)..... 7.00/set
- PN676** 1959-77 Brass Freeze Plug Set, All Pont. V-8 (RP)..... 15.00/set



ENGINE GASKET OVERHAUL SETS



- PN677** 1958-60 Complete Engine Gasket Overhaul Set, All Pontiac V-8 (RP)..... 95.00/set
- PN678** 1961-66 Complete Engine Gasket Overhaul Set, All Pontiac V-8 (RP)..... 95.00/set

Note: This kit does not include a 1961-62 timing cover seal.

- PN680** 1967-77 Complete Engine Gasket Overhaul Set, All Pontiac V-8 (RP)..... 95.00/set

We recommend and use only Felpro gaskets for all applications from stock to highly modified. Their state of the art Perma Torque, Perma Seal construction give a tight solid seal.

Note 1: These kits do not fit 301, RAIV, RAIV, 455 HO, or 455 SD. Please inquire about these applications.

Note 2: These kits do not contain any carburetor gaskets.

HARMONIC BALANCER AND HARDWARE



PN688

PN688 1968-77 Harmonic Balancer, All Pontiac V-8 exc. RAIV and 301 (GM)..... \$94.00/ea.



PN692

PN690 1959-77 Harmonic Balancer Crank Key, All Pontiac V-8 exc. (GM)..... 3.00/ea.

PN690

PN692 1959-77 Harmonic Balancer Bolt, All Pontiac V-8 exc. (GM)..... 6.00/ea.

PN693 1959-77 Harmonic Balancer Washer, All Pontiac V-8 exc. (GM)..... \$ 3.50/ea.



ENGINE OVERHAUL KITS

Complete engine overhaul kits are now available. These kits are made from the best brand names and quality on the market.

Kits include: cam, lifters, timing chain and gear set, cam bearings, connecting rod bearings, main bearings, piston rings, pistons, oil pump with screen, freeze plug set, complete gasket set, and plastigage.

Please call with application for pricing and availability.



ENJOY THE QUALITY!

Quality has always been paramount at Ames Performance - It set us apart in 1976, it set us apart in 1985, and in 1997, and will continue to set us apart in the future.

To order quality parts, please call (800) 421-AMES (2637).

For questions or ordering, call (603) 876-3345

(603) 876-4656

(603) 876-4751

SECTION THIRTEEN-ENGINE COMPARTMENT

COMPARTMENT STRAPS AND RETAINERS




PP101

PP101 P-4007 Black Nylon Compartment Strap, 2.75" (RP)..... \$.75/ea.

PP101C P-4007 Black Nylon Compartment Strap, 3.75" (RP)..... .75/ea.

You'll find these straps holding various rubber hoses and wires in the engine compartment. These products are the same black straps with raised letters denoting part #P-4007 and correct lengths.



PP102

PP102

Core Support Wire Retainers (GM).. \$ 2.00/ea.

Many full-size cars used these retainers under the top of the core support. Not easily visible, these retainers hold the wires that cross the core support.

BATTERY TRAYS AND COMPONENTS



PP111B

PP111B 1964 Battery Tray (RE)..... 14.00/ea.

PP115 1969-72 Battery Tray - GP (GM)..... 20.00/ea.

- PP115B** 1969-72 Battery Tray - GP (RE)..... \$ 14.00/ea.
PP115D 1973-76 Battery Tray - FS (GM)..... Disc.
PP115G 1973-77 Battery Tray - GP (GM) Disc.



PP115J

- PP115J** 1969-72 Battery Detailing Package - GP (RE)..... 18.00/ea.

This package includes PP115B, PP126, PP133 and PP134.



PP116

- PP116** 1955-57 Battery Hold-Down Retainer (RP) ... 14.00/ea.

This retainer is not exact but is very similar. Originals were made of four pieces spot-welded together while PP116 is stamped from one piece.



PP116B

- PP116B** 1955-57 Battery Hold-Down Rubber Pads 5.00/set

These pads mount to the top of the battery to keep the metal hold-down away from the corrosive chemicals.



PP120



PP126

- PP120** 1958-63 Battery Hold-Down Clamp - Std. Battery (RE)..... 13.00/ea.
PP121 1964 Battery Hold-Down Clamp (APE).... 13.00/ea.
PP122 1965 Battery Hold-Down Clamp (APE).... 13.00/ea.

- PP123** 1966 Battery Hold-Down Clamp (APE) \$ 13.00/ea.
PP125 1967-72 Battery Hold-Down Clamp - FS (APE)..... 13.00/ea.
PP126 1969-72 Battery Hold-Down Clamp - GP (APE)..... 5.00/ea.
PP126J 1973-77 Battery Hold-Down Clamp - ALL (APE)..... 13.00/ea.

Original battery hold-downs become corroded and ruin the appearance of an engine compartment. These reproductions (exc. PP126) are made in our own shop using correct diameter steel rod. After fabricating these clamps to exact specifications they are dipped - producing the desired coating.

Comments: Very good.

- PP129P** 1955-57 Battery Hold-Down Bolt (RP) 3.00/ea.

Two of these bolts are needed with the PP116 retainer.



PP130

- PP130** 1961-63 Battery Hold-Down Bolt (APE) 4.00/ea.

This long discontinued battery bolt has now been reproduced. Quality is excellent.

- PP131** 1964-66 Battery Hold-Down Bolt (APE) 4.00/ea.
PP132 1967-76 Battery Hold-Down Bolt - FS (GM).. 4.00/ea.
PP133 1969-72 Battery Clamp Bolt - GP (GM)50/ea.
PP132 1973-77 Battery Hold-Down Bolt - GP (GM) 4.00/ea.



PP134

- PP134** Extruded "U" Nut (5/16" x 18) (AP) ... 1.00/ea.

Similar to caged nuts, the "U" nuts are used on some battery trays, fan shrouds, etc.



PP150



PP151



PP152

- PP150** Battery Tray Coating (AP)..... 12.00/ea.

This coating sprays and looks like paint but is impervious to battery acid. This is an excellent way to preserve your battery tray and its satin-black luster.

- PP151** Cast-Iron Spray Gray (AP) 7.50/ea.


Ever wonder how those award winners keep cast-iron suspension components and master cylinders looking so new? There's a good chance those parts are painted with the Eastwood cast-iron spray paint (not heat resistant).

PP152 "Aluma Blast" Aluminum Paint (AP) \$ 6.50/ea.

Use this spray on any parts that need that clean original aluminum finish. Good for castings like transmissions.

Note: PP150 - PP152 are high quality Eastwood products.

DESERT COOLER RADIATORS



In an effort to help cure over-heating problems, we offer the finest radiators available. They are unique products designed and custom manufactured for hot weather driving.

These radiators known as "Desert Coolers" have more cooling fins than conventional radiators. They all utilize four-tube cores. If your car is now equipped with a four-core radiator these units bolt in with no modifications.

If your car has a three-core radiator, we can special-order a radiator that will bolt in with no modifications too. Please inquire about these special order radiators. You should not even consider using a three-core radiator in your Pontiac. Most Pontiac motors tend to run hot and need the added efficiency of four-core radiators.

With many companies selling inexpensive inefficient radiators, Pontiac owners must rely on these high-performance "Desert Coolers" for maximum cooling.

Note: Limited warranty: US Radiator warrants its radiators to be free from defects in material plus workmanship for 1 year from date of purchase.

PP170	1961	Desert Cooler, MT (RP)	225.00/ea.
PP171	1961	Desert Cooler, AT (RP)	225.00/ea.
PP172	1962	Desert Cooler, MT (RP)	240.00/ea.
PP173	1962	Desert Cooler, AT (RP)	240.00/ea.
PP174	1963	Desert Cooler, MT (RP)	240.00/ea.
PP175	1963	Desert Cooler, AT (RP)	240.00/ea.
PP176	1964	Desert Cooler, MT (RP)	240.00/ea.
PP177	1964	Desert Cooler, AT (RP)	240.00/ea.
PP180	1965-67	Desert Cooler, MT (RP)	270.00/ea.
PP181	1965-67	Desert Cooler, AT (RP)	270.00/ea.
PP182	1968-71	Desert Cooler, MT - ALL (RP)	270.00/ea.
PP183	1968-71	Desert Cooler, AT - ALL (RP)	270.00/ea.
PP184	1972-74	Desert Cooler, MT - FS (RP)	270.00/ea.
PP185	1972-74	Desert Cooler, AT - FS (RP)	270.00/ea.
PP186	1972	Desert Cooler, MT - GP (RP)	270.00/ea.

PP187	1972	Desert Cooler, AT - GP (RP)	\$270.00/ea.
PP189	1975	Desert Cooler, AT - FS (RP)	270.00/ea.
PP189A	1975	Desert Cooler, AT - GP (RP)	270.00/ea.
PP190	1976	Desert Cooler, AT - FS (RP)	270.00/ea.
PP190A	1976	Desert Cooler, AT - GP (RP)	270.00/ea.
PP191	1977	Desert Cooler, AT - GP	
		w/301, 305 (RP)	270.00/ea.
PP191A	1977	Desert Cooler, AT - GP	
		w/300, 403 (RP)	270.00/ea.

Please add \$15.00 radiator shipping.

Note: All radiators must be **prepaid and are drop-shipped** directly from California.

New tanks are used on all Desert Coolers; however, they do not have the "Harrison" stamping. Radiators do not come with petcocks. Radiators must be re-painted if show quality is desired.

RADIATOR COMPONENTS



PP193K



PP193P

PP193K Radiator Overflow Hose (RE)..... 1.25/ft.

This exact reproduction of the 3/8" I.D. hose with .075" wall is used in full-size applications not requiring an overflow bottle.

PP193P Brass Radiator Petcock (GM) 4.00/ea.



PP195




PP197

PP195 1969-77 Radiator to Core Support Insulators (GM)..... 8.00/pr.

PP197 Radiator Core Support Bolts (GM)50/ea.

HEATER CORES & BLOWER MOTORS



PP204	1961	Heater Core w/ AC (AP)	75.00/ea.
PP205	1961	Heater Core w/o AC (AP)	Disc.
PP206	1962	Heater Core w/ AC (AP)	Disc.
PP204	1962	Heater Core w/o AC (AP)	75.00/ea.
PP207	1963-64	Heater Core All (AP)	87.00/ea.
PP210	1965-68	Heater Core w/ AC (AP)	59.00/ea.
PP211	1965-68	Heater Core w/o AC (AP)	65.00/ea.
PP212	1969-70	Heater Core w/ AC - FS (AP)	49.00/ea.
PP212	1969-72	Heater Core w/ AC - GP (AP)	49.00/ea.
PP213	1969-70	Heater Core w/o AC - FS (AP)	52.00/ea.
PP213A	1969-72	Heater Core w/o AC - GP (AP)	49.00/ea.
PP214	1971-76	Heater Core w/ AC - FS (AP)	49.00/ea.

PP214	1971-76	Heater Core w/o AC - FS (AP)	\$ 49.00/ea.
PP216	1973-77	Heater Core w/ AC - GP (AP)	59.00/ea.
PP218	1973-77	Heater Core w/o AC - GP (AP)	59.00/ea.



PP222

PP222D


PP221	1964-77	Blower Motor w/o AC - ALL (AP)	32.00/ea.
PP222	1964-77	Blower Motor w/AC - ALL (AP)	32.00/ea.
PP222D	1964-69	Blower Motor Wire Firewall Grommet, All Exc. AC (AP)	4.00/ea.
PP228J	1971-76	Blower Motor Switch - FS exc. Automatic Temperature Control (ATC) (GM)	13.00/ea.
PP228J	1973-76	Blower Motor Switch - GP exc. ATC (GM)	13.00/ea.



PP230D

PP230D	1964-71	Evaporator Drain Tube (RE)	12.00/ea.
---------------	---------	----------------------------------	-----------

This is the black drain tube that attaches to the bottom of the Evaporator box. Usually these are missing or destroyed from the engine compartment heat.



PP232J

PP232J	1955-57	Heater Control Valve to Firewall Gasket (RE)	5.00/ea.
---------------	---------	--	----------

AUTOMATIC TEMPERATURE CONTROL VACUUM COMPONENTS



PP235JC



PP235JJ

PP235JA	1965	ATC Servo System Vacuum Canister w/AC (RE)	\$ 55.00/ea.
PP235JC	1966	ATC Servo System Vacuum Canister w/AC (RE)	49.00/ea.
PP235JJ	1965-66	ATC Servo System Vacuum Line Valve w/AC (GM)	4.00/ea.

RADIATOR HOSES



PP240	1955-56	Upper Radiator Hose w/o AC (AP) ..	12.00/ea.
PP241	1957	Upper Radiator Hose w/o AC (AP) ..	12.00/ea.
PP242	1957	Upper Radiator Hose, 3-2 BBL w/o AC (Ap)	12.00/ea.
PP245	1955-57	Lower Radiator Hose w/o AC (AP) ..	14.50/ea.
PP242	1958	Upper Radiator Hose, 3-2 BBL - ALL (AP)	12.00/ea.
PP243	1958	Upper Radiator Hose w/2 or 4 BBL w/o AC (AP)	12.00/ea.
PP246	1958	Lower Radiator Hose - ALL (AP)	14.50/ea.
PP243	1959-60	Upper Radiator Hose w/o Air Susp. w/3-2 BBL (AP)	12.00/ea.
PP248	1959-60	Upper Radiator Hose w/o Air Susp. w/2 or 4 BBL (AP)	12.00/ea.
PP250	1959-60	Lower Radiator Hose - ALL (AP)	Disc..
PP248	1961-62	Upper Radiator Hose w/2 or 4 BBL (AP)	12.00/ea.
PP243	1961-65	Lower Radiator Hose - ALL (AP)	12.00/ea.
PP252	1963	Upper Radiator Hose - ALL (AP)	15.00/ea.
PP252	1964	Upper Radiator Hose w/3-2 BBL (AP)	15.00/ea.
PP253	1964	Upper Radiator Hose w/2 or 4 BBL (AP)	Inquire
PP254	1965-66	Upper Radiator Hose w/PS, w/2 or 4 BBL (AP)	15.50/ea.
PP255	1965	Upper Radiator Hose w/o PS, w/2 or 4 BBL (AP)	14.50/ea.
PP254	1966-67	Upper Radiator Hose w/PS, w/2 or 4 BBL (AP)	15.50/ea.
PP256	1966-67	Upper Radiator Hose w/o PS, w/2 or 4 BBL (AP)	16.00/ea.
PP257	1966-68	Lower Radiator Hose - ALL (AP)	12.00/ea.
PP254	1968	Upper Radiator Hose - ALL (AP)	15.00/ea.
PP258	1969-70	Upper Radiator Hose - GP (AP)	18.00/ea.
PP254	1969-70	Upper Radiator Hose - FS (AP)	15.50/ea.
PP260	1969-70	Lower Radiator Hose - FS (AP)	13.50/ea.
PP261	1971-72	Upper Radiator Hose - GP (AP)	17.00/ea.
PP259	1969-72	Lower Radiator Hose - GP (AP)	16.00/ea.
PP262	1971-72	Upper Radiator Hose - FS (AP)	17.00/ea.
PP263	1971-72	Lower Radiator Hose - FS (AP)	12.00/ea.
PP258	1973-76	Upper Radiator Hose - GP (AP)	17.50/ea.
PP259	1973-74	Lower Radiator Hose - GP (AP)	16.00/ea.
PP264	1973-76	Upper Radiator Hose - FS (AP)	15.00/ea.

PP265	1973-76 Lower Radiator Hose - FS (AP).....	\$ 13.50/ea.
PP268	1975-77 Lower Radiator Hose - GP (AP)	16.00/ea.
PP269	1977 Upper Radiator Hose - ALL w/301, 305P and 400 (AP)	16.00/ea.


HEATER HOSES



PP274J	1969-70 Heater Hose - Molded from Heater Core to Cyl. Head (Exc. AC) - GP (APE).....	16.00/ea.
---------------	--	-----------

Finally, this molded hose is available. Since it was discontinued ten years ago, restorers have been forced to use straight hose for this application. The resulting large loop always looks unprofessional.

Comments: This hose is excellent.



PP274S	1959-74 Correct 5/8" Ribbed Heater Hose (RE).....	4.50/ft.
PP274V	1959-74 Correct 3/4" Ribbed Heater Hose (RE).....	4.50/ft.

For years, all kinds of ribbed heater hose have been sold as correct for 59-74 Pontiacs. In fact many sources sell hose with ribs sticking out! From salvage yards to original low mileage cars we've only seen the pattern illustrated above. It is this five depressed rib design between flats and peaks that we have reproduced.

Comments: Excellent detailing item.

RADIATOR & HEATER HOSE CLAMPS

PP277	Original Wire-Type Hose Clamp, 1 1/2 in. Radiator Hose (AP)	1.50/ea.
PP278	Original Wire-Type Hose Clamp, 1 3/4 in. Radiator Hose (AP)	1.50/ea.
PP279	Original Wire-Type Hose Clamp, 2 in. Radiator Hose (AP)	Inquire



PP280



PP282

PP280	Original Post-Type Hose Clamp for 1 1/2 in. Radiator Hose (APE).....	\$ 1.50/ea.
PP281	Original Post-Type Hose Clamp for 1 3/4 in. Radiator Hose (APE).....	1.50/ea.
PP282	Original Post-Type Hose Clamp for 5/8 in. Heater Hose (APE)	1.50/ea.
PP283	Original Post-Type Hose Clamp for 3/4 in. Heater Hose (APE)	1.50/ea.

In an effort to find the correct years for these heater hose clamps we used dealer showroom album photos, 60's magazine articles plus the date codes stamped on clamps taken from original cars.

We found no evidence of their use from 1957-64 (use the PP284 & PP285). In '65 most cars used PP284 & PP285 but several late-production cars were equipped with post-type clamps (earliest post-type clamp date found was April '65). 1966 and newer used the post-type.



PP284

PP284	Original Wire-Type Hose Clamp for 5/8 in. Heater Hose (AP)50/ea.
PP285	Original Wire-Type Hose Clamp for 3/4 in. Heater Hose (AP)50/ea.



PP287K

PP287K	1965-77 Heater Hose Bracket w/o AC - ALL exc. '71-'75 FS (RE)	23.00/ea.
---------------	---	-----------

This bracket mounts on the front of the passenger side head and keeps the heater hose away from the exhaust manifold.



PP290N

PP290N	1965-77 Heater Hose Nipple, ALL w/Pont. V-8 (GM).....	17.00/ea.
---------------	---	-----------



PP292A

PP292A 1966-72 Heater Blower Motor Case, ALL w/o AC (GM).....\$ 33.00/ea.

This case absolutely will not fit a car that has ever had A/C.

PP293J 1965-68 Heater Box Seal w/o AC (RE) 12.00/ea.

This piece is actually a continuation of the fire-wall pad. It mounts on the inside of the car.

FAN SHROUDS



PP300 1969-70 Fan Shroud - FS (GM)..... 65.00/ea.

PP301 1969-72 Fan Shroud - GP (GM) 65.00/ea.

Note: PP301 is just the shroud. It does not include the extension.


Please add \$7.00 shipping for PP300 & PP301 fan shrouds.



PP302

PP302 1973-77 Upper Fan Shroud, Less Extension - GP (GM)..... Disc.


FAN COMPONENTS



PP304DM

PP304DK Fan Spacer, 1 1/2" (GM)..... 14.00/ea.

PP304DL Fan Spacer, 1 15/16" (GM)..... 13.00/ea.



PP304G

PP304DM Fan Spacer, 29/32" (GM)\$ 13.00/ea.

Several different lengths of fan spacers were used on V-8 engines. These different spacers are an excellent way to reposition your fan with respect to the shroud.

PP304G 1959-76 Fan Clutch, All Pontiac V-8 (RP)..... 69.00/ea.

RADIATOR CAPS



PP305A

PP305 1955-61 Radiator Cap, 13 PSI Cap (GM) 8.00/ea.

PP305A 1955-61 Radiator Cap, Correct RC-6 13 PSI (RE)..... 25.00/ea.

PP306 1957-72 Radiator Cap, 15 PSI Cap (GM) 10.00/ea.

PP306A 1955-63 Radiator Cap, Correct Early RC-15 15 PSI (RE) 25.00/ea.

PP306B 1964-72 Radiator Cap, Correct Late RC-15 15 PSI (RE) 25.00/ea.

PP305A, PP306A, and PP306B are exact reproductions of the original RC-6 and RC-15 caps. Probably more show points are lost because of incorrect replacement caps than any other single item. PP305 and PP306 are GM replacements. They do not have the same stamped surface nor the same wording as original.

PP306J 1973-76 Radiator Cap, RC-33 (GM) 9.00/ea.

PP306L 1977 Radiator Cap (GM)..... 9.50/ea.

RADIATOR SHROUD EMBLEMS



PP309


PP310

PP309 1965-66 421 Radiator Shroud Emblem (RE) .. 33.00/ea.

PP310 1967-68 428 Radiator Shroud Emblem (RE) .. 21.00/ea.

Comments: Because of the limited market PP309 and PP310 are not die-cast. They are a low pressure casting. Overall the quality is good.

COOLANT RECOVERY TANK CAPS



PP312J

PP312J 1973 Coolant Recovery Tank Cap - GP (GM)..... 3.00/ea.

PP312L 1973-76 Coolant Recovery Tank Cap - FS (GM)..... Disc.

GROUND STRAPS



PP315 Ground Strap Set (RE)..... \$ 11.00/set
of 3

This set includes 2-9 1/2" straps and 1-6" strap with attaching hardware.


PP315A Ground Strap Set (RE)..... 11.00/set
of 3

This set includes 1-9 1/2" strap, 1-6" strap and 1-4 3/4" strap with attaching hardware.

Note: Ground straps are used in various locations on full-size Pontiacs. We have found them connecting engine blocks to cowls, inner fenders to frames, and inner fenders to outer fenders.

These straps use the same style braided wire as original and are the final complement for your detailed engine compartment.

SEALS AND GASKETS




PP320

PP339	1955	Inner Fender to Outer Fender Seal (RE).....	9.00/set
PP320	1959	Upper A-Frame Seals (RE).....	18.00/pr.
PP320A	1959	Upper A-Frame Seals w/Staples (RE).....	20.00/pr.
PP321	1960	Upper A-Frame Seals (RE).....	18.00/pr.
PP321A	1960	Upper A-Frame Seals w/Staples (RE).....	20.00/pr.
PP322	1961	Upper A-Frame Seals (RE).....	15.00/pr.
PP322A	1961	Upper A-Frame Seals w/Staples (RE).....	17.00/pr.
PP322B	1961	Splash Seal Kit - 6 Pcs. w/Staples (RE).....	22.00/set

Note 1: PP322 is included in the PP322B kit.

Note 2: Some late production 1961 models use the 1962 style A-frame seal. Please refer to the photos to determine the correct seals for your 1961.



PP322

PP323

PP323	1962	Upper A-Frame Seals (RE).....	\$ 15.00/pr.
PP323A	1962	Upper A-Frame Seals w/Staples (RE).....	17.00/pr.
PP323B	1962	Splash Seal Kit - 6 Pcs. w/Staples (RE).....	22.00/set

Note: PP323 is included in the PP323B kit.

PP323J	1962	Radiator Support to Frame Seal (RE)	12.00/pr.
PP324	1963-64	Upper A-Frame Splash Seal Kit (RE).	20.00/set
PP324A	1963-64	Upper A-Frame Splash Seal Kit w/Staples (RE).....	22.00/set
PP325	1965-70	Upper A-Frame Seals - FS (RE)	16.00/pr.
PP325A	1965-70	Upper A-Frame Seals w/Staples - FS (RE)	18.00/pr.
PP325D	1965-70	Inner Fender to Frame Splash Seals w/Staples - 4 Pcs. - FS (RE).....	6.00/set
PP325J	1965	Radiator Support to Frame Seal (RE)	12.00/pr.
PP325M	1965	Lower Radiator to Frame Seal (RE)...	17.00/pr.
PP325P	1965	Upper Radiator to Core Support Seal w/AC (RE).....	8.00/ea.



PP328

PP328	1969-71	Upper A-Frame Seals - GP (RE).....	12.00/pr.
PP328A	1969-71	Upper A-Frame Seals w/Staples - GP (RE).....	14.00/pr.

These seals cover the upper A-frames protecting the engine compartment from water, mud, snow, etc. They are die-cut from .065" masticated rubber same as originals.


Comments: Very good.

PP341J	1968-70	Radiator Support to Frame Seals w/fasteners (RE)	10.00/pr.
PP346	1959-71	Upper A-Frame Seal Staples (RE)	3.00/set of 20
PP347	1959-71	Upper A-Frame Seal Staples (RE)	1.50/set of 10

These staples are made from .048" high quality galvanized steel. Each set contains enough staples to install a pair of A-frame seals.



AIR CONDITIONING SEAL KIT



PP347J 1961-62 Air Conditioning Seal Kit (RE) \$ 29.00/set

This kit is die-stamped from correct masticated rubber. These seals attach between the core support and radiator forcing maximum air through the radiator and shroud for proper cooling. Must reuse original fasteners.



PP348K

PP348K 1965-70 Firewall Wiring Harness Gutter (RE) 7.00/ea.

This gutter mounts on the firewall and holds the engine harness as it passes behind the engine.

PAINT



PP350

PP350 Black Semi-Gloss Engine Compartment Paint, Quart (AP).....

This is the correct nitrocellulose lacquer for your restoration needs.

PP351 Flat Black Engine Compartment Paint, 11 oz. Aerosol Can (GM).....

This product is GM's own engine compartment paint. It is high quality paint but by their own admission is a later-style satin "flat black." We do not recommend this paint for restorers seeking originality. However, the product does have redeeming features. We checked it against NOS pieces and found it's perfect for '64-'68 arrowhead emblems, '65 tail panels and taillight bezels plus other applications where a black satin finish is needed.

PP352 Semi-Gloss Engine Compartment Paint (AP)

This is a true semi-gloss paint available in a spray can. Usually a difficult paint to match, this Eastwood product is an excellent paint for engine compartment detailing.



PP352




PP374

PP374	1962-66 Washer Jar - Black (RE).....	19.00/ea.
PP375	1962-66 Washer Jar - White (GM)	7.00/ea.
PP380	1971-72 Washer Jar - GP (GM)	17.00/ea.
PP381	1971-76 Washer Jar - FS (GM).....	Disc.
PP382	1973-77 Washer Jar - GP (GM)	Disc.
PP390	1962-64 Washer Jar Bracket (GM)	7.00/ea.
PP397	1962-72 Washer Jar Filter (GM)	2.00/ea.



PP398

PP397



PP397T

BODY PLUGS

PP360 1/2-in. Inner Fender Plastic Body Plug (AP) \$.50/ea.

WINDSHIELD WASHER COMPONENTS



PP365A	1970-72 Windshield Washer Nozzles, - GP (RE).....	25.00/pr.
PP365D	1971-76 Windshield Washer Nozzles, R or L - FS (GM).....	4.50/ea.
PP365G	1973-77 Windshield Washer Nozzles, R or L - GP (GM).....	Disc.

PP397T 1956-58 Washer Jar Lid Only (w/ Cap Mounted Pump) (RE)..... \$ 49.00/ea.

This is an excellent reproduction. We have found two styles of original lids. One is as pictured above. The other has the filler flip-lid on the opposite side. Your original pump must be riveted to this cap. See PX105 for decal.

PP398 1962-72 Washer Jar Cap (GM)..... 3.00/ea.



PP398JC

PP398L



PP398JC 1961-67 Washer Reservoir Refill Bottle w/ Bracket and Cap (RE) 34.00/ea.

Note: This is the glass triangular reservoir bottle accessory. It comes complete with stainless steel bracket and printed cap. Nice addition to a detailed engine compartment.

PP398K 1960-66 Washer Bottle Cap w/o Lettering (RE)..... 2.00/ea.

PP398L 1960-66 Washer Bottle Cap w/Lettering (RE). 5.00/ea.

These are the metal caps used on the triangular glass windshield washer bottles found in the engine compartment of early '60's Pontiacs.



PX361

PX355

PX352 1961-63 GM "Kleer-view" Windshield Washer Label (RE)..... 3.00/ea.

PX355 1964-67 GM Optikleen Windshield Washer Label (RE)..... 3.00/ea.

PX361 1964-67 GM "Pontiac Kleer-view" Windshield Washer Label (RE) 3.00/ea.

PP399 5/32" Rubber Hose Nozzle to Pump (AP)50/ft.

PP400 7/32" Rubber Hose Washer Bottle to Pump (AP)..... .75/ft.

WASHER PUMPS



PP405 1963-65 Windshield Washer Pump, Single Speed (RE) \$ 49.00/ea.

PP407 1968-74 Windshield Washer Pump - ALL (NOS)..... 49.00/ea.

PP410 1975-77 Windshield Washer Pump w/o Pulse (GM) 69.00/ea.

PP412 1975-77 Windshield Washer Pump w/Pulse (GM) 69.00/ea.

Note: These GM replacements function well but differ physically from original.



PP415

PP415 1963-65 & 1968-77 Washer Pump Repair Kit (RP) 9.00/kit

FIREWALL PLUGS & GROMMETS




PP500 1955-60 Firewall Grommet (RE) 2.50/ea.
Fits 1/2" hole w/1/8" center hole.

PP502 1955-60 Firewall Grommet (RE) 3.00/ea.
Fits 3/4" hole w/3/16" center hole.


PP504 1955-56 Firewall Grommet 12.50/ea.
Fits 1 3/4" x 3" oval hole w/1/2" center hole.

PP506 1956-58 Firewall Grommet 4.00/ea.
Fits 1 3/8" hole w/9/16" center hole.

PP508 1955-57 Headlight Wire Grommet..... 5.50/ea.
To be used with square clip (not included). Fits 7/8" hole w/7/16" center hole.




- PP512** 1957-58 Bonneville Fuel Injection Grommet Kit - 9 Pcs. (RE) \$ 75.00/kit
- Kit contains 4 shroud hold-down grommets, 3 shroud hole plugs, 1 three-hole wire grommet and 1 fuel injection drive seal.



- PP520** 1965-67 Firewall Grommet - Accessory Wiring (RE) \$ 14.00/ea.

AHHHH! EVERYTHING IS JUST GR - RRREAT!



We've got great service!
We've got great prices!
We've got great quality!

It doesn't have to be summer to enjoy your Pontiac.
Half the fun of owning your classic car is preparing it for the road.
When you need it, we've got it!

For ordering and price quotations, call (800) 421-AMES (2637).
For questions and ordering, call (603) 876-3345
(603) 876-4656
(603) 876-4751

SECTION FOURTEEN TRANSMISSION, CLUTCH, BRAKE

PEDAL PADS



PR100

- PR100** 1955-62 Clutch and Brake Pedal Pads, MT (RE) \$ 20.00/pr.



PR101

- PR101** 1963 Clutch and Brake Pedal Pads, MT (APE) 15.00/pr.



PR102

- PR102** 1964 Clutch and Brake Pedal Pads, MT (APE) 15.00/pr.

Comments: Excellent.




PR103

- PR103** 1965-70 Clutch and Brake Pedal Pads, MT - FS (APE) \$ 10.00/pr.
- PR103** 1969-72 Clutch and Brake Pedal Pads, MT - GP (APE) 10.00/pr.

These 14-rib pedal pads are exact reproductions of the factory design used from '65 to '70. Excellent.

Other sources sell this part, but have been forced to grind the rubber to accept trim plates and they do not have the same contours as original.

- PR115** 1965-70 Brake Pedal Pad, AT - FS (APE) 12.00/ea.
- Comments:* Excellent.



PR117

- PR117** 1969-72 Brake Pedal Pad, AT - GP (APE) 10.00/ea.



PR118




PR120

- PR118** 1971-73 Brake Pedal Pad, AT - FS (RE) \$ 15.00/ea.
PR119 1973-77 Brake Pedal Pad, AT - GP (GM) 8.00/ea.
PR120 1976-77 Brake Pedal Pad, AT exc. Custom Trim GP (GM) 4.00/ea.



PR130

- PR130** 1969-72 Accelerator Pedal - GP (APE) 15.00/ea.
PR131 1971-73 Accelerator Pedal - FS (GM) 6.00/ea.
PR131 1973 Accelerator Pedal - GP (GM) 6.00/ea.



- PR133J** 1969-73 Accelerator Pedal Pad Pin - GP (GM) 2.00/ea.
PR133J 1971-73 Accelerator Pedal Pad Pin - ALL (GM) 2.00/ea.
PR133M 1969-73 Accelerator Pedal Pad Spring - GP (GM) 2.00/ea.
PR133M 1971-73 Accelerator Pedal Pad Spring - FS (GM) 2.00/ea.
PR133R 1970-75 Accelerator Rod Pivot Support - FS (GM) 12.00/ea.
PR133R 1973-77 Accelerator Rod Pivot Support - GP (GM) 12.00/ea.



PR150



PR151

- PR150** 1963-64 Parking Brake Pedal Pad (APE) 8.00/ea.
 This emergency pedal pad has the original pattern with the correct 17 ribs. These ribs fold down the sides of the pad.

- PR151** 1965-70 Parking Brake Pedal Pad - ALL (APE) \$ 8.00/ea.

This pad has the correct eleven ribs.

- PR152** 1971-72 Parking Brake Pedal Pad - ALL (GM) 3.00/ea.

- PR152** 1976-77 Parking Brake Pedal Pad - ALL (GM) 3.00/ea.

TRIM PLATES



PR171



PR160

- PR160** 1965-70 Clutch and Brake Pad Trim, MT - FS (APE) 15.00/pr.
PR160 1969-72 Clutch and Brake Pad Trim, MT - GP (APE) 15.00/pr.
PR171 1969-72 Brake Pad Trim, AT - GP (APE) 12.00/ea.
PR173 1973-77 Brake Pad Trim, AT - GP (GM) 8.00/ea.
PR180 1965-70 Parking Brake Trim Plate - ALL (APE) 10.00/ea.



PR190

- PR190** 1969-72 Accelerator Pedal Trim Plate - GP (APE) 12.00/ea.
PR191 1971-73 Accelerator Pedal Trim Plate - FS (GM) 5.00/ea.
PR191 1973 Accelerator Pedal Trim Plate - GP (GM) 5.00/ea.

The PR160 through PR190 trim plates are some of our finest reproductions. Made from original correct stainless steel, they are stamped well within factory specifications.


Comments: Excellent.

MASTER CYLINDER CAPS, BOOTS AND DIAPHRAGMS



PR198X

PR198X 1955-57 Master Cylinder Dust Boot -
Moraine - P.B. (RE)..... \$ 22.00/ea.



PR199 1964-66 Master Cylinder Cap (APE) 15.00/ea.
Manufactured exactly like original, this cap
even has the correct instructions stamped on
top. It is yellow cad-plated.



PR199A 1964-66 Master Cylinder Cap Diaphragm
(RE)..... 9.00/ea.



PR199D 1967-70 Master Cylinder Cap w/o Power
Brakes (GM) Disc.
PR199E 1967-70 Master Cylinder Cap Diaphragm
w/o Power Brakes (GM)..... 12.00/ea.



PR199G 1969 Master Cylinder Cap w/Moraine
Disc Brakes (GM)..... 10.00/ea.



PR199H 1969 Master Cylinder Cap Diaphragm
w/Moraine Disc Brakes (GM)..... 11.00/ea.



PR199J 1970 Master Cylinder Cap w/Moraine
Disc Brakes - GP (GM)..... \$ 11.00/ea.
PR199K 1970 Master Cylinder Cap Diaphragm
w/Moraine Disc Brakes - GP (GM) .. 13.00/ea.
PR199G 1970 Master Cylinder Cap w/Moraine
Disc Brakes - FS (GM) 10.00/ea.

Note: See photo above.

PR199H 1970 Master Cylinder Cap Diaphragm
w/Moraine Disc Brakes - FS (GM) ... 11.00/ea.



PR199M 1971-75 Master Cylinder Cap w/Bendix
Brakes - FS (GM) 14.00/ea.
PR199N 1971-75 Master Cylinder Cap Diaphragm
w/Bendix Brakes - FS (GM) 6.00/ea.
PR199J 1971-75 Master Cylinder Cap w/Moraine
Disc Brakes - ALL (GM) 10.00/ea.

Note: See photo above.

PR199K 1971-75 Master Cylinder Cap Diaphragm
w/Moraine Disc Brakes - ALL (GM). 13.00/ea.
PR199M 1973-75 Master Cylinder Cap w/Bendix
Brakes - GP (GM) 14.00/ea.

Note: See photo above.

PR199N 1973-75 Master Cylinder Cap Diaphragm
w/Bendix Brakes - GP (GM)..... 6.00/ea.
PR199J 1976-77 Master Cylinder Cap - ALL (GM) 10.00/ea.

Note: See photo above.

PR199K 1976-77 Master Cylinder Cap Diaphragm
- ALL (GM) 13.00/ea.

Since many different master cylinders were
used during these years please refer to photos
to identify your cap correctly.


MASTER CYLINDER CAP BAILS



PR199T
PR199R 1967-70 Master Cylinder Cap Bail - ALL
exc. Power Brakes (GM) Disc.
PR199S 1969 Master Cylinder Cap Bail w/Moraine
Disc Brakes (GM)..... 3.00/ea.

- PR199T** 1970 Master Cylinder Cap Bail w/Moraine Disc Brakes - GP (GM) \$ 5.00/ea.
- PR199T** 1971-75 Master Cylinder Cap Bail - ALL w/Moraine Disc Brakes (GM) 5.00/ea.

BRAKE BOOSTER CHECK VALVE & GROMMET



- PR199XJ** 1962-63 Power Brake Booster Vacuum Check Valve Grommet (GM) 4.00/ea.
- PR200** 1964-77 Power Brake Booster Vacuum Check Valve w/Grommet (GM-RP). 10.00/ea.
- Note:* This valve regulates and maintains vacuum in the brake booster.
- Comments:* This valve may not have the same markings as your original.
- PR200B** 1964-77 Power Brake Booster Vacuum Check Valve Grommet (GM) 7.00/ea.

MASTER CYLINDER REBUILD KITS



KITS WITHOUT POWER BRAKES

- PR201BA** 1955-57 Master Cylinder Rebuild Kit (AP) 23.50/ea.
- PR201BC** 1958 Master Cylinder Rebuild Kit (AP) 23.50/ea.
- PR201BF** 1959-66 Master Cylinder Rebuild Kit (AP) Inquire
- PR201BH** 1967-70 Master Cylinder Rebuild Kit (AP) 43.00/ea.

KITS WITH POWER DRUM BRAKES

- PR201DA** 1959-62 Master Cylinder Rebuild Kit w/Moraine (AP) 14.00/ea.
- PR201DC** 1959-63 Master Cylinder Rebuild Kit w/Bendix (AP) Disc.
- PR201DF** 1963-65 Master Cylinder Rebuild Kit w/Moraine (AP) Inquire
- PR201DH** 1964-65 Master Cylinder Rebuild Kit w/Bendix (AP) 24.00/ea.
- PR201DK** 1966 Master Cylinder Rebuild Kit (AP) 29.00/ea.
- PR201BH** 1967-70 Master Cylinder Rebuild Kit w/Moraine (AP) 43.00/ea.
- PR201DM** 1967-70 Master Cylinder Rebuild Kit w/Bendix (AP) 42.50/ea.
- PR201DP** 1969 Master Cylinder Rebuild Kit - All GP with Moraine cylinder Exc. Disc Brakes (RP) 29.00/ea.



KITS WITH POWER DISC BRAKES

- PR201FA** 1967-68 Master Cylinder Rebuild Kit (AP) \$ 48.00/ea.
- PR201FA** 1969 Master Cylinder Rebuild Kit w/Bendix FS (AP) 48.00/ea.
- PR201FB** 1969 Master Cylinder Rebuild Kit - All GP with Disc Brakes Exc. 9 1/2"x2" Rear Drum (RP) Inquire
- PR201FC** 1969-77 Master Cylinder Rebuild Kit w/Moraine (AP) 29.00/ea.
- PR201FD** 1969-77 Master Cylinder Rebuild Kit - All GP with Disc Brakes "Bendix Cylinder" Exc. 11"x2" Rear Drum (RP) 29.00/ea.
- PR201FF** 1971-72 Master Cylinder Rebuild Kit w/Bendix FS (AP) 42.00/ea.
- PR201FH** 1973-76 Master Cylinder Rebuild Kit w/Bendix FS (AP) 42.00/ea.

Using these kits allows you to refurbish your original master cylinder. Many times rebuilding your original is preferable to purchasing incorrect replacements.

Note: To protect your master cylinder from rust use our cast-iron spray gray paint in Section Thirteen.

BEWARE OF LOW PRICED, LOW QUALITY BRAKE COMPONENTS

In keeping with our on-going commitment for quality parts, we sell only name-brand components (Bendix, Raybestos, etc.). Discount pieces have no place in your brake system.

Depend on our quality here at Ames.

MASTER CYLINDERS (ALL FS EXC. '69-77 GP)



- PR202BC** 1958 Master Cylinder, All w/ MB (RP) 89.00/ea.
- PR202BC** 1959-60 Master Cylinder, All w/ PB and Bendix Booster (RP) 89.00/ea.
- PR202BE** 1959-60 Master Cylinder, All w/ PB and Moraine Booster (RP) 89.00/ea.
- PR202BD** 1961 Moraine Master Cylinder, All w/ PB (RP) 89.00/ea.
- PR202BM** 1961 Bendix Master Cylinder, All w/ PB (RP) 89.00/ea.

PR202BM	1962 Master Cylinder, All w/ PB and 4 Mounting Bolts (RP)	\$ 89.00/ea.
PR202BR	1962 Master Cylinder, All w/ PB and 2 Mounting Bolts (RP)	75.00/ea.
PR202BW	1962-66 Master Cylinder, All w/ MB (RP)	69.00/ea.
PR202BZ	1963-65 Master Cylinder, All w/ PB (RP)	69.00/ea.
PR202CB	1966 Master Cylinder, All w/ PB (RP)	69.00/ea.
PR202CF	1967-70 Bendix Master Cylinder, All FS exc. DB (RP)	69.00/ea.
PR202CH	1967-70 Moraine Master Cylinder, All FS exc. DB (RP)	119.00/ea.
PR202CK	1967-70 Bendix Master Cylinder, All FS w/ PDB (RP)	69.00/ea.
PR202CM	1970-72 Moraine Master Cylinder, All FS w/ PDB (RP)	69.00/ea.
PR202CP	1971-72 Bendix Master Cylinder, All FS w/ PDB (RP)	69.00/ea.
PR202CM	1973-77 Master Cylinder, All FS w/ PDB (RP)	69.00/ea.

MASTER CYLINDERS (1969-77 GRAND PRIX)



PR203A	1969 Bendix Master Cylinder, All GP w/ 11" x 2" Rr Drum, exc. Disc Brakes (RP)	69.00 /ea.
PR203D	1969 Moraine Master Cylinder, All GP w/ 11" x 2" Rr Drum, exc. Disc Brakes (RP)	95.00 /ea.
PR203G	1969 Master Cylinder, All GP w/ 9 1/2" x 2" Rr Drum, exc. Disc Brakes (RP)	69.00 /ea.
PR203J	1969-77 Master Cylinder, All GP w/ Disc Brakes, exc. 1969 GP w/ 11" x 2" Rr Drum (RP)	69.00 /ea.

Note: PR202BC-PR203J are new master cylinders not remanufactured.

BOOT & BUMPERS



PR209



PR214

PR209	1955-57 Accelerator Rod Boot (APE)	7.50/ea.
PR214	1965-72 Clutch Fork Boot - ALL (GM)	10.00/ea.



PR215


PR215	1969-72 Clutch Rod Seal - GP (RE)	\$ 9.50/ea.
--------------	---	-------------



PR220



PR225




PR222

PR220	1955-77 Brake Adjusting Plug (AP)50/ea.
PR221	1967 Clutch Pedal Bumper (GM)	2.00/ea.
PR221	1969-72 Clutch Pedal Bumper - GP (GM)	2.00/ea.
PR222	1970-72 Clutch Pedal Bumper - FS (GM)	Disc.
PR225	1961-77 Clutch and Brake Pedal Assembly Pivot Bushings, AT or MT (GM)	1.00/ea.

Usually worn, these bushings will restore your sloppy AT or MT clutch and brake pedals.

Note: Requires 2 per pedal.



PR225J	1958-77 Clutch and Brake Pedal Shaft Sleeve (7/16" I.D. x 23/8" long), Cut to Length (GM)	4.00/ea.
PR225N	1969-77 Brake Pedal Pivot Bolt, All AT - GP (RP)	2.00/ea.
PR225P	1969-72 Clutch and Brake Pedal Pivot Bolt - All MT - GP (RP)	2.00/ea.
PR225W	1969-72 Clutch and Brake Pedal Pivot Bolt Lock Nut - GP (RP)	1.00/ea.
PR225YA	1969-72 Brake Clevis to Pedal Pin Retainer - GP (GM)	1.50/ea.

BACKLOCK COMPONENTS



PR228S

PR228M	1969-72 Back Lock Equalizer Shaft Pivot Bushing - GP	1.00/ea.
---------------	--	----------

- PR228P** 1969-72 Back Lock Rod to Lever Swivel - GP (GM)..... \$ 5.50/ea.
- PR228S** 1969-72 Reverse Lock-Out Rod w/ Swivel 4-sp. (GP) (RE) 75.00/ea.

FLOOR SHIFT PORCH



PR230

- PR230** 1967-72 Floor Shift Porch, MT - GP (RE) 35.00/ea.

These are STEEL reproduction shift porches. Besides being needed for 4-speed conversions, many porches on original Grand Prix have been altered for different shifters or are missing altogether.

Comments: Very good—made by the same shop as our high-quality floors, trunks and patch panels.

SHIFT BOOTS AND SEALS



PR238J

- PR238** 1965-68 Lever Seal (Plastic Strip) w/Console, AT - FS (APE) 10.00/ea.
- PR238J** 1969-77 Lever Seal (Plastic Strip) w/Console, AT - GP (GM) 4.00/ea.

These seals replace the many cracked and broken seals found on 3-speed automatic consoles.



PR239MA

- PR239M** 1955-56 3-Speed Column Shift Boot, MT (Black) (RE) 8.00/ea.
- PR239MA** 1955-56 3-Speed Column Shift Boot, MT (Orange) (RE) 10.00/ea.



PR240



PR244C

- PR240** 1960-64 Shift Boot, 4-Speed w/Bench Seat (RE)..... 22.00/ea.

- PR241** 1960-63 Shift Boot, 4-Speed w/Bucket Seats w/ or w/o Console and w/Reverse Lockout (APE)..... \$ 13.00/ea.
- PR242** 1963-64 Shift Boot, 4 Speed w/Bucket Seats w/ or w/o Console and w/o Reverse Lockout (APE)..... 13.00/ea.
- PR244C** 1965-69 Shift Boot, MT - FS (GM) 25.00/ea.
- PR244C** 1969-72 Shift Boot, MT - GP (GM)..... 25.00/ea.

Note: PR240 through PR244C are the shift boots that attach to the floor. These boots are used whether or not your manual floor shift car is equipped with a console.



PR246

- PR246** 1962-63 Shift Bellows, MT w/Console and w/Reverse Lockout (APE) 20.00/ea.
- PR247** 1963-64 Shift Bellows, MT w/Console and w/o Reverse Lockout (APE) 20.00/ea.

Note: PR246 and PR247 are the bellows which attach to the console and surround the shift lever. They are exact reproductions using original Seville grain stitched silver vinyl and molded grommets.

SHIFT BOOT TRIM PLATES



PR250

- PR249** 1960-64 Shift Boot Trim Plate, 4-Speed w/Bench Seat (RE) 9.00/ea.

Note: This fits PR240 above.

- PR250** 1960-64 Shift Boot Trim Plate, w/ or w/o Console w/Bucket Seats (APE) .. 15.00/ea.

Note: This fits PR241 and PR242 above.




PR255

- PR255** 1965-69 Shift Boot Trim Plate - FS (APE) 15.00/ea.
- PR255** 1969-72 Shift Boot Trim Plate - GP (APE)..... 15.00/ea.

The PR255 trim plate is an exact reproduction

of the original chrome bezel used between 1965 and 1972. PR255 combined with PR244C can be used to give a correct factory appearance when converting your car to a 4-speed.

BACK-UP LIGHT SWITCHES




- PR259** 1960-64 Back-Up Light Switch, 4-Speed (RP)..... \$ 55.00/ea.
Except in certain applications where the wiring harness may differ, this switch is same as original.
- PR260** 1965-67 Back-Up Light Switch, 4-Speed (RP)..... 55.00/ea.
This switch is an exact replacement for 1965-67 models.
- PR261** 1965-67 Back-Up Light Switch Bracket, MT (GM)..... 5.00/ea.
- PR262** 1965-67 Back-Up Light Switch Rod, 4-Speed (RE)..... 3.00/ea.



- PR263** 1960-67 Back-Up Light Switch Shield (RE) 9.50/ea.
This often missing shield protects the switch from road debris.
- PR264** 1968 Back-Up Light Switch, MT (GM) 24.00/ea.
PR264 fits the original 1968 shifter only.
- PR265** 1964-68 Back-Up Light Wire Clips (RE) 4.00/pr.
- PR267** 1961-72 Back-Up Light Switch, 4-Speed w/Hurst Linkage (RP) 25.00/ea.

Note: This after-market design is not the same as original. It uses a plunger switch that contacts the reverse arm activating the back-up lights. This is a less expensive alternative to PR259 or PR260.

TRANSMISSION SHIFT CABLES AND COMPONENTS




- PR275** 1965-68 Transmission Shift Cable, AT w/Console - FS (RP)..... \$ 36.00/ea.
- PR276** 1969-72 Transmission Shift Cable, AT w/Console - GP (GM) 35.00/ea.
- PR276B** 1973-77 Transmission Shift Cable, AT M40 w/Console - GP (GM) 35.00/ea.



- PR276FJ** 1969-77 Shift Cable Lever, AT w/Console - GP (GM)..... 7.00/ea.
- PR276FN** 1965-77 Shift Cable Lever Pin, AT w/Console - ALL (GM) 6.00/ea.
- PR276FR** 1965-77 Shift Cable to Lever Pin Spring Retainer, AT w/Console (GM)..... 1.00/ea.
- PR276G** 1965-74 Shift Cable Mounting Clip, AT w/Console (RE)..... 1.00/ea.

This clip is used to secure the shift cable to the shifter assembly.



- PR277J** 1969-77 Auto Transmission Shift Cable Bracket, Transmission Mounted M40 w/Console - GP (GM)..... 7.00/ea.

PR277K 1969-77 Auto Transmission Shift Cable Bracket, Transmission Mounted M38 w/Console - GP (GM)..... \$ 5.00/ea.

TRANSMISSION MOUNTS



PR279G



PR279H

PR279G 1959-60 Transmission to Crossmember Mount (RE)..... 32.00/ea.

PR279H 1961-64 Transmission to Crossmember Mount, Auto (AP)..... 37.00/ea.




PR279J



PR279K

PR279J 1961-64 Transmission to Crossmember Mount, 4-Sp. (Requires 2) (AP) 10.00/ea.

PR279K 1965-70 Transmission to Crossmember Mount (AP)..... 37.00/ea.



PR280



PR280D


PR280 1969-72 Transmission to Crossmember Mount, AT - GP (AP) 16.00/ea.

PR280D 1971-72 Transmission to Crossmember Mount - FS (AP) 16.00/ea.

PR280J 1973-76 Transmission to Crossmember Mount - FS (AP) 16.00/ea.

PR280J 1973-77 Transmission to Crossmember Mount - GP exc. '74 GP w/R.T.S. (AP)..... 16.00/ea.


PR280D 1974 Transmission to Crossmember Mount - GP w/R.T.S. (AP) 16.00/ea.



PR280M

PR280M 1969-77 Urethane Transmission Mount, - AT or MT GP (AP)..... 25.00/ea.

TRANSMISSION CROSSMEMBER INSULATORS



Transmission Rear Crossmember

PR284 1961-70 Transmission Rear Crossmember Insulators, Auto or MT - FS (APE) Inquire

Tooling is in process for these highly sought after insulators. Projected price is \$19.00/pr.

PR285 1969-72 Transmission Rear Crossmember Insulators, MT or Auto - GP (GM).... \$ 12.50/pr.

This is an exact match of the much sought after crossmember insulators.

Comments: Excellent.


PR285A 1969-72 Transmission Crossmember Support Retainer - GP (GM)..... 9.00/ea.

Note: PR285A is the metal bracket that holds the rubber crossmember insulator in place on the frame rail.



TRANSMISSION COOLING LINES

Kick-Down Vacuum Tube



Transmission Cooling Lines

Note: 55-59 lines among others should be available soon. Please inquire on availability.

PR287JA 1960 Transmission Cooling Lines - Bonneville - Steel (RE) 45.00/pr.

PR287JB 1960 Transmission Cooling Lines - Bonneville - Stainless Steel (RE) 75.00/pr.

PR287JJ 1961-62 Transmission Cooling Lines - Catalina/GP - Steel (RE)..... 45.00/pr.

PR287JK 1961-62 Transmission Cooling Lines - Catalina/GP - Stainless Steel (RE) 75.00/pr.

PR287JN 1961-62 Transmission Cooling Lines - Bonneville - Steel (RE) 45.00/pr.

PR287JO 1961-62 Transmission Cooling Lines - Bonneville - Stainless Steel (RE) 75.00/pr.

PR287RA 1969-70 Turbo 350 - 400 Transmission Cooling Lines - FS w/ AC - Steel (RE) 45.00/pr.

PR287RB 1969-70 Turbo 350 - 400 Transmission Cooling Lines - FS w/ AC - Stainless Steel (RE) 75.00/pr.


PR287RE 1969-70 Turbo 350 - 400 Transmission Cooling Lines - FS w/o AC - Steel (RE)..... 45.00/pr.

- PR287RF** 1969-70 Turbo 350 - 400 Transmission Cooling Lines - FS w/o AC - Stainless Steel (RE) \$ 75.00/pr.
- PR287RN** 1969-72 Turbo 350 Transmission Cooling Lines - GP - Steel (RE) 45.00/pr.
- PR287RO** 1969-72 Turbo 350 Transmission Cooling Lines - GP - Stainless Steel (RE) 75.00/pr.
- PR287RS** 1969-72 Turbo 400 Transmission Cooling Lines - GP - Steel (RE) 45.00/pr.
- PR287RT** 1969-72 Turbo 400 Transmission Cooling Lines - GP - Stainless Steel (RE) 75.00/pr.

Transmission cooling lines are drop-shipped directly from our manufacturer and must be prepaid.

Please add \$8.50 shipping for cooling lines.

Note: Beware of low quality reproductions of these transmission lines at discounted prices.



VACUUM MODULATOR LINES

- PR288JA** 1969-70 Vacuum Modulator Line - FS - 2 bbl - (M38) (RE) 25.00/ea.
- PR288JD** 1969-70 Vacuum Modulator Line - FS - 4 bbl - (M40) (RE) 25.00/ea.
- PR288JJ** 1969-72 Vacuum Modulator Lines - GP - 2 bbl - (M38) (RE) 25.00/ea.
- PR288JN** 1969 Vacuum Modulator Lines - GP - 4 bbl - (M40) (RE) 25.00/ea.
- PR288JR** 1970-72 Vacuum Modulator Lines - GP - 4 bbl - (M40) (RE) 25.00/ea.
- PR288JV** 1973-77 Vacuum Modulator Lines - GP - 4 bbl - (M40) (RE) 25.00/ea.

All Vacuum Modulator lines are made from steel.

OEM TRANSMISSION FILTER KITS



PR289PC

- PR289PB** 1969-77 Transmission Filter Kit, All V-8 with TH350 Trans. (GM) 11.00/kit
- PR289PC** 1967-74 Transmission Filter Kit, All V-8 with TH400 Trans. (GM) 11.00/kit

TRANSMISSION OIL PANS

- PR289PF** 1969-77 Transmission Oil Pan, TH350 First Design (GM) 27.00/ea.

- PR289PG** 1967-74 Transmission Oil Pan, TH350 Second Design (GM) \$ 46.00/ea.

Note: Second design pan has only two dimples, where the first design has three.

AUTOMATIC TRANSMISSION DIPSTICKS & TUBES



- PR289RJ** 1968-73 Transmission Dipstick, AT (M-38) -ALL (GM) 6.00/ea.
- PR289RJ** 1970-73 Transmission Dipstick, AT (M-40) - GP (GM) 6.00/ea.
- PR289RJ** 1971-73 Transmission Dipstick, AT (M-40) - FS (GM) 6.00/ea.
- PR289RL** 1974-77 Transmission Dipstick, AT -ALL (GM) 6.00/ea.
- PR289SL** 1974-77 Transmission Dipstick Tube, AT -All (GM) 13.00/ea.
- PR289SX** 1965-77 Transmission Dipstick Tube Seal, AT (GM) 2.00/ea.

PR289SX seals the dipstick tube to the transmission case.

SPEEDOMETER CABLES WITH CASINGS

YEAR	3SP	4SP	TH350	TH400
55-56	PR290H	---	---	---
57	PR290E	---	---	---
58-59	N/A	---	---	---
60-62	N/A	PR290D	---	---
63-64	N/A	---	---	---
65-66	PR290J	PR290E	---	N/A
67-68	PR290C	N/A	---	PR290C
69 GP	PR290G	PR290F *1 PR290K *2 PR290L *3	PR290A	PR290F
69 FS	---	---	PR290A	PR290A
70 GP	PR290B	PR290K *2 PR290L *3	PR290A	PR290F
70 FS	---	---	PR290A	PR290A
71 GP	PR290B	PR290M	---	PR290F
71-72 FS	---	---	PR290A	PR290A
72-75 GP	---	---	---	PR290F
73-75 FS	---	---	---	PR290K *4
73-76	---	---	---	PR290J *5
73-76 FS	---	---	---	PR290A
76-77 GP	---	---	---	PR290D

--- = NOT APPLICABLE

N/A = NOT AVAILABLE

*1 = FIRST DESIGN (ONE PIECE)

*2 = SECOND DESIGN (TWO PC. UPPER)

*3 = SECOND DESIGN (TWO PC. LOWER)

*4 = W/CRUISE CONTROL (UPPER)

*5 = W/CRUISE CONTROL (LOWER)



PR290A	Speedometer Cable (GM)	\$ 35.00/ea.
PR290B	Speedometer Cable (GM)	29.00/ea.
PR290C	Speedometer Cable (GM)	19.50/ea.
PR290D	Speedometer Cable (GM)	18.50/ea.
PR290E	Speedometer Cable (GM)	25.00/ea.
PR290F	Speedometer Cable (GM)	21.00/ea.
PR290G	Speedometer Cable (GM)	27.00/ea.
PR290H	Speedometer Cable (GM)	31.00/ea.
PR290J	Speedometer Cable (GM)	23.00/ea.
PR290K	Speedometer Cable (GM)	19.00/ea.
PR290L	Speedometer Cable (GM)	19.00/ea.
PR290M	Speedometer Cable (GM)	29.00/ea.

SPEEDOMETER CABLE

PR295	1955-72 Speedometer Cable w/o casing, Universal - ALL (GM)	15.00/ea.
--------------	---	-----------

This universal cable comes 70 inches long. Instructions are included for cutting and installation.

SPEEDOMETER CABLE GROMMET



PR295J

PR295D	1955-58 Speedometer Cable Grommet (RE)..	3.00/ea.
PR295J	Speedometer Cable Grommet (RE)..	5.00/ea.

This grommet fits into 1 1/2" firewall hole.

SHIFT KNOBS



PR301



PR302

PR301	1960-64 4-Speed Shift Knob (White w/o Pattern) (RE)	15.00/ea.
PR302	1960-64 4-Speed Shift Knob (White w/ Pattern) (RE)	20.00/ea.



PR305



PR320

PR304	4-Speed Shift Knob (White w/Pattern) (AP)	\$ 18.00/ea.
--------------	--	--------------

Many customers have requested a white four-speed knob, same dimensions as our PR305. Use where originality is not required—thread is 3/8"-16.

PR305	1965-68 4-Speed Shift Knob (Black w/Pattern) (RE)	18.00/ea.
--------------	--	-----------

PR305	1969-70 4-Speed Shift Knob (Black w/Pattern) - GP (RE)	18.00/ea.
--------------	---	-----------

This knob is slightly smaller in diameter than the original 1969-70 Grand Prix. Fit and appearance are good.

PR320	1968 Automatic Outer Handle w/Console "T" Shifter (RE)	15.00/ea.
--------------	---	-----------

This plastic reproduction will rejuvenate those original T-handles that are often broken and useless (comes w/retainer).



PR330

PR330	Hurst Brushed Aluminum T-Handle w/Checknut - ALL Hurst Shifters (AP)	27.00/ea.
--------------	--	-----------

Note: Thread is 3/8"-16.

COLUMN SHIFT COMPONENTS



PR332DA	1968-77 Column Shift Lever Knob, AT - ALL (GM)	6.00/ea.
----------------	---	----------

PR332H	1969-77 GP & 71-75 FS Column Shift Pivot Bushing AT (GM)	1.00/ea.
---------------	--	----------

PR332K	1967-77 Column Shift Control Rod to Shift Level Swivel, ALL AT (GM)	5.50/ea.
---------------	--	----------

TRANSMISSION REBUILD KITS



PR340H	1961-63 Borg Warner T10, 4-Speed Rebuild Kit (AP)	175.00/kit
---------------	--	------------

- PR340J** 1963-65 Muncie 4-Speed Rebuild Kit (AP)\$175.00/kit
PR340L 1966-74 Muncie 4-Speed Rebuild Kit (AP) 175.00/kit

All rebuild kits come complete with synchro rings, bearings, countershaft, strut keys, springs, gaskets, seals and all necessary small parts (i.e. needle bearings, snap rings, and thrust washers). Each kit carries a one-year warranty.

Note: T10 4-speeds have 9 side cover bolts and Muncie 4-speeds have 7.

SHIFTER PLATE




- PR345** 1969-72 Shifter Plate w/Nut - GP (APE)..... 25.00/ea.

These are aluminum reproductions of the GM shifter plate that adapts the factory Hurst 4-speed shifter to your Muncie transmission.

Comments: Very good.

CLUTCH COMPONENTS



Typical 1969-72 GP Linkage

- PR368** 1969-72 Clutch Countershaft (L-Shaped) - GP (APE) Inquire
PR369 1969-72 Clutch Countershaft Swivel Assembly - GP (RE) 49.00/ea.
PR369B 1969-72 Clutch Countershaft Swivel to Engine Bolt - GP (GM) 2.50/ea.

Note: This is the correct 12-point bolt used to attach the swivel assembly to the engine.

- PR369C** 1969-72 Clutch Countershaft Swivel to Engine Bolt Sleeve - GP (AP) 4.00/ea.



PR371



PR371D

- PR371** 1969-72 Clutch Rod - GP (RE) \$ 42.00/ea.
PR371D 1965-72 Clutch Rod Clip - ALL (AP) 1.00/ea.
PR372 1965-72 Clutch Fork - ALL (GM) Disc.



PR372CM

- PR372CM** 1965-72 Clutch Fork Ball Stud - All MT Pontiac V-8 (GM) 10.00/ea.
PR373 1965-72 Clutch Fork Push Rod Center Rattle Spring - ALL (RE) 10.00/ea.
PR374 1963-72 Clutch Countershaft Bushing - ALL (GM) 2.00/ea.

These are the nylon bushings located at the frame end of the clutch countershaft. They often wear, causing sloppy clutch linkage (2 required).

- PR374J** 1963-72 Clutch Countershaft Seal (GM) 2.00/ea.

This is the felt seal located at the frame bracket end of the z-bar.

- PR374N** 1963-72 Clutch Countershaft Spring Clip (GM) 1.00/ea.



This is the spring clip that retains the countershaft bushing in the clutch countershaft.

- PR374P** 1969-72 Clutch Countershaft Bushing Spacer - GP 4.00/ea.
PR375 1963-72 Clutch Countershaft to Frame Ball Stud - ALL (GM) 9.00/ea.
PR380 1965-72 Clutch Fork Push Rod (Original-Style) - ALL (GM) 5.00/ea.
PR381 1965-72 Clutch Fork Push Rod Swivel (Original-Style) - ALL (RE) 9.00/ea.



PR381A

- PR381A** 1965-72 OEM Clutch Fork Push Rod (GM) ... 17.00/ea.
 PR381A is for those applications where original equipment is a must.



PR385

- PR385** 1965-72 Clutch Fork Push Rod - ALL (GM) ... 17.00/ea.

Note: PR385 is a rugged replacement push rod used by GM for heavy duty clutch applications. It is sold as a three-piece set and is stronger than the original-style rod.

PR385J 1969-72 Clutch Spring (2-Piece) - GP (RE) \$ 15.00/pr.



PR385KD

PR385KD 1961-62 Clutch Over - Center Spring (RE) ... 25.00/ea.

This hard to find spring was just reproduced. It is a necessity on 61-62 cars to aid in depressing the clutch.

OEM CLUTCH KITS AND BOLTS



- PR390AC** 1964 Clutch Kit, 421 - 389, 3/4 spd w/ 10 spline -10 $\frac{3}{8}$ " Disc (AP) 179.00/kit
- PR390AE** 1965-66 Clutch Kit, 421 - 389, 3/4 spd w/ 10 spline -11" Disc (AP) 189.00/kit
- PR390AG** 1967-69 Clutch Kit, 400, 3/4 spd w/ 10 spline -10 $\frac{3}{8}$ " Disc (AP) 229.00/kit
- PR390AE** 1967-70 Clutch Kit, 400, HD, w/ 10 spline - 11" Disc (AP) 189.00/kit
- PR390AJ** 1970-72 Clutch Kit, 400, 3 spd. w/ 10 spline - 10 $\frac{3}{8}$ " Disc (AP) 179.00/kit
- PR390AL** 1971-72 Clutch Kit, 400, 4 spd. w/ 26 spline - 10 $\frac{1}{2}$ " Disc (AP) 179.00/kit
- PR390AE** 1969 Clutch Kit, 428, 4 spd. w/ 10 spline - 11" Disc (AP) 189.00/kit
- PR390AE** 1970-74 Clutch Kit, 455, 3 spd. w/ 10 spline - 11" Disc (AP) 189.00/kit
- PR390AN** 1970-72 Clutch Kit, 455, 4 spd. w/ 26 spline - 11" Disc (AP) 229.00/kit


These new clutch kits are made by GM's original supplier. Kits come complete with clutch disc, pressure plate, throwout bearing, pilot bearing, and alignment tool.

Before ordering please check original clutch and confirm disc size and spline count to application listing above.



PR390BJ

- PR390BJ** Clutch Alignment Tool - 10-spline (AP) \$ 4.00/ea.
- PR390BL** Clutch Alignment Tool - 26-spline (AP) 4.00/ea.



PR390GD

- PR390GD** 1964-77 Pressure Plate to Flywheel Bolt Kit, All MT Pontiac V-8 (RP) 3.00/kit
- PR390GH** 1964-77 Bell Housing to Engine Block Bolt Kit, All MT Pontiac V-8 (GM) 5.00/kit



PR390GL

- PR390GL** 1964-77 Transmission to Bell Housing Bolt Kit, All MT Pontiac V-8 (RP) 4.00/kit

Note: PR390GD - PR390GL are replacement bolt kits that will not have the same bolt markings as original.

PARKING BRAKE CABLES

- PR395** 1965-67 Front Parking Brake Cable - GP (AP) 30.00/ea.
- PR395A** 1965-67 Center Parking Brake Cable - GP (AP) 17.00/ea.
- PR395B** 1965-67 Rear Parking Brake Cable, RH or LH - GP (GM) 21.00/ea.
- PR396** 1965-70 Front Parking Brake Cable - ALL exc. GP (AP) 29.00/ea.
- PR396A** 1965-70 Center Parking Brake Cable - ALL exc. GP (AP) Disc.
- PR396B** 1965-70 Rear Parking Brake Cable, RH or LH - ALL exc. GP (AP) 34.00/ea.
- PR400** 1969-72 Rear Parking Brake Cable, RH or LH GP (GM) 21.00/ea.
- PR402** 1969-72 Center Parking Brake Cable - GP (GM) 22.00/ea.
- PR403** 1971-72 Center Parking Brake Cable - FS (GM) 21.00/ea.

PR404	1971-72	Rear Parking Brake Cable, RH or LH w/11" Brakes - FS (AP).....	\$ 35.00/ea.
PR405	1973-76	Front Parking Brake Cable - ALL exc. GP (AP).....	36.50/ea.
PR405A	1973-76	Center Parking Brake Cable - ALL exc. GP (AP).....	23.00/ea.
PR405B	1973-76	Rear Parking Brake Cable, RH or LH - ALL exc. GP (GM).....	30.00/ea.
PR407	1973-77	Front Parking Brake Cable - GP (AP).....	28.00/ea.
PR407A	1973-75	Center Parking Brake Cable w/o Catalytic Converter - GP (AP) ...	25.00/ea.
PR407B	1975-77	Center Parking Brake Cable w/Catalytic Converter - GP (GM).....	22.00/ea.
PR405B	1973-77	Rear Parking Brake Cable, RH or LH - GP (GM).....	30.00/ea.

PARKING BRAKE CABLE COMPONENTS




	PR410	PR410C	PR410D
PR410	1961-77	Parking Brake Cable Equalizer (GM).....	2.00/ea.
PR410C	1961-77	Parking Brake Cable Connector (2 Required) (GM)	1.00/ea.
PR410D	1955-77	Front Parking Brake Cable Return Spring Retainer (RP)	1.00/ea.



PR410L	1964	Front of Rear Brake Cable Guide and Hardware (RE).....	5.00/kit
---------------	------	--	----------

This is the hard to find often missing brake cable guide that the rear cable goes through.



	PR410T	
PR410T	1969-72	Parking Brake Cable Guide - GP (APE)..... 5.00/ea.
PR410T	1973-76	Parking Brake Cable Guide - FS (APE)..... 5.00/ea.

Usually worn or missing, these cable guides are necessary for proper parking brake operation. Requires 2 per car.

Note: Beware of the S-shaped guide currently

available from GM. Because of its large diameter, you need to alter your floor brace to install properly.

PARKING BRAKE RELEASE HANDLE



PR415J

PR415J	1969-72	Parking Brake Release Handle - GP (GM-RP).....	\$ 3.00/ea.
---------------	---------	--	-------------

Although not an exact replacement, this handle functions fine. The print and contours of the handle differ from the original design.

PIT PACK




PR420	1964-66	Hurst Pit Pack (AP)	9.50/set
--------------	---------	---------------------------	----------

Each kit contains enough shift rod bushings and spring clips to refurbish sloppy linkage.

Note: Some year shift linkages did not use bushings; PR420 cannot be used on these shifters.



FLYWHEEL AND FLEXPLATES



PR428HD



PR428HF

PR428HD	1964-75	MT Steel Flywheel, All Pontiac V-8 (AP).....	299.00/ea.
----------------	---------	--	------------

This 30lb. flywheel is strongly recommended for high performance applications. This will accept 10" or 11" clutch plates.

***Note:* Please add \$7.00 shipping for flywheel**

PR428HF	1967-75	Automatic Flex Plate, All V-8 with Hydramatic Trans. (RP).....	47.00/ea.
----------------	---------	--	-----------



PR429HJ

PR429HJ 1964-77 Flywheel to Crank Shaft Bolt Kit,
All MT Pontiac V-8 (RP)..... \$ 9.00/kit

FLYWHEEL AND CONVERTER COVERS



PR430

PR430 1965-77 Flywheel Cover, MT - ALL (GM)..... 19.00/ea.
PR435 1965-77 Automatic Transmission Converter
Cover - ALL (GM)..... 30.00/ea.

Note: PR435 is a plastic replacement for the original steel cover.



PR435JP

PR435JR

PR435JP 1965-77 Flywheel Cover to Bell Housing
Hardware Kit, All MT Pontiac V-8
(RE)..... 2.50/kit
PR435JR 1965-77 Converter Cover to Trans Hardware
Kit, All AT Pontiac V-8 (RE)..... 2.50/kit

BACKING PLATES



PR440B 1969-72 Front Disc Backing Plate - GP (RE)... 99.00/pr.
PR440L 1971-76 Front Disc Brake Backing Plate, LH
- FS (GM)..... 14.00/ea.
PR440R 1971-76 Front Disc Brake Backing Plate, RH
- FS (GM)..... 14.00/ea.
PR440L 1973-77 Front Disc Brake Backing Plate, LH
- GP (GM)..... 14.00/ea.
PR440R 1973-77 Front Disc Brake Backing Plate, RH
- FS (GM)..... 14.00/ea.



PR441CL

PR441CL 1970-77 Rear Drum Brake Backing Plate, LH
- GP w/ 9 1/2" Brakes (GM) \$ 39.00/ea.
PR441CR 1970-77 Rear Drum Brake Backing Plate, RH
- GP w/ 9 1/2" Brakes (GM) 39.00/ea.

BEWARE OF LOW PRICED, LOW QUALITY BRAKE COMPONENTS

In keeping with our ongoing commitment for quality parts, we sell only name-brand components (Bendix, Raybestos, etc.). Discount pieces have no place in your brake system.

Depend on our quality.

Note: Many brake components require core charges. Please inquire when ordering.

BRAKE ROTORS AND PADS (FULL SIZE)



PR445J 1971-76 Disc Brake Rotor, L or R, All FS (RP) 65.00/ea.
PR445L 1977 Disc Brake Rotor, L or R, All FS
w/ 11" x 2" Rr Drum (RP)..... 79.00/ea.
PR445N 1977 Disc Brake Rotor, L or R, All FS
w/ 9 1/2" x 2" Rr Drum (RP) 65.00/ea.
PR445S 1967-68 Disc Brake Pads, All FS, 4 pcs. (RP) . 25.00/set
PR445T 1969-77 Disc Brake Pads, All FS, 4 pcs. (RP) . 21.00/set

BRAKE ROTORS AND PADS (1969-77 GRAND PRIX)

PR446D 1969-72 Disc Brake Rotor, L or R, All GP exc.
1969 11" x 2" Rr Drum (RP) 119.00/ea.
PR446F 1973-77 Disc Brake Rotor, L or R, All GP
(RP)..... 65.00/ea.
PR446H 1969-75 Disc Brake Pads, All GP exc. 1969
11" x 2" Rr Drum 4 pcs. (RP) 21.00/set
PR446J 1976-77 Disc Brake Pads, All GP w/ PDB
4 pcs. (RP) 32.00/set



BRAKE DRUMS AND SHOES (FULL SIZE)



FRONT

PR448 1965-70 Front Brake Drum, FS All exc. Heavy Duty and exc. 1964-66 GP (RP).....\$ 99.00/ea.

Note: Full Cast Iron Drum.

PR448B 1964-65 Front Brake Drum, GP (RP)..... 99.00/ea.

PR448C 1966 Front Brake Drum, GP (RP)..... 99.00/ea.

Note: Full Cast Iron Drum.

PR448J 1955-58 Front Brake Shoes, All with Heavy Duty Chassis 12" x 2 1/4" exc. 1958 Bonneville (RP) 27.00/set

PR448K 1958 Front Brake Shoes, All Bonneville with Heavy Duty Chassis 12" x 2 1/2" (RP)..... 25.00/set

PR448L 1959-64 Front Brake Shoes, All FS (RP)..... 21.00/set

PR448M 1965-70 Front Brake Shoes, All FS (RP)..... 24.00/set

REAR

PR449B 1964-70 Rear Brake Drum, All FS exc. Heavy Duty (RP)..... 99.00/ea.

PR449C 1971-77 Rear Brake Drum, All FS w/ 11" x 2" Rear Brake (RP) 49.00/ea.

PR449J 1955-58 Rear Brake Shoes, All FS exc. Heavy Duty (RP)..... 45.00/set

PR449K 1955-58 Rear Brake Shoes, All FS Heavy Duty exc. Bonneville (RP)..... 29.00/set

PR449L 1959-64 Rear Brake Shoes, All FS (RP)..... 23.00/set

PR449M 1965-70 Rear Brake Shoes, All FS (RP)..... 23.00/set

PR449N 1971-76 Rear Brake Shoes, All FS w/ 11" x 2" Rear Brake (RP) 19.00/set

PR449P 1977 Rear Brake Shoes, All FS w/ 11" x 2" Rear Brake (RP) 19.00/set

Please add \$5.00 shipping for brake drums.



BRAKE DRUMS AND SHOES ('69-77 GRAND PRIX)

FRONT

PR450A 1969-70 Front Brake Drum, L or R, All GP w/ 2 3/4" Hub Hole (exc. 1969 w/ 11" x 2" Rear Drum) (RP)..... 125.00/ea.

PR450B 1969-70 Front Brake Shoes, All GP (exc. 1969 w/ 11" x 2" Rear Drum) (RP) ... 23.00/set

REAR

PR450J 1969-72 Rear Brake Drum, L or R, All GP (exc. 1969 w/ 11" x 2" Rear Drum) (RP)..... 75.00/ea.

PR450K 1973-75 Rear Brake Drum, L or R, All GP (RP)..... 45.00/ea.

PR450L 1976-77 Rear Brake Drum, L or R, All GP (RP)..... 45.00/ea.

PR450P 1969-75 Rear Brake Shoes, All GP (exc. 1969 w/ 11" x 2" Rear Drum) (RP)..... \$ 19.00/set

PR450S 1976 Rear Brake Shoes, All GP (RP) 19.00/set

PR450T 1977 Rear Brake Shoes, All GP (RP) 19.00/set

Please add \$5.00 shipping for brake drums.

CALIPERS, KITS AND PISTONS (FULL SIZE)



PR452A 1967-68 Four Piston Caliper, LH, All FS (RP) . Inquire

PR452B 1967-68 Four Piston Caliper, RH, All FS (RP) . Inquire

PR452C 1969-70 Brake Caliper, LH, All FS (RP) 35.00/ea.

PR452D 1969-70 Brake Caliper, RH, All FS (RP)..... 35.00/ea.

PR452E 1971-76 Brake Caliper, LH, All FS (RP) 35.00/ea.

PR452F 1971-76 Brake Caliper, RH, All FS (RP)..... 35.00/ea.

PR452G 1977 Brake Caliper, LH, All FS (RP) 35.00/ea.

PR452H 1977 Brake Caliper, RH, All FS (RP)..... 35.00/ea.

Note: PR452A - PR452H are remanufactured calipers.

PR453B 1967-68 Caliper Overhaul Kit, All FS (RP) 25.00/ea.

PR453D 1969-77 Caliper Overhaul Kit, All FS (RP) 29.00/ea.

Note: 1 kit per caliper.

PR453J 1967-68 Brake Caliper Piston, All FS (RP) 18.00/ea.

PR453K 1969-77 Brake Caliper Piston, All FS (RP) 18.00/ea.

CALIPERS, KITS AND PISTONS (1969-77 GRAND PRIX)



PR454A 1969-72 Disc Brake Caliper, LH, All GP (RP) 35.00/ea.

PR454B 1969-72 Disc Brake Caliper, RH, All GP (RP) 35.00/ea.

PR454C 1973-76 Disc Brake Caliper, LH, All GP (RP) 35.00/ea.

PR454D 1973-76 Disc Brake Caliper, RH, All GP (RP) 35.00/ea.

PR454E 1977 Disc Brake Caliper, LH, All GP (RP) 35.00/ea.

PR454F 1977 Disc Brake Caliper, RH, All GP (RP) 35.00/ea.

Note: PR454A -PR454F are remanufactured calipers.

PR455A 1969-77 Caliper Overhaul Kit, All GP (exc. 1969 11" x 2" Rear Drum) (RP) 15.00/kit

PR455B 1969-77 Caliper Overhaul Kit, All GP (exc. 1969 9 1/2" x 2" Rear Drum) (RP)..... 25.00/kit

Note: 1 kit per caliper.

PR455J 1969-77 Caliper Piston, All GP (exc. 1969 11" x 2" Rear Drum) (RP)..... 18.00/ea.

WHEEL CYLINDERS (FULL SIZE)



FRONT

PR460A	1955-57	Front Wheel Cylinder, LH, All FS (RP).....	\$ 45.00/ea.
PR460B	1955-57	Front Wheel Cylinder, RH, All FS (RP).....	45.00/ea.
PR460C	1958	Front Wheel Cylinder, LH, All FS (RP).....	39.00/ea.
PR460D	1958	Front Wheel Cylinder, RH, All FS (RP).....	39.00/ea.
PR460E	1959-64	Front Wheel Cylinder, LH, All FS (RP).....	39.00/ea.
PR460F	1959-64	Front Wheel Cylinder, RH, All FS (RP).....	39.00/ea.
PR460G	1965-Early '67	Front Wheel Cylinder, LH, All FS (RP).....	45.00/ea.
PR460H	1965-Early '67	Front Wheel Cylinder, RH, All FS (RP).....	45.00/ea.
<i>Note: Early 1967 models used a wheel cylinder with a 1 3/16" bore.</i>			
PR460J	Late 1967-70	Front Wheel Cylinder, LH, All FS (RP).....	45.00/ea.
PR460K	Late 1967-70	Front Wheel Cylinder, RH, All FS (RP).....	45.00/ea.

Note: Late 1967 models used a wheel cylinder with a 1 1/8" bore.

REAR

PR461A	1955-57	Rear Wheel Cylinder, LH, All FS (RP)	39.00/ea.
PR461B	1955-57	Rear Wheel Cylinder, RH, All FS (RP)	39.00/ea.
PR461C	1958-64	Rear Wheel Cylinder, LH, All FS (RP)	42.00/ea.
PR461D	1958-64	Rear Wheel Cylinder, RH, All FS (RP)	42.00/ea.
PR461E	1965-77	Rear Wheel Cylinder, LH or RH, All FS w/ 11" x 2" Rear Brakes exc. 1976 (RP).....	27.00/ea.
PR461F	1976	Rear Wheel Cylinder, LH or RH, All FS w/ 11" x 2" Rear Brakes (RP)	29.00/ea.

WHEEL CYLINDERS (1969-77 GRAND PRIX)



FRONT

PR462C	1969-70	Front Wheel Cylinder, LH, All GP (exc. 11" x 2" Rear Drum) (RP) ...	\$35.00/ea.
PR462D	1969-70	Front Wheel Cylinder, RH, All GP (exc. 11" x 2" Rear Drum) (RP) ...	35.00/ea.
PR462E	1969	Front Wheel Cylinder, LH, All GP (exc. 9 1/2" x 2" Rear Drum) (RP) .	45.00/ea.
PR462F	1969	Front Wheel Cylinder, RH, All GP (exc. 9 1/2" x 2" Rear Drum) (RP) .	45.00/ea.

REAR

PR462J	1969	Rear Wheel Cylinder, LH or RH, All GP (exc. 9 1/2" x 2" Rear Drum) (RP) .	25.00/ea.
PR462K	1969-75	Rear Wheel Cylinder, LH or RH, All GP (exc. 1969 11" x 2" Rear Drum) (RP).....	25.00/ea.
PR462L	1976-77	Rear Wheel Cylinder, LH or RH, All GP (RP).....	25.00/ea.

WHEEL CYLINDER OVERHAUL KITS (FULL SIZE)



FRONT

PR465B	1955-57	Front Wheel Cylinder Overhaul Kit, LH or RH, All FS (RP)	10.00/kit
PR465C	1958	Front Wheel Cylinder Overhaul Kit, LH or RH, All FS (RP)	10.00/kit
PR465D	1959-64	Front Wheel Cylinder Overhaul Kit, LH or RH, All FS (RP)	10.00/kit
PR465E	1965-Early '67	Front Wheel Cylinder Overhaul Kit, LH or RH, All FS (RP)	12.00/kit

Note: Early 1967 models use a cylinder with a 1 3/16" bore. Please measure originals before ordering.

PR465F	Late 1967-70	Front Wheel Cylinder Overhaul Kit, LH or RH, All FS (RP)	12.00/kit
---------------	--------------	--	-----------

Note: Late 1967 models use a cylinder with a 1 1/8" bore. Please measure originals before ordering.


REAR

PR465J	1955-57	Rear Wheel Cylinder Overhaul Kit, LH or RH, All FS (RP)	10.00/kit
PR465K	1958-64	Rear Wheel Cylinder Overhaul Kit, LH or RH, All FS (RP)	10.00/kit
PR465L	1965-75	Rear Wheel Cylinder Overhaul Kit, LH or RH, All FS w/ 11" x 2" Rear Brakes (RP)	10.00/kit

Note: Also fits 1977 with 11" x 2" rear brakes.

PR465M	1976	Rear Wheel Cylinder Overhaul Kit, LH or RH, All FS w/ 11" x 2" Rear Brakes (RP)	10.00/kit
---------------	------	---	-----------

WHEEL CYLINDER OVERHAUL KITS (1969-77 GRAND PRIX)



FRONT

PR466B 1969-70 Front Wheel Cylinder Overhaul Kit, All GP (RP) \$ 11.00 /kit

REAR

PR466C 1969 Rear Wheel Cylinder Overhaul Kit, All GP exc. 9½" x 2" Rear Drum (RP) 10.00/kit

PR466D 1969-75 Rear Wheel Cylinder Overhaul Kit, All GP exc. 1969 11" x 2" Rear Drum (RP) 10.00/kit

PR466E 1976-77 Rear Wheel Cylinder Overhaul Kit, All GP (RP) 10.00/kit

BRAKE HARDWARE KITS AND ADJUSTERS (FULL SIZE)



FRONT

PR470B 1955-62 Front Drum Brake Hold Down Kit, All FS (RP) 7.00 /kit

PR470D 1965-70 Front Drum Brake Hold Down Kit, All FS (RP) 10.00/kit

REAR

PR470F 1955-57 Rear Brake Hold Down Kit, All FS (RP) 7.00/kit

PR470G 1958 Rear Brake Hold Down Kit, All FS (RP) 7.00/kit

PR470H 1959-62 Rear Brake Hold Down Kit, All FS (RP) 15.00/kit

PR470J 1965-70 Rear Brake Hardware Kit, All FS (RP) 12.00/kit

PR470K 1971-75 Rear Brake Hardware Kit, All FS (RP) 12.00/kit

PR470L 1976-77 Rear Brake Hardware Kit, All FS w/ 11" x 2" Rear Brake (RP) 12.00/kit



PR472D 1963-70 Rear Brake Adjuster Kit, LH, All FS (RP) \$ 23.00/kit

PR472E 1963-70 Rear Brake Adjuster Kit, RH, All FS (RP) 23.00/kit

PR472F 1971-76 Rear Brake Adjuster Kit, LH, All FS with 11" x 2" Rear Brake (RP) 15.00/kit

PR472G 1971-76 Rear Brake Adjuster Kit, RH, All FS with 11" x 2" Rear Brake (RP) 15.00/kit

PR472H 1977 Rear Brake Adjuster Kit, LH, All FS with 11" x 2" Rear Brake (RP) 15.00/kit

PR472J 1977 Rear Brake Adjuster Kit, RH, All FS with 11" x 2" Rear Brake (RP) 15.00/kit



FRONT

PR473B 1955-62 Front Brake Adjuster, LH or RH, All FS (RP) 10.00/ea.

PR473C 1963-70 Front Brake Adjuster, LH, All FS (RP) 10.00/ea.

PR473D 1963-70 Front Brake Adjuster, RH, All FS (RP) 10.00/ea.

REAR

PR473J 1955-62 Rear Brake Adjuster, LH or RH, All FS (RP) 10.00/ea.

PR473L 1963-70 Rear Brake Adjuster, LH, All FS (RP) 10.00/ea.

PR473M 1963-70 Rear Brake Adjuster, RH, All FS (RP) 10.00/ea.


PR473N 1971-76 Rear Brake Adjuster, LH, All FS with 11" x 2" Rear Brake (RP) 10.00/ea.

PR473P 1971-76 Rear Brake Adjuster, RH, All FS with 11" x 2" Rear Brake (RP) 10.00/ea.

PR473S 1977 Rear Brake Adjuster, LH, All FS with 11" x 2" Rear Brake (RP) 10.00/ea.

PR473T 1977 Rear Brake Adjuster, RH, All FS with 11" x 2" Rear Brake (RP) 10.00/ea.

BRAKE HARDWARE KITS AND ADJUSTERS (1969-77 GRAND PRIX)



FRONT


PR475B 1969-70 Front Drum Brake Hardware Kit, All GP (RP)..... \$ 13.00/kit

REAR

PR475C 1969-75 Rear Brake Hardware Kit, All GP exc. 1969 w/ 11" x 2" Rear Drum (RP)..... 13.00/kit

PR475D 1976 Rear Brake Hardware Kit, All GP (RP)..... 12.00/kit

PR475E 1977 Rear Brake Hardware Kit, All GP (RP)..... 12.00/kit



FRONT

PR476B 1969-70 Front Brake Adjuster Kit, LH, All GP (RP)..... Disc.

PR476C 1969-70 Front Brake Adjuster Kit, RH, All GP (RP)..... Disc.

REAR

PR476J 1969-75 Rear Brake Adjuster Kit, LH, All GP (RP)..... 15.00/kit

PR476K 1969-75 Rear Brake Adjuster Kit, RH, All GP (RP)..... 15.00/kit

PR476L 1976 Rear Brake Adjuster Kit, LH, All GP (RP)..... 15.00/kit

PR476M 1976 Rear Brake Adjuster Kit, RH, All GP (RP)..... 15.00/kit

PR476N 1977 Rear Brake Adjuster Kit, LH, All GP (RP)..... 15.00/kit

PR476P 1977 Rear Brake Adjuster Kit, RH, All GP (RP)..... 15.00/kit



FRONT

PR477B 1969-70 Front Brake Adjuster, LH, All GP (RP) 10.00/ea.

PR477C 1969-70 Front Brake Adjuster, RH, All GP (RP) 10.00/ea.

REAR

PR477J 1969-72 Rear Brake Adjuster, LH, All GP (RP) 10.00/ea.
Note: Also fits 1973-75 GP with 9 1/2" x 2" Rear Brakes.

PR477K 1969-72 Rear Brake Adjuster, RH, All GP (RP) 10.00/ea.
Note: Also fits 1973-75 GP with 9 1/2" x 2" Rear Brakes.

PR477L 1973-76 Rear Brake Adjuster, LH, All GP with 11" x 2" Rear Brakes (RP)..... 10.00/ea.

PR477M 1973-76 Rear Brake Adjuster, RH, All GP with 11" x 2" Rear Brakes (RP)..... \$ 10.00/ea.

PR477N 1977 Rear Brake Adjuster, LH, All GP (RP) 10.00/ea.

PR477P 1977 Rear Brake Adjuster, RH, All GP (RP) 10.00/ea.



PR478 1955-77 Brake Adjusting Plug (AP)50/ea.

Note: Many brake components require core charges. Please inquire when ordering.

REAR END BEARING KITS



PR482 1957-64 8.4", 10-Bolt Ring Gear Bearing Kit (AP)..... 119.00/kit

PR482B 1965-72 8.2", 10-Bolt Ring Gear Bearing Kit (AP)..... 119.00/kit

PR482D 1970-72 12-Bolt Ring Gear Bearing Kit (AP) .. 119.00/kit

PR482G 1971-76 8.5", 10-Bolt Ring Gear Bearing Kit - FS (AP)..... 119.00/kit

PR482G 1973-77 8.5", 10-Bolt Ring Gear Bearing Kit - GP (AP) 119.00/kit

Note: We are unable to supply bearing kits for the FS 10-bolt rears that have 12-bolt ring gears.

WHEEL BEARINGS AND SEALS



Wheel bearings and seals are now available for full size and Grand Prix. Please inquire with your particular needs.

AXLE TAGS & VENT TUBE




PR490

PR490 Limited Slip Rear Axle Tag (RE)..... \$ 5.00/ea.



PR491

PR491 1970-72 Limited Slip Rear Axle Tag, All 455ci with 12 Bolt Rear - GP (RP)..... 6.00/ea.



PR491J

PR491J 1963-77 Rear Axle Vent Tube (RP)..... 6.00/ea.

AXLE LUBRICANTS



PR500

PR500 Limited Slip Rear Axle Lubricant 23 oz. (GM). 7.00/ea.
PR502 Limited Slip Rear Axle Additive 4 oz. (GM) 7.00/ea.




PR502

This General Motors additive enhances the operation of your positraction unit and prolongs clutch life.

PR500 must be used in conjunction with PR502 for limited slip rear axles.

It normally takes (3) PR500 and (1) PR502 to fill a rear end.

U-JOINTS



PR565 1955 U-Joint Transmission End (AP)..... 22.00/ea.

PR567 1955 U-Joint Rear Axle End w/ bolts (AP). 32.00/ea.

PR569 1956-77 U-Joint, All (AP)..... \$ 16.00/ea.
The above universal joints are genuine Spicer.

BRAKE LINE CLIPS




PR678S

PR678S Steel Line Clip, Double Line Fits 1/4" and 3/8" Lines (Green) (GM) . 1.75/ea.

PR678T Steel Line Clip, Fits 1/4" and 5/16" Lines (Black) (GM) 1.75/ea.

PR679 Steel Line Clip, Fits 5/16" and 5/8" Lines (Black) (AP) 1.75/ea.

PR679A Steel Line Clip, Fits 1/4" and 3/8" Lines (Black) (AP) 1.75/ea.



PR679A



PR679B Steel Line Clip, Fits Single 3/16" Line, Silver (3/16" Bolt Hole) (AP) 1.75/ea.

PR679C Steel Line Clip, Fits Single 1/4" Line, Silver (1/4" Bolt Hole) (AP)..... 1.75/ea.

PR679D Steel Line Clip, Fits Single 5/16" Line, Silver (3/16" Bolt Hole) (AP) 1.75/ea.

PR679E Steel Line Clip, Fits Single 3/8" Line, Silver (3/16" Bolt Hole) (AP) 1.75/ea.



PR679B - PR679E



PR679F Steel Line Clip w/ Tab, Fits Single 1/4" Line, Blue (5/32" Bolt Hole) (AP).. 1.75/ea.

PR679G Steel Line Clip w/ Tab, Fits Single 3/8" Line, Blue (5/16" Bolt Hole) (AP).. 1.75/ea.

PR679H Steel Line Clip w/ Tab, Fits Single 3/16" Line, Yellow Zinc (5/32" Bolt Hole) (AP)..... 1.75/ea.



PR679F - PR679H



PR679J Steel Line Clip, Double Line, Fits 3/8" and 1/4" Lines, Silver (5/16" Bolt Hole) (AP)..... 1.75/ea.



PR679K Steel Line Clip, Double Line, Fits 3/16" and 1/4" Lines, Silver (5/16" Bolt Hole) (AP)..... 1.75/ea.

PR679J

PR679K



PR679L	PR679L	PR679M
	Steel Line Clip, Fits 5/8" Single Line, Silver (5/32" Bolt Hole) (AP).....	Steel Line Clip w/ Tab, Fits 3/8" Single Line, Blue (5/32" Bolt Hole) (AP).....
	\$ 1.75/ea.	2.00/ea.

Note: PR678T through PR679A are shown actual size. All others are about 50%.

BRAKE LINE & SHIELDING


PR695	1955-77 1/4" Brake Line (25 foot roll) (AP).....	17.00/roll
PR696	1955-77 3/16" Brake Line (25 foot roll) (AP).....	17.00/roll



	PR697J	
PR697J	1955-77 3/16" Coiled Shielding (Brake Line) (4 ft. length) (GM).....	16.00/ea.



PRE-BENT FULL SIZE BRAKE LINES



PRE-BENT FRONT BRAKE LINES

Other years are becoming available. Please inquire if you do not see your application listed.

PR705A	1961	Front Brake Lines - Standard Drum 3pc. Steel (RE)	58.00/set
PR705AS	1961	Front Brake Lines - Standard Drum 3pc. Stainless Steel (RE)	80.00/set
PR705D	1961	Front Brake Lines - Power Drum 3pc. Steel (RE)	58.00/set
PR705DS	1961	Front Brake Lines - Power Drum 3pc. Stainless Steel (RE)	80.00/set
PR705N	1962-64	Front Brake Lines - Standard Drum 3pc. Steel (RE)	58.00/set
PR705NS	1962-64	Front Brake Lines - Standard Drum 3pc. Stainless Steel (RE)	80.00/set

PR705S	1965	Front Brake Lines - Standard Drum 3pc. Steel (RE)	\$ 58.00/set
PR705SS	1965	Front Brake Lines - Standard Drum 3pc. Stainless Steel (RE)	80.00/set
PR705W	1965	Front Brake Lines - Power Drum 3pc. Steel (RE)	58.00/set
PR705WS	1965	Front Brake Lines - Power Drum 3pc. Stainless Steel (RE)	80.00/set
PR706D	1966	Front Brake Lines - Standard Drum 3pc. Steel (RE)	58.00/set
PR706DS	1966	Front Brake Lines - Standard Drum 3pc. Stainless Steel (RE)	80.00/set
PR706H	1966	Front Brake Lines - Power Drum 3pc. Steel (RE)	58.00/set
PR706HS	1966	Front Brake Lines - Power Drum 3pc. Stainless Steel (RE)	80.00/set
PR706L	1967-68	Front Brake Lines - Standard Drum 4pc. Steel (RE)	65.00/set
PR706LS	1967-68	Front Brake Lines - Standard Drum 4pc. Stainless Steel (RE)	95.00/set
PR706P	1967-68	Front Brake Lines - Power Drum 4pc. Steel (RE)	65.00/set
PR706PS	1967-68	Front Brake Lines - Power Drum 4pc. Stainless Steel (RE)	95.00/set
PR706T	1967-68	Front Brake Lines - Power Disc 5pc. Steel (RE)	65.00/set
PR706TS	1967-68	Front Brake Lines - Power Disc 5pc. Stainless Steel (RE)	95.00/set
PR707B	1969	Front Brake Lines - Power Drum 4pc. - FS - Steel (RE)	65.00/set
PR707BS	1969	Front Brake Lines - Power Drum 4pc. - FS - Stainless Steel (RE)	95.00/set
PR707G	1969	Front Brake Lines - Power Disc 5pc. - FS - Steel (RE)	65.00/set
PR707GS	1969	Front Brake Lines - Power Disc 5pc. - FS - Stainless Steel (RE)	95.00/set
PR707J	1970	Front Brake Lines - Power Drum 5pc. - FS - Steel (RE)	65.00/set
PR707JS	1970	Front Brake Lines - Power Drum 5pc. - FS - Stainless Steel (RE)	95.00/set
PR707N	1970	Front Brake Lines - Power Disc 5pc. - FS - Steel (RE)	65.00/set
PR707NS	1970	Front Brake Lines - Power Disc 5pc. - FS - Stainless Steel (RE)	95.00/set



PRE-BENT FRONT TO REAR BRAKE LINES

Other years are becoming available. Please inquire if you do not see your application listed.

PR720B	1961-62	Front to Rear Brake Line Cat/GP - Steel (RE)	50.00/ea.
PR720BS	1961-62	Front to Rear Brake Line Cat/GP - Stainless Steel (RE)	70.00/ea.
PR720F	1961-62	Front to Rear Brake Line Bonne - Steel (RE)	50.00/ea.
PR720FS	1961-62	Front to Rear Brake Line Bonne - Stainless Steel (RE)	70.00/ea.
PR721B	1965	Front to Rear Brake Line Bonne - Steel (RE)	50.00/ea.

PR721BS	1965	Front to Rear Brake Line Bonne - Stainless Steel (RE)	\$ 70.00/ea.
PR721J	1966	Front to Rear Brake Line Cat/GP - Steel (RE)	50.00/ea.
PR721JS	1966	Front to Rear Brake Line Cat/GP - Stainless Steel (RE)	70.00/ea.
PR723C	1970	Front to Rear Brake Line - w/ Power Front Disc - 2pc. - GP - Steel (RE)...	50.00/ea.
PR723CS	1970	Front to Rear Brake Line - w/ Power Front Disc - 2pc. - GP - Stainless Steel (RE)	70.00/ea.

Note: Please add \$8.50 shipping for "Front to Rear" lines.



PRE-BENT BRAKE LINES - REAR

Other years are becoming available. Please inquire if you do not see your application listed.

PR730A	1955	Rear Brake Lines - 3pc. Steel (RE)..	35.00/set
PR730AS	1955	Rear Brake Lines - 3pc. Stainless Steel (RE)	45.00/set
PR731A	1961	Rear Brake Lines - 3pc. Steel (RE)..	35.00/set
PR731AS	1961	Rear Brake Lines - 3pc. Stainless Steel (RE)	45.00/set
PR731H	1962-64	Rear Brake Lines - 3pc. Steel (RE)..	35.00/set
PR731HS	1962-64	Rear Brake Lines - 3pc. Stainless Steel (RE)	45.00/set
PR731L	1965	Rear Brake Lines - 2pc. Steel (RE)..	25.00/set
PR731LS	1965	Rear Brake Lines - 2pc. Stainless Steel (RE)	35.00/set
PR731R	1966	Rear Brake Lines - 2pc. Steel (RE)..	25.00/set
PR731RS	1966	Rear Brake Lines - 2pc. Stainless Steel (RE)	35.00/set
PR732B	1967-68	Rear Brake Lines - 2pc. Steel (RE)..	25.00/set
PR732BS	1967-68	Rear Brake Lines - 2pc. Stainless Steel (RE)	35.00/set



COMPLETE PRE-BENT BRAKE LINE SETS



Other years are becoming available. Please inquire if you do not see your application listed.

PR740J	1961	Complete Brake Line Set - Standard Drum - 7pc. - Catalina - Steel (RE)	145.00/set
PR740JS	1961	Complete Brake Line Set - Standard Drum - 7pc. - Catalina - Stainless Steel (RE)	175.00/set

PR740M	1961	Complete Brake Line Set - Power Drum - 7pc. - Catalina - Steel (RE) .	\$145.00/set
PR740MS	1961	Complete Brake Line Set - Power Drum - 7pc. - Catalina - Stainless Steel (RE)	175.00/set
PR740S	1962-64	Complete Brake Line Set - Standard Drum - 7pc. - Cat/GP - Steel (RE)	145.00/set
PR740SS	1962-64	Complete Brake Line Set - Standard Drum - 7pc. - Cat/GP - Stainless Steel (RE)	175.00/set
PR740V	1962-64	Complete Brake Line Set - Power Drum - 7pc. - Cat/GP - Steel (RE) ...	145.00/set
PR740VS	1962-64	Complete Brake Line Set - Power Drum - 7pc. - Cat/GP - Stainless Steel (RE)	175.00/set
PR740X	1962-64	Complete Brake Line Set - Standard Drum - 7pc. - Bonne - Steel (RE)	145.00/set
PR740XS	1962-64	Complete Brake Line Set - Standard Drum - 7pc. - Bonne - Stainless Steel (RE)	175.00/set
PR740Z	1962-64	Complete Brake Line Set - Power Drum - 7pc. - Bonne - Steel (RE)	145.00/set
PR740ZS	1962-64	Complete Brake Line Set - Power Drum - 7pc. - Bonne - Stainless Steel (RE)	175.00/set
PR742D	1967-68	Complete Brake Line Set - Standard Drum - 7pc. - Cat/GP - Steel (RE)	145.00/set
PR742DS	1967-68	Complete Brake Line Set - Standard Drum - 7pc. - Cat/GP - Stainless Steel (RE)	175.00/set
PR742J	1967-68	Complete Brake Line Set - Power Drum - 7pc. - Cat/GP - Steel (RE) ...	145.00/set
PR742JS	1967-68	Complete Brake Line Set - Power Drum - 7pc. - Cat/GP - Stainless Steel (RE)	175.00/set
PR742L	1967-68	Complete Brake Line Set - Power Disc - 8pc. - Cat/GP - Steel (RE)	145.00/set
PR742LS	1967-68	Complete Brake Line Set - Power Disc - 8pc. - Cat/GP - Stainless Steel (RE)	175.00/set
PR743J	1969	Complete Brake Line Set - Power Drum - 7pc. - GP - Steel (RE)	145.00/set
PR743JS	1969	Complete Brake Line Set - Power Drum - 7pc. - GP - Stainless Steel (RE)	175.00/set
PR743L	1969	Complete Brake Line Set - Power Disc - 8pc. - GP - Steel (RE)	145.00/set
PR743LS	1969	Complete Brake Line Set - Power Disc - 8pc. - GP - Stainless Steel (RE)	175.00/set
PR744J	1970	Complete Brake Line Set - Power Drum - 8pc. - GP - Steel (RE)	145.00/set
PR744JS	1970	Complete Brake Line Set - Power Drum - 8pc. - GP - Stainless Steel (RE)	175.00/set
PR744L	1970	Complete Brake Line Set - Power Disc - 9pc. - GP - Steel (RE)	145.00/set


PR744LS	1970	Complete Brake Line Set - Power Disc - 9pc. - GP - Stainless Steel (RE).....	\$ 175.00/set
PR745J	1971-72	Complete Brake Line Set - Power Disc - 9pc. - GP - Steel (RE)	145.00/set
PR745JS	1971-72	Complete Brake Line Set - Power Disc - 9pc. - GP - Stainless Steel (RE).....	175.00/set
PR746J	1973-77	Complete Brake Line Set - Power Disc - 7pc. - GP - Steel (RE)	145.00/set
PR746JS	1973-77	Complete Brake Line Set - Power Disc - 7pc. - GP - Stainless Steel (RE).....	175.00/set

Note: Please add \$8.50 shipping for complete brake line kits.

Note: Brake lines require pre-payment and are drop-shipped directly from the manufacturer.

Comment: All fittings, flares, armor, etc. are excellent. Sets do not include rubber flex hoses or clips.

FRONT & REAR BRAKE FLEX HOSE - U.S. CARS



PR750	1960-72	Flex Hose Retaining Clip, Front or Rear (RE).....	1.00/ea.
--------------	---------	---	----------

PR750J	1960	Front Flex Hose, Drum Brakes (2 required) (RE)	\$ 27.00/ea.
PR750L	1961-64	Front Flex Hose, Drum Brakes (2 required) (RE)	27.00/ea.
PR750N	1965	Front Flex Hose, Drum Brakes (2 required) (RE)	29.00/ea.
PR750R	1966-68	Front Flex Hose, Drum Brakes (2 required) (RE)	19.00/ea.
PR750T	1967-68	Front Flex Hose, Disc Brakes (2 required) (RE)	32.00/ea.
PR750W	1969-70	Front Flex Hose, Drum Brakes - FS (2 required) (RE)	32.00/ea.
PR750Y	1969-70	Front Flex Hose, Disc Brakes - FS (2 required) (RE)	39.00/ea.
PR751B	1969-70	Front Flex Hose, Drum Brakes - GP (2 required) (RE)	24.00/ea.
PR751D	1969-71	Front Flex Hose, Disc Brakes - GP (2 required) (RE)	22.00/ea.
PR751F	1972	Front Flex Hose, Disc Brakes - GP (2 required) (RE)	25.00/ea.
PR753J	1960	Rear Flex Hose (RE).....	28.00/ea.
PR753L	1961-64	Rear Flex Hose (RE).....	28.00/ea.
PR753N	1965	Rear Flex Hose (RE).....	Inquire
PR753R	1966-68	Rear Flex Hose (RE).....	Inquire
PR754B	1969-70	Rear Flex Hose - GP (RE).....	30.00/ea.

FRONT & REAR BRAKE FLEX HOSE - CANADIAN CARS

PR758	1960-68	Canadian Front Flex Hose, Drum Brakes (2 required) (RE).....	22.00/ea.
PR758D	1960-63	Canadian Rear Flex Hose (RE)	24.00/ea.
PR758F	1964	Canadian Rear Flex Hose (RE)	22.00/ea.
PR758H	1965	Canadian Rear Flex Hose (RE)	35.00/ea.
PR758K	1966	Canadian Rear Flex Hose (RE)	33.00/ea.
PR758M	1967-68	Canadian Rear Flex Hose (RE)	35.00/ea.



BEWARE OF LOW PRICED, LOW QUALITY BRAKE COMPONENTS


In keeping with our ongoing commitment for quality parts, we sell only name-brand components (Bendix, Raybestos, etc.). Discount pieces have no place in your brake system.

Depend on our quality.

A.P.E. SIMPLY HAS THE BEST SERVICE! ENOUGH SAID!

For ordering or price quotations, please call (800) 421-AMES (2637).
For questions or ordering, call (603) 876-3345
(603) 876-4656
(603) 876-4751

SECTION FIFTEEN - SUSPENSION



SUSPENSION

PS100J	1955	King Pin Set (AP)	\$ 99.00/set
PS100K	1956-57	King Pin Set (AP)	93.00/set
PS100W	1955-57	Lower Ball Joint (AP)	99.00/ea.
PS101	1958-64	Lower Ball Joint (AP)	55.00/ea.
PS102	1966-70	Lower Ball Joint - FS (AP)	59.00/ea.



Note: PS102 also fits 1965 models if they do not have flanged edges on the lower control arm or a plate welded over the ball joint.

PS103	1971-76	Lower Ball Joint - FS (AP)	29.00/ea.
PS104	1969-72	Lower Ball Joint - GP (AP)	22.00/ea.
PS104D	1973-77	Lower Ball Joint - GP (AP)	22.00/ea.
PS104J	1955-57	Upper Ball Joint (AP)	108.00/ea.
PS104K	1958	Upper Ball Joint (AP)	99.00/ea.
PS104L	1959-63	Upper Ball Joint, LH (AP)	75.00/ea.
PS104M	1959-63	Upper Ball Joint, RH (AP)	75.00/ea.
PS105L	1964-70	Upper Ball Joint, LH - FS (AP)	49.00/ea.
PS105R	1964-70	Upper Ball Joint, RH - FS (AP)	49.00/ea.
PS106	1971-76	Upper Ball Joint - FS (AP)	19.00/ea.
PS107	1969-72	Upper Ball Joint - GP (AP)	19.00/ea.
PS107D	1973-77	Upper Ball Joint - GP (AP)	19.00/ea.
PS107TA	1955-57	Upper Control Arm Shaft w/Bushings (AP)	99.00/ea.
PS107TC	1958-62	Upper Control Arm Shaft w/Bushings (AP)	99.00/ea.
PS107TF	1963-64	Upper Control Arm Shaft w/Bushings (AP)	79.00/ea.
PS107TH	1965-70	Upper Control Arm Shaft w/Bushings - FS (AP)	59.00/ea.
PS107TK	1969-72	Upper Control Arm Shaft w/Bushings - GP (AP)	45.00/ea.
PS108	1971-73	Upper Control Arm Shaft - FS (AP)	52.00/ea.
PS109	1974-76	Upper Control Arm Shaft - FS (AP)	52.50/ea.

PS108	1973	Upper Control Arm Shaft - GP (AP)	\$ 52.00/ea.
PS109	1974-77	Upper Control Arm Shaft - GP (AP)	52.50/ea.
PS112L	1961	Inner Tie Rod, LH (AP)	49.00/ea.
PS112R	1961	Inner Tie Rod, RH (AP)	49.00/ea.
PS112SL	1962-63	Inner Tie Rod, LH (AP)	85.00/ea.
PS112SR	1962-63	Inner Tie Rod, RH (AP)	85.00/ea.
PS112TL	1964	Inner Tie Rod, LH (AP)	85.00/ea.
PS112TR	1964	Inner Tie Rod, RH (AP)	85.00/ea.
PS112L	1965-68	Inner Tie Rod, LH (AP)	51.50/ea.
PS112R	1965-68	Inner Tie Rod, RH (AP)	51.50/ea.
PS113L	1969-70	Inner Tie Rod, LH - FS (AP)	86.00/ea.
PS113R	1969-70	Inner Tie Rod, RH - FS (AP)	86.00/ea.
PS114	1971-76	Inner Tie Rod - FS (AP)	20.00/ea.
PS115	1969-70	Inner Tie Rod - GP (AP)	17.00/ea.
PS116	1971-72	Inner Tie Rod - GP (AP)	43.00/ea.
PS116A	1973-77	Inner Tie Rod - GP (AP)	23.00/ea.
PS116SA	1955-58	Outer Tie Rod (AP)	36.00/ea.
PS116SF	1959-60	Outer Tie Rod, LH (AP)	69.00/ea.
PS116SG	1959-60	Outer Tie Rod, RH (AP)	69.00/ea.
PS116SJ	1961-63	Outer Tie Rod (AP)	39.00/ea.
PS116SK	1964	Outer Tie Rod (AP)	69.00/ea.
PS117	1965-70	Outer Tie Rod End - FS (NOS)	69.00/ea.
PS118	1971-76	Outer Tie Rod End - FS (AP)	20.00/ea.
PS119	1969-70	Outer Tie Rod End - GP (AP)	43.00/ea.
PS120	1971-72	Outer Tie Rod End - GP (AP)	41.00/ea.
PS120A	1973-77	Outer Tie Rod - GP (AP)	21.00/ea.



PS120SA	1955-63	Tie Rod End Dust Boot (RE)	4.50/ea.
PS121	1963-70	Center Link - FS (AP)	195.00/ea.
PS122	1971-72	Center Link - FS (AP)	Disc.
PS123	1969-72	Center Link - GP (AP)	79.00/ea.

PS123A	1973-76	Center Link - FS (AP)	\$ 89.00/ea.
PS123B	1973-77	Center Link - GP (AP)	109.00/ea.
PS123PA	1955-62	Idler Arm Bracket (AP)	70.00/ea.
PS123PD	1955-60	Idler Arm (AP)	95.00/ea.
PS123PF	1961-62	Idler Arm (AP)	74.00/ea.
PS124	1963-70	Steering Idler Arm - FS (AP)	99.00/ea.
PS125	1971-72	Steering Idler Arm - FS (AP)	31.00/ea.
PS126	1969-72	Steering Idler Arm - GP (AP)	29.00/ea.
PS126A	1973-74	Steering Idler Arm - ALL (AP)	33.00/ea.
PS126B	1975-76	Steering Idler Arm - FS (AP)	33.00/ea.
PS126C	1975-77	Steering Idler Arm - GP (AP)	33.00/ea.
PS130	1955-76	Tie Rod Adjusting Sleeve - FS (AP)	11.00/ea.
PS130A	1969-70	Tie Rod Adjusting Sleeve - GP (AP)	10.00/ea.
PS130	1971-77	Tie Rod Adjusting Sleeve - GP (AP)	11.00/ea.

RUBBER BUMPERS



PS133



PS136



PS137

PS139

PS132R	1955-56	Rear Axle to Frame Bumper (Mounts on Spring) (RE)	35.00/pr.
PS133	1965-72	Rear Axle to Frame Bumper - ALL (RE)	6.00/ea.
PS133D	1973-76	Rear Axle to Frame Bumper - FS (RE)	6.00/ea.
PS133H	1973-77	Rear Axle to Frame Bumper - GP (GM)	5.00/ea.
PS135	1965-76	Pinion Bumper - FS (GM)	Disc.
PS136	1969-77	Pinion Bumper - GP (GM)	8.00/ea.
PS137	1957-70	Upper Control Arm Bumper - FS (GM)	9.00/ea.
PS137	1969-72	Upper Control Arm Bumper - GP (GM)	9.00/ea.
PS137D	1973-77	Upper Control Arm Bumper - GP (GM)	3.00/ea.
PS137X	1955-57	Lower Control Arm Bumpers (RE)	42.00/pr.
PS138	1961-70	Lower Control Arm Bumper - FS (GM)	Disc.
PS139	1969-72	Lower Control Arm Bumper - GP (GM)	7.00/ea.
PS140	1971-72	Lower Control Arm Bumper - FS (GM)	9.00/ea.
PS142	1973-77	Lower Control Arm Bumper - ALL w/R.T.S. (GM)	Disc.

FRONT CONTROL ARM BUSHINGS & HARDWARE



PS170	1965-72	Upper A-frame to Frame Bolt Kit (RP)	12.00/kit
Consists of 4 bolts, 4 washers and 4 nuts to at-			

tach the front upper A-frame shaft to the frame rail.

PS179	1965-70	Upper Control Arm Shaft Bushings - FS-PR (RP)	\$ 16.00/pr.
PS180	1969-72	Upper Control Arm Shaft Bushing - GP-PR (RP)	10.00/pr.
PS181	1971-72	Upper Control Arm Shaft Bushing - FS-PR (RP)	10.00/pr.
PS182	1965-70	Lower Control Arm Bushing Kit, w/ Oval Rear Bushing - FS-PR (RP)	17.00/pr.
PS182	1969-72	Lower Control Arm Bushing Kit, w/ Oval Rear Bushing - GP-PR (RP)	17.00/pr.
PS179 and PS182 are only available as kits. One kit does one A-frame.			
PS184	1971-72	Lower Control Arm Bushing, Front - FS (GM)	13.00/ea.
PS185	1971-72	Lower Control Arm Bushing, Rear - FS (GM)	11.00/ea.

REAR CONTROL ARMS, BUSHINGS & HARDWARE



PS186

PS186	1969-72	Rear Lower Control Arm w/Rubber Bushings, Boxed - GP (RE)	199.00/pr.
PS186	1969-70	Rear Lower Control Arm w/Rubber Bushings, Boxed - FS (RE)	199.00/pr.
PS186C	1969-72	Rear Lower Control Arm w/ Urethane Bushings, Boxed - GP (RE)	219.00/pr.
PS186C	1969-70	Rear Lower Control Arm w/ Urethane Bushings, Boxed - FS (RE)	219.00/pr.




PS186H

PS186H	1969-72	Rear Upper Control Arm w/Rubber Bushing - GP (RE)	79.00/ea.
PS186HB	1969-72	Rear Upper Control Arm w/ Urethane Bushing - GP (RE)	89.00/ea.
PS187	1965-70	Rear Lower Control Arm Rubber Bushing, FS (AP)	12.00/ea.
PS187	1969-72	Rear Lower Control Arm Rubber Bushing - GP (AP)	12.00/ea.
PS187	1965-70	Rear Upper Control Arm Rubber Bushing - FS (AP)	12.00/ea.
PS187	1969-72	Rear Upper Control Arm Rubber Bushing - GP exc. 12-Bolt Rear Axle (AP)	12.00/ea.
PS189	1973-75	Rear Lower Control Arm exc. R.T.S. - GP (GM)	Disc.
PS189A	1973-75	Rear Lower Control Arm w/R.T.S. - GP (GM)	Disc.

PS189H	1973-77	Rear Upper Control Arm w/R.T.S. - GP (GM).....	Disc.
PS190	1965-72	Rear Control Arm Bolt (RE)	5.00/ea.
PS190B	1965-72	Rear Control Arm Nut (GM)	1.00/ea.

STABILIZER BARS, RUBBER BUSHINGS & BRACKETS



	PS208		PS201		PS208
PS201	1969-77	Front Stabilizer Bar (1.25" dia.) - GP (GM).....			96.00/ea.
PS202	1969-72	Rear Stabilizer Bar (.875" dia.) - GP (GM).....			86.00/ea.

PS202 must be used with some type of boxed control arms.

Note: Please add \$7.00 shipping for stabilizer bars.



PS203

PS203	1969-72	Rear Anti-Sway Bar Shims - GP (GM).....	2.00/ea.
--------------	---------	---	----------

Note: Use as required.

PS203J	1969-72	Rear Anti-Sway Bar Mounting and Shim Kit - GP (RE)	10.00/kit
---------------	---------	--	-----------

This kit includes: 4 bolts, nuts, washers and 2 shims to mount the rear sway bar to your existing boxed lower control arms.

PS205	1959-64	Front Stabilizer Bar End Link Kit - FS (AP).....	14.50/pr.
PS206	1965-70	Front Stabilizer Bar End Link Kit - FS (AP).....	13.00/pr.
PS207	1971-76	Front Stabilizer Bar End Link Kit - FS (AP).....	13.00/pr.
PS207	1973-77	Front Stabilizer Bar End Link Kit - GP (AP).....	13.00/pr.
PS208	1969-72	Front Stabilizer Bar End Link Kit - GP (GM).....	21.00/pr.



PS210

PS216

PS208T	1955-57	Front Stabilizer Bar to Frame Bushing w/3/4" Bar (RE)	28.00/pr.
PS209	1960-70	Front Stabilizer Bar to Frame Bushing w/3/4" Bar (GM)	Disc.

PS210	Front Stabilizer Bar to Frame Bushing w/7/8" Bar (RP)	\$ 5.50/ea.
PS211	Front Stabilizer Bar to Frame Bushing w/1" Bar (RP)	3.50/ea.
PS212	Front Stabilizer Bar to Frame Bushing w/1 1/8" Bar (GM)	5.00/ea.
PS213	Front Stabilizer Bar to Frame Bushing w/1 1/4" Bar (GM)	5.00/ea.

To determine correct stabilizer bar diameter measure circumference and divide by 3.14.

PS216	Front Stabilizer Bar to Frame Bushing Bracket - ALL exc. 1 1/4" Bar (GM).....	6.50/pr.
PS217	Front Stabilizer Bar to Frame Bushing Bracket w/1 1/4" Bar (GM)...	13.00/pr.

HIGH PERFORMANCE SUSPENSION COMPONENTS



Energy Suspension components are the finest in the industry. We use only their top quality black graphite impregnated bushings for all urethane applications.

URETHANE FRONT CONTROL ARM BUSHINGS



Note: You must use your original oval steel shells for the PS220 kit.

DO NOT DISCARD THEM!!

PS220	1969-72	Front Control Arm Bushings, 8 Pcs. - GP (AP)	60.00/set
--------------	---------	---	-----------

Note: Bushings come with outer metal shell, except oval. Your original oval steel sleeve must be used.

PS221	1971-73	Front Control Arm Bushings, 8 Pcs. - FS (AP).....	75.00/set
PS221	1973	Front Control Arm Bushings, 8 Pcs. - GP (AP)	75.00/set
PS223	1974-76	Front Control Arm Bushings, 8 Pcs. - FS (AP).....	75.00/set
PS223	1974-77	Front Control Arm Bushings, 8 Pcs. - GP (AP)	75.00/set

Note: Sets contain bushings for 2 upper and 2 lower control arms.

URETHANE FRONT STABILIZER BUSHINGS



PS230	Stabilizer Bar to Frame Bushings & Brackets w/3/4" Bar (AP).....	\$ 18.00/set
PS230J	Stabilizer Bar to Frame Bushings & Brackets w/ 13/16" Bar (AP).....	18.00/set
PS231	Stabilizer Bar to Frame Bushings & Brackets w/7/8" Bar (AP).....	18.00/set
PS232	Stabilizer Bar to Frame Bushings & Brackets w/15/16" Bar (AP)	18.00/set
PS233	Stabilizer Bar to Frame Bushings & Brackets w/1" Bar (AP).....	18.00/set
PS234	Stabilizer Bar to Frame Bushings & Brackets w/11/8" Bar (AP)	18.00/set
PS235	Stabilizer Bar to Frame Bushings & Brackets w/11/4" Bar (AP)	18.00/set

Note: PS230 through PS235 consist of 2 bushings and 2 brackets which mount the stabilizer bar to the frame.

PS245	1965-70 Front Stabilizer End Link Kit - FS (AP).....	18.00/set
PS246	1971-76 Front Stabilizer End Link Kit - FS (AP).....	18.00/set
PS247	1969-72 Front Stabilizer End Link Kit - GP (AP).....	18.00/set
PS246	1973-77 Front Stabilizer End Link Kit - GP (AP).....	18.00/set



HIGH PERFORMANCE FRONT STABILIZER BAR KITS

PS250	1961-64 11/8" Front Stabilizer Bar Kit (AP)	199.00/kit
PS250D	1965-70 11/8" Front Stabilizer Bar Kit - FS (AP)	199.00/kit
PS250J	1971-76 11/8" Front Stabilizer Bar Kit - FS exc. S.W. (AP)	199.00/kit

PS250-PS250J are afterproduct kits which do not mount like originals.



PS252

PS252	1969-72 11/4" Front Stabilizer Bar Kit - GP (GM-AP).....	125.00/kit
PS253	1973-77 11/4" Front Stabilizer Bar Kit - GP (GM-AP).....	125.00/kit

PS252 and PS253 include: 1-GM front bar; 2-urethane frame bushings w/brackets; 2-urethane end links w/bushings.

Comments: These kits have the largest diameter bar that we recommend for street use.

Please add \$7.00 shipping for sway bar kits.



REAR ANTI-SWAY BAR KITS

PS258D	1961-64 1" Rear Anti-Sway Bar Kit (AP)	\$176.00/kit
PS258J	1965-76 1" Rear Anti-Sway Bar Kit - FS exc. '71-76 S.W. (AP).....	176.00/kit
PS258N	1969-77 1" Rear Anti-Sway Bar - GP (AP).....	176.00/kit

PS258D-PS258N are afterproduct kits which do not mount like originals.



PS260

PS260	1969-72 Rear Anti-Sway Bar Kit - GP (GM-RE).....	259.00/kit
PS260K	1969-72 Rear Anti-Sway Bar Kit w/ Urethane Bushings - GP (GM-RP)	279.00/kit

PS260 and PS260K include two boxed lower control arms (complete w/bushings), the 7/8" anti-sway bar plus necessary hardware to bolt bar to control arms.

Please add \$7.00 shipping for rear anti-sway bar kits.

URETHANE CONTROL ARM BUSHINGS

PS267	1965-70 Urethane Rear Axle Control Arm Bushings - FS (AP)	11.00/ea.
PS267	1969-77 Urethane Rear Axle Control Arm Bushing - GP (AP)	11.00/ea.
PS268	1965-70 Urethane Rear Axle Control Arm Bushing Set, 8 Pcs. - FS (AP).....	75.00/set
PS268	1969-77 Urethane Rear Axle Control Arm Bushing Set, 8 Pcs. - GP (AP)	75.00/set



TRACTION BARS



PS276

PS275	1961-64 Adjustable Traction Bar Kit (AP)	179.00/kit
PS276	1969-72 Adjustable Traction Bar Kit - GP (AP).....	169.00/kit

These traction bar kits are designed to reduce wheel hop and wheel spin, which will greatly improve acceleration. They are adjustable to fine tune to your application.

Note: These bars do not have provisions for mounting a rear sway bar.

KYB GAS SHOCK ABSORBERS



PS280 1958-62 Front Gas Shocks Exc. AS (AP)..... \$ 75.00/pr.
Note: For PS280 applications, mounting holes may need to be elongated on bottom of shock.

PS281 1963-70 Front Gas Shocks - FS (AP)..... 75.00/pr.

PS282 1971-76 Front Gas Shocks - FS (AP)..... 75.00/pr.

PS283 1969-77 Front Gas Shocks - GP (AP)..... 75.00/pr.

PS284 1958-62 Rear Gas Shocks Exc. AS (AP)..... 79.00/pr.

Note: PS284 will not work on cars equipped w/shocks that have studs on both ends. We cannot supply a shock for this application.

PS285 1963-70 Rear Gas Shocks Exc. Station Wagon or HD Susp. - FS (AP) 75.00/pr.

PS286 1969-70 Rear Gas Shocks w/HD Susp. or Station Wagon - FS (AP) 75.00/pr.

PS287 1971-76 Rear Gas Shocks Exc. Station Wagon or HD Susp. - FS (AP) 75.00/pr.

PS288 1971-76 Rear Gas Shocks w/HD Susp. or Station Wagon - FS (AP) Disc.

PS289 1969-77 Rear Gas Shocks - GP (AP)..... 75.00/pr.

For superior road handling at a reasonable price KYB Gas-a-just shocks are simply the best. 280 p.s.i. of N2 gas give these shocks extremely quick rebound action keeping tires firmly on the road without any shock fade generally associated with hydraulic shocks.

Comments: Finest quality shocks for the price.

PS289T Shock Paint (Gray) 11 oz. Aerosol (AP)..... 6.00/ea.

This is the correct gray paint used on original Delco shocks.



PS290 1955-77 Urethane Front Shock Absorber Upper Grommets, 4 Pcs. (A-body) (AP)..... 5.00/set

This kit contains enough to do two shocks.

PS291 1958-77 Urethane Rear Shock Absorber Lower Grommets, w/Original-style Shocks, 2 Pcs. (A-body) (AP) 4.00/pr.

This kit contains enough to do two shocks.

PS292 1958-77 Urethane Rear Shock Absorber Lower Grommets, w/KYB Gas Shocks, 2 Pcs. (A-body) (AP) 4.00/pr.

This kit contains enough to do two shocks.



PS295 1964-77 Front Lower Control Arm Shock Nuts (GM) \$ 1.00/ea.

These are the nuts that push on the lower control arm.

PS295J 1964-77 Front Shock Mounting Kit (GM)..... 8.00/set

This kit contains four shock nuts (PS295) and four bolts to replace your originals



FRONT COIL SPRINGS

YEAR	MODEL & BODY STYLE	w/o AC		w/AC	
		REG	HD	REG	HD
1958	ALL exc. SW	PS300		PS304	
1959-60	ALL	PS304		PS308	
1961	ALL	PS300		PS308	
1962-63	ALL	PS304		PS308	
1964	ALL	PS304		PS308	
1965	Catalina Conv.	PS320		PS312	PS308
1965	Catalina HT	PS320		PS312	PS324
1965	Star Chief, Bonneville, Grand Prix	PS300	PS308	PS312	PS324
1966	Catalina 2 Dr.	PS320	PS308	PS312	PS308
1966	Catalina 2 Dr. HT	PS320	PS308	PS312	PS324
1966	Catalina Conv.	PS300	PS308	PS312	PS308
1966	2+2 ALL	PS304	PS308	PS324	PS324
1966	Star Chief, Bonneville 2 Dr. HT	PS328	PS308	PS312	PS324
1966	Bonneville Conv.	PS300	PS308	PS304	PS324
1966	Grand Prix	PS300	PS308	PS312	PS308
1967	Catalina 2 Dr.	PS300	PS308	PS312	PS324
1967	Catalina 2 Dr. HT	PS320	PS308	PS312	PS324
1967	Catalina Conv.	PS320	PS308	PS312	PS324

1967	Executive & Bonneville 2 Dr. HT	PS300	PS308	PS312	PS324
1967	Bonneville Conv.	PS300	PS308	PS304	PS324
1967	Grand Prix	PS320	PS324	PS312	PS324
1968	Catalina 2 Dr.	PS328	PS308	PS304	PS324
1968	ALL exc. Catalina 2 Dr.	PS328	PS308	PS332	PS324
1969	ALL exc. Bonneville & GP	PS312	PS308	PS332	PS324
1968	Bonneville HT & Conv.	PS312	PS308		PS324
1969-71	Grand Prix		PS308		PS336
1970	ALL exc. Grand Prix	PS312	PS308	PS332	PS324
1971	ALL exc. Grand Prix	PS316	PS308		PS344
1972	Catalina Conv.		PS348		PS348
1972	Grand Prix		PS348	PS336	
1973	ALL exc. GP	PS316	PS340	PS344	PS340
1974	ALL exc. GP	PS344	PS340	PS346	PS334
1975/76	ALL exc. GP	PS348	PS340	PS348	PS334
1973-77	Grand Prix	PS342	PS308	PS338	PS324

FRONT SPRINGS

PS300	Front Springs (AP).....	\$109.00/pr.
PS304	Front Springs (AP).....	99.00/pr.
PS308	Front Springs (AP).....	109.00/pr.
PS312	Front Springs (AP).....	110.00/pr.
PS316	Front Springs (AP).....	135.00/pr.
PS320	Front Springs (AP).....	113.50/pr.
PS324	Front Springs (AP).....	109.00/pr.
PS328	Front Springs (AP).....	96.50/pr.
PS332	Front Springs (AP).....	124.00/pr.
PS334	Front Springs (AP).....	119.00/pr.
PS336	Front Springs (AP).....	111.00/pr.
PS338	Front Springs (AP).....	119.00/pr.
PS340	Front Springs (AP).....	107.50/pr.
PS342	Front Springs (AP).....	93.50/pr.
PS344	Front Springs (AP).....	119.00/pr.
PS346	Front Springs (AP).....	119.00/pr.
PS348	Front Springs (AP).....	159.00/pr.

Please add \$7.00 shipping for front springs.

REAR SPRINGS

PS350	Rear Springs (AP).....	79.00/pr.
PS353	Rear Springs (AP).....	150.00/pr.
PS355	Rear Springs (AP).....	110.00/pr.



REAR COIL SPRINGS

YEAR	MODEL & BODY STYLE	w/o AC		w/AC	
		REG	HD	REG	HD
1961-64	ALL	PS370	PS350	PS370	PS350
1965-66	ALL		PS353		PS353
1967-69	Catalina 2 Dr. HT	PS355		PS355	
1967-68	Catalina Conv.	PS355	PS360	PS355	PS360
1967-68	Bonneville, Executive-ALL Models	PS365	PS360	PS365	PS360
1967	Grand Prix	PS370	PS360	PS370	PS360
1968	Grand Prix	PS355	PS375	PS355	PS375
1969	Catalina Conv.	PS370		PS370	
1969	Bonneville and Executive, 2 Dr. HT	PS365		PS365	
1969	Bonneville and Executive, Conv.	PS380		PS380	
1969-72	Grand Prix.	PS385		PS385	
1970	Catalina ALL 2 Dr.	PS370		PS370	
1970	Bonneville and Executive, ALL 2 Dr.	PS365		PS365	
1971	Catalina , ALL	PS390		PS390	
1971-72	Bonneville & Grandville, Conv.	PS395		PS395	
1971-72	Bonneville & Grandville, 2 Dr. HT	PS390		PS390	
1972	Catalina 2 Dr. HT	PS395		PS390	
1972	Catalina Conv.	PS395		PS395	
1973	ALL exc. Grand Prix	PS395		PS395	
1974/76	ALL exc. Grand Prix	PS397	PS393	PS397	PS393
1973/77	Grand Prix	PS370	PS380	PS370	PS380

PS360	Rear Springs (AP).....	\$ 99.00/pr.
PS365	Rear Springs (AP).....	110.00/pr.
PS370	Rear Springs (AP).....	99.00/pr.
PS375	Rear Springs (AP).....	119.00/pr.
PS380	Rear Springs (AP).....	91.00/pr.
PS385	Rear Springs (AP).....	89.00/pr.
PS390	Rear Springs (AP).....	74.00/pr.
PS393	Rear Springs (AP).....	99.00/pr.
PS395	Rear Springs (AP).....	99.00/pr.
PS397	Rear Springs (AP).....	119.00/pr.

Please add \$6.00 shipping for rear springs.

SPRING INSULATORS



PS399

PS398T 1958 Rear Spring Insulators (RE) \$ 28.00/pr.


PS399 1961-64 & 1967-77

Rear Spring Insulators (GM) 5.50/pr.

PS399B 1965-66 Rear Spring Insulators (RE) 18.00/pr.

PS398T-PS399B are the insulators that mount between the top of the spring and the frame.

REAR LEAF SPRINGS



PS399J 1955-57 Replacement Rear Leaf Springs (AP) 349.00/pr.

These new replacement springs will rejuvenate your sagging rear suspension.

Please add \$18.00/pr. shipping for PS399J.

BODY MOUNTS & HARDWARE

We've been able to reproduce practically all the body mounts for the 1955 and newer full-size Pontiacs. Old, cracked, and worn mounts always detract from a restoration. We recommend new mounts not only for restorations now underway but also for those that have been completed using the old mounts. (Several people have jacked one side and then the other off the frame and slid in new mounts.)

1955-'60 BODY MOUNTS & HARDWARE



PS401

PS401 1955-57 Body Mount Assembly - HT (RE) 8.00/asm.

Note 1: Each assembly consists of one rubber and steel upper body mount and one rubber lower body mount. Square mount measures 2 1/16" x 2 1/16" x 1/2" thick.

Note 2: These hardtop mounts are supplied with a thin sheet metal spacer designated by original GM part numbers. (Several of our customers' cars do not have this spacer. If your car was assembled without shims, simply remove from our mounts and discard.)

PS402K 1958 Body Mount Assembly - HT (RE) \$ 8.00/asm.

Each assembly consists of one rubber and steel upper body mount and one rubber lower body mount. Square mount measures 2 1/16" x 2 1/16" x 1/2" thick.

PS403K 1959 Body Mount Assembly - HT (RE) 8.00/asm.

PS404 1960 Body Mount Assembly - HT (RE) Inquire



PS405K

PS405K 1955-60 Body Mount Assembly - CVT (RE) ... 5.00/asm.

Each assembly consists of one flat rubber square and one flat rubber round body mount. Square mount measures 1 3/4" x 2 1/4" x 5/16" thick.

Note: We have found some 55-60 convertibles use a square mount with a steel sleeve - measuring about 1/2" in thickness. Please use PS401 if you have this style mount.



PS407


PS407 1955-60 Body Mount Hardware Assembly - HT and CVT (AP) 1.50/asm.

Each assembly consists of one grade five bolt and one special body mount washer.

1961-72 FULL-SIZE BODY MOUNTS & HARDWARE




1961-72 full-size Pontiacs (except 1969-72 GP's) used several different body mounts in various combinations. With so many variations, we are offering our mounts as individual assemblies in order for each customer to select the correct combination of mounts for his car. Use the following dimensions to identify the mounts for your application.



PS410 Body Mount Assembly, Upper & Lower - FS (RE)\$ 9.00/asm.

Use PS420 body mount hardware with this assembly.


Note: A few original mount assemblies we received had a small thin lower mount (1 5/8" O.D.). In all cases we will be supplying the large stronger, more common mount illustrated above.



PS411 Body Mount Assembly, Upper & Lower - FS (RE) 9.00/asm.

Use PS420 body mount hardware with this assembly. The upper mount in this assembly is similar to PS410. However, it is distinguished by the much larger inside hole diameter and straight tube hole design.


Note: A few original mount assemblies we received had a small thin lower mount (1 5/8" O.D.). In all cases we will be supplying the large stronger, more common mount illustrated above.



PS412 Body Mount Assembly, Upper & Lower - FS (RE) 9.00/asm.

Use PS420 body mount hardware with this assembly.

Note: A few original mount assemblies we received had a small thin lower mount (1 5/8" O.D.). In all cases we will be supplying the large stronger, more common mount illustrated above.




PS413 Body Mount Assembly, Upper & Lower - FS (RE)\$ 9.00/asm.

Use PS421 body mount hardware with this assembly.

Note: This mount seems to have two applications. In some cases it functions as a true body mount using a lower mount and bolt. In other applications it has no bolt and is simply a rider or dummy (see PS414).


PS414 Body Mount - Upper Only - FS (RE). 6.00/ea.

Note: Refer to upper mount diagram for PS413.




PS415 Upper Body Mount - FS (RE) 4.00/ea.

This mount is rubber only with no hole for a bolt. It is used simply as a rider or dummy.



- PS416** Body Mount Assembly, Upper & Lower - FS (RE)\$ 8.00/asm.
Use PS422 body mount hardware with this assembly.



Upper-
Rubber w/Steel

Lower-Rubber

PS417

- PS417** Body Mount Assembly, Upper & Lower - FS (RE) 8.00/asm.
Use PS422 body mount hardware with this assembly.



PS420

- PS420** Body Mount Hardware Assembly - FS (AP)..... 1.50/asm.
This assembly consists of one 7/16" x 2" bolt and one special 1 7/8" body mount washer.
- PS421** Body Mount Hardware Assembly - FS (AP)..... 1.50/asm.
This assembly consists of one 7/16" x 2" bolt and one special 1 5/8" body mount washer.
- PS422** Body Mount Hardware Assembly - FS (AP)..... 1.50/asm.
This assembly consists of one 7/16" x 3" bolt and one special body mount washer.

1969-77 GP BODY MOUNT AND HARDWARE KITS

- PS425** 1969-72 Body Mount Set - GP (RE) 83.00/set
This set includes all upper and lower body mounts necessary for one car. See PS441 for core support mounting kit.
- PS426** 1969-72 Body Mount Hardware Kit - GP (AP) 17.00/kit
This kit includes the correct 2" x .525" x .125" washers plus enough grade 5 bolts to install a full set of body mounts.




PS430

- PS430** 1973-77 Body Mount Set - GP (GM).....\$ 235.00/set
This set includes all upper and lower body mounts necessary for one car.
- PS431** 1973-77 Body Mount Bolt Kit (AP)..... 8.00/kit
This kit contains enough bolts to install PS430.


CORE SUPPORT MOUNTING KITS

Note: The following core support kits contain all necessary mounts, bolts, and washers for your restoration.



PS435

- PS435** 1961-64 Core Support Mounting Kit - FS (RE) 20.00/kit
- PS435K** 1961-64 Core Support Shims - FS (RE) 1.50/ea.
These are the special square shims used to adjust the core support with respect to the frame.
- PS437** 1965 Core Support Mounting Kit - FS (RE) 20.00/kit
This is a one year only kit. Although the upper mounts look similar to several round body mounts now available, dimensions between the two are not compatible.
- PS437K** 1965 Core Support Shims - FS (RE)75/ea.
These are the round shims used to adjust the core support with respect to the frame.
- PS439** 1966-72 Core Support Kit - FS (RE)..... 12.00/kit



PS441

- PS441** 1969-72 Core Support Kit - GP (RE) 12.00/kit
- PS443** 1973-74 Core Support Kit - GP (RE) Inquire
- PS445** 1975-77 Core Support Kit - GP (RE) Inquire

PAINT & UNDERCOATING



PS472

PS471 Chassis Black Paint (1 Qt.) (AP)..... Disc.

Use chassis black paint on frame, rear end, control arms, etc. This charcoal tinted semi-gloss is supplied to us by GM's source.

PS472 3M Rubberized Undercoating, 20 Oz. Aerosol Can (AP)..... \$ 11.00/ea.

The best aerosol undercoating we've found. Excellent for factory undercoated seams (such as inner and outer rear wheelwell seams, transmission hump seams, etc.).

STEERING BOX & BOLTS



PS510

PS510 1969-72 Quick Ratio Steering Box - GP (RP) . 179.00/ea.

This remanufactured steering box is lock to lock 3 turns vs. the originals at 4 turns. Some 1969-72's were equipped with quick ratio boxes originally.

Note: Please add \$7.00 additional shipping.



PS515 & PS516

PS515 1969-77 Steering Box Bolt (GM) 3.00/ea.

PS516 1964-77 Steering Box Bolt Washer (GM-RP) . \$ 2.00/ea.

This washer is a GM replacement. Dimensions are correct, the shape is octagonal instead of round like the originals.

POWER STEERING HOSE



PS530 1964-70 Power Steering Hose (All exc. '69-70 GP) (AP)..... 44.00/ea.

PS532 1969-70 Power Steering Hose - GP (AP)..... 32.00/ea.

PS534 1971-72 Power Steering Hose - ALL (AP)..... 30.00/ea.

PS536 1973-76 Power Steering Hose - ALL (AP)..... 30.00/ea.

The afterproduct hoses do not have the same configuration as originals.

STEERING COUPLERS



PS540 1967-77 Steering Column Coupling, w/ Standard Steering (GM)..... 49.00/ea.

PS541 1967-77 Steering Column Coupling, w/ Power Steering (GM)..... 69.00/ea.

These are the flange assembly couplings that connect the steering box to the steering column. There are many afterproduct versions on the market that are less expensive 2-piece designs. We feel that with such a product, safety is a major concern. Therefore, factory GM couplings are the only replacement we handle.



Visit us on the
World Wide Web

<http://www.amesperf.com>
email: customer.service@amesperf.com

SECTION SIXTEEN - WHEELS

RALLY II CENTER COMPONENTS



PT101K




PT103K

Now that GM has started discontinuing Rally II center cap components, we have undertaken our own reproduction caps.


These new center caps have been designed to overcome problems associated with the original Rally II retaining clips. The original clips inevitably scratch the freshly painted wheel surface and bend upon installation, many times resulting in a loose fit. This poor fit aids the thieves who constantly steal these caps (even at shows). Each year more customers are paying additional money for afterproduct locking devices to save their investment.

Our new reproduction incorporates a simple yet effective locking arrangement. Now centers can be bolted firmly in place making loose fit, scratching and theft virtually impossible.



PT101K

PT101K	1967-Early 1970	Black PMD Rally II Complete Caps (APE).....	\$ 25.00/ea.
PT101L	1967-Early 1970	Black PMD Rally II Complete Caps (Set of 4) (APE).....	95.00/set
PT102K	Late 1970-72	Red PMD Rally II Complete Caps (APE).....	25.00/ea.
PT102L	Late 1970-72	Red PMD Rally II Complete Caps (Set of 4) (APE).....	95.00/set
PT103K	1967-Early 1970	Black PMD Rally II Lucite Centers (APE).....	12.00/ea.
PT104K	Late 1970-72	Red PMD Rally II Lucite Centers (APE).....	12.00/ea.



For those requiring original equipment caps, we will continue to offer these products until discontinued by GM.

Please inquire concerning these products.



PT106

PT106	1973-75 Rally II Centers (GM).....	\$ 19.00/ea.
PT106A	1976-77 Rally II Centers (GM).....	Disc.

WHEELCOVER LUCITE CENTERS



PT106BH

PT106BH	1967-70 Wheelcover Lucite Center (Black)	
	- PMD (27/16" dia.) (RE)	19.00/ea.
PT106BL	1967-70 Wheelcover Lucite Center (Black)	
	- PMD (23/4" dia.) (RE)	19.00/ea.
PT106BN	1967-70 Wheelcover Lucite Center (Black)	
	- Power Disc Brake (27/16" dia.) (RE)	19.00/ea.
PT106BR	1970-72 Wheelcover Lucite Center (Red)	
	- PMD (27/16" dia.) (RE)	19.00/ea.
PT106BT	1970-72 Wheelcover Lucite Center (Red)	
	- PMD (23/4" dia.) (RE)	19.00/ea.
PT106BV	1970-72 Wheelcover Lucite Center (Red)	
	- Power Disc Brake (27/16" dia.) (RE)	19.00/ea.

Note: These are Lucites only

CENTER CAP LOCKS

PT106D	1967-72 Rally II Center Cap Locks (APE)	15.00/set
These locks use the same style locking arrangement as our reproduction Rally II center caps. See diagram above PT101K.		
PT106F	1973-75 Rally II Center Cap Loc (AP).....	18.00/set
<i>Note: These work only on the early wheels that have three notches on the center hole circumference.</i>		



PT106J

PT106J 1971-76 Honeycomb Cap Loc (AP)..... \$ 18.00/set

PT106F and PT106J are used to keep your caps from falling off or being stolen. The Cap Loc™ fills a long-felt need. They work well; however, if they appear loose, bend the spring retainer on the cap for more tension.

WHEEL ORNAMENTS AND DECALS



PT108

PT107 1971 Honeycomb Wheel Ornament - GP (NOS)..... 25.00/ea.

PT108 1972-77 Honeycomb Wheel Ornament - GP (GM)..... 31.00/ea.



PT108RC

PT108RC 1951,53 Wire Wheel Lucite Center (Silver/Red) (RE)..... 79.00/ea.

PT108RE 1952 Wire Wheel Lucite Center (Gold/Red) (RE) 79.00/ea.

These lucites are also used for the grille emblem.



PT109

PT109 1963-64 Wire Wheel Hubcap Decal (RE) \$ 25.00/set

Comments: Excellent—these are anodized red.

TRIM RINGS



PT111F

PT111F 1967-71 Replacement Trim Rings for 14 x 6-inch Rally II Wheels (GM) \$ 25.00/ea.

PT111H 1967-71 Set of Four PT111F's (GM) 99.00/set

This excellent GM replacement is the same as original except that it is polished on all surfaces and has a different clip arrangement.

PT112F 1969-72 Trim Rings for 14 x 7-inch Rally II Wheels (RE)..... 25.00/ea.

PT112H 1969-72 Set of Four PT112F's (RE) 99.00/set

These new reproductions are exact and affordable.

PT113F 1969-72 Trim Rings for 14 x 7-inch Rally II Wheels (GM) 60.00/ea.

PT113H 1969-72 Set of Four PT113F's (GM) 240.00/set

PT113K 1969-72 14 x 7-inch Rally II Trim Rings (RE) .. 75.00/set

These have the same contours as original, but are 2 1/2" deep instead of 3"—an excellent low cost alternative.

Note: Original design 1973-'77 14 x 7-inch trim rings are discontinued. PT112H, PT113H, and PT113K can be used as replacements.

PT113P 1970-77 15 x 7-inch Rally II Trim Rings (AP) .. 99.00/set

These have the same shape as GM's early design. Quality is superb and highly recommended.

PT114F 1970-73 Trim Rings for 15 x 7-inch Rally II Wheels (GM) 60.00/ea.

PT114H 1970-73 Set of Four PT114F's (GM) 240.00/set

PT114K 1973-77 Trim Rings for 15 x 7-inch Rally II Wheels (GM) 60.00/ea.

PT114P 1973-77 Set of Four PT114K's (GM)..... 240.00/set


PT115F 1971-75 Trim Rings for 14 x 7-inch Honeycomb Wheels (GM) Disc.

PT115H 1971-75 Set of Four PT115F's (GM) 216.00/set

PT115K 1973-76 Trim Rings for 15 x 7-inch Honeycomb Wheels (GM) 56.00/ea.

PT115P 1973-76 Set of Four PT115K's (GM)..... 240.00/set

NO ADDITIONAL DISCOUNTS AVAILABLE ON TRIM RING SETS PT111H—PT115P.



SPINNER HUBCAPS



PT130

PT130 1957 Bonneville Spinner Hubcaps (RE).... \$60.00/ea.

These are a high quality reproduction. With good used caps becoming very expensive these new reproductions are an excellent value.

8-LUG WHEEL CENTER CAPS & TRIM RINGS



PT140

PT147

PT140 1960-62 8-Lug Wheel Center Cap (RE)..... 45.00/ea.

PT140A 1960-62 8-Lug Wheel Center Cap Set (RE) 175.00/set

Now available, these caps have been well-received.

Comments: Fit is excellent.

PT147 1960-62 Trim Rings for Aluminum 8-Lug Wheel (RE)..... 25.00/ea.

PT148 1960-62 Trim Rings for Aluminum 8-Lug Wheel (RE)..... 99.00/set of 4




PT149

PT149 1963-68 Trim Rings for Aluminum 8-Lug Wheel (RE)..... 60.00/ea.


PT150 1963-68 Trim Rings for Aluminum 8-Lug Wheels (RE).....\$ 225.00/set of 4

This difficult reproduction was completed in the spring of 1990. Hundreds have been sold to satisfied customers. Shape, fit, and luster are excellent.

STAINLESS STEEL LUG NUTS



PT152R



PT153R

PT152 1960-62 Wheel Lug Nut Set (Aluminum 8-Lug Wheels) (16 LH Thread, 16 RH Thread - 1/2") S.S. (RE) 139.00/set

PT152L 1960-62 Wheel Lug Nut (Aluminum 8-Lug Wheel), LH - 1/2" S.S. (RE) 5.00/ea.

PT152R 1960-62 Wheel Lug Nut (Aluminum 8-Lug Wheel), RH - 1/2" S.S. (RE)..... 5.00/ea.

PT153 1963 Wheel Lug Nut Set (Aluminum 8-Lug Wheels) (16 LH Thread, 16 RH Thread - 1/2") S.S. (RE) 139.00/set

PT153L 1963 Wheel Lug Nut (Aluminum 8-Lug Wheel), LH - 1/2" S.S. (RE) 5.00/ea.

PT153R 1963-68 Wheel Lug Nut (Aluminum 8-Lug Wheel), RH - 1/2" S.S. (RE)..... 5.00/ea.

PT154 1964-68 Wheel Lug Nut (Aluminum 8-Lug Wheels) (32 RH Thread - 1/2") S.S. (RE) 139.00/set

PT152 - PT154 are all highly polished stainless steel.

RALLY II LUG NUTS



PT156



PT158

PT156 1969-70 Rally II Lug Nuts (Black Center 7/16" Thread) - GP (RE)..... 49.00/set

PT156A 1969-70 Rally II Lug Nuts (Black Center 7/16" Thread) - GP (RE)..... 2.50/ea.

PT157 1969-70 Rally II Lug Nuts (Red Center 7/16" Thread) - GP (RE)..... 49.00/set

PT157A 1969-70 Rally II Lug Nuts (Red Center 7/16" Thread) - GP (RE)..... 2.50/ea.

An exact reproduction using GM's blueprint with correct steel, correct dimensions, and correct threads. We also had these nuts thread-tested by the watch dogs of the afterproduct market, SEMA and FSI.

Comments: Finest on the market.

- PT158** 1971-77 Grand Prix Lug Nuts w/Rally II or Honeycomb Wheels, 7/16" Thread (GM)..... \$ 1.50/ea.
- PT158A** 1971-77 Grand Prix Lug Nut Set w/Rally II or Honeycomb Wheels, 7/16" Thread (GM)..... 27.00/set
- PT159** 1971-77 Full-Size Lug Nuts w/Rally II Wheels - 1/2" Thread (GM)..... 1.50/ea.
- PT159A** 1971-77 Full-Size Lug Nut Set w/Rally II Wheels - 1/2" Thread (GM)..... 27.00/set

PT158-PT159A stainless steel capped nuts can also be used on earlier cars with Rally II wheels.

- PT160** 1971-77 Grand Prix Lug Nuts w/Rally II or Honeycomb Wheels - 7/16" Thread (Chrome) (RE)..... 45.00/set
- PT160A** 1971-77 Grand Prix Lug Nuts w/Rally II or Honeycomb Wheels - 7/16" Thread (Chrome) (RE)..... 2.50/ea.

PT160 and PT160A are excellent alternatives to the stainless capped nuts. These chromed versions have the same shape but not the problems associated with a capped nut.



- PT162** 1977 Aluminum Wheel Lug Nuts - 7/16" Thread (AP) 4.00/ea.
- PT162A** 1977 Aluminum Wheel Lug Nut Set - 7/16" Thread (AP) 75.00/set

Finally a less expensive alternative is available for the aluminum wheel lug nut used with both snowflake and turbo wheels. GM's pricing has risen dramatically on this nut making PT162 economically desirable.

Note: This nut differs from GM in shape slightly (referring to the photos above notice the difference in flange angle). Also, the surface finish is not as smooth as GM's.

- PT163** 1977 Aluminum Wheel Lug Nut - 7/16" Thread (GM) 10.00/ea.
- PT163A** 1977 Aluminum Wheel Lug Nut Set - 7/16" Thread (GM) 197.00/set



PT164S

- PT164L** 1960-63 Steel Wheel Standard Lug Nut - LH thread 1/2" (RP) 1.50/ea.
- PT164R** 1960-77 Steel Wheel Standard Lug Nut - FS RH thread 1/2" (RP) 1.50/ea.
- PT164S** 1969-77 Steel Wheel Standard Lug Nut - GP RH thread 7/16" (RP) 1.00/ea.



WHEEL STUDS



- PT168J** 1960-70 Front Wheel Stud - Drum exc. 8-Lug - FS - RH thread 1/2" (RP) \$ 1.50/ea.
- PT168L** 1965-68 Front Wheel Stud - 8-Lug Drum - FS - RH thread 1/2" (RP) 1.50/ea.
- PT168N** 1969-70 Front Wheel Stud - Disc -FS - RH thread 1/2" (RP) 1.50/ea.
- PT168P** 1969-70 Front Wheel Stud - Drum - GP 7/16" (RP)..... 1.50/ea.
- PT168R** 1969-72 Front Wheel Stud - Disc - GP 7/16" (RP)..... 1.50/ea.
- PT168T** 1971-77 Front Wheel Stud - Disc - FS 1/2" (RP) 1.50/ea.
- PT168W** 1973-77 Front Wheel Stud - Disc - GP 7/16" (RP)..... 1.50/ea.
- PT169C** 1960-70 Rear Wheel Stud - FS - RH thread 1/2" (RP) 1.50/ea.
- PT169E** 1969-77 Rear Wheel Stud - GP 7/16" (RP)..... 1.50/ea.
- PT169G** 1971-77 Rear Wheel Stud - FS 1/2" (RP)..... 1.50/ea.



PT170

- PT170** 1960-68 8-Lug Hold-Down Plate (RE) 30.00/ea.

Note: This plate is stamped like originals. It is made from the same thickness stock, has the correct crimped notches, and is stamped to have the correct concave contour. The plate was used not only to anchor the eight-lug spare in the trunk, but also to hold the rim securely when mounting and dismounting the tire.

Comments: Excellent—beware of less expensive inferior products on the market. All the reproductions we've seen are flame cut from 3/16" or 1/4" flat stock. They exhibit none of the original crimped or contoured surfaces.

PAINT



- PT295** 1960-63 8-Lug Aluminum Color Drum Paint, 12 oz. Aerosol Can (AP)..... 7.50/ea.

There is controversy on whether these early drums were painted or left natural. Many people feel their original drums were painted, so we've decided to supply this bare aluminum color paint.

PT297	1964-68 8-Lug Black Wheel Paint (Semi-Gloss), 12 oz. Aerosol Can (AP).....	\$ 7.50/ea.
PT297A	1964-68 8-Lug Black Wheel Paint (Semi-Gloss) Lacquer, 1 Pt. (AP).....	Disc.
PT301	Rally I and Rally II Silver Wheel Paint, 12 oz. Aerosol Can (AP).....	8.00/ea.
PT303A	Rally I and Rally II Silver Wheel Paint Lacquer, 1 Pt. (AP)	Disc.
PT305	Rally II Charcoal Wheel Paint, 5 oz. Aerosol Can (AP)	5.00/ea.
PT307A	Rally II Charcoal Wheel Paint Lacquer, 1 Pt. (AP).....	Disc.

For years, controversy has circulated concerning the Rally II charcoal paints available from various vendors.

In an effort to resolve these questions, we have compared an NOS '71 spare wheel and tire with several spares from low mileage originals. Using these for a color match we now have our own mix (PT307A).

Comments: Absolutely the best we've seen.



PT308J	Rally II and Honeycomb Gray Wheel Paint (Enamel), Aerosol Can (AP).....	6.00/ea.
---------------	---	----------

PT308J paint is a mix of the original gray used on the back of Rally II and Honeycomb wheels. It is also used between the beads of the inner rim.

PT309	1967-77 14" Rally II Mask Kit (5 Wheels) (RE)	8.00/kit
PT311	1969-77 15" Rally II Mask Kit (5 Wheels) (RE)	8.00/kit

The fastest, most sensible way to paint Rally II wheels. Simply sandblast, prime and paint wheels silver. Apply mask kit, tape off perimeter, and paint the center charcoal.

'69-77 G/P RALLY II WHEELS




PT401	14 x 6" Pre-Painted Rally II Wheel (RE).....	\$ 95.00/ea.
PT402	14 x 7" Pre-Painted Rally II Wheel (RE).....	95.00/ea.
PT403	15 x 7" Pre-Painted Rally II Wheel (RE).....	98.00/ea.

New Rally II wheels have just been reproduced. Stamped as original, these powder coated wheels have been safety tested and approved. As with all factory wheels, these reproductions have some degree of irregularities in their stampings.

Please add \$7.00 shipping per wheel.

RALLY II WHEEL SETS



Between 1969 and 1977, many Rally II wheel combinations were available from GM. To help meet your specific needs, create your own Rally II wheel sets by choosing from the various wheels (PT401 - PT403), trim rings (PT111F - PT114P), lug nuts (PT156 - PT160A), and center caps (PT101K - PT106A).

There will be a 15% discount from the retail price of the components that make up the wheel set.

With the 15% discount and the choices available, Rally II wheel sets start as low as \$489.00.

No additional discounts available on wheel sets.

Please add \$32.00 shipping for complete wheel sets.

SECTION SEVENTEEN - MISCELLANEOUS

CAR COVERS



PV101	1955-56	Flannel-Lined Car Cover w/Storage Bag	\$195.00/ea.
PV103	1957	Flannel-Lined Car Cover w/Storage Bag	195.00/ea.
PV105	1958	Flannel-Lined Car Cover w/Storage Bag	Inquire
PV107	1959-60	Flannel-Lined Car Cover w/Storage Bag	Inquire
PV109	1961-63	Flannel-Lined Car Cover w/Storage Bag	195.00/ea.
PV111	1964-70	Flannel-Lined Car Cover w/Storage Bag - Catalina and '64-'68 GP	195.00/ea.
PV112	1964-76	Flannel-Lined Car Cover w/Storage Bag - Bonneville.....	195.00/ea.
PV113	1971-76	Flannel-Lined Car Cover w/Storage Bag - Catalina.....	195.00/ea.
PV115	1969-72	Flannel-Lined Car Cover w/Storage Bag - GP	195.00/ea.
PV115A	1973-77	Flannel-Lined Car Cover w/Storage Bag - GP	195.00/ea.
PV120	All Years	Anti-Theft Steel Cable w/Lock	10.00/ea.

Our new line of car covers offers the ultimate protection for your Pontiac's finish. Pre-shrunk 100% cotton outer with flannel lining protects from dust, scratches and dents while allowing moisture to escape. Of all the car covers we've

seen to date, these flannel-lined covers far exceed the quality of unlined cotton covers.

Note: These covers are recommended for indoor use only. At the time of catalog printing several patterns for the above years have not been finalized. Please call to see if your year and body style are available.

Please add \$7.00 shipping for car covers.

PV125	1964-70	Technalon Car Cover - Catalina and '64-'68 GP	\$225.00/ea.
PV125A	1964-76	Technalon Car Cover - Bonneville ..	225.00/ea.
PV126	1971-76	Technalon Car Cover - Catalina	225.00/ea.
PV127	1969-72	Technalon Car Cover - GP	225.00/ea.
PV127A	1973-77	Technalon Car Cover - GP	225.00/ea.

We do not recommend outdoor storage of vehicles; however, when it is necessary, Technalon covers will protect your Pontiac's finish from the elements. They are made from the waterproof "Evolution 4" material which maintains complete breathability. Being one of the thickest covers available, it protects against scratches and minor dents as well.

Please add \$5.00 shipping for car PV125 - PV127A covers.


CAR CARE COMPONENTS



PV130

PV130	104+ Octane Boost, 12 Oz. Bottle	8.00/ea.
--------------	--	----------

This product gets rid of low octane knocking and causes no unwanted side effects.



DON'T GET TRAPPED!

Don't get trapped by high prices in the Pontiac industry. Some suppliers continue to charge unrealistic prices for their products while we here at Ames Performance have tried to keep the lid on price increases.

For ordering or price quotations, please call (800) 421-2637.
For questions or ordering, call (603) 876-3345
(603) 876-4656
(603) 876-4751



PV131



PV133

PV131 Mother's Mag and Aluminum Wheel Polish, 5 Oz. Jar (AP)..... \$ 6.50/ea.

PV133 Mother's 100% Carnauba California Gold Wax, 12 Oz. Jar (AP)..... 19.50/ea.

Mother's products have been the favorite of street machine and custom car show fanatics for years.

AFTERMARKET DECALS



PV173 Harry the A.P.E. Decal (AP) 2.00/ea.

Harry's ego rears its ugly (and hairy) head with his own decal. Also perfect for your 1/4 window or perhaps the windshield of your buddy's Mopar. Photo shown is 2/3 actual size.



PV176

PV176 "The Heartbeat Stops Here" Decal (AP) 5.00/ea.

Vinyl decal is self-adhesive, measures 2 1/2" x 6 1/2" and is red and silver.



PV177

PV177 "We Build Excitement" Decal 3" x 6" (AP)

Disc.

PV177A "We Build Excitement" Decal 6" x 12" (AP)

Disc.

These decals when adhered will leave just the outlined die-cut letters. Letters are red and white.



PV178

PV178 8" Pontiac Parts Decal (AP) \$ 4.00/ea.



PV178A

PV178A 10" Authorized Pontiac Indian Head Service Decal (AP)..... 6.00/ea.

PLEASE DON'T TOUCH



PV180A

PV180 "Please Don't Touch" Window Tag (White) (AP).....

Disc.

PV180A "Please Don't Touch" Window Tag (Black) (AP).....

6.00/pr.

These 5" x 5" plastic tags can be stuck to any window with the small suction cups.

FENDER COVERS

PV180E
PV180G

Harry Fender Cover 15.00/ea.
Ames Performance Fender Cover.... 15.00/ea.



PV180J

PV180J "We Build Excitement" Fender Cover (AP) 18.00/ea.



PV180K

PV180K "GRRRRR" Fender Cover (AP).....\$ 19.00/ea.



PV180L

PV180L "Heartbeat Stops Here" Fender Cover (AP) 19.00/ea.

With this fender cover you will be able to protect your finely restored Pontiac and irritate a Chevy owner all at the same time.



PV180P

PV180P "Pontiac Racing" Fender Cover (AP) 18.00/ea.



PV180R

PV180R Plain Fender Cover (AP)..... 10.00/ea.

HATS, PATCHES, AND KEY CHAINS



PV202

PV202 Solid Brass Pontiac Key Chain (AP) 7.50/ea.



PV202A

PV202A Pontiac Arrowhead Door Lock Scratch

Guards (AP)..... \$ 8.00/pr.

These peel and stick nylon guards save wear and tear on your car's finish.



PV204

PV204 "We Build Excitement" Hats—One size fits all—Colors Available: Black, blue or white (AP).....

Disc.

Please specify color when ordering.



PV205

PV205 Hat w/Pontiac Emblem (AP) Inquire



PV206

PV206 Hat w/Pontiac Indian Head Inquire



PV207

PV207 Hat w/Grand Prix Logo..... Inquire



PV208

PV208 Ames Performance Hats - One size fits all—Colors Available: Black, red, or white (AP)..... 6.50/ea.



PV213

PV213 20" by 24" Scene of the Sixties Full-Color Poster—depicts stop light scene featuring a '64 GTO, a '67 GTO, a '67 Shelby GT 350 and a '63 Corvette Coupe (our own product).. 5.00/ea.



PV215

- PV215** 20" x 24" Full-Color "Pontiac Power" Poster (our own product) \$ 5.00/ea.



VIDEOS



- PV217** 1997 "Ames Performance Pontiac Nationals" Video 25.00/ea.
 Note: Special Deal!! With orders over \$100.00 .. 15.00/ea.
PV217A 1998 "Ames Performance Pontiac Nationals" Video 25.00/ea.
 Note: Special Deal!! With orders over \$100.00 .. 15.00/ea.

These videos cover the events held in August at Norwalk Raceway.

T-SHIRTS



PV220

- PV220** Swiss Cheese Catalina T-shirt (AP)..... 16.00/ea.
 These white t-shirts are top quality 100% preshrunk cotton and are available in S, M, L, XL, and XXL. Please specify size when ordering.

Note: Please add \$2.00 for XXL.



PV222

- PV222** Factory Muscle T-shirt (AP)..... \$ 16.00/ea.
 These top quality 100% preshrunk cotton t-shirts are available in either white or denim blue. Please specify color and size when ordering. S, M, L, XL, and XXL.

Note: Please add \$2.00 for XXL.



PV226

- PV226** Ames Performance T-Shirt - Silkscreened w/Pontiac Arrowhead on Front & Ames Logo on Back (AP)..... 11.00/ea.
 These top quality t-shirts are now available in red or black. Please specify color and size when ordering. S, M, L, XL, XXL.

Note: Please add 2.00 for XXL.



PV228

- PV228** Harry the A.P.E. T-Shirt - Silkscreened with Ames Logo on Front & Harry on Back (AP) 11.00/ea.
 These top quality t-shirts are now available in white or ash (light gray). Please specify color and size when ordering. S, M, L, XL, XXL.

Note: Please add 2.00 for XXL.



PV230

PV230 "We Build Excitement" T-Shirt (Silkscreened) (AP)

Inquire

These black or white 100% cotton T-shirts come with a 2-color silkscreened print on the front. Please specify color and size when ordering S, M, L, XL, XXL.

Note: Please add \$2.00 for XXL.



PV232 "We Build Excitement" Sweatshirt (Silkscreened) (AP)

Inquire

These heavyweight 50/50 cotton polyester blend sweatshirts are also available in black or white. They utilize the same print as PV230. Please specify color and size when ordering S, M, L, XL, XXL.

Note: Please add \$3.00 for XXL.



PV234 "We Build Excitement" Satin Jacket (AP)

Inquire

Available in blue, black, and red, these 100% nylon jackets have cotton flannel linings and knit cuffs, collars, and waistbands. Embroi-

dered front and back with "We Build Excitement" logo. Please specify color and size when ordering S, M, L, XL, XXL.

Note: Please add \$4.50 for XXL.


LICENSE PLATES



PV301 Gr-rrr! License Plate—Orange w/Black Letters (AP) \$ 4.00/ea.

PV301A "Ram Air" Gr-rrr! License Plate—Orange w/Black Letters—Stamped w/Six 4" Louvers (AP) 10.00/ea.

PV302 Pontiac License Plate (AP) 4.00/ea.



PV304 "Pontiac - We Build Excitement" License Plate - White or Black (AP) 4.00/ea.

PV305 "Tin Indian" License Plate (AP) 4.00/ea.

PV306 "Pontiac Racing" License Plate (AP) 4.00/ea.

CLOCKS



PV326

PV325 Gr-rrr! License Plate Clock (AP) 16.00/ea.

PV326 Pontiac License Plate Clock (AP) 16.00/ea.

PV327 "We Build Excitement" License Plate Clock White or Black (AP) 16.00/ea.

PV328 "Tin Indian" License Plate Clock (AP) 16.00/ea.

PV329 "Pontiac Racing" License Plate Clock (AP) 16.00/ea.

These are great battery-operated clocks. Hang them in your shop, garage, den or game room.



Equipped with bold brass hands these clocks have precision quartz movements and keep excellent time.

Note: Batteries not included.

AFTER-PRODUCT ACCESSORY MATS



PV330

- PV329R** Accessory Mats w/Embroidered Indian Head (4 Pcs.) Daytona Weave (AP)\$ 115.00/set
- PV329T** Accessory Mats w/Embroidered Indian Head (4 Pcs.) Lurex Carpet (AP) 115.00/set
- PV330** Accessory Mats w/Embroidered Indian Head (4 Pcs.) 80/20 (AP) 85.00/set

These 4-piece mat sets have a rubber backing with nipples and a carpet face. These mats are available in the same colors as our carpets.

Note: These are a generic mat and do not always fit exact contours of all cars. See PA100-PA123 for exact original-style mats.

DUSTERS



PV333

- PV333** California Car Duster (AP) 19.00/ea.



PV333A

- PV333A** Mini Duster (AP) 10.00/ea.

These dusters have specially treated cotton fibers that will lift off dust without scratching painted surfaces. Their baked-in paraffin wax fibers will actually work better the dirtier they get. After years of wiping with wet towels and worrying about scratching, we now use the California Car Dusters exclusively.



PV334

- PV334** Spot Rot (AP)\$ 16.00/ea.

We've used these for years and have found them to be extremely useful in discovering body rot and filler. The manual provides instructions for use as well as locations to inspect when purchasing cars.

Note: When inspecting show car quality paint, we place a thin piece of tape over the magnet.

MUSCLECARDS™



PV335

- PV335** Musclecards™ Commemorative Collector's Edition (AP) 32.00/box

Collector cards have been a staple of the American sports scene for years. Now muscle car enthusiasts have their own trading cards available. Each card contains full color photos, specs, commentary, etc. Every box contains 288 cards and is guaranteed to contain the full set of 102 of your favorite muscle cars (including GTO, Camaro, GTX, Mustang, 442, Corvette, GS, Chevelle and more).

MUSCLECARDS II™



PV336

- PV336** Musclecards II™ Collector's Edition (AP) 35.00/box

This second series of Musclecards™ is now available. Using a new format, these cards complement the very successful first edition. Every box of Musclecards II™ contains 360 cards. There are 90 cards in a set with the added value of 6-10 "King of the Hill II" gold cards and one promo card.

ENGINE CRADLES



PV340

- PV340** Pontiac Engine Cradle (AP).....\$ 89.00/ea.
PV341 Corporate Block Engine Cradle (AP)..... 89.00/ea.
 These cradles are excellent for storing and moving your Pontiac engine blocks or complete engines. Built from square tubing they have 4 casters for maneuverability. Cradles are rated for 900 pounds and are very stable.



PV345


- PV345** Rear End Dolly (AP) 75.00/ea.
 These cradles are excellent for storing or moving rear ends. Built from square tubing they have 4 casters for maneuverability.

TRAILER STRAPS & TIE DOWNS



- PV371** 21" Axle Strap-5,000 lb. (AP) 7.00/ea.
PV373 33" Axle Strap-5,000 lb. (AP) 8.00/ea.
PV377 Adjustable Tie Back Strap-10,000 lb. (AP)..... 17.00/ea.
PV381 2" x 6' Ratchet Tie Down-10,000 lb. (AP) 25.00/ea.
PV383 2" x 8' Ratchet Tie Down-10,000 lb. (AP) 27.00/ea.
PV385 2" x 10' Ratchet Tie Down-10,000 lb. (AP) 28.00/ea.
PV387 1" x 12' Ratchet Tie Down-2,000 lb. (AP) 14.00/ea.
 All of these tie down components are made from top quality webbing.
PV389 Heavy Duty Recessed "D" Ring-5000 lb. (AP) 10.00/ea.

2 DOOR BUMPER STOP KITS



- PV401** 1955-57 Bumper Stop Kit (RE)..... \$ 18.50/kit
PV403 1958 Bumper Stop Kit (RE)..... 24.00/kit
PV405 1959-62 Bumper Stop Kit (RE)..... 25.00/kit
PV406 1963 Bumper Stop Kit (RE)..... 26.00/kit
PV407 1964 Bumper Stop Kit (RE)..... 17.50/kit
PV408 1965 Bumper Stop Kit (RE)..... 15.50/kit
PV409 1966 Bumper Stop Kit (RE)..... 18.50/kit
PV411 1967 Bumper Stop Kit (RE)..... 23.00/kit
PV413 1968 Bumper Stop Kit (RE)..... 23.00/kit
PV415 1969 Bumper Stop Kit - FS (RE) 21.00/kit
PV417 1970 Bumper Stop Kit - FS (RE) 19.00/kit
PV419 1971-76 Bumper Stop Kit - FS (RE) 15.00/kit
PV421 1969 Bumper Stop Kit - GP (RE)..... 18.00/kit
PV423 1970-72 Bumper Stop Kit - GP (RE)..... 16.00/kit

Each kit contains the correct hood to fender bumpers, hood front bumpers, glove box bumpers, door bumpers, and trunk bumpers.

Note: 4 door bumper stop kits are available. Please inquire.

LOCK SETS



DOORS AND IGNITION

- PV501** 1955-57 Ignition and Door Lock Set w/2 Original-Style Keys (Sedans) (NOS)..... 48.00/set
PV503 1955-57 Ignition and Door Lock Set w/2 Late-Style Keys (Sedans) (NOS). 43.00/set
PV505 1955-57 Ignition and Door Lock Set w/2 Original-Style Keys (2 Dr. HT and Conv.) (NOS) 48.00/set
PV507 1955-57 Ignition and Door Lock Set w/2 Late-Style Keys (2 Dr. HT and Conv.) (NOS) 43.00/set
PV509 1955-57 Ignition and Door Lock Set w/2 Original-Style Keys (4 Dr. HT) (NOS)..... 48.00/set
PV511 1955-57 Ignition and Door Lock Set w/2 Late-Style Keys (4 Dr. HT) (NOS)..... 43.00/set
PV513 1958 Ignition and Door Lock Set (Exc. Wagons) w/2 Original-Style Keys (NOS) 48.00/set
PV515 1958 Ignition and Door Lock Set (Wagons) w/2 Original-Style Keys (NOS)..... 48.00/set

PV517	1959	Ignition and Door Lock Set (ALL 2 Dr. Models) w/2 Original- Style Keys (NOS)	\$ 55.00/set
PV519	1959	Ignition and Door Lock Set (ALL 4 Dr. Models) w/2 Original- Style Keys (NOS)	75.00/set
PV521	1960	Ignition and Door Lock Set (ALL 2 Dr. Models) w/2 Original- Style Keys (NOS)	75.00/set
PV523	1960	Ignition and Door Lock Set (ALL 4 Dr. Models) w/2 Original- Style Keys (NOS)	75.00/set
PV525	1961-64	Ignition and Door Lock Set (Exc. 4 Dr. HT) w/2 Original-Style Keys (NOS)	43.00/set
PV527	1961-64	Ignition and Door Lock Set (Exc. 4 Dr. HT) w/2 Late-Style Keys (NOS)	38.00/set
PV529	1961-64	Ignition and Door Lock Set (4 Dr. HT) w/2 Original-Style Keys (NOS)	48.00/set
PV531	1961-64	Ignition and Door Lock Set (4 Dr. HT) w/2 Late-Style Keys (NOS)	43.00/set
PV533	1965	Ignition and Door Lock Set w/2 Original-Style Keys (NOS)	65.00/set
PV535	1965	Ignition and Door Lock Set w/2 Late-Style Keys (NOS)	Disc.
PV537	1966	Ignition and Door Lock Set w/2 Original-Style Keys (NOS)	Inquire
PV539	1966	Ignition and Door Lock Set w/2 Late-Style Keys (NOS)	Disc.
PV541	1967	Ignition and Door Lock Set w/2 Original-Style Keys (NOS)	Inquire
PV543	1967	Ignition and Door Lock Set w/2 Late-Style Keys (NOS)	Disc.
PV545	1968	Ignition and Door Lock Set w/2 Original-Style Keys (NOS)	36.00/set
PV547	1968	Ignition and Door Lock Set w/2 Late-Style Keys (NOS)	30.00/set
PV549	1969-70	Ignition and Door Lock Set w/2 Keys - ALL (NOS)	30.00/set
PV551	1971-73	Ignition and Door Lock Set w/2 Keys - FS (NOS)	29.00/set
PV553	1971-73	Ignition and Door Lock Set w/2 Keys - GP (NOS)	30.00/set

GLOVE BOX AND DECK LID



PV575	1955-58	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys (NOS)	49.00/set
PV577	1955-58	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys (NOS)	39.00/set
PV579	1959-60	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys (NOS)	35.00/set
PV581	1959-60	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys (NOS)	27.00/set

PV587	1961-62	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - Exc. GP (NOS)	\$ 34.00/set
PV589	1961-62	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - Exc. GP (NOS)	29.00/set
PV590	1962	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - GP (NOS)	45.00/set
PV590A	1962	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - GP (NOS)	35.00/set
PV591	1963-64	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys (NOS)	32.00/set
PV593	1963-64	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys (NOS)	28.00/set
PV595	1965	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - Exc. GP (NOS)	31.00/set
PV595A	1965	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - Exc. GP (NOS)	26.00/set
PV596	1966	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - Exc. GP (NOS)	30.00/set
PV596A	1966	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - Exc. GP (NOS)	26.00/set
PV597	1967	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - ALL exc. Bonneville & GP (NOS)	39.00/set
PV599	1967	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - ALL exc. Bonneville & GP (NOS)	25.00/set
PV601	1967	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - Bonneville & GP (NOS)	45.00/set
PV603	1967	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - Bonneville & GP (NOS)	35.00/set
PV605	1968	Glove Box and Deck Lid Lock Set w/2 Original-Style Keys (NOS)	30.00/set
PV607	1968	Glove Box and Deck Lid Lock Set w/2 Late-Style Keys (NOS)	26.00/set
PV609	1969	Glove Box and Deck Lid Lock Set w/2 Keys - FS (NOS)	39.00/set
PV609A	1970-77	Glove Box and Deck Lid Lock Set w/2 Keys -FS (NOS)	25.00/set
PV611	1969-72	Glove Box and Deck Lid Lock Set w/2 Keys -GP (NOS)	Inquire
PV609A	1973-77	Glove Box and Deck Lid Lock Set w/2 Keys -GP (NOS)	25.00/set

CONSOLE, GLOVE BOX AND DECK LID



PV625	1962	Console, Glove Box and Deck Lid Lock Set w/2 Original-Style Keys (NOS).....	\$ 52.50/set
PV627	1962	Console, Glove Box and Deck Lid Lock Set w/2 Late-Style Keys (NOS).....	48.00/set
PV629	1963-64	Console, Glove Box and Deck Lid Lock Set w/2 Original-Style Keys (NOS).....	47.00/set
PV631	1963-64	Console, Glove Box and Deck Lid Lock Set w/2 Late-Style Keys (NOS).....	43.00/set
PV633	1965	Console, Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - Exc. GP (NOS)	45.00/set
PV635	1965	Console, Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - Exc. GP (NOS)	41.50/set
PV637	1966	Console, Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - Exc. GP (NOS)	47.00/set
PV639	1966	Console, Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - Exc. GP (NOS)	42.00/set
PV641	1967	Console, Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - ALL exc. Bonneville & GP (NOS)	44.00/set
PV643	1967	Console, Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - ALL exc. Bonneville & GP (NOS)	40.00/set
PV645	1967	Console, Glove Box and Deck Lid Lock Set w/2 Original-Style Keys - Bonneville & GP (NOS)	57.00/set

PV647	1967	Console, Glove Box and Deck Lid Lock Set w/2 Late-Style Keys - Bonneville & GP (NOS)	\$ 44.00/set
PV649	1968	Console, Glove Box and Deck Lid Lock Set w/2 Original-Style Keys (NOS).....	47.00/set
PV651	1968	Console, Glove Box and Deck Lid Lock Set w/2 Late-Style Keys (NOS).....	42.00/set

CONSOLE AND DECK LID

PV675	1969-72	Console and Deck Lid Lock Set w/2 Keys - GP (NOS)	28.00/set
--------------	---------	---	-----------

Note: This set utilizes the black bezel on the console lock.

DOOR, GLOVE BOX AND DECK LID



PV691	1974-76	Door, Glove Box and Deck Lid Lock Set w/2 Keys - FS (NOS)	40.00/set
PV693	1974-77	Door, Glove Box and Deck Lid Lock Set w/2 Keys - GP (NOS)	40.00/set

SECTION EIGHTEEN - LITERATURE

PW105A



- PW105A** *Ultimate Auto Detailing*
by David H. Jacobs, Jr. \$ 20.00/ea.

This book replaces Auto Detailing for Show and Profit with more techniques and supplies. It illustrates professional techniques for making your car look like new again. Chapters include: special tools and cleaners, waxing and buffing, engine compartment detailing, interior finishing and more. 208 pages, 404 photos.

- PW107** *Car and Driver on Pontiac 1961-75* 19.00/ea.

This book contains 20 reprinted articles from *Car and Driver Magazine*. Included are road tests, technical data and comparisons of

GTO's, LeMans, Tempests, 2+2, GP, Grand Am and various Firebirds.

PW109



- PW109** *Pontiac Racer's High-Performance Handbook*
by Pete McCarthy \$ 20.00/ea.

This book is written with hands-on experience by three California drag racers. It completely explores all facets of high-performance Pontiac engines. The book covers part numbers, casting numbers, and the author's view of best blocks, heads, cams, etc. 100 pages with 82 illustrations. This book deals almost exclusively with performance Pontiac engines.

PW110



- PW110** *Pontiac Muscle Car Performance 1955-79*
by Pete McCarthy\$ 29.00/ea.

This publication is the most definitive work on Pontiac engines and drive trains ever attempted. It contains the information of PW109 plus numbers for all engine components from 1955 to 1979. Pete spent years on this project which also includes histories and documentation of the factory racecars. (224 pages).

Comments: The best.



PW112

- PW111** *Performance Tuning Pontiacs of the 60's*.....

This book contains articles from various *Hot Rod* issues pertaining to engine, transmission and suspension modifications. With 100 pages of facts and figures this softbound book is very beneficial to performance-minded enthusiasts.

- PW112** *Pontiac High-Performance Engine Design & Blueprint Assembly* by Craig Hendrickson & Kern Osterstock 20.00/ea.

This is another fine book written by drag racers Craig Hendrickson and Kern Osterstock, well-known for their original work at H-O Racing Specialties; it delves into various modifications to increase power from your Pontiac. They also outline the construction of a full competition engine for street and strip. 96 pages with 31 illustrations.



PW113



PW114

- PW113** *Pontiac Heavy-duty Parts and Specs*
by Craig Hendrickson and Kern Osterstock 10.00/ea.

Another of H-O books, this softbound publication details parts and specifications for all high-performance Pontiacs of the 60's and 70's—31 pages.

Note: Both PW112 and PW113 are highly recommended.

- PW114** *1966-67 Shop Manual* by Motorbooks..... Disc.
Contains valuable information for all '66-'76 FS cars. Covers basic tune-ups to complete engine overhauls.

PW117



PW120



- PW116** *Catalog of American Car ID Numbers 1950-59*.....\$ 20.00/ea.
PW117 *Catalog of American Car ID Numbers 1960-69*..... 20.00/ea.
PW118 *Catalog of American Car ID Numbers 1970-79*..... 20.00/ea.

These books were compiled by the staff at *Cars & Parts Magazine*. They contain the keys to de-scrambling VIN codes, cowl tags, engine numbers, trim codes, and paint codes.

- PW120** *Fifties Flashback: The American Car*
by Dennis Adler 30.00/ea.



This hard cover book captures all the cars of the Fifties from sports cars to luxury cruisers. Adler has completed a history that details the postwar auto industry. Spectacular photography. 160 pages with 155 photographs.

PW122



PW123



- PW122** *Illustrated Pontiac Buyer's Guide*
by John Gunnell..... Disc.

Covers the whole line of Grand Prix, Catalinas, and other sedans. A must for Pontiac Lovers. 192 pages, 250 illustrations.

- PW123** *Standard Catalog of Pontiac 1926-1995* 20.00/ea.



Offers year by year overview of all Pontiac models. Lists options and some production numbers. 304 pages, B & W photographs.

PW124



PW125



- PW124** *Pontiac 1946-78: The Classic Postwar Years*.. 15.00/ea.

Discussion of Pontiacs with information about people involved at General Motors. Technical information not completely accurate in all cases. 203 pages, B & W photographs.

- PW125** 1962 *Pontiac High Performance and Super-Duty Specification and Parts Manual* (Reprint)..... 9.00/ea.

PW126



PW131



- PW126** 1963 *Pontiac Special Equipment Catalog and Reference Guide (Reprint)*..... \$ 9.00/ea.
PW131 *How to Restore Metal Auto Trim* by Jeff Lilly.. 15.00/ea.



Excellent book for showing how to remove and fix stainless trim. Everything from tools to cleaning, repairing, welding, straightening and buffing. 96 pages.

PW132



PW133



- PW132** *Engine Detailing* by David H. Jacobs, Jr. 18.00/ea.


This book contains information from basic cleaning and degreasing to detailing methods. Packed full of products and methods of detailing and maintaining your engine compartment, this book is beneficial to any car owner.

- PW133** *How to Restore Your Muscle Car* by Greg Donahue and Paul Zazarine..... 26.00/ea.

This book shows special techniques and basic skills needed to restore your collectible car. It gives the latest information on chemicals, tools, and procedures used to paint, clean, degrease, derust, weld, rewire, etc. on your classic car. This book is a valuable guide to any restorer. It contains 1300 photographs, charts, and diagrams. (352 pages).

Comments: Excellent.

PW134



PW135

- PW134** *Super Tuning and Modifying Carter Carburetors* by Dave Emanuel 19.00/ea.
PW135 *Rochester Carburetors* by Doug Roe..... 19.00/ea.

PW134 and PW135 offer history and a large amount of technical information.

PW136



PW137

- PW136** *Holley Rebuilding and Modifying* by Jeff Williams.....\$ 19.00/ea.
PW137 *Super Tuning and Modifying Holley Carburetors* by Dave Emanuel 19.00/ea.

Both Holley books offer comprehensive information, however PW136 may be a better choice for the beginner while PW137 is more appropriate for the experienced mechanic.



PW138


- PW138** *Auto Math Handbook* 19.00/ea.

Excellent book for figuring all aspects of automotive calculations - compression ratios, rear end & tire ratios, horsepower, etc. Very informative. 148 pages.

- PW142** *Pontiac! They Built Excitement* by Thomas E. Bonsall..... Disc.

This hardcover book contains the history of Pontiac from 1893 to the 1992 Bonneville SSEI. Very informational with design photos and interviews with several Pontiac officials. Covers the development of the Firebird among various other models. 160 pages. Over 300 illustrations.

PW143



PW144

- PW143** *Motor City Muscle* by Mike Mueller 30.00/ea.

This hardcover book offers a comprehensive overview of the musclecar era. Included are sections on the Pontiac GTO, Trans Am, and full-size cars. The book also contains an incredible amount of information on other makes from this period. 192 pages, excellent photography.

- PW144** *American Muscle* 30.00/ea.



This excellent book details many of the spectacular muscle cars in the now disbanded Otis Chandler collection. 192 pages, 190 color photographs.

PW148



PW148 *Standard Catalog of American Cars 1946-1975* edited by John Gunnell.....
Gives a brief overview on more than 1000 vehicles. Covers various models, production figures, options, and historical footnotes. Over 1700 photographs and 864 pages.

PW149



PW149 *Standard Catalog of American Cars 1976-1986*.....
Very similar to PW148 plus pinpoints good investments and future collectibles.

Disc.

Inquire



PW154

PW154 *Glory Days: When Horsepower and Passion Ruled Detroit* by Jim Wangers 25.00/ea.
This new book gives fresh insight into the birth of the Pontiac GTO. Jim Wangers was responsible for the marketing campaign that propelled Pontiac to the fore front of the muscle car era. Jim uses his 45-year career to provide his view as to what happened during those times. Each copy is personally signed.

PW157



PW158

PW157 *Turbo-Hydra-matic 350 Handbook* by Ron Sessions 17.00/ea.
PW158 *Turbo-Hydra-matic 400 Transmission* by Ron Sessions 20.00/ea.
Both these books go deeper into troubleshooting and repairing transmissions. Very detailed information is supplied in the text. These books also contain information on special performance modifications for the street or track.

PW159



PW165

PW159 *Automotive Upholstery Handbook* by Don Taylor 22.00/ea.
Contains chapters on: Tools of the trade and sewing, how to pattern, cut and fit, marking

and installing complete interiors, vinyl roofs, convertible tops, and much more. Its detailed instructions will help you do quality work. 224 pages. 550 b&w photos.

PW165 *Steering Wheel Restoration Handbook* by Jack Turpin \$ 17.00/ea.

This manual gives step by step instructions on repairing and restoring steering wheels with standard shop tools. 20 pages. 80 illustrations.



PW166

PW166 *Pontiac Muscle Cars* by Mike Mueller 14.00/ea.

Complete history and color photos of Pontiac muscle cars from the late 50's to the early 70's. Firebirds, Formulas, Trans Ams, GTOs and full-size cars are all pictured with interior, exterior, and engine compartment shots. 96 pages and 80 colored illustrations.

ASSEMBLY MANUALS

PW180 1970 Grand Prix Assembly Manual 32.00/ea.
PW181 1971 Grand Prix Assembly Manual 29.00/ea.

Assembly manuals are used on GM production lines to show workers how each piece is assembled and installed. These assembly manual photocopies cover '70 and '71 Grand Prix, Tempests, LeMans, and GTOs. They include an exploded view of every section of the car detailing all part numbers and installation procedures. This once privileged information is invaluable to any restorer.

Comments: Photocopy work is fair to good.

FISHER BODY MANUALS



PW231

PW227 1963 Fisher Body Manual (Photocopy) Inquire
PW228 1964 Fisher Body Manual (Photocopy) 40.00/ea.
PW229 1965 Fisher Body Manual (Photocopy) 40.00/ea.
PW230 1966 Fisher Body Manual (Reprint) 29.00/ea.
PW231 1967 Fisher Body Manual (Reprint) 29.00/ea.
PW232 1968 Fisher Body Manual (Reprint) 29.00/ea.
PW233 1969 Fisher Body Manual (Reprint) 29.00/ea.
PW234 1970 Fisher Body Manual (Reprint) 29.00/ea.
PW235 1971 Fisher Body Manual (Reprint) 29.00/ea.
PW236 1972 Fisher Body Manual (Reprint) 29.00/ea.
PW237 1973 Fisher Body Manual (Original) Inquire

PW238	1974	Fisher Body Manual (Original)	\$ 25.00/ea.
PW239	1975	Fisher Body Manual (Original)	29.00/ea.
PW240	1976	Fisher Body Manual (Original)	Inquire
PW241	1977	Fisher Body Manual (Original)	Inquire

Fisher body manuals explore all aspects of disassembling, servicing, and installation of GM body components. Combine these with our shop manuals, and you will have more than adequate information for all aspects of your restoration.

SHOP MANUALS



PW252

PW242	1955	Shop Manual (Photocopy)	45.00/ea.
PW242A	1956	Shop Manual (Photocopy)	45.00/ea.
PW243	1957	Shop Manual (Photocopy)	45.00/ea.
PW244	1958	Shop Manual (Photocopy)	45.00/ea.
PW245	1959	Shop Manual (Photocopy)	55.00/ea.
PW246	1960	Shop Manual (Photocopy)	55.00/ea.
PW249	1963	Shop Manual (Photocopy)	60.00/ea.
PW250	1964	Shop Manual Supplement to '63 Shop Manual (Photocopy)	20.00/ea.
PW251	1965	Shop Manual (Photocopy)	60.00/ea.
PW252	1966	Shop Manual - Full-Size Pontiac Models (Reprint)	39.00/ea.
PW253	1967	Shop Manual - ALL Pontiac Models (Reprint)	45.00/ea.
PW254	1968	Shop Manual - ALL Pontiac Models (866 pages) (Reprint)	39.00/ea.
PW255	1969	Shop Manual - ALL Pontiac Models (866 pages) (Reprint)	42.00/ea.
PW256	1970	Shop Manual - ALL Pontiac Models (1284 pages) (Photocopy) —2 Volumes	70.00/set

PW257	1971	Shop Manual - ALL Pontiac Models (Reprint)	\$ 69.00/ea.
PW257B	1972	Shop Manual - ALL Pontiac Models (Reprint)	80.00/ea.
PW257D	1973	Shop Manual - ALL Pontiac Models (Reprint)	69.00/ea.
PW257J	1974	Shop Manual - ALL Pontiac Models (Original)	Inquire
PW260	1955-70	Pontiac Parts Book (Photocopy)	85.00/set

This is a copy of an original Pontiac parts book used by the dealer. It shows most parts numbers for 1960-70 models. (Only missing numbers would be those discontinued before 1970.)

Other sources sell current parts books which have no listing for discontinued parts.

OWNER'S MANUALS



PW272


PW272	1957	Pontiac Owner's Manual	20.00/ea.
PW282	1967	Pontiac Owner's Manual	11.00/ea.
PW283	1968	Pontiac Owner's Manual	11.00/ea.
PW284	1969	Pontiac Owner's Manual	11.00/ea.
PW285	1970	Pontiac Owner's Manual	11.00/ea.

CONVERTIBLE TOP MANUALS



PW327

PW316	1955	Convertible Top Manual (GM)	6.00/ea.
--------------	------	-----------------------------------	----------



Does Ford = General Motors = Chrysler?

No! Of course not.

Does Ford = Pontiac = Plymouth?

No! Of course not.

We could never know enough or stock enough or care enough about *all* cars. Therefore,

WE SELL PONTIAC ONLY

For ordering and price quotations, call (800) 421-AMES (2637).

For questions and ordering, call (603) 876-3345


(603) 876-4656

(603) 876-4751

PW322	1961	Convertible Top Manual (GM)	\$ 6.00/ea.
PW323	1962	Convertible Top Manual (GM)	6.00/ea.
PW324	1963	Convertible Top Manual (GM)	6.00/ea.
PW325	1964	Convertible Top Manual (GM)	6.00/ea.
PW326	1965	Convertible Top Manual (GM)	6.00/ea.
PW327	1966	Convertible Top Manual (GM)	6.00/ea.
PW328	1967	Convertible Top Manual (GM)	6.00/ea.
PW329	1968	Convertible Top Manual (GM)	6.00/ea.

All convertibles were originally supplied with this manual in the glovebox. It covers operation and maintenance of the convertible top.

PW340	1964	New Car Accessory Price List (RE) ...	3.00/ea.
--------------	------	---------------------------------------	----------



PW370

PW370	1960	Pontiac GM Cars Retail Price Book (RE)	3.00/ea.
PW374	1964	Pontiac GM Cars Retail Price Book (RE)	3.00/ea.
PW375	1965	Pontiac GM Cars Retail Price Book (RE)	3.00/ea.
PW376	1966	Pontiac GM Cars Retail Price Book (RE)	3.00/ea.
PW381	1971	Pontiac GM Cars Retail Price Book (RE)	3.00/ea.



PW427

PW405	1965	Pontiac Accessories Catalog (32 pages)	Disc.
--------------	------	--	-------

This shows all accessories and codes available in 1965.

PW407	1965	Grand Prix 8-Page Color Brochure..	Disc.
PW410	1966	Grand Prix 3-Page Color Foldout	\$ 10.00/ea.
PW415	1967	Pontiac Full Line Color Catalog (54 pages)	12.00/ea.

This catalog has short writeups on all Pontiacs produced in 1967 (exc. Firebird) along with their general specifications.

PW427	1970	Pontiac Full Line Color Catalog (22 pages)	12.00/ea.
--------------	------	--	-----------

See *Note* under PW415.

PW430	1971	Pontiac Full Line Color Catalog (23 pages)	12.00/ea.
--------------	------	--	-----------

This catalog has short writeups on all Pontiacs including Firebirds produced in 1971.

PW435	1972	Pontiac Full Line Color Catalog (31 pages)	12.00/ea.
--------------	------	--	-----------

Same as PW430.

Note: PW400 through PW435 are all original GM catalogs or brochures. They may have dealership names printed on them.


SECTION NINETEEN - DECALS

The decal section is divided into groups that correspond to the sections of this catalog. In other words, the first group of decals is for the interior, and so forth. Catalog sections for which there are no decals are omitted. We are not responsible for improper application of decals.

INTERIOR DECALS



PX118



PX158

PX370	1955	Battery Warranty Certificate (RE)	\$ 3.00/ea.
PX457	1955-60	Delco Battery Owner's Certificate (RE)	3.00/ea.
PX381	1961-64	Delco Battery Owner's Certificate (RE)	3.00/ea.

PX382	1965-68	Delco Battery Owner's Certificate (RE)	\$ 3.00/ea.
--------------	---------	--	-------------

PX101	1955-59	Service Policy (RE)	3.00/ea.
--------------	---------	---------------------------	----------

PX369	1960-64	Service Policy (RE)	3.00/ea.
--------------	---------	---------------------------	----------

PX313	1955-59	Owner's Identification Card (RE)	3.00/ea.
--------------	---------	--	----------

PX368	1968	Owner's Identification Card (RE)	3.00/ea.
--------------	------	--	----------

PX233	1955-58	Lighter Instruction Tag (RE)	3.00/ea.
--------------	---------	------------------------------------	----------

PX454	1955-56	Hydramatic Instruction Survivor Sleeve (RE)	4.00/ea.
--------------	---------	---	----------

PX103	1955-58	Glove Box Key Decal (RE)	3.00/ea.
--------------	---------	--------------------------------	----------

PX226	1955-62	Compass Glove Box Instruction Decal (RE)	3.00/ea.
--------------	---------	--	----------

PX161	1957	Glove Box Paint Instruction Decal (RE)	3.00/ea.
--------------	------	--	----------

PX458	1957	Lacquer Paint Instruction Card (RE) ..	3.00/ea.
--------------	------	--	----------

PX698	1958-63	Power Antenna Instruction Tag (RE) ..	3.00/ea.
--------------	---------	---------------------------------------	----------

PX117	1965	Tire Pressure Decal (RE)	\$ 3.00/ea.
PX118	1966	Tire Pressure Decal (RE)	3.00/ea.
PX119	1967	Tire Pressure Decal (RE)	3.00/ea.
PX121	1968	Tire Pressure Decal (RE)	3.00/ea.
PX450	1969	Tire Pressure Decal - GP (RE)	3.00/ea.
PX305	1971	Tire Pressure Decal - GP (RE)	3.00/ea.
PX333	1974	Tire Pressure Decal - KE (RE)	3.00/ea.
PX472	1974-75	Tire Pressure Decal - KE (RE)	3.00/ea.
PX404	1969-72	Ignition Lock Sunvisor Sleeve, 6" (RE)	3.00/ea.
PX452	1969-72	Ignition Lock Sunvisor Sleeve, 7" (RE)	3.00/ea.
PX468	1972	Seat Belt Instruction Sleeve - GP (RE)	3.00/ea.
PX405	1973-75	Ignition Lock Sunvisor Sleeve (RE) ..	3.00/ea.
PX367	1973	Sunvisor Clean Air Decal (RE)	3.00/ea.
PX331	1973	Sunvisor Starting Instructions (RE)	3.00/ea.
PX330	1974-76	Sunvisor Starting Instructions Decal (RE)	3.00/ea.
PX308	1975-76	Push Start Warning Decal (RE)	3.00/ea.
PX610	1976-78	Hurst Modification Decal (RE)	3.00/ea.
PX162	1971-73	Vehicle Safety Maintenance Decal - FS (RE)	3.00/ea.
PX304	1971	Vehicle Safety Maintenance Decal - GP (RE)	3.00/ea.
PX158	1972-74	Fuel Recommendation Decal (RE) ..	3.00/ea.
PX505	1966-69	Build Sheet (RE)	3.00/ea.
PX502	1968	New Car Inspection Sheet (RE)	3.00/ea.
PX508	1969	New Car Inspection Sheet (RE)	3.00/ea.
PX371	1970	New Car Pre-delivery Sheet (RE)	3.00/ea.
PX248	1971	New Car Pre-delivery Sheet (RE)	3.00/ea.
PX464	1972	New Vehicle Inspection Sheet (RE) ..	3.00/ea.
PX477	1973	New Vehicle Inspection Sheet (RE) ..	3.00/ea.
PX501	1974	New Vehicle Inspection Sheet (RE) ..	3.00/ea.
PX500	1975	New Vehicle Inspection Sheet (RE) ..	3.00/ea.
PX503	1976	Hurst Hatch Inspec/Warranty Sheet (RE)	3.00/ea.
PX380	1974-78	Superlift Air Shock Glove Box Card (RE)	3.00/ea.
PX536	1976	Catalytic Converter Caution Decal (RE)	3.00/ea.
PX465	1976-77	Headlight Dimmer Instruction Tag (RE)	3.00/ea.



DOOR COMPONENT DECALS

Correct stamped aluminium mark of excellence door badges are now available. See Section Five for these excellent reproductions.



PX100	1967	GM Mark of Excellence Turquoise Foil Decal (RE)	3.00/ea.
--------------	------	---	----------

PX186	1968 & Newer	GM Mark of Excellence Blue Foil Decal (RE)	\$ 3.00/ea.
--------------	--------------	--	-------------

Note: PX100 and PX186 are the embossed aluminium foil decal.

PX175	1963-66	New Car Window Price Sticker (RE)	3.00/ea.
PX177	1967	New Car Window Price Sticker (RE)	3.00/ea.
PX495	1968-69	New Car Window Price Sticker (RE)	3.00/ea.
PX473	1970	New Car Window Price Sticker (RE)	3.00/ea.
PX212	1971	New Car Window Price Sticker (RE)	3.00/ea.
PX213	1972-73	New Car Window Price Sticker (RE)	3.00/ea.
PX620	1974	New Car Window Price Sticker (RE)	3.00/ea.
PX609	1977-79	New Car Window Price Sticker (RE)	3.00/ea.

CONVERTIBLE TOP DECALS

PX155	1970-73	Convertible Top Bracket Decal (RE) ..	3.00/ea.
--------------	---------	---------------------------------------	----------

TRUNK COMPONENT DECALS



PX126




PX140A



PX229

PX494	1958	Jack Instructions (RE)	3.00/ea.
PX140	1960	Jack Instructions (RE)	4.00/ea.
PX140A	1960	Trunk Water Test Inspection Decal (RE)	4.00/ea.
PX166	1961	Jack Instructions (RE)	3.00/ea.
PX133	1962	Jack Instructions (RE)	3.00/ea.
PX134	1963	Jack Instructions (RE)	3.00/ea.
PX113	1964	Jack Instructions (RE)	3.00/ea.
PX511	1962-64	Jack Base Decal (Caution) (RE)	3.00/ea.
PX125	1965	Jack Instructions (RE)	3.00/ea.

PX623



PX624



PX126	Early 1966	Jack Instructions exc. Conv. (RE) .	\$ 3.00/ea.		PX378	1956	2 BBL Oil-Bath Air Cleaner Decal (RE).....	\$ 3.00/ea.
		See photo on previous page for identification.			PX131	1957	Air Cleaner Service Decal w/Paper Element (RE).....	3.00/ea.
PX623	Late 1966	Jack Instructions exc. Conv. (RE) .	3.00/ea.		PX554	1957	Tri-Power Air Cleaner Service Decal (RE).....	3.00/ea.
		See photo on previous page for identification.			PX347	1958-60	4 BBL and 1958 2 BBL Air Cleaner Decal (RE)	3.00/ea.
PX624	Late 1966	Jack Instructions, Conv. (RE).....	3.00/ea.		PX350	1959-60	Tri-Power Air Cleaner Service Decal w/ A59C element (RE).....	4.00/ea.
		See photo on previous page for identification.			PX555	1958	Tri-Power Air Cleaner Service Decal (RE).....	Disc.
PX111	1967	Jack Usage Instructions (RE).....	3.00/ea.		PX349	1959-64	Air Cleaner Service Instruction Decal, Red w/A96C (RE).....	3.00/ea.
PX112	1967	Jack Stowage Instructions exc. Conv. (RE).....	3.00/ea.				Use this decal with foam and screen element.	
PX312	1967	Jack Stowage Instructions - Conv. (RE).....	3.00/ea.		PX580	1959-64	Air Cleaner Service Instruction Decal, White w/A96C (RE)	3.00/ea.
PX217	1968	Jack Instructions - ALL exc. Conv. (RE).....	3.00/ea.				Use this decal with foam and screen element.	
PX529	1968	Jack Stowage Instructions - Conv. (RE).....	3.00/ea.		PX196	1962-63	421 HO Air Cleaner Decal (RE).....	5.00/ea.
PX385	1969	Jack Instructions - GP (RE).....	3.00/ea.		PX197	1962-63	421 SD Air Cleaner Decal (RE)	5.00/ea.
PX921	1970	Jack Instructions - GP (RE).....	3.00/ea.		PX198	1962-63	421 GP Air Cleaner Decal (RE).....	5.00/ea.
PX147	1971-72	Jack Instructions - GP (RE).....	3.00/ea.		PX150	1964	Tri-Power Air Cleaner Service Decal (RE).....	3.00/ea.
PX151	1973	Jack Instructions - GP (RE).....	3.00/ea.		PX556	1965	389 Tri-Power & Police 421 Air Cleaner Service Decal (RE)	3.00/ea.
PX154	1974-77	Jack Instructions - GP (RE).....	3.00/ea.		PX557	1965	Calif. 389 Tri-Power & Police 421 Air Cleaner Service Decal (RE).....	3.00/ea.
PX625	1973	Jack Instructions - Grandville Conv. (RE).....	3.00/ea.		PX558	1965	421 Tri-Power Non-Police Air Cleaner Service Decal (RE)	3.00/ea.
					PX559	1965	Calif. 421 Tri-Power Non-Police Air Cleaner Service Decal (RE)	3.00/ea.
PX335	1955	Jack Base Decal (RE)	3.00/ea.		PX159	1965-66	389/421 Air Cleaner Service Decal w/A96C (RE).....	3.00/ea.
PX310	1956-57	Jack Head Decal (RE).....	3.00/ea.				Use this decal with foam and screen element.	
PX178	1957	Jack Base Decal (RE)	3.00/ea.		PX170	1965-70	Air Cleaner Service Decal w/A98 (RE).....	3.00/ea.
PX240	1959	Jack Decal (RE).....	3.00/ea.				Use with pancake filter only.	
PX372	1959-61	Jack Base Decal (RE)	3.00/ea.		PX210	1968	350 - 2 BBL Air Cleaner Service Decal w/A331C (RE).....	3.00/ea.
PX229	1958	Air Suspension Decal (RE)	3.00/ea.		PX183	1968-69	2 BBL Heavy Duty Air Cleaner Service Decal w/A277C (RE)	3.00/ea.
PX359	1971-74	Air-Shock Decal (RE)	3.00/ea.		PX184	1968	400 - 4 BBL Air Cleaner Service Decal (RE)	3.00/ea.
PX286	1975-78	Air-Shock Decal (RE)	3.00/ea.		PX182	1968	428 - 4 BBL Air Cleaner Service Decal exc. GP (RE).....	3.00/ea.
PX332	1973-77	Space Saver Inflator Bottle Decal (RE).....	3.00/ea.		PX886	1968-69	428 - 4 BBL Air Cleaner Service Decal - GP (RE)	3.00/ea.
PX326	1973-77	Space Saver Spare Warning Decal (RE).....	3.00/ea.		PX228	1967-70	Keep Your GM Car All GM Air Cleaner Decal (RE).....	3.00/ea.
PX595	1977	Space Saver Spare Warning Decal (RE).....	3.00/ea.		PX383	1971	Keep Your GM Car All GM Air Cleaner Decal (RE).....	3.00/ea.
PX324	1976-77	Anti-Spin Trunk Decal (RE)	3.00/ea.		PX455	1972-73	V-8 - 2 BBL Keep Your GM Car All GM Air Cleaner Decal (RE)	3.00/ea.
PX306	1977	Aluminum Wheel Warning Decal (RE).....	3.00/ea.		PX439	1972-73	V-8 - 4 BBL Keep Your GM Car All GM Air Cleaner Decal (RE)	3.00/ea.
					PX328	1974	Keep Your GM Car All GM Air Cleaner Decal (RE).....	3.00/ea.
					PX440	1975	Keep Your GM Car All GM Air Cleaner Decal exc. 455 (RE)	3.00/ea.


ELECTRICAL RELATED

PX172	1963-67	Transistor Ignition Coil Decal (RE) ...	3.00/ea.
PX173	1963-66	Transistor Amplifier Decal (RE)	3.00/ea.
PX614	1967	Transistor Amplifier Decal (RE)	3.00/ea.
PX336	1963-67	Breakerless Ignition Decal (RE)	3.00/ea.

ENGINE COMPONENT AND COMPARTMENT DECALS



PX228



PX197

PX348	1955	2 BBL Air Cleaner Service Decal (RE).....	3.00/ea.
PX132	1955-57	4 BBL Air Cleaner Service Decal w/Oil Bath Air Cleaner (RE)	3.00/ea.

PX622	1975	Keep Your GM Car ALL GM Air Cleaner Decal - 455 (RE)	\$ 3.00/ea.
PX441	1976	Keep Your GM Car All GM Air Cleaner Decal (ALL exc. 400 engine) (RE)	3.00/ea.
PX534	1976	Keep Your GM Car All GM Air Cleaner Decal (400-FS) (RE)	3.00/ea.
PX604	1976	Keep Your GM Car All GM Air Cleaner Decal (400-GP) (RE)	3.00/ea.
PX582	1977	Keep Your GM Car All GM Air Cleaner Decal (400-4V) (RE)	3.00/ea.
PX593	1977	Keep Your GM Car All GM Air Cleaner Decal 2BBL (RE)	3.00/ea.
PX171	1970	Regular Fuel Engine Valve Cover Decal (RE)	3.00/ea.
PX104	1955-58	AC Oil Filter Decal (RE)	3.00/ea.
PX309	1955-60	Oil Filter Decal (RE)	3.00/ea.



PX309A

PX309A	1960-67	PF7 Oil Filter Decal (RE)	4.00/ea.
---------------	---------	---------------------------------	----------

This decal can be used on spin-on oil filters to make them look original.



PX311	1955-57	Oil Filler Cap Decal Pink (RE)	3.00/ea.
PX438	1955-57	Oil Filler Cap Decal Orange (RE)	3.00/ea.
PX311A	1958-60	Oil Filler Cap Decal (RE)	4.00/ea.
PX234	1955-63	Generator Warning Tag (RE)	3.00/ea.
PX532	1960	Caution Fan Decal (RE)	4.00/ea.
PX533	1961	Caution Fan Decal (RE)	3.00/ea.



	PX115	PX105	
PX115	1962-63	Caution Fan Decal (Horiz.) (also '64 GP) (RE)	3.00/ea.
PX143	1962-63	Caution Fan Decal (Vert.) (RE)	3.00/ea.
PX114	1964	Caution Fan Decal (RE)	3.00/ea.
PX128	1965-66	Caution Cooling Decal (RE)	3.00/ea.
PX129	1967-68	Caution Cooling Decal (RE)	3.00/ea.
PX144	1970-72	Caution Cooling Decal (RE)	3.00/ea.
PX157	1973	Caution Cooling Decal (RE)	3.00/ea.
PX285	1974-78	Engine Coolant Decal (RE)	3.00/ea.
PX469	1963	Caution Radiator Cap Decal - GP (RE)	3.00/ea.
PX116	1963-65	Battery Warning Decal (RE)	3.00/ea.
PX187	1955-56	Power Steering Lid Decal (RE)	3.00/ea.
PX188	1955-56	Power Steering Pulley Decal (RE)	3.00/ea.
PX506	1955-60	Methanol Anti-Freeze Tag (RE)	3.00/ea.
PX142	1964-65	Anti-Freeze Tag (RE)	3.00/ea.
PX287		GM Dealer Installed Anti-Freeze Decal (RE)	3.00/ea.





PX287A

PX287A	1957-66	GF-61-P Fuel Filter Decal (RE)	\$ 4.00/ea.
---------------	---------	--------------------------------------	-------------

Make your afterproduct fuel filter look like original with this correctly printed decal.

PX203	1957	Paint Finish Decal (RE)	3.00/ea.
PX105	1955-58	Trico Windshield Washer Decal (RE)	3.00/ea.
PX351	1955-60	GM Windshield Washer Bracket Decal (RE)	3.00/ea.
PX352	1961-63	GM "Kleer-view" Windshield Washer Label (RE)	3.00/ea.



	PX361	PX355	
PX361	1964-67	GM "Pontiac Kleer-view" Windshield Washer Label	3.00/ea.
PX355	1964-67	GM Optikleen Windshield Washer Label (RE)	3.00/ea.
PX353	1968-72	GM Windshield Washer Bottle Label (RE)	3.00/ea.



	PX208	PX497	
PX497	1960	Heater Box Inspection Decal (under hood) (RE)	4.00/ea.
PX470	1963	Air Conditioner Compressor Belt Instruction Decal (RE)	3.00/ea.
PX149	1957-65	Air Compressor Warning Decal (RE)	3.00/ea.
PX204	1964-65	Frigidaire Air Compressor Decal (RE)	3.00/ea.
PX205	1966	Frigidaire Air Compressor Decal (RE)	3.00/ea.
PX206	1967	Frigidaire Air Compressor Decal (RE)	3.00/ea.

PX207	1968-70	Frigidaire Air Compressor Decal (RE).....	\$ 3.00/ea.
PX208	1971	Frigidaire Air Compressor Decal (RE).....	3.00/ea.
PX209	1972	Frigidaire Air Compressor Decal (RE).....	3.00/ea.
PX215	1973	Frigidaire Air Compressor Decal (RE).....	3.00/ea.
PX236	1974	Frigidaire Air Compressor Decal (RE).....	3.00/ea.
PX594	1977	Delco Air Compressor Decal (RE) ...	4.00/ea.
PX314	1965	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX315	1966	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX316	1967	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX317	1968	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX318	1969	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX319	1970	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX320	1971	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX321	1972	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX322	1973	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX375	1974	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX376	1975	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX377	1976	Harrison AC Evaporator Decal (RE) .	3.00/ea.
PX596	1977	New Refrigerant AC Evaporator Decal (RE)	4.00/ea.



PX200

PX139	1968	350-2V Emission Decal (RE)	3.00/ea.
PX138	1968	400-2V Emission Decal (RE)	3.00/ea.
PX168	1968	350-4V, 400-4V, 428-4V Emission Decal (RE)	3.00/ea.
PX890	1969	ALL 2 BBL V-8 Emission Decal (RE).	3.00/ea.
PX891	1969	ALL 4 BBL V-8 Emission Decal (RE).	3.00/ea.
PX192	1970	ALL 2 BBL V-8 Emission Decal (RE).	3.00/ea.
PX185	1970	ALL 4 BBL V-8 Emission Decal exc. 455 (RE)	3.00/ea.
PX239	1970	455-4V Emission Decal (RE)	3.00/ea.
PX379	1971	400-4V AT Emission Decal (RE)	3.00/ea.

PX200	1971	400-4V MT Emission Decal (RE)	\$ 3.00/ea.
PX357	1972	350 AT Emission Decal (RE)	3.00/ea.
PX167	1972	400-2V AT Emission Decal exc. GP (RE)	3.00/ea.
PX202	1972	400-4V Emission Decal (RE)	3.00/ea.
PX201	1972	455-4V Emission Decal (RE)	3.00/ea.
PX530	1972	400-2V Emission Decal - GP (RE)	3.00/ea.
PX524	1973	400-AT Emission Decal (RE)	3.00/ea.
PX553	1973	400-MT Emission Decal (RE)	3.00/ea.
PX528	1973	455-AT Emission Decal (RE)	3.00/ea.
PX245	1973	455-MT Emission Decal (RE)	3.00/ea.
PX327	1974	350-AT Emission Decal (RE)	3.00/ea.
PX302	1974	350-MT Emission Decal (RE)	3.00/ea.
PX241	1974	400-AT Emission Decal (RE)	3.00/ea.
PX230	1974	400-MT Emission Decal (RE)	3.00/ea.
PX531	1974	455-AT Emission Decal (RE)	3.00/ea.
PX496	1976	400-AT Emission Decal (RE)	3.00/ea.
PX611	1976	400-MT Emission Decal (RE)	3.00/ea.
PX525	1976	455-MT Emission Decal (RE)	3.00/ea.
PX523	1977	400-AT Emission Decal w/Perf. Option (RE)	3.00/ea.

AFTERMARKET AIR CLEANER DECALS



PX412

PX407	326-2V Air Cleaner Decal (AP)	4.00/ea.
PX408	326-4V Air Cleaner Decal (AP)	4.00/ea.
PX409	350-2V Air Cleaner Decal (AP)	4.00/ea.
PX410	350-4V Air Cleaner Decal (AP)	4.00/ea.
PX411	389-2V Air Cleaner Decal (AP)	4.00/ea.
PX412	389-4V Air Cleaner Decal (AP)	4.00/ea.
PX413	400-2V Air Cleaner Decal (AP)	4.00/ea.
PX414	400-4V Air Cleaner Decal (AP)	4.00/ea.
PX416	421-4V Air Cleaner Decal (AP)	4.00/ea.
PX417	428-4V Air Cleaner Decal (AP)	4.00/ea.
PX418	455-4V Air Cleaner Decal (AP)	4.00/ea.
PX419	455-4V Hi Perf. Air Cleaner Decal (AP)	4.00/ea.
PX732	Pontiac 389 Ram Air 360 HP Valve Cover Decal (AP)	4.00/ea.
PX354	Pontiac 421 Tri-Power 425 HP Valve Cover Decal (AP)	4.00/ea.

INDEX

A/C Vent Deflectors.....22
Accessory Floor Mats.....3, 4
A-frame Seals.....140
Air Cleaners.....105, 116, 117
Air Filter Elements.....105, 116
Alternator Related.....112, 113
Antenna Components.....94-96
Arm Rests.....11-13
Ash Tray.....13

Batteries.....100
Battery Cables.....100, 101
Battery Tray Components.....133, 134
Blower Motors.....136
Body Mounts.....170-172
Body Plugs.....76
Brake Calipers.....156
Brake Lines.....161-163
Brake Pads.....155

Brake Repair Kits.....157-159
Brake Shoes.....156
Brake Drums.....156
Bumper Bolts.....35, 94
Bumper Stop Kits.....185
Camshafts.....130
Carburetor Floats.....122
Carburetor Rebuilding Kit.....122

Car Care Products.....179, 180
Car Covers.....179
Carpets.....4, 5
Center Cap Locks.....174, 175
Cigarette Lighters.....20
Clutch Components.....152-155
Clutch Kits.....153
Coat Hooks.....28
Coil.....127

Coil Springs	168-169
Console Components	15, 16
Control Arm Components	165-166
Convertible Armrest Bezels	26
Convertible Armrest Covers	13
Convertible Top Cleaner	68, 69
Convertible Top Components	66-71
Cowl Grilles	40

Dash Circuits	101
Dash Inserts	17-20
Decals	180, 192-196
Deck Lid Arrowheads	86, 87
Distributors	127
Distributor Caps	127
Dome Lamp Components	26
Door Badges	46
Door Components	44-60
Door Handles & Gaskets	44-46
Door Hinges	47
Door Jamb Edging	29
Door Jamb Louvers	76
Door Panel Carpeting	9-10
Door Panel Fasteners	9
Door Sill Plates	60

Electrical Related	96-101
Emblems	
Console	15
Deck Lid	86-88
Front End	31, 32
Front Fender	36-38
Grille	31, 32
Hood	39, 40
Horn Button	14
Rear 1/4	72, 73
Tail Panel	86-88
Engine Bearings	131
Engine Compartment	
Components	133-142
Engine Components	105-133
Engine Cradle	185
Engine Gasket Sets	132
Engine Mounts	128, 129
Exhaust Manifold	
Components	119, 120
Exhaust Manifold Coating	119
Exhaust Pipe Hangers	89, 90
Exhaust Systems	118, 119

Fan Clutch	138
Fan Shrouds and Guards	138
Fenders	39
Fender Covers	180, 181
Firewall Pads	10
Flexplates	154
Floor Insulation	5, 6
Floor Pans & Braces	29, 30
Flowmaster Mufflers	119
Flywheels	154
Freeze Plugs	132
Front Arrowheads	31, 32
Front End Trim	35
Front Fender Components	36-39
Fuel Filters	109, 110
Fuel Hose	108
Fuel Lines	106-109
Fuel Pump	107
Fuel Pump Eccentric	130

Gas Doors	93
Gas Gauge Sending Units	92
Gas Tanks	92
Gas Tank Straps	92, 93
Glove Boxes	25

Grille Components	32-34
Ground Straps	139

Harmonic Balancers	133
Hats	181
Headlight Components	35
Headlight Door Components	32-34
Headliners	23, 24
Heater Cores	135, 136
Hood Arrowheads	39, 40
Hood Components	39-44
Horn Button Components	14
Horns and Relays	99
Hose Clamps	137

Inner Door Panel Components	9
Inner Panel Water Shield	10
Insulation, Underhood	43, 44
Interior Components	26

Keys	
Console	15, 16
Door	46
Glove Box	25, 26
Ignition	99
Trunk	84
Key Chains	181
K & N Air Filters	116

Lamp Kit	
Underhood	42
Trunk	83

Lenses	
Back-up	91, 92
Console Courtesy	15
Side Marker	36
License Lamp	93
Parking Light	34
Shift Indicator	15
Taillight	90, 91
Light Bulbs	97, 98
Line Clips	109, 160
Literature	187-192
Lock Pillar Weatherstrip	76
Lock Pulls & Ferrules	53, 54
Locks	
Console	15, 16
Door	46
Glove Box	25, 26
Ignition	98
Trunk	84, 85
Lock Sets	185-187
Lug Nuts	176-177

Main Bearing Caps	131, 132
Master Cylinder Components	143-146
Mirror Components	16, 17, 49, 50
Mouldings	
Rear Window Reveal	62, 63
Rocker Panel	60, 61
Windshield Reveal	63

Oil Caps	128
Oil Dipsticks & Tubes	118
Oil Filters	117
Oil Filter Adapters	121
Oil Pans	118
Oil Pumps	132

Package Trays	22, 23
Padded Dashes	31
Paint	
Battery Tray	134
Chassis	173

Engine	121
Engine Compartment	140
Jack	83
Trunk Spatter	83
Wheel	177, 178
Parking Brake Components	153, 154
Parking Light Components	34, 35
Patch Panels	
Trunk	85
PCV Components	123
PCV Hose	123
Pedal Pads and Trim	142, 143
Piston Rings	132
Points	127
Polyurethane Suspension	
Components	166-167
Power Steering Hoses	173
Posters	181, 182
Printed Circuits	101

Radiator Caps	138
Radiator and Heater Hoses and	
Clamps	136, 137
Radiators	135
Radio Speaker Components	98
Rear End Components	159, 160
Rear End Dolly	185
Rear End Trim	86-88
Rear Seat Divider Panel	81, 82
Rear 1/4 Trim	72, 73
Rearview Mirrors and	
Components	16, 17, 49, 50
Relays	99

Rocker Arms	129
Rocker Panel Components	38, 60, 61
Rubber Bumpers	
Console	27
Door	48
Gas Door	94
Glove Box	27
Hood	40, 41
Kits	185
Trunk	83

Seam Sealer	30, 77
Seat Components	6-9
Seat Padding	7
Seat Piping	7
Seat Springs	7
Shift Boots and Trim	147
Shift Cables	148
Shift Knobs	151
Shift Porches	147
Shock Absorbers	168
Shop Manuals	191
Spare Tire Covers	81
Spark Plugs	125, 126
Spark Plug Wires and	
Brackets	125-127
Speakers	98
Speaker Enclosures	98
Speedometer Cables	151
Splash Seals	140, 141
Spot Rot	184
Starters, High Torque	120, 121
Steering Box	173
Steering Column Seals	11
Steering Wheels Components	14, 15
Suspension Components	164-170
Sunshade Components	27, 28
Sway Bar Kits	167
Switches	
Convertible Top	21, 70
Directional Signal	96

Door Jamb	48, 49
Headlight	97
Headlight Dimmer	97
Ignition	98
Neutral Safety	97
Oil Pressure	99
Power Antenna	21
Power Window	10
Stop Light	97
Temperature	99
Thermostatic Vacuum	124

T-Shirts	182
Tachometers	13, 42
Tailgate Components	88, 89
Taillight Lenses	90, 92
Thermostat Housings	111
Throttle Components	114, 115
Timing Chain Sets	130
Timing Chain Cover	131
Traction Bars	167
Trailer Straps	185
Transmission Cooling Lines	149, 150
Transmission Mounts	149
Transmission Rebuild Kits	151, 152
Transmission Filter Kits	150
Transmission Vacuum Lines	150
Trim Adhesive	23
Trim Rings	175, 176
Tri-Power Components	105-111, 114
Trunk Components	78-86
Trunk Mats	78, 79
Trunk Spatter Paint	83

Valve Covers	127, 128
Vanity Mirrors	17
Vinyl Harness Wrap	101
Voltage Regulators	99, 100

Water Pumps	112
Water Pump Divider Plates	112
Weatherstrip	
Adhesive	82
Convertible Top	70, 71
Door	56, 57
Glass Channel	55
Lock Pillar	76
Pillar Post	71
Roof Rail	54
Trunk	82
Vent Window	59, 60
Rear 1/4 Window	74, 75
Wheel Components	174-178
Wheel Cylinders	157
Wheel Sets	178
Wheelwell Mouldings	
Front	39
Window Guides	56, 57
Window Lace	29
Window Motors	52, 74
Window Regulator	
Handles	51, 73
Window Rollers	51, 52
Windshield Channels	63, 64
Windshield Washer	
Components	140, 142
Windshield Washer	
Nozzles	140
Windshield Wiper	
Components	64, 65
Windshield Mouldings	62, 63
Wire Loom	101
Wiring Harnesses	102-104

PONTIAC PEOPLE SHARE IN THE SUCCESS OF AMES PERFORMANCE.

A note about Ames Performance — our goals, our philosophy, our dedication to Pontiacs and Pontiac People.

For years Ames Performance has used its promotion budget differently from most companies in the restoration products industry. Most other companies spend their advertising budgets promoting their company through extensive magazine ads. Often much money is spent using expensive color, compensating known personalities, sending miscellaneous mailings, etc.

Ames Performance has felt this form of advertising is necessary but to a limited degree. Instead we allocate a large budget percentage to projects that directly benefit our customers and the image of classic Pontiacs.

Every year we reinvest a significant amount of customer dollars for extensive new product tooling. No other company has spent a fraction of our outlay for new Pontiac products. Our products may be available from other companies but the tooling expense, quality control, and product management originate here at Ames Performance.

A second emphasis involves our customers and how to give something back for your support. First and foremost is low and fair pricing. Many times our daily pricing is lower than sale prices around the industry.

Another important benefit here at Ames Performance is our sales staff. From the beginning, we decided to sell Pontiac parts - only Pontiac parts. This has allowed our sales representatives and technical staff to become the most product knowledgeable team in the country. To further enhance our technical support, we have purchased a large number of restored and original cars for reference. Our entire staff has access to these Pontiacs to help answer the most detailed question.

Several years ago we started our most successful method of rewarding customers with event involvement. Not only do we help sponsor numerous Pontiac club shows and events, we were platinum sponsors of the hospitality suite at the '98 Pontiac Southern Nationals in Dallas, Texas; the principal sponsor for all aspects of the Ames Performance Pontiac Nationals at Norwalk, Ohio; plus sponsors of the hospitality suite (food and beverages) at the GTOAA Nationals. We also hosted a complimentary open house here at our company in conjunction with the 1998 POCI Nationals. We always stipulate that our major promotions must include complimentary benefits for show participants.


Lastly, we are focusing on promoting classic Pontiacs throughout the country. Pontiacs have never received their fair share of publicity or exposure in an arena dominated by Chevy and Ford. Increased awareness of classic Pontiacs benefits everyone from Pontiac Motor Division, collectors and enthusiasts down to high school students noticing our mark for the first time. Promotion money allocated for this purpose includes The American Automotive Heritage Foundation (promotes classic cars in high school shop classes); major sponsorship of the Auto Custom Carpet 1969 Judge Hardtop driven by Jeff Moses (owner of ACC) and Steve Ames on a ten-stop circuit from Los Angeles to Detroit on the "Hot Rod Magazine" Power Tour; being invited to display a 1969 Judge convertible at The Smithsonian Institute in Washington, D.C.; being active in ARMO (Automotive Restoration Market Association) plus having a representative on their select committee; and of course traveling with our truck and vending trailer to swap meets across the country. Personal contact at swap meets has always had top priority at Ames starting in 1976 with a rusty station wagon.

That sums us up — who we are, where we've been and where we're going. The following pages outline some of our activities.

Thank you for requesting our catalog.

Steve Ames
Steve Ames

AMES PERFORMANCE WINS ARMO AWARD



The Ames Performance team recently won the SEMA-ARMO award for "Best Restoration Parts Retailer" in the country. This award is given to the company that has continuously demonstrated exceptional service, integrity and business ethics. We are especially proud to receive this award since it is open to all muscle and classic car retailers involved in the restoration industry.



Four ARMO awards were presented at the San Antonio awards banquet in February 1999. L to R: Kurt Strohacker (Eastwood Co.) - Best New Product; Jeff Moses (Auto Custom Carpets) - Best Manufacturer; Steve Ames (Ames Performance) - Best Retailer; Dennis Gage (My Classic Car) - Best Associate Company.

AMES COMMITMENT TO QUALITY REPRODUCTIONS



These new headlight actuator prototypes were cycled hundreds of times before acceptance. Our own reproductions have (APE) designations after the description in our catalog.



Many new products don't need cycling but require extensive micrometer work for exact tolerances. The projects shown here are 8-lug trim rings, center caps and lug nuts.

AMES PERFORMANCE OPEN HOUSE



Besides business tours and car collection tours, there are always food and beverages available for Pontiac lovers.



Hundreds of Pontiac enthusiasts toured the Ames Performance facilities during our last open house.

1999 AMES PERFORMANCE PONTIAC NATIONALS



Out of almost 250 show cars this elite group achieved best of class honors. Winners (L to R): Dick Cash (Best Grand Prix); Pete Rust (Best Open Class); Paula & Doug Bousley (Best Firebird/TA); Betsy & Ron Thomas (Best Fullsize) and Daryl Anderson (Best GTO/Judge-unavailable for photo)



Almost three hundred Pontiac race cars descended on Norwalk for Sunday's eliminations. Winners were (L to R): Steve Silket (Pro); Ron Raiden (Super Pro and King of the Hill) and Dean Martelli (Stock).



On race day, hectic drivers and pit crews were treated to free cold drinks and cookies from the Ames Cool Down Cart.



Everyone in attendance marveled at the last remaining '63 Tempest Super Duty Wagon. Meticulously restored by owner Randy Williams (left) and Scott Tiemann. It was the highlight of the show for Pontiac Motorsports Director Fred Simmons (right).

SMITHSONIAN INSTITUTE'S "SALUTE TO MOTORSPORTS AND AUTOMOTIVE PERFORMANCE."



Approximately thirty cars from across the country were invited to The Smithsonian Institute for their 100 year anniversary celebration of the automobile



On Thursday the anniversary display moved to The Capitol lawn. Here Steve Ames talks politics and Pontiacs with Senator Ben Nighthorse Campbell (R-CO)

HOT ROD MAGAZINE'S "POWER TOUR" WITH OUR MAJOR SPONSORSHIP OF THE AUTO CUSTOM CARPET 1969 JUDGE



The main objective of sponsoring the ACC GTO was to enhance the Pontiac image across the country. At every stop thousands of car enthusiasts were exposed to The Judge (Springfield, IL is pictured)



Setting up with the ACC tractor trailer display in Lansing, IL



The new higher speed limits were just what the Judge ordered.



Pulling the trans and clutch fork ball on the side of the road near Chicago was not our favorite part of the trip.

NATION WIDE ROAD SHOWS



We display products at shows across the country in order to keep personal contact with our customers.

We'll be at the following flea markets this year: (Note: Space numbers when shown are in parenthesis)

- | | | |
|-------|---|-----------------------------------|
| Jan. | - | Springfield, MA |
| April | - | Charlotte, NC (D38-46) |
| | - | Spring Englishtown, NJ (J141-144) |
| | - | Spring Carlisle, PA (P11-15) |
| June | - | GTOAA National Convention |
| July | - | POCI National Convention |
| | - | Summer Carlisle, PA (P17-21) |
| Aug. | - | Norwalk, OH |
| Sept. | - | Fall Englishtown, NJ (J143-146) |
| Oct. | - | Fall Carlisle, PA (P14-18) |
| | - | Stafford Springs, CT |

ORDER FORM

JOIN US AT NORWALK RACEWAY FOR THE 9TH ANNUAL 2000
Ames Performance

TRI POWER

PONTIAC Nationals

AUGUST 12 & 13, 2000



AS HOST FOR THE NATIONALS, THE LARGEST ALL-PONTIAC SHOW AND RACE EVENT, AMES PERFORMANCE WANTS TO THANK AND EXPRESS OUR APPRECIATION TO ALL PARTICIPANTS BY PROVIDING:

- Ames Performance Hospitality Tent
- Complimentary Continental Breakfasts (Saturday & Sunday)
- Complimentary Catered buffet on Saturday Evening
- Free Drawing for Suite Tickets for Sunday's Racing Event
- Free Two-Day Passes for Next Year's Event Awarded to Race Eliminator Winners and Best of Show Category Winners
- Various raffles totaling hundreds of dollars of free Pontiac parts.
- All Car Show and Race Participants and a Guest are Eligible.

If you missed the first eight Pontiac Nationals you missed meeting some great Pontiac people like:

Jim Mattison-Pontiac Historic Services
 Bill Blair-Racer/Collector
 Jim Wangers-Pontiac Marketing
 Linda Vaughn-Miss Hurst
 Jim Butler-Racer, Engine Builder
 Pete McCarthy-Pontiac Enthusiast Magazine



Plus You Missed:

Terry McGean-High Performance Pontiac
 Mac McKellar-GM Performance Engineer
 Ted Jones-ESPN2
 Fred Simmons-Pontiac Motorsports Director
 John Sawruk-Pontiac Historian
 Mark Pawruk-Pro Stock



Over 300 Race Cars



Hospitality Tent-Complimentary catered buffet-
 Complimentary continental breakfasts



L to R-Eric Larsen (Driver-Grocery Getter); Arnie
 Beswick; Linda Vaughn (Miss Hurst); Bill Knafel
 (Owner-Tin Indian Race Teams)



All Pontiac Flea Market



Over 200 Show Cars



Arnie "The Farmer" Beswick



Norwalk is unquestionably one of the finest and
 well managed race tracks in the country (note the
 glassed in air conditioned suites - over 100 free
 passes are given away for Sunday's race.)

All Norwalk photos by Kruger's Photos

Presented
 By



**DRAG RACE-
 HOSPITALITY TENT**
 Each Day

BILL KLAUS
 PONTIAC • CADILLAC • GMC TRUCK

**CAR SHOW-
 SWAP MEET**
 Saturday & Sunday

For Event Information Contact: Super Duty Productions -
 P.O.Box 714 - Norwalk, OH 44857 (419)663-7383

